Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19007734/QSD3Q2

Date: 05/01/2021

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSN30768918000

Claimant Vehicle No:

SMA7623Y

Insured Vehicle No:

GX3930L

Date of Loss: 30/04/2019 Nature of Claim: TP

Claim SNM19D201891C02 No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA7623Y**

Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Engine No: 2ZR8412763 19/06/2018 (Man. Year: 2018) Reg. Date: Chassis No: ZYX102114433 Colour: Odometer: 140552 km Silver

Engine Capacity: 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

215/60R17 Front Tyre Size: 215/60R17 Rear Tyre Size: Front Left Side: Rear Left Side: West Lake 6 mm West Lake 6 mm Front Right Side: Rear Right Side: West Lake 6 mm West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,913.60	118.50	1,795.10	93.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	920.00	620.00	300.00	32.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,833.60	738.50	2,095.10	73.94
+ GST 7.00/7.00% (S\$)	198.35	51.70	146.65	73.93
Nett Amount (S\$)	3,031.95	790.20	2,241.75	73.94

INSPECTION

Date of Assignment: 02/05/2019

20/10/2020 Inspected At: Hua Hong Pte Ltd (Sungei Kadut) Date Inspected:

25D Sungei Kadut Street 1

Singapore 729332

Estimated Period of Repair: 2.0 days

Adjuster: OI SUN PIN Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Reference			
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2021)	
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	Print Code: (Unsubmitted, no print-code for SMA7623Y)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.			

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	546.00 FL	*-FL
2	10		*FRONT BUMPER CLIP	Serviceable	25.00 FL	*- FL
3	1		*FRONT BUMPER RETAINER (RH)	Serviceable	113.90 FL	*- FL
4	1		*FRONT FENDER ARCH GARNISH	Scratched	158.00 FL	*158.00 FL
5	1		*FRONT HEAD LAMP (RH)	Serviceable	1,549.10 FL	*- FL
F=Fra	F=Franchise part. L=ListItemDisc.					
				Sub Total (S\$)	2,392.00	158.00
	- List Item Discount on L Items 20.00/25.00% (S\$) _			478.40	39.50	
				Total Parts (S\$)	1,913.60	118.50
	Report was unsubmitted during this print-out.					

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISMANTLE & CHANGE FRONT BUMPER, FRONT RH HEAD LAMP, KNOCKING & PULL STRAIGHT FRONT RH FENDER AND ALL AREA AFFECTED BY ACCIDENT	New	500.00	200.00
2	TO PERFORM WIRE CHECKING	New	20.00	20.00
3	TO SPRAY FRONT BUMPER AND FRONT RH FENDER	New	400.00	400.00
	Gross Labour Cost (S\$)		920.00	620.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >