



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18019916/Gtd3e2-1

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 07-05-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	GBD 2293M	Veh. Inspected	GBG 1010D
Policy No.	DMCVSN3003321800	Coverage (\$)	0.00
Claim No.	SNM18D05177	Excess (\$)	0.00
Assign From	Chee So Chow	Assign Date	30/04/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE 3.0 DX	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KDH2010219006	Colour	SILVER
Odometer	43713	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/80 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/80 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195/80 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195/80 R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	28/10/2018	Inspection Date	03/05/2019
Survey held at	ANN JOO MOTOR PL BLK 176 SIN MING DRIVE #01-17 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	14 Working Days
-------------------------------------	-----------------