Serveyor:	ti.	REF: 053/ASM180	11838/71903-	Special Instruction:	
		ASSIC	NMENT (Office)	1/5: \$ 929	0.00
From (Person)	: Vishna Rother	nor Asm (Asat)	Date/Time: 25 2019	Harry South	
Estimated Cos	t:	Bill to:	Date time: 2 5 8019	Third Parties:	
		SIII to.		Claimant:	1 1 1 1 3
OD/TP Re-ins	spection / Evalua	e:	h .		d Auto Appruisa
			7	Workshop: Ko	h & Him Moto
To Inspect Vel	hicle No:	KT1452L	Insured: GBG 48	393C	
at Workshop n	n/s Ko	oh & tim	Tel: 9100 4:	390	
of	160 Sin Mil	ng Drive # 05.	-14	3	
		9	Claim No: \$8 M 00	IVAME /TT	
				- x - 1 1 1 C/ 3 1 .	
			Excess:	No.	2 2 7
Make of Veh: Client's Record)			D.O.A 22 06 2	1018	
_ item z iteeo, u,		17/5	1190 10am		
D				H.O.D. Endorsement/Date:	
Date/Time: _		Person Contacted:	Vehicle IN / C	OUT	
Date/Time:	Confi	med with	inal Fig days	(Red \$ / % O	. 8 minima
Date/Time:	3 5 19 Submi	it Final Fig USST 4	inal Fig,days	0,210,000	inginai_days)
			days (Red \$ 70.0	/_//_%; Original_	_days)
Date/Time	Action/Instruction				
	SK11452L-C	53/ASM/8011838	1124bez	AOA W	(200
	9186 18930	-083/ ASM 180163	8/1/24be2	Dut in 16	01-015
					DU18
		DESCUVED	o o MAV 2010		
		RECEIVED	3 U-MAT - 2013		
					atto
					March 12
	1			/ (1	
2 F				7	
Pora(1) · I	Powts Co			2	9/2/2019
Para(1) : F	Parts found no	replaced (To h	ighlight R or UB,	LR, Etc)	9/2/2010
Para(1) : F	Parts found no	replaced (To h	ighlight R or UB,	LR, Etc)	9/2/2010
•					9/2/2019
•					1/2 kolo
•			nighlight R or UB,		9/2/2019
•					9/2/2010
•					1/2 kolo
•					9/2/2010
•					9/2/2010
Para(2) : (Comments on o				1/2 kolo
Para(2) : (9/2/2010
Para(2) : (Comments on o	consistency of dan		istent : NC)	9/2/2010
Para(2) : (Comments on o	consistency of dan	nages (Parts Not Cons	istent : NC) Fee Charged:	Date:
Para(2) : (Nett Value Market Value	consistency of dan	nages (Parts Not Cons	istent : NC) Fee Charged: Basic & Add	Date:
Para(2) : (Comments on o	consistency of dan	nages (Parts Not Cons	Fee Charged: Basic & Add Transport	
Para(2) : (Nett Value Market Value Salvage Value	consistency of dan	nages (Parts Not Cons	istent : NC) Fee Charged: Basic & Add	
Para(2) : C	Nett Value Market Value Salvage Value Nett Value	consistency of dan	nages (Parts Not Cons	Fee Charged: Basic & Add Transport Photos	
Para(2) : C	Nett Value Market Value Salvage Value Nett Value	consistency of dan	Inspected/	Fee Charged: Basic & Add Transport Photos Others Total	190
Para(2) : (Nett Value Market Value Salvage Value Nett Value	eonsistency of dan	Inspected/ Evaluated by: 2) Date/Time	Fee Charged: Basic & Add Transport Photos Others Total File Return to	190
Para(2) : C Para(3) : N	Nett Value Market Value Salvage Value Nett Value	consistency of dan	Inspected/	Fee Charged: Basic & Add Transport Photos Others Total File Return to	190

CONSTRUCT :	Tautikh.	ASSIGN	MENT (Office)				
Smart claim	Jas Tan	of	Asm	Da	ite/Time:	810c20FC	11-41am
Estimated Cost			Bill to:				
OD / TP/ WS To Inspect Vel		SKT 1451L	V i CS	Insured:	GB6	4893C	
at Workshop n	n/s	Koh a lim		Tel:	9100	4390	
of		160 Sin Mind	Drue \$05-14				
Policy No			Claim No:	S6 11100	1249		
Sum Insured:_			Excess:				
Make of Veh:				D.	O.A.	22062018	
(Client's Record)							

CA / REV /	REP. / REV 241		0		II.O.D. Endor		
CA / REV /	REP. / REV 241	HRS 'WP' Person Contact	ed: Soon		H.O.D. Endon		H
CA / REV /	REP. / REV 241 27061018 149	Person Contact			0		
CA / REV /	REP. / REV 24 1	Person Contact	ate		icle (IN) C	DUT	
CA / REV /	REP. / REV 241 D7061018 149 Action/Instruction SKT 14511	Person Contact (X) Estim (S/TML 600	ate		icle (IN) C		
CA / REV /	REP. / REV 24 1	Person Contact (X) Estim (S/TML 600	ate		icle (IN) C	DUT	
CA / REV /	REP. / REV 241 D7061018 149 Action/Instruction SKT 14511	Person Contact (X) Estim (S/TML 603	ate		icle (IN) C	DUT	

ASSIGNMENT

From: Date:	Veh No: SKT 1452 L. Yr Regn: 2015 , May
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD/TP/WS/TPRES/ODRES/EVA/INV/MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Mitsubishi untlander c.c 2360.
at Workshop m/s	Colour Blue A/C: Insured / Std / NI / NA
of	Sp.Reading T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CINO: Juny X TGF3 WFZ 601970
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 225/55 R18
(Policy Condition)	R: u -
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Ruels force.
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. C mm R/Bal. C mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 17/5/19.
Lum Sum: % 3 Val.: Yes or No	Survey held at Koh & Lim.
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	r
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
^	
Date/Time, File Pass to? : Prell. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
Add Fe	
	:Interview (\$) Photos
Report Format :	: Tech, Invs (3) others
Lump Sum / LB.E (5	:Westend (S
	TOTAL

Tech Invs (\$

Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

Others

TOTAL

100

Nivitha (LKK Auto)

From:

Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Sent:

Thursday, 2 May 2019 10:43 AM

To: ,

assignments

Cc:

Admin-D (LKKAuto)

Subject:

FW: Acknowledgement Your ref : SKT1452L Our ref : S8M00LV9MC/JT

Attachments:

TP KOH & LIM-LOD.pdf

Hi

Tp RE-INSPECTION. Kindly assist. CS3/ASM18011838/T1z4be2

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: <u>MeiKwan@lkkauto.com</u> | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Susan Lim/Fion Pee <kohlimmotoring@gmail.com>

Sent: Monday, 29 April, 2019 3:05 PM

To: VISHNU BATHAM Shekhar < shekhar.batham@axa.com.sg>

Cc: TAN Jas <jas.tan@axa.com.sg>

Subject: Re: Acknowledgement Your ref: SKT1452L Our ref: S8M00LV9MC/JT

Dear Officers

Good day,

Kindly be informed that we would like to book a resurvey for vehicle SKT1452L.

The vehicle will be in for resurvey on 14.05.2019 (Tue) 1000-1300hrs.

Thank You Best Regards Susan

91004390

KOH & LIM MOTORING SERVICES

On Thu, Sep 20, 2018 at 1:03 PM VISHNU BATHAM Shekhar <shekhar.batham@axa.com.sg> wrote:

ACCIDENT INVOLVING GBG4893C AND SKT1452L ON 22/06/2018

Without Prejudice

We would like to conduct a re-inspection of your client's vehicle **SKT1452L**. Please let us know a suitable date and time.

We acknowledge receipt of your letter dated 06/09/2018 and the enclosures on 18/09/2018

We would appreciate that in letting us know the date, your client could allow us at least 10 days of lead-time. This is to allow us to co-ordinate with the surveyor concerning the re-inspection date and time.

May we hear from you in due course.

For future correspondence, please reply to TAN Jas at jas.tan@axa.com.sq

Regards,

Shekhar Batham

AXA Singapore



-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Singapore - Externals or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

60109860

160 Sin Ming Drive #05-14 Singapore 575722 Reg.No.52953985C Hp 91004390/91254449 Fax 64841482

Email:kohlimmotoring@gmail.com

06.09.2018

Our Ref

: SKT 1452 L

Your Ref

: GBG 4893 I

Lim Kuan Hong

C/o Koh & Lim Motoring Service

Attn: Motor Claims Department

AXA Insurance Pte Ltd 8 Shenton Way, #27-01

AXA Tower

Singapore 068811

Dear Sir/Mdm,



RE: ACCIDENT INVOLVING SKT 1452 L & GBG 4893 L ON 22.06.2018.

We refer to the above matter.

We are repairer of vehicle no. <u>SKT 1452 L</u> which was involved in an accident with vehicle no. <u>GBG 4893 L</u>, which is insured with you.

The accident was clearly caused by your insured's negligence. We are therefore seeking compensation from you for the financial losses as itemized below:-

Days

Cost Of Repair

\$9,290.00

Survey Fee

\$878.00

Rental Fee

12

\$150.00

\$1,800.00

Total

\$11,968.00

We enclose copies of the relevant documents to support our claim.

Your prompt settlement of my claim would be much appreciated.

Please contact Susan (91004390). Alternatively, you may fax to 64841482 should you have any queries.

Thank you for your kind attention.

Yours faithfully,

Koh & Lim Motoring Services.



160 Sin Ming Drive #05-14 Singapore 575722

Reg.No.52953985C HP 91004390/91254449 Fax 6484 1482

Email:kohlimmotoring@gmail.com

M/s AXA Insurance Pte Ltd DATE 06.09.2018

8 Shenton Way, #27-01 CAR NO SKT 1452 L

AXA Tower S068811 MAKE Mitsubishi Outlander

Qty	Pcs	JMYXTGF3WFZ001970		UNIT PRICE	AMOUNT
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	pc pc pc pc pc pc pc pc pc pc pc pc pc p	Tailgate assembly Tailgate windscreen glass moulding Tailgate windscreen dam kit Tailgate windscreen wiper blade Tailgate windscreen wiper arm Tailgate windscreen wiper motor Tailgate outer reflector Tailgate outer reflector Clip Tailgate outer reflector Mitsubishi logo Tailgate Outlander emblem Tailgate Mivec Technology plate Tailgate motorised lock assembly Rear end outer panel Rear end panel top garnish Rear end panel top garnish clip Tailgate lock striker Tailgate opening weather-strip Rear combination lamp – o/s Rear bumper face Rear bumper reverse lamp bezel – o/s Rear bumper reverse lamp bezel – n/s Rear bumper impact bracket – o/s Rear bumper impact bracket – n/s Rear bumper side retainer – o/s To be continu	e on Pg 2		
1	4		Pg 1 of 3	Total	

160 Sin Ming Drive #05-14 Singapore 575722 Reg.No.52953985C HP 91004390/91254449 Fax 6484 1482 Email:kohlimmotoring@gmail.com

M/s AXA Insurance Pte Ltd DATE 06.09.2018

8 Shenton Way, #27-01 CAR NO SKT 1452 L

AXA Tower S068811 MAKE Mitsubishi Outlander

Qty	Pcs	JMYXTGF3WFZ001970	UNIT PRICE	AMOUNT
		Continue from Pg 1		
		Special Nett Item		
1 1 1 1	pc pc pc pc	Tailgate inner sealer Tailgate windscreen glass sealant Rear license plate with casing Tailgate C & C plate Rear end outer panel joint sealant		
		Recommended Labour		
		To cut/weld rear end outer panel to renew and repair rear bumper lower guard including replacement of the rear accident damaged parts.		
		To remove/install tailgate windscreen glass to facilitate the replacement of the tailgate panel include performing water leakage test.		
		To transfer tailgate locking mechanism and other components to new tailgate panel include checking components for function.		
		To transfer tailgate parking aid camera to new tailgate panel include testing for functions.		
		To be continue on Pg 3		
0	h	Pg 2 of 3	Total	

Koh\& Lm Motoring Services.

160 Sin Ming Drive #05-14 Singapore 575722

Reg.No.52953985C HP 91004390/91254449 Fax 6484 1482

Email:kohlimmotoring@gmail.com

M/s AXA Insurance Pte Ltd DATE 06.09.2018

8 Shenton Way, #27-01 CAR NO SKT 1452 L

AXA Tower S068811 MAKE Mitsubishi Outlander

Qty	Pcs	JMYXTGF3WFZ001970	UNIT PRICE	AMOUNT
		Continue from Pg 2		
		Recommended Labour		
		To remove/install trunk compartment trim finishers, garnishes and interior upholstery to facilitate the replacement of the rear end outer panel.		
		To check rear lightings and right side door electrical wiring systems include performing water leakage test.		
		To install rear bumper parking sensors to new bumper face include testing for functions.		
		To putty and respray painting on tailgate, rear end outer panel, rear bumper face and rear bumper lower guard.		
		Rust proofing on the rear accident affected portions.		
		Lump Sum Cost of Repair:		\$9,290.00
\	DA	Pg 3 of 3	Total	\$9,290.00

Koh & Um Motoring Services.



Registered Address: 126 Joo Seng Road #05-12 Gold Pine Industrial Building Singapore 368355

Operation Address: 160 Sin Ming Drive, #08-05 Sin Ming AutoCity Singapore 575722 Tel: 6266 2307 Fax: 6266 2306

	AGREEMENT	0.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	260	1 3
HIRER'S PARTICULAR	Veh No :>	Replace Ve	h No :	
Name: (as in I/C) 100 Yuan Heng	Mileage Out :	Mileage Ou	t:	
NRIC / PASSPORT No . S&E31885E	Make & Model	Make & Mo	del	
Address (Res): 61E Chica Chu Kang Road	Auto / Manual	Auto / Man	ual	
5681393	OUT : Date 25	OUT : Date		
Name & Address of Employer: Set employed	OUT : Time	OUT : Time		
• /	RENTAL CHARGES	3		
Occupation : Driving Exp :	Daily (2 0\$ 50)		4.800	0.0
D/L No: S8031885© D/L Type : Local/International	Weekly @\$		7.303	
Pass Date Date of Birth : i\ OCT 1980	Monthly @\$			
Tel : (0) (R) HP/PG ·	Hours @S			
ADDITIONAL DRIVER'S PARTICULARS Name: (as in I/C) NRK TZELIN	Others @\$			1
	CDW @S		1	
NRIC / PASSPORT No S 27 1 67 2 Pass Date : Date of Birth : 0307 1882	PAI @\$			
Address (Res): 61 E Choa Chu Kang Ad S659398				
Tel/Hp: 98312177		B-TOTAL \$	1325	30
Refundable Deposit :	OUT	IN		-
Cash/Nets/Cheque/VISA/MC Cards No :	Live y	1		-
(A) - ACCIDENTS (D) - DENTS (S) - SCRATCHES	\ n \ \ \	W2 >		
FRONT	E F E	F		-
	EXTENSION			_
	Collection Service			
	Misc.			
	ESTIMATED TOTAL	RENTAL \$		
LEFT RIGHT	Sales Person Code :			
REAR	Hirer is responsible for the first damage to first party. (i.e.) Ri (including windscreen) and al collision / damage to third paracident / damage.	CA LEASING	O.00 exc	Vehicless fo
ACCESSORIES CHECK	Hirer's Signature	24		
Ashtray Cig Lighter S / Tyre STD Tools Jack Hub Caps	ATTACHER TO A STATE OF THE PARTY OF THE PART			
Radio / Cass CD/Cartridges S / RIM	Addition Driver's Signature			
We agreed to the ferms and conditions above, overleaf and that all it ence(s) is/are current and not disqualified from driving. You may charge MPORTANT ONLY PERSONS ABOVE 25 YEARS OF AGE WITH MORE THAN 2 YEARS AGREEMENT MAY DRIVE THE VEHICLE. VEHICLE IS STRICTLY FOR SINGAPORE USE ONLYAND MAY NOT BE DRIVI RICA LEASING PTE LTD IN THE EVENT OF AN ACCIDENT, THE HIRER OR AUTHORIZED DRIVER: (i) shalf are immediate steps to complete and sign Form MAR 1 (Motor Accident Report form REPORT SCEHEME* (the form will be made available when the accident is report to the C (ii) shalf aport to the police within 24 hours from the occurrence, the following types of accide (a) injury case.	e all amount due on the rental to m DRIVING EXPERIENCE AUTHORIS EN OUT OF SINGAPORE WITHOUT F In) and do all other acts required in compliance Dwneri	ED LICENSE	eard D AND SIGN NT OF THE C	ING '
(b) non-injury case myolying a Government vehicle or damage to Government property		Log card and Ve		

34	DEPOSIT REFUND	REMARKS	CHECKED BY	MILEAGE	TIME IN	DATE IN
-62				3 2414	1.359	els four
SIGNATURE OF HIRER/DRIVER				2004	1	1.4.5



Our Reference

: 18/0092/TP

Invoice Number

: 1450

Date: 30 July 2018

Mr Lim Kuan Hong C/o 160 Sin Ming Drive #05-14 Sin Ming AutoCity Singapore 575722

INVOICE

DESCRIPTION	AMOUNT S\$		
Professional Inspection Fee (SKT 1452 L)	\$480.00		
Coloured Photographs (98 pieces)	\$98.00		
Transport Fee	\$60.00		
Re-inspection Fee (30/06/2018, 02/07/2018 & 06/07/2018)	\$240.00		
TOTAL	\$878.00		

Terms of payment: Cash on delivery All payments payable to "Allied Auto Appraisal"



Allied Auto Appraisal





Our Ref : 18/0092/TP Your Ref : Not Advised : Not Advised Date: 29 June 2018

Mr Lim Kuan Hong C/o 160 Sin Ming Drive #05-14 Sin Ming AutoCity Singapore 575722

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT (WITHOUT PREJUDICE)

Detailed accounts of our inspection are as follows:

(1) REFERENCE

Name of Claimant	:	Mr. Lim Kuan Hong	Date of Request	:	29 June 2018
Policy Number	:	Not Advised	Referred By		Insured
Claim Number		Not Advised	Date of Inspection		29 June 2018
Accident Date	:	22 June 2018	Date of Re-inspection		30 Jun, 2 Jul & 6 Jul 2013
Repairer	:	Koh & Lim Motoring Services	Sum Insured	:	Not Applicable
		160 Sin Ming Drive	Excess Amount	:	Not Applicable
		#05-14 Sin Ming AutoCity	3rd Party Vehicle		GBG 4893 C
		Singapore 575722	3rd Party Insurer	1	AXA Insurance Singapore
			NEW ATTENDATE PLANTAGE CHILDRAN		Pte Ltd

(2) PARTICULARS OF VEHICLE

Registration Number	:	SKT 1452 L	Mileage	-	56,422 km
Make & Model		Mitsubishi Outlander 2.4 CVT	Chassis Number	:	JMYXTGF3WFZ00197C
Date of Registration	:	26 May 2015	Engine Number	:	4B12PL4690
Colour	:	Blue	Engine Capacity	_ :	2,360 cc


(3) PRE-ACCIDENT CONDITION (STATIC TEST ONLY)

Steering	: In order	Paint Work	:	Good
Foot-brake	: In order	Modification	:	Sports rim
Hand-brake	: In order	General Condition	:	Average

(4) TYRE CONDITION

	Remaining Thread Depth (%)	Make	Size
Front right tyre	90%	Roadstone	P225/55R18
Front left tyre	90%	Roadstone	P225/55R18
Rear right tyre	95%	Roadstone	P225/55R18
Rear left tyre	95%	Roadstone	P225/55R18

(5) POINT OF IMPACT



(6) GENERAL DESCRIPTION OF DAMAGES

The impact of the collision has damaged/affected the tailgate, right rear combination lamp, rear end panel, rear bumper face and etc.

Please refer to the Annex for a detailed account of the damages and photographs taken.

(7) RECOMMENDATION

We have inspected thoroughly the actual damages found on the vehicle before we conclude as to whether the parts needed replacement or repairs. The estimated cost of repair submitted by the repairer is \$13,489.10. We have adjusted the cost to \$10,322.70 and recommend that the repairs to be taken on a lump sum basis of \$9,290.00. In our opinion, the damaged parts are consistent with that caused by the accident.

(8) REMARKS

We have not authorised the repairs. However, for information, under normal circumstances, the period of repair should not exceed <u>8</u> working days.

This inspection was conducted on a "Without Prejudice" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report and photographs.

Allied Auto Appraisal

Motor Vehicle Appraiser





ANNEX

REPAIR DETAILS	(SKT 1452 L)
----------------	--------------

lo	Qty	Particulars	Condition	Repairer's	Adjuster's
	diy		Condition	Amount	Amount
		Nett Items			
1	1	Tailgate Assembly	Badly Dented	1,166.00	1,166.00
2	1	Tailgate Windscreen Glass	Serviceable	965.00	0.00
	1	Tailgate Windscreen Glass Moulding	Necessary	121.00	121.00
Į	1	Tailgate Windscreen Dam Kit	Necessary	110.00	110.00
	1	Tailgate Windscreen Wiper Blade	Missing/Dislodged	35.00	35.00
ii.	1	Tailgate Windscreen Wiper Arm	Broken	70.00	70.00
CI.	1	Tailgate Windscreen Wiper Motor	Shaft Bent	550.00	550.00
	1	Tailgate Outer Reflector	Len Cracked	752.00	752.00
	11	Tailgate Outer Reflector Clip @\$4.00 each	Necessary	44.00	44.00
0	1	Tailgate Outer Reflector Mitsubishi Logo	Necessary	37.00	37.00
1	2	Tailgate License Plate Lamp @\$37.00 each	Serviceable	74.00	0.00
2	1	Tailgate OUTLANDER Emblem	Necessary	103.00	103.00
3	1	Tailgate MIVEC TECHNOLOGY Plate	Necessary	83.00	83.00
1	1	Tailgate Motorised Lock Assembly	Dented/Bent	1,273.00	1,273.00
5	1	Rear End Outer Panel	Badly Dented	296.00	296.00
3	1	Rear End Panel Top Garnish	Dented/Deformed	123.00	123.00
7	4	Rear End Panel Top Garnish Clip @\$4.00 each	Necessary	16.00	16.00
3	1	Tailgate Lock Striker	Bent	24.00	24.00
9	1	Tailgate Opening Weather-strip	Deformed/Kinked	232.00	232.00
)	1	Rear Combination Lamp - O/s	Len Cracked/Broken	748.00	748.00
1	1	Rear Combination Lamp - N/s	Serviceable	748.00	0.00
2	1	Rear Bumper Face	Dented/Deformed	1,158.00	1,158.00
3	6	Rear Bumper Clip @\$3.00 each	Necessary	18.00	18.00
4	2	Rear Bumper Parking Sensor @\$336.00 each	Dented/Malfunction	672.00	672.00 SH 2
5	1	Rear Bumper Reverse Lamp - O/s	Serviceable	187.00	0.00
6	1	Rear Bumper Reverse Lamp - N/s	Serviceable	187.00	0.00
7	1	Rear Bumper Reverse Lamp Bezel - O/s	Holder Snapped	73.00	73.00
3	1	Rear Bumper Reverse Lamp Bezel - N/s	Holder Snapped	73.00	73.00
)	1	Rear Bumper Lower Guard	Scratched - To Repair	565.00	0.00
)	1	Rear Bumper Impact Bracket - O/s	Dented/Bent	78.00	78.00
1	1	Rear Bumper Impact Bracket - N/s	Dented/Bent	78.00	78.00
2	1	Rear Bumper Side Retainer - O/s	Holder Broken	20.00	20.00
3	1	Rear Bumper Side Retainer - N/s	Serviceable	20.00	0.00
			- 386	10,699.00	7,953.00
			17.40 Less 10% _	1,069.90	795.30

Our Ref: 18/0092/TP Vehicle No: SKT 1452 L

Allied Auto Appraisal

			Sub-Total	9,629.10	7,157.70
		Special Nett Items		15/30537.38	500 Tri 0.000 00 00 00 00 00 00 00 00 00 00 00
34	1	Tailgate Inner Sealer	Necessary	80.00	60.00
35	1	Tailgate Windscreen Glass Sealant	Necessary	80.00	60.00
36	1	Rear License Plate With Casing	Dented/Bent	60.00	55.00 45
37	1	Tailgate C&C Plate	Necessary	30.00	30.00
38	1	Rear End Outer Panel Joint Sealant	Necessary	80.00	60.00 40
			Total Parts (S\$)	9,959.10	7,422.70 734

Recommended Labour

No	Particulars	Repairer's Amount	Adjuster's Amount
1	To cut/weld rear end outer panel to renew and repair rear bumper lower guard including replacement of the rear accident damaged parts.	1,500.00	1,200.00 900
2	To remove/install tailgate windscreen glass to facilitate the replacement of the tailgate panel include performing water leakage test.	180.00	150.00 120
3	To transfer tailgate locking mechanism and other components to new tailgate panel include checking components for function.	150.00	120.00 60
4	To transfer tailgate parking aid camera to new tailgate panel include testing for functions.	120.00	80.00 40
5	To remove/install trunk compartment trim finishers, garnishes and interior upholstery to facilitate the replacement of the rear end outer panel.	250.00	180.00 60
6	To check rear lightings and right side door electrical wiring systems include performing water leakage test.	80.00	50.00 30
7	To install rear bumper parking sensors to new bumper face include testing for functions.	80.00	60.00 3
8	To putty and re-spray painting on tailgate, rear end outer panel, rear bumper face and rear bumper lower guard.	1,050.00	980.00 800
9	Rust-proofing on the rear accident affected portions.	120.00	80.00 40
	Total Labour (S\$)	3,530.00	2,900.00
	Total Repair Cost (S\$)	13,489.10	10,322.70

Adjusted Repair Cost (Lump sum basis) \$\$9,290.00

\$\$9,290.00 7992.40 45\$ 6400