

2/03/2009

n2

ASS. REC. BY:

REF: CS/FCI 19007772/ KVD3

Special Instruction:

Survey: Lenix

ASSIGNMENT (Office)

CWS

From (Person): Serineof FCIDate/Time: 25.19 3:18 p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 9884BInsured: SH 6569Uat Workshop m/s Trans - Cab AutoTel: 62876666of M2 Amk strut 63

Policy No:

Claim No: D19002857 MF5H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 28.4.20193.5.2019

CA / REV / REP. / REV 24 HRS

"w"

H.O.D. Endorsement:

Date/Time: 25.19 4:41 p.m

Person Contacted:

AmandaVehicle IN/OUT

Date/Time	Action/Instruction	
	<u>Johnnie (✓)</u>	
	<u>SHB 9884B - CS/TP1800382m / Kbn 2</u>	<u>D.O.A - 12/03/2018</u>
	<u>SH 6569U - CC3/AXA 11006927 / H/W 282K</u>	<u>D.O.A - 07/04/2011</u>
<u>6/5/19</u>	<u>Email preli revised to FCI</u>	

Surveyor

ASSIGNMENT

From:

Date: 31/5/2019

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SHB 9884B

at Workshop m/s

Transcab

of

No. 2 AMK St. 63

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1wp

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 9884B

Yr Regn:

08, 13

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Pengout Latitude G.C.

1995

Colour

M. White / Red

NC: Insured / Std / NI / NA

Sp. Reading

56081608

T/Radio: Insured / Std / NI / NA

Eng/No:

VFIABL 15AUC 273396

C/No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

28/4/19

D.O.I.

3/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/5/19

Get injury.
Lip & 76501

(Red 38,441.68, 839)

date of accident 28/4/2019

RECEIVED 06 MAY 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 6/5 - typist

Report Format :

CWS

Lump Sum / I.B.I. (\$

7650/2

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

___ S + RS ___ SI

) Photos

) Others

TOTAL

350

MOTOR SURVEY ASSIGNMENT

Date	30-04-2019	Our Ref No. D19002857MFSH
Accident Date	28-04-2019	Claim Type. Third Party
Insured Vehicle	SH6569U	Third Party Vehicle. SHB9884B
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	AMANDA TAY	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: EST. COR - \$46091.68	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 6 May 2019 2:02 PM
To: calvin.er@transcab.com.sg; Ng Wai Yin
Cc: SUR; jasminetan@transcab.com.sg
Subject: SHB 9884B-DOA: 28/4/2019
Attachments: MARK EST.pdf

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Lump Sum \$ 7650/- @ 3 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 6 May 2019 1:53 PM
To: 'CWS Motor Claims'; SUR
Cc: 'Serene Ler'
Subject: RE: SURVEY ASSESSMENT - D19002857MFSH/1, SHB 9884B
Attachments: SHB 9884B PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHB 9884B
Date of survey: 3/5/2019
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 2 May 2019 4:35 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19002857MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed that repairer agreed to survey on 3/5/2019.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 2 May, 2019 3:41 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002857MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19002857MFSH

Our ref: CS/FCI19007772/Kvd3

Date : 6/5/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 9884B


We thank for your instruction on 2/5/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 3/5/2019 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$46,091.68
Revised Estimate Amount	: S\$7,650.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHB9884B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Apr 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000469
Chassis No.:	VF1ABL15AUC273396
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Aug 2013
First Registration Date:	30 Aug 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2021
PARF Rebate Amount:	\$8,748.00

Intended COE Rebate Details

COE Expiry Date:	29 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$54,952.00
COE Rebate Amount:	\$16,027.00
Total Rebate Amount:	\$24,775.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 29 Apr 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHB 9884B**AAD1904-257**

Not Notified
11 Sep @ 7650h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SHB 9884P

VF1ABL15AUC273396

RENAULT

LATITUDE

29.4.2019

FCIL

30/8/2013

	PART
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	HEADLAMP LH
1	HEADLAMP PANEL FRT LH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER INSULATOR RH
1	DOOR PANEL FRT RH
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	RADIATOR FAN COWLING
1	RADIATOR FAN MOTOR LH
1	RADIATOR FAN MOTOR RH
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET
1	DOOR MIRROR ASSY RH
1	DOOR PANEL FRT RH
1	BONNET
1	BONNET INSULATOR

LIST

\$	CM	1,259.42	✓
\$	M	181.75	✓
\$	M	394.68	✓
\$	CM	150.77	✓
\$	CM	123.88	✓
\$	CM	472.83	✓
\$	SL	266.80	X
\$	M	207.21	✓
\$	R	914.08	✓
\$	CM	1,184.43	✓
\$	R	152.15	✓
\$	SL	1,184.43	X
\$	R	152.15	X
\$	R	783.83	✓
\$	CM	278.84	✓
\$	R	15.79	✓
\$	SL	130.84	X
\$	R	2,844.66	X
\$	SL	1,707.78	} X
\$	SL	225.36	
\$	SL	1,353.75	
\$	SL	820.54	
\$	SL	967.36	
\$	SL	1,479.46	
\$	R	615.90	
\$	R	89.79	
\$	SL	1,483.40	} X
\$	R	2,844.66	
\$	R	1,941.63	✓
\$	SL	405.73	X

24633.9

Trans-cab Auto Services Pte Ltd

AAD1904-257

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9884B

1	BONNET STRUT LH	\$	88.61	
1	BONNET STRUT RH	\$	88.61	
1	BONNET HINGE LH	\$	348.31	
1	BONNET HINGE RH	\$	348.31	
1	BONNET LOCK	\$	305.48	
1	BONNET CABLE	\$	119.19	
1	BONNET CABLE COVER	\$	161.03	
1	BONNET SEAL OUTER	\$	92.36	
1	BONNET SEAL INNER	\$	157.28	
1	SUBFRAME OUTER FRT	\$	2,652.45	
1	SUBFRAME BRACKET OUTER LH	\$	92.36	
1	SUBFRAME BRACKET OUTER RH	\$	92.36	
1	ENGINE UNDERTRAY	\$	564.98	
1	A/C CONDENSER	\$	2,020.37	
1	A/C CONDENSER GARNISH LH UPPER	\$	39.67	
1	A/C CONDENSER GARNISH RH UPPER	\$	39.67	
1	A/C CONDENSER GARNISH LH	\$	58.81	
1	A/C CONDENSER GARNISH RH	\$	59.60	
1	LOWER ARM RH	\$	685.76	
1	KUNCKLE ARM RH	\$	846.98	
1	ABSORBER FRT RH	\$	360.54	
1	STABILIZER BAR FRT	\$	604.65	
1	DRIVESHAFT RH	\$	1,747.45	
1	WIPER RESERVOIR	\$	348.25	
1	WIPER RESERVOIR NECK	\$	136.11	X
1	WIPER RESERVOIR MOTOR	\$	270.06	X

TOTAL	\$	36,963.11
10%	\$	3,696.31
	\$	33,266.80

Special Nett

1SET	BUMPER CLIP FRT	\$	66.00	
1	BUMPER BRACKET CLIP FRT RH	\$	12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	X

Trans-cab Auto Services Pte Ltd

AAD1904-257

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9884B

2	FRAME FULL SUPPORT PANEL NUT	\$	nn 20.00 X
2	FRAME FULL SUPPORT PANEL STUD	\$	nn 30.00 X
1SET	WHEELARCH CLIP FRT RH	\$	nn 30.50
6	BONNET INSULATOR CLIP L70Y	\$	nn 7.30
2	BONNET STRUT L70Y	\$	nn 88.61
2	BONNET CABLE CLIP L70Y	\$	nn 6.31
2	BONNET CABLE COVER SCREW L70Y	\$	nn 10.85
1	WINDSCREEN SEALANT	\$	nn 253.80
1	FRONT WINDSCREEN MOULDING	\$	nn 120.00
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn 100.00
1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	nn 80.00 605n
1	FRONT RIGHT DOOR STICKER '6555-3333'	\$	nn 50.00 155n
1	FRONT RIGHT TYRE	\$	nn 330.00 2081n 264
1	FRONT RIGHT TYRE RIM	\$	nn 380.00 X

87

TOTAL	\$	1,734.88
--------------	-----------	-----------------

TOTAL PARTS	\$	35,001.68
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 5001
Putty and spray painting of the affected portion.	\$	4,000.00 8801
To rust-proofing of the affected areas.	\$	170.00 901
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	220.00 601
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1904-257**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9884B

To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	~ 380.00	X
To replace, refix and top up coolant for radiator	\$	~ 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	~ 170.00	X
To transfer of front windscreen fittings and conduct water seepage test	\$	~ 170.00	X

TOTAL \$ 11,090.00**Over All Total \$ 46,091.68****LUMP SUM (REPAIR DAY)****15 DAYS****3 days**

46261.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19007772/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6569U	Veh. Inspected	SHB 9884B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002857MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	02/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	VF1ABL15AUC273396	Colour	METALLIC WHITE / RED	
Odometer	616688	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/04/2019	Inspection Date	03/05/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9884B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER FRT	CRACKED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	MISSING	181.75	181.75
1	BUMPER ABSORBER FRT	MISSING	394.68	394.68
1	BUMPER RETAINER FRT RH	CRACKED	150.77	150.77
1	BUMPER SUPPORT FRT	CRACKED	123.88	123.88
1	BUMPER UNDERTRAY FRT	CRACKED	472.83	472.83
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE RH	MISSING	207.21	207.21
1	BUMPER BEAM FRT	BENT	914.08	914.08
1	HEADLAMP RH	CRACKED	1,184.43	1,184.43
1	HEADLAMP PANEL FRT RH	BENT	152.15	152.15
1	HEADLAMP LH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT RH	BENT	783.83	783.83
1	WHEELARCH FRT RH	CRACKED	278.84	278.84
1	FENDER BRACKET LOWER RH	BENT	15.79	15.79
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE "RENAULT"	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	RADIATOR FAN COWLING	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,479.46	-
1	FRAME FULL SUPPORT PANEL	TO REPAIR SEE LABOUR	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-

Report Ref No. CS/FC119007772/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET	BENT	1,941.63	1,941.63
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	SUBFRAME OUTER FRT	TO REPAIR SEE LABOUR	2,652.45	-
1	SUBFRAME BRACKET OUTER LH	TO REPAIR SEE LABOUR	92.36	-
1	SUBFRAME BRACKET OUTER RH	TO REPAIR SEE LABOUR	92.36	-
1	ENGINE UNDERTRAY	SERVICEABLE	564.98	-
1	A/C CONDENSER	SERVICEABLE	2,020.37	-
1	A/C CONDENSER GARNISH LH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH RH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH	SERVICEABLE	58.81	-
1	A/C CONDENSER GARNISH RH	SERVICEABLE	59.60	-
1	LOWER ARM RH	SERVICEABLE	685.76	-
1	KNUCKLE ARM RH	SERVICEABLE	846.98	-
1	ABSORBER FRT RH	SERVICEABLE	360.54	-
1	STABILIZER BAR FRT	SERVICEABLE	604.65	-
1	DRIVESHAFT RH	TO REPAIR SEE LABOUR	1,747.45	-
1	WIPER RESERVOIR	DENTED	348.25	348.25
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-

Report Ref No. CS/FCI19007772/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-3,696.32	-840.95
			33,266.83	7,568.59
	<u>SPECIAL NETT ITEMS</u>			
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT RH (SN)	NECESSARY	30.50	30.50
6	BONNET INSULATOR CLIP L70Y (SN)	NOT NECESSARY	7.30	-
2	BONNET STRUT L70Y (SN)	NOT NECESSARY	88.61	-
2	BONNET CABLE CLIP L70Y (SN)	NOT NECESSARY	6.31	-
2	BONNET CABLE COVER SCREW L70Y (SN)	NOT NECESSARY	10.85	-
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	253.80	-
1	FRONT WINDSCREEN MOULDING (SN)	NOT NECESSARY	120.00	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	FRONT RIGHT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	FRONT RIGHT DOOR STICKER "6555-3333" (SN)	NECESSARY	50.00	15.00
1	FRONT RIGHT TYRE (80%)(SN)	CUT	330.00	264.00
1	FRONT RIGHT TYRE RIM (SN)	TO REPAIR SEE LABOUR	380.00	-
			1,734.87	435.50
	<u>LABOUR</u>			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF HEADLAMP PANEL FRT LH,DOOR PANEL FRT RH,FRAME FULL SUPPORT PANEL,FRAME FULL SUPPORT BRACKET,DOOR PANEL FRT RH,BONNET HINGE LH,BONNET HINGE RH,BONNET LOCK,SUBFRAME OUTER FRT,SUBFRAME BRACKET OUTER LH,SUBFRAME BRACKET OUTER RH,DRIVESHAFT RH AND FRONT RIGHT TYRE RIM.		4,500.00	500.00

Report Ref No. CS/FCI19007772/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,000.00	880.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	90.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF BONNET FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO VACUUM, REPLACE, REFILL AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-
	TO REPLACE, REFILL AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO VACUUM, REPLACE, REFILL AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			11,260.00	1,550.00
	GRAND TOTAL		46,261.70	9,554.09
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,650.00

Report Ref No. CS/FC119007772/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.