

Shu Fatt Auto Works
Singapore
159723

Claim Reference:
 Assessment number: SF078
 Version: 1810
 Date calculated: 06/06/2019 3:22 PM

Full Report
 Registration: SFH823D
 Printed: 06/06/2019 3:22 PM

Code	Description	WU	Price SGD
NO NUMBER	R + R LANDING PANEL SUPPORT	2.0	10.00 ✓
531041	R + R L/F WHEELHOUSE COVER	4.0	20.00 ✓
851061	R + R WASHER NOZZLES	3.0	15.00 ✓
851091	R + R WASHER RESERVOIR	6.0	30.00 ✓
B085	R + R FRONT WIPER MOTOR	4.0	20.00 ✓
B085	R + R BLOWER GRILLE	3.0	15.00 ✓
NO NUMBER	R + R L/SILL RAIL	7.0	35.00 ✓
NO NUMBER	R + R R/SILL RAIL	7.0	35.00 ✓
M020	R + R RADIATOR	7.0	35.00 ✓
	INCLUDES: BLEED COOLING SYSTEM		
M010	RENEW CONDENSER	10.0	50.00 ✓
NO NUMBER	REFILL AIR CONDITIONING	4.0	20.00 ✓
0471	BONNET REPAIR	10.0*	50.00 ✓
1124	R/WHEELHOUSE REINF REPAIR	8.0*	40.00 ✓
5966	R/S-MEMBER REINFORCE REPAIR	40.0*	200.00 ✓
Labour Cost		Hrs	WU
Panel / Mechanical Labour		18.20	182.0
Total of Labour			910.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT PEARL/MICA	WU Price SGD
	FRT BUMPER REINF SURFACE PAINT	4.0
	R/F WING NEW PART PAINTING	11.0
	LOCK CARRIER SUPPORT SURFACE PAINT	4.0
	FRONT PANEL CPL SURFACE PAINT	7.0
	BONNET REPAIR PAINTING >50%	36.0
	L/F WING SURFACE PAINT	6.0
	R/WHEELHOUSE REINF SURFACE PAINT	4.0
	R/WING REINFORCEMENT SURFACE PAINT	5.0
	R/S-MEMBER REINFORCE SURFACE PAINT	4.0

Paint Material Per Part

Code	Description	Price SGD
0339	FRT BUMPER REINF SURFACE PAINT	1.25
0742	R/F WING NEW PART PAINTING	24.25
0988	LOCK CARRIER SUPPORT SURFACE PAINT	1.99
1009	FRONT PANEL CPL SURFACE PAINT	16.43

Shu Fatt Auto Works
Singapore
159723

Claim Reference:

Assessment number: SF078

Version: 1810

Date calculated: 06/06/2019 3:22 PM

Full Report

Registration: SFH823D

Printed: 06/06/2019 3:22 PM

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET REPAIR PAINTING >50%	57.28
0741	L/F WING SURFACE PAINT	11.70
1124	R/WHEELHOUSE REINF SURFACE PAINT	2.49
1168	R/WING REINFORCEMENT SURFACE PAINT	7.47
5966	R/S-MEMBER REINFORCE SURFACE PAINT	1.99

Labour Cost - Paint

Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint			81.0	
Preparation Main Work Metal		2.50	25.0	125.00
Total	10 WU/h	10.60	106.0	530.00

Material Cost - Paint

	Price SGD
New Part Painting	24.25
Repair Painting	57.28
Surface-/Blend Paint	43.32
Material-constant Metal Preparation	28.60
Total	153.45

Spare Parts

prices as at 2015-06-01/01

Code	Description	Part Number	Supplier	Price SGD
① 0281	FRONT BUMPER	52119 0K949	BR	300.00
② 0322	R/F BUMPER BRACKET	52147 0K010	DT	30.00
③ 0338	R/F UPP BUMPER BRKT	52115 0K020	BR	55.00
④ 0339	FRT BUMPER REINF	52021 0K022	DD	180.00
⑤ 0350	FRT BUMPER CLAMP KIT	52161 02030	PC	24.00
⑥ 0410	GRILLE	53111 0K300	BR	230.00
⑦ 0411	RADIATOR GRILLE TRIM	53121 0K140	BR	160.00
⑧ 0431	MANUFACTURER BADGE	75311 0K060	PC	50.00
⑨ 0527	UPP RAD GRILLE SEAL	53397 0K020	TN	45.00
⑩ 0562	RIGHT HEADLAMP ASSY	81110 0K270	ER	280.00
⑪ 0638	R/F FOG LAMP CPL	81210 0K051	ER	160.00
⑫ 0742	R/F WING	53811 0K020	ER	250.00
⑬ 0988	LOCK CARRIER SUPPORT	53208 0K010	DD	70.00
⑭ 1009	FRONT PANEL CPL	53201 0K010	DD	380.00
⑮ 4465	CONDENSER	88460 0K110	DD	560.00
⑯ 7761	RADIATOR	16400 0C220	Twisted	350.00

Shu Fatt Auto Works
Singapore
159723

Claim Reference:

Assessment number: SF078

Version: 1810

Date calculated: 06/06/2019 3:22 PM

Full Report

Registration: SFH823D

Printed: 06/06/2019 3:22 PM

Code	Description	Part Number	Supplier	Price SGD
7767	AIR GUIDE PANEL	16711 0C110	/ CR4	130.00
1002	arch clips	arch clips	/ APC	24.00
1005	rt rad gar	rt rad gar	/ CR4	40.00
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 3,318.00
u: Used parts				Addition(+10.00%) 331.80
Total				3,649.80

Extras

Code	Description	Price SGD
1009	no. plate no. plate	35.00*
1010	coolant coolant	20.00*
1011	ac freon ac freon	100.00*
1012	reset ECU reset ECU	80.00*
Total Extras		235.00

Final Calculation

	SGD	SGD
Parts		
Addition(+10.00%)	3,318.00	
Total Parts	331.80	3,649.80
Labour Time Base 10 WU/h		
Total 182.0 WU X 50.00 SGD/h	910.00	
Total of Labour		910.00
Total Of Extras		235.00
Paint Work Time Base 10 WU/h		
Labour Cost 106.0 WU X 50.00 SGD/h	530.00	
Material Cost	153.45	
Total Paint Including Material		683.45
Repair Cost Excludes GST		5,478.25
GST (+7.00%)		383.48
Repair Cost Included GST		5,861.73

\$ 5,478.25
 12 days

Shu Fatt Auto Works
Singapore
159723

Claim Reference:

Assessment number: SF078

Version: 1810

Date calculated: 06/06/2019 3:22 PM

Full Report

Registration: SFH823D

Printed: 06/06/2019 3:22 PM

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: SF078
Version: 1810
Date calculated: 09/07/2019 10:51 AM

Full Report
Registration: SFH823D
Printed: 10/07/2019 9:29 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	27/04/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	FORTUNER
Sub Model:	FORTUNER
Model Sheet Number:	70 64 02
Registration:	SFH823D

VIN number:

Odometer:

Model Specs

FROM 01/2011	2.7 LTR 118KW	4WD	PREPARE OFF VEHICLE
TWO COAT PEARL/MICA			

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: SF078
 Version: 1810
 Date calculated: 09/07/2019 10:51 AM

Full Report
 Registration: SFH823D
 Printed: 10/07/2019 9:29 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
NO NUMBER	R + R L/ENGINE COMPARTMENT PROTECTION	3.0	15.00	
B140	RENEW FRONT PANEL	34.0	170.00	
B110	RENEW R/F WING	6.0	30.00	
NO NUMBER	R + R L/R FRONT FOGLAMP	1.0	5.00	
B040	R + R BOTH HEADLAMPS	4.0	20.00	
	DOES NOT INCLUDE: ADJUST HEADLAMPS			
B040	RENEW R/HEADLAMP	4.0	20.00	
	INCLUDES: BUMPER REMOVE AND REFIT AND ADJUST HEADLAMPS.			
B020	RENEW FRONT BUMPER (REMOVED)	10.0	50.00	
	INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT			
	NOT INCLUDED: RADIATOR GRILLE R + R			
NO NUMBER	R + R FRONT BUMPER REINFORCEMENT	2.0	10.00	
B030	R + R RADIATOR GRILLE	2.0	10.00	
610101	R + R L/F WING MUDFLAP	1.0	5.00	

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:

Assessment number: SF078

Version: 1810

Date calculated: 09/07/2019 10:51 AM

Full Report

Registration: SFH823D

Printed: 10/07/2019 9:29 AM

Code	Description	WU	Price SGD
NO NUMBER	R + R LANDING PANEL SUPPORT	2.0	10.00
531041	R + R L/F WHEELHOUSE COVER	4.0	20.00
851061	R + R WASHER NOZZLES	3.0	15.00
851091	R + R WASHER RESERVOIR	6.0	30.00
B085	R + R FRONT WIPER MOTOR	4.0	20.00
B085	R + R BLOWER GRILLE	3.0	15.00
NO NUMBER	R + R L/SILL RAIL	7.0	35.00
NO NUMBER	R + R R/SILL RAIL	7.0	35.00
M020	R + R RADIATOR	7.0	35.00
	INCLUDES: BLEED COOLING SYSTEM		
M010	RENEW CONDENSER	10.0	50.00
NO NUMBER	REFILL AIR CONDITIONING	4.0	20.00
0471	BONNET REPAIR	10.0*	50.00
1124	R/WHEELHOUSE REINF REPAIR	8.0*	40.00
5966	R/S-MEMBER REINFORCE REPAIR	40.0*	200.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		18.20	182.0
Total of Labour			910.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT PEARL/MICA	WU Price SGD
	FRT BUMPER REINF SURFACE PAINT	4.0
	R/F WING NEW PART PAINTING	11.0
	LOCK CARRIER SUPPORT SURFACE PAINT	4.0
	FRONT PANEL CPL SURFACE PAINT	7.0
	BONNET REPAIR PAINTING >50%	36.0
	L/F WING SURFACE PAINT	6.0
	R/WHEELHOUSE REINF SURFACE PAINT	4.0
	R/WING REINFORCEMENT SURFACE PAINT	5.0
	R/S-MEMBER REINFORCE SURFACE PAINT	4.0

Paint Material Per Part

Code	Description	Price SGD
0339	FRT BUMPER REINF SURFACE PAINT	1.25
0742	R/F WING NEW PART PAINTING	24.25
0988	LOCK CARRIER SUPPORT SURFACE PAINT	1.99
1009	FRONT PANEL CPL SURFACE PAINT	16.43

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:

Assessment number: SF078

Version: 1810

Date calculated: 09/07/2019 10:51 AM

Full Report

Registration: SFH823D

Printed: 10/07/2019 9:29 AM

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET REPAIR PAINTING >50%	57.28
0741	L/F WING SURFACE PAINT	11.70
1124	R/WHEELHOUSE REINF SURFACE PAINT	2.49
1168	R/WING REINFORCEMENT SURFACE PAINT	7.47
5966	R/S-MEMBER REINFORCE SURFACE PAINT	1.99

Labour Cost - Paint

	Factor	50.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			81.0	
	Preparation Main Work Metal		2.50	25.0	125.00
Total		10 WU/h	10.60	106.0	530.00

Material Cost - Paint

	Price SGD
New Part Painting	24.25
Repair Painting	57.28
Surface-/Blend Paint	43.32
Material-constant Metal Preparation	28.60
Total	153.45

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0281	FRONT BUMPER	52119 0K949			300.00
0322	R/F BUMPER BRACKET	52147 0K010			30.00
0338	R/F UPP BUMPER BRKT	52115 0K020			55.00
0339	FRT BUMPER REINF	52021 0K022			180.00
0350	FRT BUMPER CLAMP KIT	52161 02030			24.00
0410	GRILLE	53111 0K300			230.00
0411	RADIATOR GRILLE TRIM	53121 0K140			160.00
0431	MANUFACTURER BADGE	75311 0K060			50.00
0527	UPP RAD GRILLE SEAL	53397 0K020			45.00
0562	RIGHT HEADLAMP ASSY	81110 0K270			280.00
0638	R/F FOG LAMP CPL	81210 0K051			160.00
0742	R/F WING	53811 0K020			250.00
0988	LOCK CARRIER SUPPORT	53208 0K010			70.00
1009	FRONT PANEL CPL	53201 0K010			380.00
4465	CONDENSER	88460 0K110			560.00
7761	RADIATOR	16400 0C220			350.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:

Assessment number: SF078

Version: 1810

Date calculated: 09/07/2019 10:51 AM

Full Report

Registration: SFH823D

Printed: 10/07/2019 9:29 AM

Code	Description	Part Number	Supplier	Price SGD
7767	AIR GUIDE PANEL	16711 0C110		130.00
1002	arch clips	arch clips		24.00
1005	rt rad gar	rt rad gar		40.00
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 3,318.00
u: Used parts				Addition(+10.00%) 331.80
Total				3,649.80

Extras

Code	Description	Price SGD
1009	no. plate no. plate	35.00*
1010	coolant coolant	20.00*
1013	ac freon	100.00*
1014	reset ECU	80.00*
Total Extras		235.00

Final Calculation

	SGD	SGD
Parts	3,318.00	
Addition(+10.00%)	331.80	
Total Parts		3,649.80
Labour Time Base 10 WU/h		
Total 182.0 WU X 50.00 SGD/h	910.00	
Total of Labour		910.00
Total Of Extras		235.00
Paint Work Time Base 10 WU/h		
Labour Cost 106.0 WU X 50.00 SGD/h	530.00	
Material Cost	153.45	
Total Paint Including Material		683.45
Repair Cost Excludes GST		5,478.25
GST (+7.00%)		383.48
Repair Cost Included GST		5,861.73

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:

Assessment number: SF078

Version: 1810

Date calculated: 09/07/2019 10:51 AM

Full Report

Registration: SFH823D

Printed: 10/07/2019 9:29 AM

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 May 2019 10:27 Sendback Est	03 May 2019 11:36 \$8,954.39	06 May 2019 10:02 Edit Adj Rpt	\$5,478.25 Edit Estimates	\$5,478.25 View Rpt		Pending for Survey Report Cancel Case
Supp #1	06 Jun 2019 10:32	06 Jun 2019 16:31 \$425.50	06 Jun 2019 16:31			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	CHORDWATTANADECHAR NARINPAT@FANYAENG ANUSARA, ID: S8780927G, Tel: +6582426665, Email: peemainarinpat@gmail.com		
Vehicle Reg. No.:	SFH823D	Date of Loss:	27/04/2019 16:00 - :59 [98 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 592186	Policy/Cover Note No.:	29080339QMX (Comprehensive) Coverage: 27/04/2018 - 21/08/2019
		Excess:	\$1,000.00
Repairer:	Shu Fatt Auto Works (HQ) Block 1009 Bukit Merah Lane 3, #01-90, 159723 Bukit Merah - Tel: 62730119		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 05/06/2019]		
Driver/Custodian:	CHORDWATTANADECHAR NARINPAT@FANYAENG ANUSARA (32 / Female), NRIC: S8780927G, Tel: +6582426665 Email: peemainarinpat@gmail.com		
Adj Asg. Remarks:	Car in. Please revert and arrange for survey on 06/05/2019- monday in the morning. Vehicle is in Shu Fatt Auto Works now. Surveyor to check on the market value & rebate if it is economical to repair. Also to check tyres,brakes & steering wheels are in efficient condition. To get servicing records from our insured.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (17/07/2019): Alert - Adj Mandate Approved (\$5478.25) - SFH823D - Claim Handler: Vimmala D/O ...
- MSIG_SG (05/07/2019): Alert - Adj Mandate Approved (\$8091.39) - SFH823D - Claim Handler: Vimmala D/O ...
- MSIG_SG (07/05/2019): Alert - Adj Mandate Approved (\$5053.39) - SFH823D - Claim Handler: Pauline Soh ...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SFH823D (592186)

OD

Apr 27 2019 4:00PM

[CHORDWATTANADECHAR NARINPAT@FANYAENG ANUSARA]

Shu Fatt Auto Works

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports

No	Finalized On	Shu Fatt Auto Works (HQ)	Thumbnail	Print
1	29/04/19 13:02	Accident Statement	Load HTM	
2	03/05/19 11:36	Repairer Estimates	Load HTM	
3	06/06/19 16:31	Repairer Estimates Suppl. #1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/05/19 10:27	Adjuster Immediate Advice	Load HTM	
2	10/06/19 10:28	Adjuster Immediate Advice	Load HTM	
3	10/07/19 15:58	Adjuster Immediate Advice	Load HTM	

Photos/Images

No	Finalized On	Shu Fatt Auto Works (HQ)	Thumbnail	Print
1	29/04/19 11:04	General View [Linked Accident Report Documents]	Load JPG	☒
2	29/04/19 11:04	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	29/04/19 11:04	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	29/04/19 11:04	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	29/04/19 11:04	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	29/04/19 11:04	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	29/04/19 11:04	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
8	29/04/19 11:04	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
9	29/04/19 11:04	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
10	29/04/19 11:04	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
11	29/04/19 11:04	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
12	29/04/19 11:04	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
13	29/04/19 11:04	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
14	29/04/19 11:05	chassis no [Linked Accident Report Documents]	Load JPG	☒
15	29/04/19 11:10	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
16	29/04/19 11:10	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
17	29/04/19 11:10	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
18	29/04/19 11:10	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
19	03/05/19 10:30	1	Load JPG	☒
20	03/05/19 10:30	2	Load JPG	☒
21	03/05/19 10:30	3	Load JPG	☒
22	03/05/19 10:30	4	Load JPG	☒
23	03/05/19 10:30	5	Load JPG	☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	Shu Fatt Auto Works (HQ)		Thumbnail Print
24	03/05/19 10:30	6		Load JPG ☒
25	03/05/19 10:30	7		Load JPG ☒
26	03/05/19 10:30	8		Load JPG ☒
27	03/05/19 10:30	9		Load JPG ☒
28	03/05/19 10:30	10		Load JPG ☒
29	03/05/19 10:30	11		Load JPG ☒
30	03/05/19 10:30	12		Load JPG ☒
31	03/05/19 10:30	13		Load JPG ☒
32	03/05/19 10:30	14		Load JPG ☒
33	03/05/19 10:30	15		Load JPG ☒
34	03/05/19 10:30	16		Load JPG ☒
35	03/05/19 10:30	17		Load JPG ☒
36	03/05/19 10:30	18		Load JPG ☒
37	03/05/19 10:30	19		Load JPG ☒
38	03/05/19 10:30	20		Load JPG ☒
39	03/05/19 10:30	21		Load JPG ☒
40	03/05/19 10:30	22		Load JPG ☒
41	03/05/19 10:30	23		Load JPG ☒
42	03/05/19 10:30	24		Load JPG ☒
43	03/05/19 10:30	25		Load JPG ☒
44	03/05/19 10:30	26		Load JPG ☒
45	03/05/19 10:30	27		Load JPG ☒
46	03/05/19 10:30	28		Load JPG ☒
47	03/05/19 10:30	29		Load JPG ☒
48	03/05/19 10:30	tyre make		Load JPG ☒
49	03/05/19 10:30	tyre make		Load JPG ☒
50	03/05/19 10:30	tyre size		Load JPG ☒
51	03/05/19 10:30	Chassis Number		Load JPG ☒
52	03/05/19 10:30	Odometer Reading		Load JPG ☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	06/05/19 18:05	General View		Load JPG ☒
2	06/05/19 18:05	General View		Load JPG ☒
3	06/05/19 18:05	General View		Load JPG ☒
4	06/05/19 18:05	General View		Load JPG ☒
5	06/05/19 18:05	General View		Load JPG ☒
6	06/05/19 18:05	General View		Load JPG ☒
7	06/05/19 18:05	General View		Load JPG ☒
8	06/05/19 18:05	General View		Load JPG ☒
9	06/05/19 18:05	General View		Load JPG ☒
10	06/05/19 18:05	General View		Load JPG ☒
11	06/05/19 18:05	General View		Load JPG ☒
12	06/05/19 18:05	General View		Load JPG ☒
13	06/05/19 18:05	General View		Load JPG ☒
14	06/05/19 18:05	General View		Load JPG ☒
15	06/05/19 18:05	General View		Load JPG ☒
16	06/05/19 18:05	General View		Load JPG ☒
17	06/05/19 18:05	Chassis Number		Load JPG ☒
18	06/05/19 18:05	General View		Load JPG ☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	Shu Fatt Auto Works (HQ)	Thumbnail	Print
19	06/05/19 18:05	General View	 Load JPG	☒
20	06/05/19 18:05	General View	 Load JPG	☒
21	06/05/19 18:05	General View	 Load JPG	☒
22	06/05/19 18:05	Odometer Reading	 Load JPG	☒
23	06/05/19 18:05	General View	 Load JPG	☒
24	06/05/19 18:05	General View	 Load JPG	☒
25	06/05/19 18:05	General View	 Load JPG	☒
26	06/05/19 18:05	General View	 Load JPG	☒
27	06/05/19 18:05	General View	 Load JPG	☒
28	06/05/19 18:05	General View	 Load JPG	☒
29	06/05/19 18:05	General View	 Load JPG	☒
30	06/05/19 18:05	General View	 Load JPG	☒
31	06/05/19 18:05	General View	 Load JPG	☒
32	06/05/19 18:05	General View	 Load JPG	☒
33	06/05/19 18:05	General View	 Load JPG	☒
34	06/05/19 18:05	General View	 Load JPG	☒
35	06/05/19 18:05	General View	 Load JPG	☒
36	06/05/19 18:05	General View	 Load JPG	☒
37	06/05/19 18:05	General View	 Load JPG	☒
38	06/05/19 18:05	General View	 Load JPG	☒
39	06/05/19 18:05	General View	 Load JPG	☒
40	06/05/19 18:05	General View	 Load JPG	☒
41	06/05/19 18:05	General View	 Load JPG	☒
42	06/05/19 18:05	General View	 Load JPG	☒
43	06/05/19 18:05	General View	 Load JPG	☒
44	06/05/19 18:05	General View	 Load JPG	☒
45	06/05/19 18:05	General View	 Load JPG	☒
46	06/05/19 18:05	General View	 Load JPG	☒
47	06/05/19 18:05	General View	 Load JPG	☒
48	06/05/19 18:05	General View	 Load JPG	☒
49	06/05/19 18:05	General View	 Load JPG	☒
50	06/05/19 18:05	General View	 Load JPG	☒
51	06/05/19 18:05	General View	 Load JPG	☒
52	06/05/19 18:05	General View	 Load JPG	☒
53	06/05/19 18:05	General View	 Load JPG	☒
54	06/05/19 18:05	General View	 Load JPG	☒
55	06/05/19 18:05	General View	 Load JPG	☒
56	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
57	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
58	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
59	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
60	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
61	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
62	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
63	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
64	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
65	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
66	13/05/19 20:18	Photographs of Damaged Parts	Load JPG	☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	Shu Fatt Auto Works (HQ)	Thumbnail	Print
67	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
68	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
69	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
70	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
71	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
72	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
73	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
74	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
75	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
76	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
77	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
78	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
79	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
80	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
81	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
82	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
83	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
84	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
85	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
86	13/05/19 20:18	Photographs of Damaged Parts	 Load JPG	☒
87	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
88	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
89	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
90	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
91	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
92	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
93	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
94	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
95	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
96	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
97	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
98	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
99	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
100	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
101	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
102	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
103	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
104	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
105	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
106	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
107	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
108	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
109	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
110	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
111	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
112	13/05/19 20:19	Reinspection Photo	 Load JPG	☒
113	16/05/19 09:54	Photographs of Damaged Items	 Load JPG	☒
114	16/05/19 09:54	Photographs of Damaged Items	Load JPG	☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	Shu Fatt Auto Works (HQ)	Thumbnail	Print
115	16/05/19 09:54	Photographs of Damaged Items	Load JPG	☒
116	16/05/19 09:54	Photographs of Damaged Items	Load JPG	☒
117	16/05/19 09:54	Photographs of Damaged Items	Load JPG	☒
118	16/05/19 09:54	Photographs of Damaged Items	Load JPG	☒
119	16/05/19 09:54	Photographs of Damaged Items	Load JPG	☒
120	16/05/19 09:54	Photographs of Damaged Items	Load JPG	☒
121	16/05/19 09:54	Photographs of Damaged Items	Load JPG	☒
122	16/05/19 09:54	Photographs of Damaged Items	Load JPG	☒
123	16/05/19 09:54	Photographs of Damaged Items	Load JPG	☒
124	18/07/19 08:59	Photographs of Damaged Parts	Load JPG	☒
125	18/07/19 08:59	Photographs of Damaged Parts	Load JPG	☒
126	18/07/19 08:59	Photographs of Damaged Parts	Load JPG	☒
127	18/07/19 08:59	Photographs of Damaged Parts	Load JPG	☒
128	18/07/19 08:59	Photographs of Damaged Parts	Load JPG	☒
129	18/07/19 08:59	Photographs of Damaged Parts	Load JPG	☒
130	18/07/19 08:59	Photographs of Damaged Parts	Load JPG	☒
131	18/07/19 08:59	Photographs of Damaged Parts	Load JPG	☒
132	18/07/19 08:59	Photographs of Damaged Parts	Load JPG	☒
133	18/07/19 08:59	Photographs of Damaged Parts	Load JPG	☒
134	18/07/19 08:59	Photographs of Damaged Parts	Load JPG	☒
135	18/07/19 08:59	Photographs of Damaged Parts	Load JPG	☒
136	18/07/19 08:59	Photographs of Damaged Parts	Load JPG	☒
137	18/07/19 08:59	Photographs of Damaged Parts	Load JPG	☒
138	18/07/19 08:59	Photo After Spray	Load JPG	☒
139	18/07/19 08:59	Photo After Spray	Load JPG	☒
140	18/07/19 08:59	Photo After Spray	Load JPG	☒
141	18/07/19 08:59	Photo After Spray	Load JPG	☒
142	18/07/19 08:59	Photo After Spray	Load JPG	☒
143	18/07/19 08:59	Photo After Spray	Load JPG	☒
144	18/07/19 08:59	Photo After Spray	Load JPG	☒
145	18/07/19 08:59	Photo After Spray	Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	Shu Fatt Auto Works (HQ)	Thumbnail	Print
1	29/04/19 11:03	Accident Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	03/05/19 10:47	Driver's Driving License	Load PDF	
3	03/05/19 10:47	parf value enquiry	Load PDF	
4	03/05/19 10:47	Thailand Driving License	Load PDF	
5	03/05/19 11:33	audatex report	Load PDF	
6	03/05/19 11:35	Insurance Cover Note	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/05/19 10:28	SFH 823D GIA.pdf	Load PDF	
2	07/05/19 10:28	ESTIMATE.pdf	Load PDF	
3	10/07/19 15:57	AUDATEX.pdf	Load PDF	
4	18/07/19 15:03	SUPPLEMENTARY	Load PDF	

Linked Accident Report Documents

View

Assessment Reports	1 per page ▼	☒
--------------------	--------------	-------------------------------------

Assessment Reports			1 per page	Thumbnail	Print
No	Finalized On	Shu Fatt Auto Works (HQ)		Thumbnail	Print
1	29/04/19 13:02	Accident Statement	1	Load HTM	
Photos/Images			3 per page		
No	Finalized On	Shu Fatt Auto Works (HQ)		Thumbnail	Print
1	29/04/19 11:04	General View	1	Load JPG	
2	29/04/19 11:04	Accident Photo	1	Load JPG	
3	29/04/19 11:04	Accident Photo	1	Load JPG	
4	29/04/19 11:04	Accident Photo	1	Load JPG	
5	29/04/19 11:04	Accident Photo	1	Load JPG	
6	29/04/19 11:04	Accident Photo	1	Load JPG	
7	29/04/19 11:04	Accident Photo	1	Load JPG	
8	29/04/19 11:04	Accident Photo	1	Load JPG	
9	29/04/19 11:04	Accident Photo	1	Load JPG	
10	29/04/19 11:04	Accident Photo	1	Load JPG	
11	29/04/19 11:04	Accident Photo	1	Load JPG	
12	29/04/19 11:04	Accident Photo	1	Load JPG	
13	29/04/19 11:04	Accident Photo	1	Load JPG	
14	29/04/19 11:05	chassis no	1	Load JPG	
15	29/04/19 11:10	Accident Photo	1	Load JPG	
16	29/04/19 11:10	Accident Photo	1	Load JPG	
17	29/04/19 11:10	Accident Photo	1	Load JPG	
18	29/04/19 11:10	Accident Photo	1	Load JPG	
Documentation			1 per page		
No	Finalized On	Shu Fatt Auto Works (HQ)		Thumbnail	Print
1	29/04/19 11:03	Accident Sketch Plan	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19007809/ESD3S2

Date: 18/07/2019

REFERENCE

Insured/Claimant: CHORDWATTANADECHAR NARINPAT@FANYAENG ANUSARA

Policy No: 29080339QMX

Date of Loss: 27/04/2019

Nature of Claim: OD

Claim No: 592186

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFH823D**
Make & Model: TOYOTA FORTUNER, 2.7 (A)
Reg. Date: 22/02/2011 (Man. Year: 2011)
Colour: Grey
Engine Capacity: 2694 cc
Market Value/New Car Price: S\$38,000.00
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 2TR7041968
Chassis No: MR0ZX69G200102407
Odometer: 108056 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/65R17 Rear Tyre Size: 265/65R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,300.80	3,649.80	2,651.00	42.07
Miscellaneous Items	380.00	235.00	145.00	38.16
Paintwork Materials	209.09	0.00	209.09	100.00
Labour	1,765.00	910.00	855.00	48.44
Paintwork Labour	725.00	683.45	41.55	5.73
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,379.89	5,478.25	3,901.64	41.60
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	8,379.89	4,478.25	3,901.64	46.56
+ GST 7.00/7.00% (S\$)	586.60	313.48	273.12	46.56
Nett Amount (S\$)	8,966.49	4,791.73	4,174.76	46.56

INSPECTION

Date of Assignment: 06/05/2019 Present Location: Shu Fatt Auto Works (HQ)
Date Inspected: 06/05/2019 Inspected At: Shu Fatt Auto Works (HQ)
Estimated Period of Repair: 12.0 days Block 1009 Bukit Merah Lane 3, #01-90
Singapore 159723

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2019)
Parts:	192	TOYOTA FORTUNER 2.7 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFH823D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare parts. (WCP)		6,075.30 F	-
2	1		*FRT NUMBER PLATE (WCP)	Not Necessary	-	*- F
3	1		*FRONT BUMPER (WCP)	Broken	-	*300.00 F
4	1		*L/F UPP BUMPER BRKT (WCP)	Not Necessary	-	*- F
5	1		*R/F UPP BUMPER BRKT (WCP)	Broken	-	*55.00 F
6	1		*FRT BUMPER REINF (WCP)	Dented	-	*180.00 F
7	1		*FRT BUMPER CLAMP KIT (WCP)	Necessary	-	*24.00 F
8	1		*GRILLE (WCP)	Broken	-	*230.00 F
9	1		*RADIATOR GRILLE TRIM (WCP) (CHROME)	Broken	-	*160.00 F
10	1		*MANUFACTURER BADGE (WCP)	Necessary	-	*50.00 F
11	1		*R/F WING BADGE (WCP)	Not Necessary	-	*- F
12	1		*LEFT HEADLAMP ASSY (WCP)	Not Necessary	-	*- F
13	1		*RIGHT HEADLAMP ASSY (WCP)	Broken	-	*280.00 F
14	1		*R/F FOG LAMP CPL (WCP)	Broken	-	*160.00 F
15	1		*R/F WING (WCP)	Dented	-	*250.00 F
16	1		*R/F WING CLAMP KIT (WCP)	Not Necessary	-	*- F
17	1		*R/F W-ARCH MOULDING (WCP)	Not Necessary	-	*- F
18	1		*R/W-HOUSE INSULATION (WCP)	Not Necessary	-	*- F
19	1		*LOCK CARRIER SUPPORT (WCP)	Dented	-	*70.00 F
20	1		*FRONT PANEL CPL (WCP)	Dented	-	*380.00 F
21	1		*R/ENG ROOM PROTECT (WCP)	Not Necessary	-	*- F
22	1		*CONDENSER (WCP)	Dented	-	*560.00 F
23	1		*RADIATOR (WCP)	Twisted	-	*350.00 F
24	1		*FRT ENG PROT PANEL (WCP)	Not Necessary	-	*- F
25	1		*L/HORN (WCP)	Not fitted	-	*- F
26	1		*R/HORN (WCP)	Not Necessary	-	*- F
27	1		*HL CLIPS (WCP)	Not Necessary	-	*- F
28	1		*GRILLE CLIPS (WCP)	Not Necessary	-	*- F
29	1		*ARCH CLIPS (WCP)	Necessary	-	*24.00 F
30	1		*BUMP BRKT (WCP)	Not Necessary	-	*- F
31	1		*FOG BULB (WCP)	Not Necessary	-	*- F
32	1		*RT RAD GAR (WCP)	Crushed	-	*40.00 F
33	1		*LH RAD GAR (WCP)	Not Necessary	-	*- F
34	1		*RAD GAR CLIPS (WCP)	Not Necessary	-	*- F
35	1		*SPLASH GAR CLIP (WCP)	Not Necessary	-	*- F
36	1		*BUMP CTR GAR (WCP)	Not Necessary	-	*- F
Supplementary #1						
37	1		*Radiator fan cowling (WCP)	Broken	143.00 F	*130.00 F
38	1		*Right headlamp holder (WCP)	Missing	33.00 F	*30.00 F

Report was unsubmitted during this print-out.

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Materials				
1	1	Paintwork materials	209.09	0.00
Miscellaneous Items				
2	1	AC FREON AC FREON (NECESSARY)	-	100.00
3	1	COOLANT (NECESSARY)	-	20.00
4	1	NO. PLATE NO. PLATE (BROKEN)	-	35.00
5	1	RESET ECU RESET ECU (NECESSARY)	-	80.00
6	1	special net	380.00	0.00
Sub Total (S\$)			589.09	235.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Paintwork	New	725.00	530.00
2	MATERIAL COST.	New	-	153.45
Labour Items				
3	Panel/Mechanical	New	1,565.00	910.00
Supplementary #1				
Labour Items				
4	Repair right chassis cross member - 40wu	New	200.00	0.00
Gross Labour Cost (S\$)			2,490.00	1,593.45

Report was unsubmitted during this print-out.

< END OF ESTIMATES >