

REF: CS/FCI 19007809 / A+ d3 | n2  
 ASSIGNMENT (01000)  
 CWS Adrian  
 Henry Kuo of FCI  
 Date/Time: 2:46pm @ 3/5/19

OUI: (C) WS/TP/RES/OF/RES/ENA/REV/IMY/CS  
 To: Dept of Vehicle Ho SMA 5671 X Brand: SHC 0989L  
 # Work shop of N-51 Automotive Tel: 68420051  
 of 2 Kaki Bkt Ave 2 # 01-18  
 Policy No. Claim No. D19002893MFSH  
 Date of Veh. DOA 29/4/2019  
 (C) Rent's Record

CA / REV / RDP / REV 24 HRS (DS)  
 Date/Time: 2:46pm @ 3/5/19 Person Contacted: eileen Vehicle IN (OUI)

Date/Time	Action/Instruction (✓) (Urgency)
	SMA 5671 X - X
	SHC 0989L - CS/FCI 18001511 / M/He2 DOA: 20/01/2018
16/5 -	Sent email to FCI pending estimate.

REF: FCI

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD  TP / WS / TP RES / OD RES / LVA / INV / MY  
 To Inspect Vehicle No: **SMAS671X**  
 at Workshop no: **N-51**  
 of **2 Kaki Bukit Ave 2 #01-17**  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

N/S	O/S

Veh No: **SMAS671X** Yr From: **2018 June**  
 Type:  M.Cm / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: **Toyota Prius Plus Hybrid** cc **1758**  
 Colour: **Blue** AC: Insured / Std / Nil / NA  
 Sp. Reading: **94648** TA/Radio: Insured / Std / Nil / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **JTDZS3E400J028048**  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In order / Jammed / Leaked / Burnt or  
 Brake:  In order / Jammed / Leaked / Burnt or  
 Modi:  Nil / ~~Other~~ / STD A/Rim or  
 Tyre Size: F: **205/60R16**  
 R: **205/60R16**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO /  YOKO or  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: **06** mm R/Bal: **06** mm  
 L/Bal: **06** mm L/Bal: **06** mm  
 D.O.A: \_\_\_\_\_ D.O.L: **13/05/19**  
 Survey held at: **NSI**  
 Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP 1st Cap.
	Lump Sum \$3900 (Red: 3270.11; 45%)

RECEIVED 17 SEP 2019

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) **16/9 Typist**  
 Date/Time, File Return to?

Days Of Repair: **5**  
 Resurvey No. of Trip: **2**

Add Fee:  Site Insp (\$) )  
 Interview (\$) )  
 Tech. Insp (\$) )  
 Weekend (\$) )

Survey Fee:	150
Transportation:	50
3 + 100	50+50
Photos	56
Others	
TOTAL	<b>356</b>

Report Format: **TP**  
 Lump Sum / L.B.I: (\$) **3900**

**MOTOR SURVEY ASSIGNMENT**

**Date** 02-05-2019 **Our Ref No.** D19002893MFSH

**Accident Date** 29-04-2019 **Claim Type.** Third Party

**Insured Vehicle** SHC0989L **Third Party Vehicle.** SMA5671X

**Survey Location** 2 KAKI BUKIT AVENUE 2 #01-18 KAKI BUKIT AUTOHUB

**Contact Person.** ZI TING

**Contact No.** 68420051/ 67440510 **Fax No.** 67410510

**Survey Type** WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

**Appointed Surveyor** LKK AUTO CONSULTANTS PTE LTD

**Contact Person** NA **Fax No.** 68416315

**Contact Number.** NA

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

**Cc : Workshop** N-51 AUTOMOTIVE PTE LTD **Attention.** NIL

**Cc : TP Solicitor** NA **TP Solicitor Fax No.** NA

**Officer Incharge** HENRY KAO

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Thursday, 16 May 2019 2:44 PM  
**To:** Admin-D (LKKAuto); 'CWS Motor Claims'; assignments  
**Cc:** 'Henry Kao Cai Jie'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19002893MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SMA 5671X on 13/5/2019  
We are pending estimate from repairer.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Friday, 3 May 2019 2:50 PM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Henry Kao Cai Jie' <[HenryKao@msfirstcapital.com.sg](mailto:HenryKao@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D19002893MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Friday, 3 May 2019 2:24 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Henry Kao Cai Jie

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

*TP 1st Cap.*

GRAB RENTALS PTE LTD  
 18 SIN MING LANE #01-08 MIDVIEW CITY  
 SINGAPORE 573960

*Denise.*

## ESTIMATE

Repair Code : CLM15210

Date in : 29/04/2019

Vehicle Num. : SMA5671X

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng# : JTDZS3EU00J028048/2ZR0B83553

Contact : 66550005 98232272

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>repld</i>	1	523.90	✓ 523.90
REAR BUMPER LOWER COVER <i>cancel.</i>	1	179.00	✓ 179.00
REAR BUMPER LOWER SPOILER <i>repld</i>	1	721.00	✓ 721.00
REAR BUMPER REINFORCEMENT <i>Best</i>	1	350.50	✓ 350.50
REAR BUMPER REINFORCEMENT BRACKET L/R <i>Best</i>	2	198.70	✓ 397.40
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	98.00	✓ 196.00
REAR END PANEL <i>repld</i>	1	781.45	✓ 781.45
REAR END PANEL ANTENNA SENSOR <i>cancel.</i>	1	485.00	125 <del>485.00</del>
REAR END PANEL INNER TOP GARNISH <i>repld</i>	1	287.90	✓ 287.90
REAR TAILGATE 'HYBRID' EMBLEM	1	50.00	+ 50.00
REAR TAILGATE 'PRIUS' EMBLEM <i>new</i>	1	52.30	+ 52.30
REAR TAILGATE WEATHER STRIP	1	360.70	+ 360.70
REAR TAILLAMP BACK RUBBER GASKET L/R <i>new</i>	2	69.50	139.00 <i>ps.</i>
REAR TAILLAMP L/R <i>cancel</i>	2	630.00	630.00 <del>1,260.00</del>
REAR TAILLAMP LOWER BRACKET L/R <i>new</i>	2	68.00	+ 136.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD  
 18 SIN MING LANE #01-08 MIDVIEW CITY  
 SINGAPORE 573960

Contact : 66550005 98232272

## ESTIMATE

Repair Code : CLM15210  
 Date in : 29/04/2019  
 Vehicle Num. : SMA5671X  
 Model : TOYOTA PRIUS PLUS (AUTO)  
 Chassis/Eng# : JTDZS3EU00J028048/2ZR0B83553

	Subtotal before discount	4232.15	5,920.15
Percentage discount 25%		3174.11	1,480.04
	<b>Sub-total 1</b>		<b>4,440.11</b>
REAR BUMPER CLIPS - SET <i>Nu</i>	1	50.00	<del>30</del> 50.00
REAR BUMPER LOWER SPOILER CLIPS - SET <i>Nu</i>	1	60.00	<del>30</del> 60.00
REAR BUMPER REVERSE SENSOR - SET <i>Dangd</i>	1	250.00	<del>200</del> 250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>Nu</i>	1	30.00	<del>10</del> 30.00
	Subtotal before discount		390.00
Percentage discount 0%			0.00
	<b>Sub-total 2</b>		<b>390.00</b>
	<b>Parts-total</b>		<b>4,830.11</b>

## LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.		40	60.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	1450	50	120.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.		600	1,100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.		700	1,000.00
To apply anti-rust chemical on repaired and replaced panel.			60.00
	<b>Labour Total</b>		<b>2,340.00</b>
	<b>Parts &amp; Labour Total</b>		<b>7,170.11</b>

*Adrian Ling,*  
*h/s 18/05/19.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

*total 4894.11*  
*h/s 3910 ✓*  
*05 Days ✓*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19007810/Atd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-09-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 989L	Veh. Inspected	SMA 5671X
Policy No.		Coverage (\$)	0.00
Claim No.	D19002893MFSH	Excess (\$)	0.00
Assign From	HENRY KAO	Assign Date	03/05/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS PLUS HYBRID	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTDZS3EU00J028048	Colour	BLUE
Odometer	94648	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/04/2019	Inspection Date	13/05/2019
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 5671X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DEFORMED	523.90	523.90
1	REAR BUMPER LOWER COVER	CRACKED	179.00	179.00
1	REAR BUMPER LOWER SPOILER	DEFORMED	721.00	721.00
1	REAR BUMPER REINFORCEMENT	BENT	350.50	350.50
2	REAR BUMPER REINFORCEMENT BRACKET L/R @\$198.70	BENT	397.40	397.40
2	REAR BUMPER SIDE RETAINER L/R @\$98.00	NECESSARY	196.00	196.00
1	REAR END PANEL	DENTED	781.45	781.45
1	REAR END PANEL ANTENNA SENSOR	CRACKED	485.00	125.00
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	287.90	287.90
1	REAR TAILGATE "HYBRID" EMBLEM	NOT NECESSARY	50.00	-
1	REAR TAILGATE "PRIUS" EMBLEM	NOT NECESSARY	52.30	-
1	REAR TAILGATE WEATHER STRIP	NOT NECESSARY	360.70	-
2	REAR TAILLAMP BACK RUBBER GASKET L/R @\$69.50	NECESSARY	139.00	40.00
2	REAR TAILLAMP L/R @\$630.00	N/S CRACKED	1,260.00	630.00
2	REAR TAILLAMP LOWER BRACKET L/R @\$68.00 LESS 25% DISCOUNT	NOT NECESSARY	136.00	-
			-1,480.04	-1,058.04
			<b>4,440.11</b>	<b>3,174.11</b>
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR BUMPER LOWER SPOILER CLIPS (SN)	NECESSARY	60.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	30.00	10.00
			<b>390.00</b>	<b>270.00</b>
<b>LABOUR</b>				
TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,AND REWIRE FOR PARKING SENSOR.			60.00	40.00
TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR).			120.00	50.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		1,100.00	600.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHAGNE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		1,000.00	700.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		60.00	60.00
			2,340.00	1,450.00
	<b>GRAND TOTAL</b>		<b>7,170.11</b>	<b>4,894.11</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,900.00</b>

Report Ref No. CS/FCI19007810/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.