

REGISTRATION

REP es/FCI19007812/Ktd3/n2
Agent of Instruction

Surveyor Kenneth

ASSIGNMENT (Office)

CWS

From (Person) Sitharan

of FEI

Date/Time: 2:16pm @ 3/5/2019

Estimated Cost

Bill to

OD / IT / AWS / TP RES / OD RES / EVA / INV / MY TCS

To Inspect Vehicle No

SLD6310C

Insured

SHC7071M

at Workshop no:

Massive Trading

Tel

9108 2728

of

Blk 5038 # 01-405 AMK Ind. Park 2

Policy No:

Claim No

D19002895MP84

Sum Insured

Excess

Make of Veh:

(Client's Record)

D.O.A

2/5/2019

CA / REV / REP / REV 24 HRS up

6/5/2019

H.O.D. Endorsement

Date/Time: 2:37pm @ 3/5/19

Person Contacted

Anthony

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SM1319E-X

SHC7071M - CC3/CAI14016435/H/2m3q2

DoA: 26/02/2019

7/5 @ 11:49am - verified via email preli advise.

22/5 11:50am @ 3:30¹⁵⁰ email & confirm (Red: 6629.16 : 670%)

REF: FCI

ASSIGNMENT

SLD 6310C

From: Date: 6/5/19

Veh No: SMC 1319E Yr Regn: 06, 16

Estimated Cost:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SMC 1319E
at Workshop m/s: Massive Trading
of: Blk 5038 - Amk Ind. Park 2 #01-405

Make: Honda Vezel C.C. 1498

Colour: M. Purple A/C: Insured / Std / NI / NA

Sp. Reading: 28169 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured: Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:


Modi: Nil / S/Rim / STD / Rim or

(Policy Condition)

Tyre Size:

F:

R:

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 866k

Front

Rear

IDAC Accident Report: Consistent? : Yes or No

R/Bal. 5 mm

R/Bal. 3 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 5 mm

L/Bal. 3 mm

Est. Repairs: .04 days Res.: Yes or No

D.O.A. 2/5/19

D.O.I. 6/5/19

Lum Sum: % 3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS 1 up

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 22 MAY 2019

Date/Time, File Pass to?

1) H Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$))

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation.

S + RS, SI

Photos

Others

TOTAL

170

50

50+50

23

343



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002895MFSH

Date: 7/5/2019

Our Ref: CS/FCI19007812/Ktd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLD 6310U

Please be informed that we had conducted the inspection of the abovementioned vehicle 6/5/2019 at the premises of M/s Massive Trading have the following to report: -

Workshop Estimate Amount	: S\$	9,301.40
Revised Estimate Amount	: S\$	2,934.44
"Check" Items Amount	: S\$	1,518.64
Market Value	: S\$	
LTA Reimbursement Value	: S\$	
Nett Value	: S\$	

Description of Damage:
The vehicle sustained damages at the rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Kenneth
Automotive Assessor

MOTOR SURVEY ASSIGNMENT**Date** 02-05-2019 **Our Ref No.** D19002895MFSH**Accident Date** 02-05-2019 **Claim Type.** Third Party**Insured Vehicle** SHC7071M **Third Party Vehicle.** SLD 6310D
SMC1319E**Survey Location** Blk 5038 #01-405 Ang mo kio industrial Pk 2**Contact Person.** ANTHONY**Contact No.** 91082728/ 91082728**Fax No.** 0**Survey Type** WITHOUT PREJUDICE:**Appointed Surveyor** LKK AUTO CONSULTANTS PTE LTD**Contact Person** NA**Fax No.** 68416315**Contact Number.** NA**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST**Cc : Workshop** MASSIVE TRADING & AUTO **Attention.** NIL**Cc : TP Solicitor** TEO KENG SIANG LLC **TP Solicitor Fax No.** 63335676**Officer Incharge** SITHARA**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 7 May 2019 11:47 AM
To: Admin-D (LKKAUTO); 'Sithara'; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEYOR APPOINTED; OUR REF : D19002895MFSH ; YOUR REF: SMC1319E
Attachments: PRELI ADVISED SLD 6310C.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLD 6310C**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 6 May 2019 10:27 AM
To: 'Sithara' <Sithara@msfirstcapital.com.sg>; 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; JANICE.KEE@KSTEOPTR.COM
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SURVEYOR APPOINTED; OUR REF : D19002895MFSH ; YOUR REF: SMC1319E

Dear Sithara,

Noted with thanks.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sithara [<mailto:Sithara@msfirstcapital.com.sg>]
Sent: Monday, 6 May 2019 10:21 AM
To: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; JANICE.KEE@KSTEOPTR.COM
Cc: 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'LKK SUR' <sur@lkkauto.com>
Subject: RE: SURVEYOR APPOINTED; OUR REF : D19002895MFSH ; YOUR REF: SMC1319E

WITHOUT PREJUDICE

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541"
H/P 91082728

Fax : 64816131

Lin Peng Ngoh
538 Miltonia Close
#04-43
Singapore 768113

Vehicle No : SLD 6310 C
Make/Model : Honda Vezel 1.5 X A
Year : 2018

Not Authorised
Resurvey Bk repair
4 days
LLP 83050p

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy	1100.00
1 pc	Rear tail-gate glass moulding	
1 pc	Rear tail-gate emblem " H "	
1 pc	Rear tail-gate emblem : Vezel "	
1 pc	Rear tail-gate outer garnish	
1 pc	Rear tail-gate inner lock	201.00
1 pc	Rear tail-gate inner lock sensor	
1 pc	Rear tail-gate inner trim board	
2 pcs	Rear tail-gate lamp component	
1 pc	Rear boor rubber	
1 pc	Rear end panel	
1 pc	Rear end panel inner garnish	
1 pc	Rear bumper	508.50
2 pcs	Rear bumper reflector	
1 pc	Rear bumper lower garnish	
1 pc	Rear radio antenna sensor	
2 pcs	Rear fender inner trim	
1 pc	Rear exhaust silencer	

Ry	\$1,450.70	✓
Na	\$105.20	✓
nn	\$45.10	X
me	\$50.20	✓
Sm	\$385.60	X
del	\$285.60	✓
rd	\$187.10	✓
sea	\$455.90	X
na	\$850.60	X
rd/w	\$225.80	✓
R	\$455.10	X
my	\$185.90	✓
Ry	\$955.70	✓
Sm	\$274.20	X
Sm	\$175.20	X
Sm	\$175.60	X
Sm	\$850.20	X
R	\$975.10	X
	\$8,088.80	
Less 20 %	\$1,617.76	
	\$6,471.04	

S Nett

1 pc	Rear tail-gate glass sealant
1 pc	Rear reverse sensor
20 pcs	Rear bumper clip
1 pc	Rear no plate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature:
Date:

Na	\$55.00	4050
del	\$200.00	✓
na	\$40.00	✓
Sm	\$40.00	X
	\$335.00	
balance c/f	\$6,806.40	04

SMA 8829 P

balance b/f \$6,806.40

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$900.00 550/

To putty and spray paint

\$900.00 480/

Check & reconnect wiring.

\$45.00 15/

To respray anti-rust proofing treatment

\$180.00 30/

Remove/refit rear windscreen to facilitate repair

\$100.00 ✓

Remove/refit rear tail-gate mechanism to new door.

\$150.00 60/

Remove/renew rear exhaust silencer.

nn \$120.00 X

Remove/refit rear boot upholstery to facilitate repair.

nn \$100.00 X

Total

\$9,301.40

9838.80

~~9839.10~~

Massive Trading & Auto

Blk 503B #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/P 91082728

Fax : 64816131

Lin Peng Ngoh
538 Miltonia Close
#04-43
Singapore 768113

Vehicle No : SLD 6310 C
Make/Model : Honda Vezel 1.5 X A
Year : 2018

Qty	Description	Unit Price	Amount
<u>Supplementary Part</u>			
2 pcs	Rear side bumper		
	<i>C 225-30</i>		
		<i>MS.14</i>	<i>450.60</i>
		\$336.10	\$672.20 ✓
		Less 20 %	\$134.44
			<u>\$537.76</u>

H: Eaneth

Part - 2,507.76
Supplementary - 537.76
s Netl - 380.00
Labour -



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19007812/Ktd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 23-05-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7071M	Veh. Inspected	SLD 6310C
Policy No.		Coverage (\$)	0.00
Claim No.	D19002895MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	03/05/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11115313	Colour	METALLIC PEARL WHITE
Odometer	28169	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	5 mm
L/H Front Tyre	215/60 R16	DUNLOP	5 mm
R/H Rear Tyre	215/60 R16	DUNLOP	3 mm
L/H Rear Tyre	215/60 R16	DUNLOP	3 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	02/05/2019	Inspection Date	06/05/2019
Survey held at	MASSIVE TRADING & AUTO BLK 225 #07-579 ANG MO KIO AVE 1 SINGAPORE 560225		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 6310C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAIL-GATE ASSY	BENT	1,450.70	1,100.00
1	REAR TAIL-GATE GLASS MOULDING	NECESSARY	105.20	105.20
1	REAR TAIL-GATE EMBLEM "H"	NOT NECESSARY	45.10	-
1	REAR TAIL-GATE EMBLEM "VEZEL"	NECESSARY	50.20	50.20
1	REAR TAIL-GATE OUTER GARNISH	SERVICEABLE	385.60	-
1	REAR TAIL-GATE INNER LOCK	DENTED	285.60	201.00
1	REAR TAIL-GATE INNER LOCK SENSOR	DENTED	187.10	187.10
1	REAR TAIL-GATE INNER TRIM BOARD	SERVICEABLE	455.90	-
2	REAR TAIL-GATE LAMP COMPONENT @\$425.30	SERVICEABLE	850.60	-
1	REAR BOOT RUBBER	DENTED / CUT	225.80	225.80
1	REAR END PANEL	TO REPAIR SEE LABOUR	455.10	-
1	REAR END PANEL INNER GARNISH	MTG CRACKED	185.90	185.90
1	REAR BUMPER	BENT	955.70	508.50
2	REAR BUMPER REFLECTOR @\$137.10	SERVICEABLE	274.20	-
1	REAR BUMPER LOWER GARNISH	SERVICEABLE	175.20	-
1	REAR RADIO ANTENNA SENSOR	SERVICEABLE	175.60	-
2	REAR FENDER INNER TRIM @\$425.10	SERVICEABLE	850.20	-
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	975.10	-
2	REAR SIDE BUMPER @\$336.10 (ADDITIONAL)	MTG CRACKED	672.20	450.60
	LESS 20% DISCOUNT		-1,752.20	-602.86
			7,008.80	2,411.44
SPECIAL NETT ITEMS				
1	REAR TAIL-GATE GLASS SEALANT (SN)	NECESSARY	55.00	40.00
1	REAR REVERSE SENSOR (SN)	DENTED	200.00	200.00
20	REAR BUMPER CLIP @\$2.00 (SN)	NECESSARY	40.00	40.00
1	REAR NO PLATE (SN)	SERVICEABLE	40.00	-
			335.00	280.00

Report Ref No. CS/FCI19007812/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR EXHAUST SILENCER.		900.00	550.00
	TO PUTTY AND SPRAY PAINT.		900.00	480.00
	CHECK & RECONNECT WIRING.		45.00	15.00
	TO RESPRAY ANTI-RUST PROOFING TREATMENT.		180.00	30.00
	REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIR.		100.00	100.00
	REMOVE/REFIT REAR TAIL-GATE MECHANISM TO NEW DOOR.		150.00	60.00
	REMOVE/RENEW REAR EXHAUST SILENCER.	NOT NECESSARY	120.00	-
	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR.	NOT NECESSARY	100.00	-
			2,495.00	1,235.00
	GRAND TOTAL		9,838.80	3,926.44
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,150.00

Report Ref No. CS/FCI19007812/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.