



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

DATE : 03-05-2019

VEHICLE NO. : GBG7279G
ACCIDENT DATE : 02-05-2019 12:45
THIRD PARTY REF. : GBF9903E

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEICLE GBG7279G TOYOTA HIACE

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	REAR LAMP LH	300.80
2	1	REARLAMP LOWER PANEL LH	100.00
3	1	REAR LAMP LOWER PANEL BRACKET LH	45.00
4	1	REAR BUMPER	415.00
5	10	REAR BUMPER CLIP@\$5.00	50.00
			910.80
LESS 25 %			227.70
TOTAL (A)			683.10

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	30.00
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	680.00
3	1	SPRAYPAINTING CHARGES	650.00
TOTAL (D)			1,360.00
ESTIMATE TOTAL			2,043.10

not done
the job. Behind
3 days.
24/6/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: