

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19007870/AGA3Q2

Date: 10/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100463235

Claimant
Vehicle No : SLD4956C **Insured Vehicle No :** SJT5233M

Date of Loss: 28/04/2019 Nature of Claim: TP Claim No: 5050788506SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD4956C	Engine No:	B14NET160280715
Make & Model:	CHEVROLET CRUZE NB, 1.4 (A)	Chassis No:	KL1JA6989GK337598
Reg. Date:	20/06/2016 (Man. Year: 2016)	Odometer:	93915 km
Colour:	Black		
Engine Capacity:	1362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,269.70	5,339.80	6,929.90	56.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,680.00	1,540.00	2,140.00	58.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,949.70	6,879.80	9,069.90	56.87
Approved Total (Overridden) (\$\$)		5,500.00		
Nett Amount (\$\$)	15,949.70	5,500.00	10,449.70	65.52
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (\$\$)		749.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		6,256.45		

INSPECTION

Date of Assignment: 03/05/2019

Date Inspected: 03/05/2019 Inspected At: Xin Hua Workshop Pte Ltd (HQ)
23 Kaki Bukit Ave 4 #04-01
Singapore 415933

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR DOOR LH	Repair	1,603.00 FL	*- FL
2	1		*RR DOOR BLACK STICKER LH	Not Necessary	123.00 FL	*- FL
3	1		*RR DOOR HANDLE LH	Cut	565.00 FL	*565.00 FL
4	1		*RR DOOR HANDLE KNOB LH	Not Necessary	97.00 FL	*- FL
5	1		*RR DOOR HANDLE INNER BASE LH	Not Necessary	187.00 FL	*- FL
6	1		*RR FENDER LH	Dented	2,196.00 FL	*2,196.00 FL
7	1		*RR FENDER INNER SHIELD LH	Not Necessary	193.00 FL	*- FL
8	10		*RR FENDER INNER SHIELD CLIP	Necessary	65.00 FL	*30.00 FL
9	1		*RR FENDER QUARTER GARNISH	Necessary	157.00 FL	*157.00 FL
10	1		*RR WINDSCREEN MLDG	Necessary	118.00 FL	*118.00 FL
11	1		*RR AXLE	Not Necessary	3,277.00 FL	*- FL
12	1		*RR RIMS LH (16 INCH)	Cut	875.00 FL	*875.00 FL
13	1		*RR WHEEL BEARING LH WITH HUB	Not Necessary	573.00 FL	*- FL
14	1		*RR SHOCK ABSORBER LH	Not Necessary	288.00 FL	*- FL
15	1		*RR SHOCK ABSORBER TOP MOUNTING LH	Not Necessary	148.00 FL	*- FL
16	1		*RR BUMPER	Deformed	1,256.00 FL	*1,256.00 FL
17	1		*RR BUMPER CHROME MLDG RH	Necessary	152.00 FL	*152.00 FL
18	1		*RR BUMPER CHROME MLDG LH	Necessary	152.00 FL	*152.00 FL
19	1		*RR BUMPER CHROME MLDG CHROME	Necessary	205.00 FL	*205.00 FL
20	1		*RR BUMPER SIDE RETAINER LH (INNER)	Not Necessary	116.00 FL	*- FL
21	1		*RR BUMPER SIDE RETAINER LH (OUTER)	Necessary	116.00 FL	*116.00 FL
22	1		*RR TAILLAP LH	Not Necessary	521.00 FL	*- FL
23	10		*RR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
24	10		*RR FENDER INNERSHIELD CLIP	Not Necessary	40.00 FS	*- FS
25	1		*RR WINDSCREEN SEALANT	Necessary	65.00 FS	*30.00 FS
26	1		*RR WINDSCREEN INNER SEAL	Necessary	40.00 FS	*30.00 FS
27	1		*RR WINDSCREEN SOLAR FILM	Not Necessary	200.00 FS	*- FS
28	1		*RR TYRE LH	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,568.00	5,922.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,298.30	582.20
Total Parts (\$\$)	12,269.70	5,339.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,OIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,200.00	600.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA,RR DOOR LH ,RR FENDER LH ,RR BUMPER LH ROCKER PANEL	New	1,000.00	600.00
3	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	120.00	30.00
4	REMOVE AND REFIX SEAT ,CUSHION /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS	New	200.00	60.00
5	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	120.00	50.00
6	TRANSFER OF INTERNAL MECHANISM FROM OLD DOOR PANEL TO NEW DOOR PANEL	New	200.00	0.00
7	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	60.00	0.00
8	TO REMOVE AND REFIT REAR WINDSCREEN DUE TO REPLACEMENT OF REAR FENDER	New	200.00	120.00
9	TO CONDUCT 4 WHEEL ALIGNMENT	New	180.00	80.00
10	REMOVE AND REPLACE LHR UNDER CARRIAGE PARTS	New	400.00	0.00
Gross Labour Cost (\$\$)			3,680.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >