

ASS. REC. BY:

REF: CS/MSG/19007908/1 Dvd3/n2

Special Instruction:

Survey: Dryen

ASSIGNMENT (Office)

min/min

From (Person): Katharine Wongof MSGDate/Time: 6.5.19 14.55 p.m

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 7818LInsured: SJZ 5123Rat Workshop m/s Chunni MotorTel: 64836016of BK 10 # 01-05/06 AMK AutopointPolicy No: 27014296smp

Claim No: _____

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 3.5.2019

(Client's Record)

7/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 6.5.19 3.10p.mPerson Contacted: LYNNVehicle IN/OUT

| Date/Time | Action/Instruction | |
|-----------|--------------------------------------|--------------------|
| | Johnyote ✓ | |
| | SHA 7818L - CS/TMI/15021449/H/ubd1 | D.O.A - 14/12/2015 |
| | SJZ 5123R - CS/MSG/16012226/T/191302 | D.O.A - 29/06/2016 |
| 10/5/19 | Send preli revised via merimen | |

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

8

days

Res.: Yes or No

Lump Sum: _____

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SHA 7818 L** Reg: **June 2015**

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: **Hyundai I40** C.C. **1685**

Colour: **Blue** A/C: Insured / Std / NI / NA

Sp. Reading: **425860** T/Radio: Insured / Std / NI / NA

Eng/No: **D4FDFU504411**

C/No: **KMHLB41UMFU069600**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **In order** / Jammed / Leaked / Burnt or

Brake: **In order** / Jammed / Leaked / Burnt or

Modi: **NB** / S/Rim / STD A/Rim or

Tyre Size: F: _____

205/60 R16

R: _____

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

P/Bal: **S** mm

R/Bal: **S** mm

L/Bal: **S** mm

L/Bal: **S** mm

D.O.A. **03/05/2019**

D.O.I. **07/05/2019**

Survey held at **Chunni AMK**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MSIG 5525123R

10/06/19

Insured 2/5 12000/- with 8 days 8 reg (Red 9687.20, 4510)

RECEIVED 10 JUN 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) **10/6- typst**

Report Format :

menimen

Lump Sum / I.B.I. (\$)

12000/-

Days Of Repair: **8**

Resurvey No. of Trip: **2**

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. \$1

) Photos

) Others

TOTAL

200

11

211

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

| | |
|---|--|
| To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 | From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933 |
| Attn: Katherine Wong Chew Shong | |
| Date: 10 May 2019 | |

Preliminary Advice

| | | | |
|--------------------|-----------------------------|-------------------------|--------------|
| Insured Vehicle No | : SJZ5123R | Accident Date | : 03/05/2019 |
| TP Vehicle No | : SHA7818L | Assignment Date | : 06/05/2019 |
| Make | : HYUNDAI I40 | Est. Duration of Repair | : 7 |
| Date of Inspection | : 7/5/2019 | | |
| Inspection At | : CHUNNI MOTOR WORK PTE LTD | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 20,576.80 |
| Revised Amount | :S\$ | 13,926.72 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 13,926.72 |

| | | |
|-----------------|------|--|
| Lump Sum Repair | :S\$ | |
|-----------------|------|--|

Total Loss Consideration

| | | |
|--------------------|------|--|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | |
| COE / PARF Rebate | :S\$ | |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | |

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Main | 03 May 2019 | | 06 May 2019 14:55 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All |
|--|---|------------------------|--|----------|
| CLAIM SUBFOLDER DETAILS | | | [Created by insurer] | |
| Insured: | HO LI KHENG, ID: S6914004A | | | |
| Main Claimant: | COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R | | | |
| Vehicle Reg. No.: | SHA7818L | Date of Loss: | 03/05/2019 10:00 - :59 [46 Months and 15 Days From LTA Reg Date (Man Yr)] | |
| Claim Type: | TP | Policy/Cover Note No.: | 27014296SMP (Comprehensive) Coverage: 01/12/2018 - 30/11/2019 | |
| Vehicle Reg. No. (Insured): | SJZ5123R | Policy No. (Claimant): | | |
| | | Excess: | | |
| Repairer: | Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016 | | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544] | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/05/2019] | | | |
| Driver/Custodian (Insured): | TAN CHANEL (26 / Female), NRIC: S9216349J Email: | | | |
| Adj Asg. Remarks: | on WP. LIABILITY:100% CONTACT: MS IRENE/LYNN 6542 5119/6542 7162 | | | |
| ASSOCIATED MAIL RECEIVED | | | View All Compose Case Mail | |
| There are no mail for this case. | | | | |
| <div> <div> <div>ALL ASSOCIATED TASKS</div> <div> <div>Due Date</div> <div>Priority</div> <div>Type</div> <div>Task Group</div> <div>Subject</div> <div>Handler</div> <div>Assigned By</div> <div>Completed On</div> <div>Created On</div> <div>Done?</div> </div> </div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> </div> | | | | |
| No results. | | | | |

MCD619057197 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 03/05/2019 15:28
 SUBMITTED BY: Catherine Poo May Jun

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 03/05/2019 15:28
 Date Of Accident 03/05/2019 10:10
 Exact Location Of Accident ALONG DORSET RD TWDS KAMPONG JAVA RD
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHA7818L
 Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
 Vehicle Particulars
 Manufacturer HYUNDAI
 Model I40
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
 Insurance Company
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number D-18088936MFSH
 Cover Note Number
 Driver
 Name of Driver ANG SZE MIN
 NRIC No S7102720A
 Date Of Birth 23/01/1971
 Occupation OUTDOOR
 Date Of Driving Pass 27/11/2014
 Driving Experience 4 YEARS AND 5 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-84205816
 Fax Number
 Contact Number
 EMail Address NOEMAIL

Address 152 02-3008 ANG MO KIO AVENUE 5
 Postcode 560152
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) Involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 4
 Passenger 1 NAME: : -
 GENDER: : MALE
 Passenger 2 NAME: : -
 GENDER: : MALE
 Passenger 3 NAME: : -
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJZ5123R
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver TAN CHANEL
 NRIC/Passport Number S9216349J

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

RHT FRT

No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

03.05.2019 @ 1130AM

A - SHA 7818L
B - SJZ 5123R



Along Dorset Road Twds Kampong Java Rd

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 03.05.2019 @ 1010 hrs i was travelling along Dorset Rd Twds Kampong Java Rd with
2 male and one female on board.

I was travelling straight and suddenly veh (B) SJZ 5132R cut into my lane and collided into my
taxi front left portion.

I have company video and photos at scene to support my claims and no injuries.

Veh (B) SJZ 5132R Tan Chanel S9216349J

DECLARATION

COMPANY TRANSPORTATION POLICY
We declare the foregoing particulars are true in every respect.
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: FION

MS16

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|-----|---|------|------------|-------------|
| | Front Bumper Cover <i>distorted / mostly broken</i> | | \$ | 544.50 ✓ |
| | Front Bumper Sponge <i>NH</i> | | \$ | 99.20 X |
| | Front Bumper Reinforcement <i>NH</i> | | \$ | 402.10 X |
| | Front Bumper Grille (LH) <i>out</i> | | \$ | 41.60 ✓ |
| | Front Bumper Bracket Top (LH) <i>NH</i> | | \$ | 22.40 X |
| | Front Bumper Bracket (LH) <i>broken</i> | | \$ | 24.60 ✓ |
| | Headlamp Support Top Cover <i>NH</i> | | \$ | 222.60 X |
| | Headlamp Support Panel Assy <i>broken</i> | | \$ | 907.40 ✓ |
| | Headlamp (LH) <i>broken</i> | | \$ | 1,388.00 ✓ |
| | Front Fender (LH) <i>Dented</i> | | \$ | 663.00 ✓ |
| | Front Fender Apron Panel (LH) <i>Dented</i> | | \$ | 637.00 ✓✓ |
| | Front Fender Shield (LH) <i>torn</i> | | \$ | 174.90 ✓ |
| | Air Cleaner Bottom Assy <i>broken</i> | | \$ | 325.00 ✓ |
| | Front Wheel Rim (LH) <i>& distorted</i> | | \$ | 325.30 ✓✓ |
| | Front Wheel Hub Cap (LH) <i>BT</i> | | \$ | 107.10 ✓ |
| | Front Wheel Bearing <i>& Dam</i> | | \$ | 540.50 ✓✓ |
| | Front Shock Absorber (Assy) (LH) <i>& distorted</i> | | \$ | 342.20 ✓✓ |
| | Front Shock Absorber Mounting (LH) <i>NH</i> | | \$ | 108.80 X |
| | Front Drive Shaft (LH) <i>& Dam</i> | | \$ | 1,030.80 ✓✓ |
| | Rack & Pinion Assy <i>& Dam</i> | | \$ | 1,191.30 ✓✓ |
| | STG Tie End <i>& distorted</i> | | \$ | 62.60 ✓✓ |
| | Stabilizer Bar <i>& distorted</i> | | \$ | 252.30 ✓✓ |
| | Stabilizer Bar Bush (LH) <i>NH</i> | | \$ | 16.40 X |
| | Stabilizer Bar Link <i>& distorted</i> | | \$ | 61.10 ✓✓ |
| | Stabilizer Bracket <i>NH</i> | | \$ | 24.00 X |
| | Front Suspension Lower Arm (LH) <i>& distorted</i> | | \$ | 529.30 ✓✓ |
| | Knuckle Arm (LH) <i>& distorted</i> | | \$ | 552.00 ✓✓ |
| | Engine Under Cover <i>NH</i> | | \$ | 334.60 X |
| | Engine Crossmember <i>→ distorted</i> | | \$ | 2,094.40 ✓✓ |
| | ABS Sensor (LH) <i>NH</i> | | \$ | 234.00 X |
| | Wiring-Engine <i>→ housing broken</i> | | \$ | 3,326.00 ✓✓ |
| | Electric Power Steering <i>NH</i> | | \$ | 3,641.00 X |
| | SUB TOTAL | | \$ | 20,226.00 |
| | LESS 20% | | \$ | 4,045.20 |
| | DISCOUNTED TOTAL | | \$ | 16,180.80 |
| | Front Tyre (LH) <i>SVC</i> | | \$ | 216.00 |
| | | | | Nett X |

Amount

700/-
~~600/-~~
500/-
300/-
400/-
NN
← 1500/-
600/-
NN
← 1500/-
← 500/-
1500/-

ESTIMATE TOTAL

\$ 20,576.80

21,687.20

13926.72

1110.40

15037.12

2 | 512000 |

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7818L (Supplementary)

DATE : 7.05.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|-----|--|------|------------|-------------|
| | Headlamp (RH) mounting bracket | | | \$ 1,388.00 |
| | SUB TOTAL | | | \$ 1,388.00 |
| | LESS 20% | | | \$ 277.60 |
| | DISCOUNTED TOTAL | | | \$ 1,110.40 |
| |  | | | |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 7818 L

Technician:

Mileage: 425860

Time Printed 7.5.19 1:46 PM

HYUNDAI I40

Front : Left

| Actual | BEFORE | Specified Range |
|--------|--------|-----------------|
| 0°09' | | -3°00' 3°00' |
| 6°27' | | -0°19' 5°41' |
| -2°05' | | -1°30' 1°30' |
| 21°01' | | |
| 21°11' | | |

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

| Actual | BEFORE | Specified Range |
|--------|--------|-----------------|
| -1°10' | | -3°00' 3°00' |
| 6°30' | | -0°19' 5°41' |
| 0°14' | | -1°30' 1°30' |
| 14°42' | | |
| 13°32' | | |

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

| Actual | BEFORE | Specified Range |
|--------|--------|-----------------|
| 1°20' | | -3°00' 3°00' |
| -0°03' | | -3°00' 3°00' |
| 6°19' | | -3°00' 3°00' |
| -1°51' | | -3°00' 3°00' |

Rear : Left

| Actual | BEFORE | Specified Range |
|--------|--------|-----------------|
| -1°32' | | -3°30' 2°30' |
| -0°05' | | -1°30' 1°30' |

Camber
Toe

Rear : Right

| Actual | BEFORE | Specified Range |
|--------|--------|-----------------|
| -1°24' | | -3°30' 2°30' |
| 0°02' | | -1°30' 1°30' |

Rear

Cross Camber
Total Toe
Thrust Angle

| Actual | BEFORE | Specified Range |
|--------|--------|-----------------|
| -0°07' | | -3°00' 3°00' |
| -0°03' | | -3°00' 3°00' |
| -0°04' | | -3°00' 3°00' |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19007908/DVD3N2

Date: 11/06/2019

REFERENCE

| | | | |
|-----------------------|--------------------------------------|----------------------|----------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | 27014296 |
| Claimant Vehicle No : | SHA7818L | Insured Vehicle No : | SJZ5123R |
| Date of Loss: | 03/05/2019 | Nature of Claim: | TP |
| | | Claim No: | 592545 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No: | SHA7818L | Engine No: | D4DFDU504411 |
| Make & Model: | HYUNDAI I40, 1.7 D (A) | Chassis No: | KMHLB41UMFU069600 |
| Reg. Date: | 18/06/2015 (Man. Year: 2015) | Odometer: | 425860 km |
| Colour: | Blue | | |
| Engine Capacity: | 1685 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|----------------|------------------|----------------|
| Front Tyre Size: | 205/60 R16 | Rear Tyre Size: | 205/60 R16 |
| Front Left Side: | West Lake 5 mm | Rear Left Side: | West Lake 5 mm |
| Front Right Side: | West Lake 5 mm | Rear Right Side: | West Lake 5 mm |

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|------------------|------------------|--------------|
| Parts | 17,507.20 | 13,207.12 | 4,300.08 | 24.56 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,180.00 | 1,830.00 | 2,350.00 | 56.22 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 21,687.20 | 15,037.12 | 6,650.08 | 30.66 |
| Approved Total (Overridden) (S\$) | | 12,000.00 | | |
| (S\$) | 21,687.20 | 12,000.00 | 9,687.20 | 44.67 |
| + GST 7.00/7.00% (S\$) | 1,518.10 | 840.00 | 678.10 | 44.67 |
| Nett Amount (S\$) | 23,205.30 | 12,840.00 | 10,365.30 | 44.67 |

INSPECTION

Date of Assignment: 06/05/2019

Date Inspected: 07/05/2019 Inspected At:

Chunni Motor Work Pte Ltd - Amk (HQ)
Blk 10 #01-05/06, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|--|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 11 Jun 2019) |
| Parts: 143 | HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SHA7818L) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk * |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|---------------------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER COVER | Distorted/Mounting Broken | 544.50 FL | *544.50 FL |
| 2 | 1 | | *FRONT BUMPER SPONGE | Not Necessary | 99.20 FL | *- FL |
| 3 | 1 | | *FRONT BUMPER REINFORCEMENT | Not Necessary | 402.10 FL | *- FL |
| 4 | 1 | | *FRONT BUMPER GRILLE (LH) | Cut | 41.60 FL | *41.60 FL |
| 5 | 1 | | *FRONT BUMPER BRACKET TOP (LH) | Not Necessary | 22.40 FL | *- FL |
| 6 | 1 | | *FRONT BUMPER BRACKET (LH) | Broken | 24.60 FL | *24.60 FL |
| 7 | 1 | | *HEADLAMP SUPPORT TOP COVER | Not Necessary | 222.60 FL | *- FL |
| 8 | 1 | | *HEADLAMP SUPPORT PANEL ASSY | Broken | 907.40 FL | *907.40 FL |
| 9 | 1 | | *HEADLAMP (LH) | Broken | 1,388.00 FL | *1,388.00 FL |
| 10 | 1 | | *FRONT FENDER (LH) | Dented | 663.00 FL | *663.00 FL |
| 11 | 1 | | *FRONT FENDER APRON PANEL (LH) | Dented | 637.00 FL | *637.00 FL |
| 12 | 1 | | *FRONT FENDER SHIELD (LH) | Torn | 174.90 FL | *174.90 FL |
| 13 | 1 | | *AIR CLEANER BOTTOM ASSY | Broken | 325.00 FL | *325.00 FL |
| 14 | 1 | | *FRONT WHEEL RIM (LH) | Distorted | 325.30 FL | *325.30 FL |
| 15 | 1 | | *FRONT WHEEL HUB CAP (LH) | Bent | 107.10 FL | *107.10 FL |
| 16 | 1 | | *FRONT WHEEL BEARING | Damaged | 540.50 FL | *540.50 FL |
| 17 | 1 | | *FRONT SHOCK ABSORBER (ASSY)(LH) | Distorted | 342.20 FL | *342.20 FL |
| 18 | 1 | | *FRONT SHOCK ABSORBER MOUNTING (LH) | Not Necessary | 108.80 FL | *- FL |
| 19 | 1 | | *FRONT DRIVE SHAFT (LH) | Damaged | 1,030.80 FL | *1,030.80 FL |
| 20 | 1 | | *RACK & PINION ASSY | Damaged | 1,191.30 FL | *1,191.30 FL |
| 21 | 1 | | *STG TIE END | Distorted | 62.60 FL | *62.60 FL |
| 22 | 1 | | *STABILIZER BAR | Distorted | 252.30 FL | *252.30 FL |
| 23 | 1 | | *STABILIZER BAR BUSH (LH) | Not Necessary | 16.40 FL | *- FL |
| 24 | 1 | | *STABILIZER BAR LINK | Distorted | 61.10 FL | *61.10 FL |
| 25 | 1 | | *STABILIZER BRACKET | Not Necessary | 24.00 FL | *- FL |
| 26 | 1 | | *FRONT SUSPENSION LOWER ARM (LH) | Distorted | 529.30 FL | *529.30 FL |
| 27 | 1 | | *KNUCKLE ARM (LH) | Distorted | 552.00 FL | *552.00 FL |
| 28 | 1 | | *ENGINE UNDER COVER | Not Necessary | 334.60 FL | *- FL |
| 29 | 1 | | *ENGINE CROSSMEMBER | Distorted | 2,094.40 FL | *2,094.40 FL |
| 30 | 1 | | *ABS SENSOR (LH) | Not Necessary | 234.00 FL | *- FL |
| 31 | 1 | | *WIRING-ENGINE | Housing Broken | 3,326.00 FL | *3,326.00 FL |
| 32 | 1 | | *ELECTRIC POWER STEERING | Not Necessary | 3,641.00 FL | *- FL |
| 33 | 1 | | *HEADLAMP (RH) | Mounting Broken | 1,388.00 FL | *1,388.00 FL |
| 34 | 1 | | *FRONT TYRE (LH) | Serviceable | 216.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|------------------|
| Sub Total (\$\$) | 21,830.00 | 16,508.90 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 4,322.80 | 3,301.78 |
| Total Parts (\$\$) | 17,507.20 | 13,207.12 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | PANEL BEATING | New | 1,500.00 | 700.00 |
| 2 | SPRAY PAINTING CHARGE | New | 750.00 | 500.00 |
| 3 | WIRING CHARGE | New | 50.00 | 30.00 |
| 4 | TUFF KOTE | New | 50.00 | 40.00 |
| 5 | TOWING CHARGE | New | 50.00 | 0.00 |
| 6 | REMOVE/REFIX UNDERCARRIAGE (FRT) | New | 200.00 | 150.00 |
| 7 | FRT WHEEL ALIGNMENT | New | 120.00 | 60.00 |
| 8 | REMOVE/REFIX AIRCON & REFILL GAS | New | 150.00 | 0.00 |
| 9 | REMOVE/REFIX DASHBOARD | New | 450.00 | 150.00 |
| 10 | REMOVE/REFIX FUSE BOX | New | 180.00 | 50.00 |
| 11 | DIAGNOSTIC & RESETTING TO ERASE FAULT CODE } | New | 480.00 | 150.00 |
| 12 | RE-SET FRT ABS SYSTEM } | New | 200.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 4,180.00 | 1,830.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >