



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 8165B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT L/H DOOR (CONSISTENT)	DENTED	980.20	980.20
2	FRONT L/H DOOR HINGE @ \$132.00 (CONSISTENT)	NOT NECESSARY	264.00	-
1	FRONT L/H DOOR INNER LOCK (CONSISTENT)	NOT NECESSARY	578.20	-
1	FRONT L/H DOOR INNER RUBBER (CONSISTENT)	NOT NECESSARY	272.60	-
1	REAR BUMPER (CONSISTENT)	TORN	625.20	625.20
8	REAR BUMPER CLIP @ \$6.50 (CONSISTENT)	NECESSARY	52.00	30.00
1	REAR L/H BUMPER SIDE RETAINER (CONSISTENT)	NECESSARY	132.10	132.10
1	REAR L/H DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	980.30	-
2	REAR L/H DOOR HINGE @ \$132.00 (CONSISTENT)	NOT NECESSARY	264.00	-
1	REAR L/H DOOR INNER LOCK (CONSISTENT)	NOT NECESSARY	578.20	-
1	REAR L/H DOOR INNER RUBBER (CONSISTENT)	NOT NECESSARY	272.60	-
1	REAR L/H FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	972.45	-
1	REAR L/H TYRE (CONSISTENT)	NOT NECESSARY	350.00	-
1	L/H ROCKER PANEL SKIRT (CONSISTENT)	TO REPAIR SEE LABOUR	850.00	-
10	L/H ROCKER PANEL SKIRT CLIP @ \$6.50 (CONSISTENT)	NOT NECESSARY	65.00	-
	LESS 25% DISCOUNT		-	-441.87
			7,236.85	1,325.63
<u>SPECIAL NETT ITEMS</u>				
1	REAR L/H RIM (SN) (CONSISTENT)	CUT	850.00	450.00
1	DOOR FRAME STRIP (SN) (CONSISTENT)	NECESSARY	180.00	90.00
			1,030.00	540.00
<u>LABOUR</u>				
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.	NOT NECESSARY	150.00	-
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR L/H DOOR, REAR L/H FENDER AND L/H ROCKER PANEL SKIRT.		1,600.00	500.00

Report Ref No. CC4/ASM19007945/Apa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING.		1,800.00	900.00
			3,650.00	1,430.00
GRAND TOTAL			11,916.85	3,295.63
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CC4/ASM19007945/Apa3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.