

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19007947/ADA3Q2

Date: 27/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100510624
Claimant
Vehicle No : SDQ880P **Insured Vehicle No :** SGD1808B
Date of Loss: 26/04/2019 **Nature of Claim:** TP **Claim No:** 4731209807SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDQ880P**
 Make & Model: AUDI Q3, 1.4 TFSI (A) Engine No: CZD240305
 Reg. Date: 16/08/2016 (Man. Year: 2016) Chassis No: WAUZZZ8U8GR113304
 Colour: Blue Odometer: 36759 km
 Engine Capacity: 1395 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R17 Rear Tyre Size: 235/55 R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,656.40	2,767.40	1,889.00	40.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,072.00	2,572.00	2,500.00	49.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,728.40	5,339.40	4,389.00	45.12
+ GST 7.00/7.00% (S\$)	680.99	373.76	307.23	45.12
Nett Amount (S\$)	10,409.39	5,713.16	4,696.23	45.12
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,895.16		

INSPECTION

Date of Assignment: 08/05/2019
 Date Inspected: 08/05/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
 55 Ubi Road 1
 Singapore 408699
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,354.00 FS	*1,083.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	112.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Distorted	434.00 FS	*346.80 FS
4	1		*REAR BUMPER TOWING COVER -LH/RH	Not Necessary	63.00 FS	*- FS
5	1		*REAR BUMPER TAIL LIGHT -LH	Cracked	418.00 FS	*334.40 FS
6	1		*REAR BUMPER CARRIER	Bent	569.00 FS	*454.80 FS
7	1		*FOAM FILLER PIECE	Not Necessary	78.00 FS	*- FS
8	1		*REAR BUMPER GUIDE SECTION -LH	Damaged	91.00 FS	*72.40 FS
9	2		*REAR BUMPER SENSOR	Not Necessary	462.00 FS	*- FS
10	1		*REAR BUMPER SENSOR SEAL RING	Not Necessary	5.00 FS	*- FS
11	2		*REAR WHEEL ARCH TRIM -LH/RH	Necessary	472.00 FS	*377.60 FS
12	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS
13	1		*AIR VENT LHS REAR	Cracked	98.40 FS	*98.40 FS
					Total Parts (S\$)	4,656.40 2,767.40

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR LHS TAIL LAMP PANEL	New	1,200.00	500.00
2	TO RESPRAY LHS TAIL LAMP PANEL	New	1,000.00	550.00
3	TO REMOVE AND REINSTALL REAR PARKING AID ,CHECK FUNCTION	New	280.00	280.00
4	TO DISMANTLE AND RENEW REAR BUMPER ,TO REINSTALL LHS TAIL LAMP PANEL AND LHS REAR FENDER .RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
5	TO RESPRAY REAR BUMPER	New	1,200.00	550.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			5,072.00	2,572.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >