Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19007957/APA3Q2

Date: 25/01/2021

REFERENCE

Vehicle No:

India International Insurance Pte Handling Insurer:

D18MPC0000517

Odometer:

Ltd Claimant

YM1228P

Insured Vehicle No:

SKZ2759P

Date of Loss: 11/04/2019 Nature of Claim: TP Claim No:

HIDDEN

722373 km

MPC2019D0000341

DESCRIPTION & IDENTIFICATION OF VEHICLE

YM1228P Reg No:

Make & Model: ISUZU NHR69EU3ES, 3.1 D (M)

Engine No: Reg. Date: 01/09/2005 (Man. Year: 2005) Chassis No: JAANHR69E57100242

Colour: Blue

Engine Capacity: 3059 cc Market Value/New Car

Price:

N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

CONDITION OF TYRES

175 R14C Front Tyre Size: 175 R14C Rear Tyre Size: Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,419.10	1,360.88	1,058.22	43.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	650.00	300.00	31.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,369.10	2,010.88	1,358.22	40.31
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	3,369.10	1,600.00	1,769.10	52.51
+ Loss of Use (3.0 x S\$10	00.00/day) (S\$)	300.00		
+ Doc/S	earch Fee (S\$)	7.45		

Nett Liability (S\$)

INSPECTION

Date of Assignment: 03/05/2019

Date Inspected: 03/05/2019 Inspected At: Hua Meng Spray Painting Workshop

Global Sum Settlement (S\$)

(HQ)

1,907.45

1.900.00

No 1 Kaki Bukit Avenue 6, #01-61

Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference
Part Source: (Last Synchronised: 18 Dec 2020)

Parts: N/A ISUZU NHR69EU3ES 3.1 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YM1228P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

NO.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH MUDFLAP	Cracked	212.80 F	*212.80 FL
2	1		*FUEL TANK	Dented	1,700.30 FS	*1,000.00 FS
3	1		*FUEL TANK FUSTENER	Not Necessary	276.00 FS	*-FS
4	1		*ADVERTISEMENT STICKER	Necessary	230.00 FS	*180.00 FS
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.			
				Sub Total (S\$)	2,419.10	1,392.80
	- List Item Discount on L Items 0.00/15.00% (S\$)			0.00	31.92	
	Total Parts (S\$)		2,419.10	1,360.88		
_						

0----

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE & REINSTALL FUEL TANK	New	150.00	100.00
2	PANEL BEATING	New	400.00	250.00
3	RESPRAY PAINTING	New	400.00	300.00
		Gross Labour Cost (S\$)	950.00	650.00
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >