

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19007962/KBA3Q2

**Date:** 26/06/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**

**Vehicle No :** SJZ720A

**Insured Vehicle No :** SJS4393X

Date of Loss: 03/05/2019

Nature of Claim: TP

Claim No: 9023340040SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ720A**

Make & Model: KIA CERATO FORTE, 1.6 SX (A)

Engine No: G4FC9H251011

Reg. Date: 25/06/2009 (Man. Year: 2009)

Chassis No: KNAFH221395067843

Colour: White

Odometer: 151977 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45R17

Rear Tyre Size:

225/45R17

Front Left Side: Hankook 7 mm

Rear Left Side:

Hankook 6 mm

Front Right Side: Hankook 7 mm

Rear Right Side:

Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,643.40	7,103.00	3,540.40	33.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,350.00	3,510.00	840.00	19.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,993.40</b>	<b>10,613.00</b>	<b>4,380.40</b>	<b>29.22</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,000.00</b>		
<b>(S\$)</b>	14,993.40	8,000.00	6,993.40	46.64
<b>+ GST 7.00/7.00% (S\$)</b>	1,049.54	560.00	489.54	46.64
<b>Nett Amount (S\$)</b>	<b>16,042.94</b>	<b>8,560.00</b>	<b>7,482.94</b>	<b>46.64</b>
<b>+ Car Rental (23.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		2,461.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>11,028.45</b>		

### INSPECTION

Date of Assignment: 06/05/2019

Date Inspected: 06/05/2019 Inspected At:

Chew Goon Motor (AMK)

Blk 10 Ang Mo Kio Industrial Park 2A,

#01-15/16 & 17, AMK Autopoint

Singapore 568047

Estimated Period of Repair: 14.0 days

---

**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT	Bent	340.00 FL	*340.00 FL
2	2		*BOOT HINGES	Repair	120.00 FL	*- FL
3	1		*BOOT CENTER EMBLEM	Necessary	115.00 FL	*115.00 FL
4	1		*BOOT LAMP RH	Cut	258.00 FL	*258.00 FL
5	1		*BOOT LAMP GASKET RH	Not Necessary	45.00 FL	*- FL
6	1		*BOOT LOCK	Bent	65.00 FL	*65.00 FL
7	1		*BOOT LOCK CATCH	Repair	8.00 FL	*- FL
8	12		*BOOT TRIM BOARD CLIPS	Necessary	12.00 FL	*12.00 FL
9	1		*BOOT WEATHERSTRIP	Distorted/Dented	45.00 FL	*45.00 FL
10	1		*BOOT OUTER GARNISH	Warped	155.00 FL	*155.00 FL
11	1		*REAR BUMPER	Buckled	698.00 FL	*698.00 FL
12	10		*REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
13	1		*REAR BUMPER SPONGE	Cracked	125.00 FL	*125.00 FL
14	2		*REAR BUMPER BRACKETS	Cracked	52.00 FL	*52.00 FL
15	1		*REAR BUMPER REINFORCEMENT	Cracked	360.00 FL	*360.00 FL
16	3		*REAR BUMPER LOWER RETAINERS	Cracked	75.00 FL	*75.00 FL
17	1		*REAR BUMPER REVERSE SENSORS (3 Pcs)	Shorted (2 Pcs only)	885.00 FL	*590.00 FL
18	4		*REAR BUMPER REVERSE SENSOR HOLDERS	Necessary	320.00 FL	*320.00 FL
19	1		*REAR BUMPER REVERSE SENSOR WIRING HARNES	Serviceable	230.00 FL	*- FL
20	1		*REAR BUMPER LOWER LIP SEAL	Necessary	45.00 FL	*45.00 FL
21	2		*REAR BUMPER CORNER RETAINERS	Serviceable	116.00 FL	*- FL
22	2		*TAILLAMPS	Serviceable	640.00 FL	*- FL
23	2		*TAILLAMP GASKETS	Not Necessary	90.00 FL	*- FL
24	1		*TAILLAMP PANEL LH	Repair	140.00 FL	*- FL
25	1		*END PANEL	Bent	130.00 FL	*130.00 FL
26	1		*END PANEL GARNISH	Dented	30.00 FL	*30.00 FL
27	1		*REAR FENDER TRIM BOARD LH	Serviceable	105.00 FL	*- FL
28	1		*SPARE TYRE PANEL	Bent/Buckled	580.00 FL	*580.00 FL
29	1		*SPARE TYRE INSULATION	Necessary	190.00 FL	*190.00 FL
30	1		*SPARE TYRE TOP BOARD	Serviceable	105.00 FL	*- FL
31	1		*BONNET	Bent	578.00 FL	*578.00 FL
32	1		*BONNET RUBBER SEAL	Serviceable	52.00 FL	*- FL
33	1		*BONNET INNER SEAL	Serviceable	85.00 FL	*- FL
34	10		*BONNET INSULATOR CLIPS	Not Necessary	10.00 FL	*- FL
35	1		*FRONT GRILLE	Dented	241.00 FL	*241.00 FL
36	1		*FRONT GRILLE EMBLEM	Necessary	40.00 FL	*40.00 FL
37	1		*FRONT BUMPER	Buckled	510.00 FL	*510.00 FL
38	10		*FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
39	1		*FRONT BUMPER REINFORCEMENT	Bent	208.00 FL	*208.00 FL
40	1		*FRONT BUMPER SPONGE	Cracked	98.00 FL	*98.00 FL
41	1		*FRONT BUMPER NUMBER PLATE GARNISH	Dented	58.00 FL	*58.00 FL
42	1		*HEADLAMP	Serviceable	565.00 FL	*- FL
43	1		*SUPPORT PANEL	Bent	438.00 FL	*438.00 FL
44	1		*AIR CONDENSER	Bent	694.00 FL	*694.00 FL
45	1		*RADIATOR	Serviceable	1,150.00 FL	*- FL
46	1		*FRONT NUMBER PLATE	Dented	45.00 FS	*45.00 FS
47	1		*REAR BUMPER LOWER LIP	Cracked	650.00 FS	*650.00 FS
48	1		*FRONT BUMPER LED LAMP	Serviceable	160.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 11,731.00 7,815.00**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>					1,087.60	712.00
<b>Total Parts (\$\$)</b>					<b>10,643.40</b>	<b>7,103.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE/TRANSFER BOOT FITTINGS AND ACCESSORIES	New	100.00	50.00
2	TO CONDUCT REAR ELECTRICAL CHECK,REPLACE REVERSE SENSORS,MODULE,WIRING & REPROGRAM SYSTEM	New	180.00	90.00
3	TO DISMANTLE/REFIT TRUNK COMPARTMENT BOARD,TRIMS ETC	New	80.00	60.00
4	TO REMOVE/REMOUNT REAR AND FRONT BUMPER LIP.SUPPLY ADHESIVE TAPES,SEALANT,RIVETS ETC	New	180.00	80.00
5	TO REMOVE/REFILL AIR CON GAS	New	120.00	100.00
6	TO REFIT/REFILL RADIATOR COOLANT	New	60.00	50.00
7	TO APPLY RUST PROOFING/RESEAL TUFF COATING	New	150.00	120.00
8	TO SUPPLY REAR PANEL BODY SEALANT	New	80.00	60.00
9	LABOUR CHARGE-PANEL BEATING,REPAIRING OF FRONT CHASSIS MEMBER,REAR FLOOR PANEL,CHASSIS MEMBER,INNER PANEL,2 REAR FENDERS ETC.CNT,WELD END PANEL,SPARE TYRE PANEL AND PARTS REPLACEMENT	New	1,800.00	1,500.00
10	TO RESPRAY AFFECTED AREAS	New	1,600.00	1,400.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,350.00</b>	<b>3,510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >