

## CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

## **ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info			
CHINA TATOTHE THEHDANCE (CINCADODE)	Cust No/Name	/Mr Lim Sze Hwee (lin Zihui)		
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00	Reg No/Reg Date	SLM4760C*1F / 31/03/2017		
Springleaf Tower	Date In/Mileage	04/05/2019/ 0		
Singapore 079909	Chassis No	KNACC81CVH5058710		
Attn: Claims Dept.	Engine No	G4LEHS179007		
Contact No 63896111	Make/Model	KIA/NIRO 1.6 A		
AND THE STATE OF T	Colour/Trim	K3R / WK		

ount No	Terms	Date/Time	Printed	CSE	Operator		WIP No			
				DS	303 / Renemer		23804			
0010						Qty	Unit Price	Disc%	Ап	ount
MIPNT8808	38								-	250.00
		ING							0	
MIPNT8808	38								80	100.00
		G/WIRING S'	STEM ON	REAR ACCIDE	NT					
									200	600.00
		evenence our			arur.				200	000.00
TO REMOVE	E & RE-II	NSTALL ALL	CARPETS,	TRIMMING TO	GIVE					
		R ON LHR A	CCIDENT	AFFECTED ARE	AS			1/0	X	600.00
MIPNT880	88	DOOR COMPO	UTNITE /NE/	CUANTEN				1010	,	
		DOUR COMPO	AEM 12/WE	CHAN13M		-			900	1800.00
MILNISSO	CE LUD D	OOD IND CA	DNIEU LUI	OTD MITTER	TE FOO S	125	1		/	
			MISH, LI	Gast Brandar	110012		7)			
STRAIGHT	EN DEEUB	M ALTEN ON	HR ACO	DENT AFFECT	ED       ( C	166	7			
	LIT, NEI ON	arynerum on	41111 7104	ration of						
	88							. 1	, X	180.00
								NIV	6 .	
									X	50.00
									112-	1000.00
MIPNT980	88								410	1260.00
		ON REAR ACC	IDENT AF	FECTED AREAS	1.000 X	* 00	1217 00	0.00		1317.00
1					10 pers					33.00
					5 (					26.00
					X NO					11.00
					× /					9.00
					1/ NEC					15.00
					1104					113.0
					- 4 aut	1.00	201.00	0.00		201.0
					/	1.00				144.0
		4 - 50			- Cut	1.00				1250.0
KS 52933		California Commission		TRE PRESSUR	X NN	1.00	125.00	0.00		125.0
NOTES					17 10.0					
	DIAGNOSTI MIPNTB800 TO CHECK AFFECTED MIPNTB800 TO REMOVI WAY ACCE: MIPNTB800 TO TRANSI MIPNTB800 TO REPAI TO REPAI TO REPAI TO REPAI TO REPAI MIPNTB80 WHEEL AL MIPNTB80 WHEEL AL MIPNTB80 WHEEL BA MIPNTBR WHEEL BA MIPNTBR WHEEL BA MIPNTBR WHEEL B	MIPNT88088 DIAGNOSTIC/SCANN MIPNT88088 TO CHECK LIGHTIN AFFECTED AREAS MIPNT88088 TO REMOVE & RE-I WAY ACCESS REPAI MIPNT88088 TO TRANSFER LHR MIPNT88088 TO REPLACE LHR D TO REPAIR LH SID STRAIGHTEN, REFORM AREAS MIPNT88088 WHEEL ALIGNMENT MIPNT88088 WHEEL BALANCING MIPNT88088 WHEEL BALANCING MIPNT98088 SPRAY PAINTING O KS 77003 G5 000 KS 779310 ZE 000 KS 79310 ZE 000 KS 79310 ZE 000 KS 79310 ZE 000 KS 79310 ZE 000 KS 86381 G5 000 KS 87731 G5 000	MIPNT88088 DIAGNOSTIC/SCANNING MIPNT88088 TO CHECK LIGHTING/WIRING SY AFFECTED AREAS MIPNT88088 TO REMOVE & RE-INSTALL ALL WAY ACCESS REPAIR ON LHR AN MIPNT88088 TO TRANSFER LHR DOOR COMPON MIPNT88088 TO REPLACE LHR DOOR, LHR GAN TO REPAIR LH SIDE SILL STRAIGHTEN, REFORM, ALIGN ON AREAS MIPNT88088 WHEEL ALIGNMENT MIPNT88088 WHEEL BALANCING MIPNT88088 SPRAY PAINTING ON REAR ACC KS 77003 G5 000 LKS 779310 ZE 000 LKS 79310 ZE 000 LKS 86383 G5 000 LKS 86383 G5 000 LKS 87731 G5 000 LKS 87731 G5 000 LKS 87751 G5 000W K LKS 87741 G5 000	Description of Good MIPNT88088 DIAGNOSTIC/SCANNING MIPNT88088 TO CHECK LIGHTING/WIRING SYSTEM ON AFFECTED AREAS MIPNT88088 TO REMOVE & RE-INSTALL ALL CARPETS, WAY ACCESS REPAIR ON LHR ACCIDENT AMIPNT88088 TO TRANSFER LHR DOOR COMPONENTS/MED TO REPLACE LHR DOOR, LHR GARNISH, LHI TO REPAIR LH SIDE SILL STRAIGHTEN, REFORM, ALIGN ON LHR ACCIDENT AREAS MIPNT88088 WHEEL ALIGNMENT MIPNT88088 WHEEL BALANCING MIPNT88088 SPRAY PAINTING ON REAR ACCIDENT AF KS 77003 G5 000 KS 79310 ZE 000 KS 79310 ZE 000 KS 86381 G5 000 KS 86383 G5 000 KS 87539 G5 000 KS 87539 G5 000 KS 87731 G5 000 KS 87751 G5 000W KS 877	Description of Goods / Services MIPNT88088 DIAGNOSTIC/SCANNING MIPNT88088 TO CHECK LIGHTING/WIRING SYSTEM ON REAR ACCIDED AFFECTED AREAS MIPNT88088 TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO WAY ACCESS REPAIR ON LHR ACCIDENT AFFECTED ARE MIPNT88088 TO TRANSFER LHR DOOR COMPONENTS/MECHANISM MIPNT88088 TO REPLACE LHR DOOR, LHR GARNISH, LHR OTR MEDGLE TO REPAIR LH SIDE SILL STRAIGHTEN, REFORM, ALIGN ON LHR ACCIDENT AFFEGT AREAS MIPNT88088 WHEEL ALIGNMENT MIPNT88088 WHEEL ALIGNMENT MIPNT88088 WHEEL BALANCING MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS KS 77003 G5 000  KS 79410 D8 000  KS 79410 D8 000  KS 79310 2E 000  KS 79310 2E 000  KS 86381 G5 000  KS 86383 G5 000  KS 87539 G5 000  KS 87731 G5 000  KS 87751 G5 000W  KS 87751 G5 000W  KS 87751 G5 000W  KL SIDE SILL MLDG-AS KS 87741 G5 000  LH GARNISH ASSY-QTR	Description of Goods / Services  MIPNT88088 DIAGNOSTIC/SCANNING MIPNT88088 TO CHECK LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS MIPNT88088 TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO GIVE WAY ACCESS REPAIR ON LHR ACCIDENT AFFECTED AREAS MIPNT88088 TO TRANSFER LHR DOOR COMPONENTS/MECHANISM MIPNT88088 TO REPLACE LHR DOOR, LHR GARNISH, LHR QTR MEDGJETC TO REPAIR LH SIDE SILL STRAIGHTEN, REFORM, ALIGN ON LHR ACCIDENT AFFECTED AREAS MIPNT88088 WHEEL BALANCING MIPNT88088 WHEEL BALANCING MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS KS 77003 G5 000 LH PANEL ASSY-REAR D KS 79310 ZE 000 LH UPR HINGE ASSY-RR KS 79310 ZE 000 LH UPR HINGE ASSY-RR KS 79310 ZE 000 LH TAPE-RR DR BLACK KS 87539 G5 000 LH TAPE-RR DR BLACK KS 87539 G5 000 LH TAPE-RR DR BLACK KS 87539 G5 000 LH FILM - ANTI-CHIPP KS 87731 G5 000 LH MLDG ASSY-RR DR W KS 87751 G5 000W K LH SIDE SILL MLDG-AS KS 87751 G5 000W K LH SIDE SILL MLDG-AS KS 87751 G5 000W K LH SIDE SILL MLDG-AS KS 87741 G5 000 LH GARNISH ASSY-QTR	Description of Goods / Services  IPPNT88088 DIAGNOSTIC/SCANNING MIPNT88088 DI CHECK LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS MIPNT88088 TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO GIVE MAY ACCESS REPAIR ON LHR ACCIDENT AFFECTED AREAS MIPNT88088 TO TRANSFER LHR DOOR COMPONENTS/MECHANISM MIPNT88088 TO REPLACE LHR DOOR, LHR GARNISH, LHR OTR MIDGGETT TO REPAIR LH SIDE SILL STRAIGHTEN, REFORM, ALIGN ON LHR ACCIDENT AFFECTED AREAS MIPNT88088 WHEEL ALIGNMENT MIPNT88088 WHEEL BALANCING MIPNT88088 WHEEL BALANCING MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS KS 77003 G5 000  LH PANEL ASSY-REAR D  KS 79310 ZE 000  LH LWR HINGE ASSY-RR  1.00 KS 79310 ZE 000  LH TAPE-RR DR BLACK X 1.00 KS 86381 G5 000  LH TAPE-RR DR BLACK X 1.00 KS 86383 G5 000  LH TAPE-RR DR BLACK X 1.00 KS 87731 G5 000 KH SILL MLDG-AS LH GANISH ASSY-QTR LOO KS 87741 G5 000 KS 87741 G5 000 LH GARNISH ASSY-QTR LOO LOO KS 87741 G5 000 LH GARNISH ASSY-QTR LOO LOO KS 87741 G5 000 LH GARNISH ASSY-QTR LOO LOO KS 87741 G5 000 LH GARNISH ASSY-QTR LOO LOO KS 87741 G5 000 LH GARNISH ASSY-QTR LOO LOO KS 87741 G5 000 LH GARNISH ASSY-QTR LOO LOO KS 87741 G5 000 LH GARNISH ASSY-QTR LOO LOO KS 87741 G5 000 LH GARNISH ASSY-QTR LOO LOO KS 87741 G5 000 LH GARNISH ASSY-QTR LOO LOO KS 87741 G5 000 LH GARNISH ASSY-QTR LOO LOO KS 87741 G5 000 LH GARNISH ASSY-QTR LOO LOO KS 87741 G5 000 LH GARNISH ASSY-QTR LOO LOO KS 87741 G5 000 LH GARNISH ASSY-QTR LOO LOO KS 87741 G5 000 LOO	Description of Goods / Services  WIPNT88088 DIAGNOSTIC/SCANNING WIPNT88088 TO CHECK LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS MIPNT88088 TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO GIVE WAY ACCESS REPAIR ON LHR ACCIDENT AFFECTED AREAS MIPNT88088 TO TRANSFER LHR DOOR COMPONENTS/MECHANISM MIPNT88088 TO REPLACE LHR DOOR, LHR GARNISH, LHR QTR MEDGJETC TO REPAIR LH SIDE SILL STRAIGHTEN, REFORM, ALIGN ON LHR ACCIDENT AFFEGTED  AREAS MIPNT88088 WHEEL ALIGNMENT MIPNT88088 WHEEL ALIGNMENT MIPNT88088 WHEEL BALANCING MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS KS 77003 G5 000  LH PANEL ASSY-REAR MIPNT88088 WHEEL BALANCING MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS KS 779310 2E 000  LH UPR HINGE ASSY-RR  LOO S33.00 KS 79310 2E 000  LH TAPE-RR DR BLACK SS 86381 G5 000  LH TAPE-RR DR BLACK SS 86383 G5 000  LH TAPE-RR DR BLACK SS 87531 G5 000  LH TAPE-RR DR BLACK SS 87531 G5 000  LH TAPE-RR DR BLACK SS 87531 G5 000  LH MLDG ASSY-RR DR SS 87731 G5 000  LH MLDG ASSY-RR DR SS 87731 G5 000  LH GARNISH ASSY-QIR SS 87731 G5 000  LH GARNISH ASSY	Description of Goods / Services  AIPNT88088 DIAGNOSTIC/SCANNING AIPNT88088  WHEEL ALIGNMENT AIPNT88088  WHEEL ALIGNMENT AIPNT88088  WHEEL ALIGNMENT AIPNT88088  WHEEL BALANCING MIPNT88088  MHEEL BALANCING MIPNT88088  SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS KS 77003 65 000  LH PARE ASSY-REAR D  LOO 1317.00 0.00  KS 79310 2E 000  LH UWR HINGE ASSY-RR  AND 1.00 1317.00 0.00  KS 86383 G5 000  LH TAPE-RR DR BLACK  AND 1.00 11.00 0.00  KS 87731 G5 000  LH MLDG ASSY-RR DR W  LH GARNISH ASSY-QTR  AND 1.00 11.00 0.00  KS 87731 G5 000  LH SIDE SILL MLDG-AS  LH GARNISH ASSY-QTR  AND 1.00 11.00 0.00  KS 87741 G5 000  LH GARNISH ASSY-QTR  AND 1.00 144.00 0.00  7 1250.00 0.00	Description of Goods / Services  ATPINT8B088 DIAGNOSTIC/SCANNING MIPNT8B088 TO CHECK LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS MIPNT8B088 TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO GIVE MAY ACCESS REPAIR ON LHR ACCIDENT AFFECTED AREAS MIPNT8B088 TO REPAIR LHR DOOR COMPONENTS/MECHANISM MIPNT8B088 TO REPAIR LH SIDE SILL STRAIGHTEN, REFORM, ALIGN ON LHR ACCIDENT AFFEGTED  AREAS MIPNT8B088 WHEEL BALANCING MIPNT8B088 WHEEL BALANCING MIPNT8B088 WHEEL BALANCING MIPNTB008 KS 7903 G5 000 LH PANEL ASSY-REAR DR KS 79010 20 000 LH LUPR HINGE ASSY-RE KS 79310 2E 000 LH LUPR HINGE ASSY-RE KS 79310 2E 000 LH LUPR HINGE ASSY-RE KS 79310 2E 000 LH TAPE-RR DR BLACK KS 86383 G5 000 LH TAPE-RR DR BLACK KS 86383 G5 000 LH TAPE-RR DR BLACK KS 87539 G5 000 LH TAPE-RR DR BLACK KS 87539 G5 000 LH TAPE-RR DR BLACK KS 87531 G5 000 LH HIND ASSY-RD DR KS 87731 G5 000 LH HIND ASSY-RD DR KS 87731 G5 000 LH GARNISH ASSY-QTR LOO 113.00 0.00 KS 87731 G5 100 COUNT WHEEL ASSY-ALUMINIUM CALL CALL CALL CALL CALL CALL CALL CAL

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

## **ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info			
CUINA TAIDING INCUDANCE (CINCADODE)	Cust No/Name	/Mr Lim Sze Hwee (lin Zihui)		
CHINA TAIPING INSURANCE (SINGAPORE)  3 Anson Road #16-00	Reg No/Reg Date	SLM4760C*1F / 31/03/2017		
Springleaf Tower	Date In/Mileage	04/05/2019/ 0		
Singapore 079909	Chassis No	KNACC81CVH5058710		
Attn: Claims Dept.	Engine No	G4LEHS179007		
Contact No 63896111	Make/Model	KIA/NIRO 1.6 A		
emates to delete to the control of the	Colour/Trim	K3R / WK		

account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
0000018	Credit	04/05/2019/ 11:02	DS	303 / Renemer		23804		
		Description of Good			Qty	Unit Price	Disc%	Amount
	REPLACEN	5/2019 ALONG MEE TOH HIRD PARTY MENT CAR TP INS: C						
	400			ima	the Repaire  To day  Hats produce  No Regal mo  Supplementa is subject to 1  Acknowledged Signature:	dification(s) is allo iry (linn(s) must be final approval from	ng: painting ing resurvey irmation out Prejudio wed resurveyed	and
	Af	ays. The pollet	sh tos 8288	ort2	Date:			
	C	58/5/19.						
Confirm &	accepted	by			Parts Labour Standard Speciali Others (L Sundry Total (W)	st Job .ub,etc)		3,244. 0. 0. 4,840. 0. 0. 8,084.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.