

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19007997/APA3Q2
Date: 08/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100458650-03
Claimant Vehicle No :	SLF3060H	Insured Vehicle No :	SGG3506T
Date of Loss:	03/05/2019	Nature of Claim:	TP
		Claim No:	2043533607SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF3060H	Engine No:	2ZR1814866
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDGG20W70J004809
Reg. Date:	23/08/2016 (Man. Year: 2016)	Odometer:	66477 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,322.65	2,245.65	7,077.00	75.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,920.00	830.00	3,090.00	78.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,242.65	3,075.65	10,167.00	76.77
Approved Total (Overridden) (S\$)		2,400.00		

Nett Amount (S\$)	13,242.65	2,400.00	10,842.65	81.88
+ Car Rental (5.0 x S\$140.00/day + 7.00% GST) (S\$)		749.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,156.45		
Global Sum Settlement (S\$)		3,150.00		

INSPECTION

Date of Assignment: 06/05/2019

Date Inspected: 07/05/2019

Estimated Period of Repair: 4.0 days

Inspected At:

ACE AUTOLUTION PTE LTD
 13 KAKI BUKIT ROAD 4
 #03-29 BARTLEY BIZ CENTRE
 SINGAPORE 417807

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Cracked	1,110.00 FL	*1,110.00 FL
2	1		*FRONT HEADLAMP BRACKET LH	Not Necessary	155.00 FL	*- FL
3	1		*FRONT BUMPER	Deformed	970.00 FL	*569.00 FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Necessary	105.00 FL	*65.00 FL
5	1		*FRONT BUMPER FOGLAMP LH	Cracked	343.20 FL	*343.20 FL
6	1		*FRONT BUMPER FOGLAMP COVER LH	Deformed	178.00 FL	*178.00 FL
7	1		*FRONT BUMPER ENGINE LOWER COVER	Not Necessary	235.00 FL	*- FL
8	1		*FRONT FENDER LH	Dented	840.00 FL	*689.00 FL
9	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	370.00 FL	*- FL
10	1		*FRONT GRILLE	Not Necessary	320.00 FL	*- FL
11	1		*FRONT BONNET	Not Necessary	1,210.00 FL	*- FL
12	1		*FRONT SUPPORT PANEL	Not Necessary	611.00 FL	*- FL
13	1		*FRONT ABSORBER LH	Not Necessary	558.00 FL	*- FL
14	1		*FRONT LOWER ARM LH	Not Necessary	620.00 FL	*- FL
15	1		*FRONT KNUCKLE ARM LH	Not Necessary	495.00 FL	*- FL
16	1		*FRONT BEARING LH	Not Necessary	555.00 FL	*- FL
17	1		*FRONT BAR LINK LH	Not Necessary	350.00 FL	*- FL
18	1		*FRONT TIE ROD END LH	Not Necessary	135.00 FL	*- FL
19	1		*FRONT DOOR LH	Not Necessary	1,555.00 FL	*- FL
20	1		*FRONT WIPER SPARE TANK	Not Necessary	275.00 FL	*- FL
21	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
22	1		*SET FRONT RIM LH	Not Necessary	550.00 FS	*- FS
23	1		*SET FRONT TYRE LH	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,070.20	2,984.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,747.55	738.55
Total Parts (\$\$)	9,322.65	2,245.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,600.00	400.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,400.00	400.00
3	TO REMOVE ,REFIX WIRING SYSTEM AT ACCIDENT DAMAGE AREAS AND CHECK FOR PROPER FUNCTION	New	150.00	30.00
4	TO REMOVE AND REPLACE REVERSE SESORS AD TEST FOR PROPER FUNCTION	New	100.00	0.00
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	270.00	0.00
6	TO REMOVE AND REPLACE UNDERCARRIAGE PART	New	250.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT TEST	New	150.00	0.00
Gross Labour Cost (S\$)			3,920.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >