

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III19007998/K1PA3Q2
Date: 25/08/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SHC6670R	Insured Vehicle No :	SHA3921Y
Date of Loss:	05/05/2019	Nature of Claim:	TP
		Claim No:	MCT19050112

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6670R	Engine No:	D4FDEH313306
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5588168
Reg. Date:	09/03/2015 (Man. Year: 2014)	Odometer:	442323 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Achilles 7 mm	Rear Left Side:	Achilles 7 mm
Front Right Side:	Achilles 7 mm	Rear Right Side:	Achilles 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,122.40	3,068.50	1,053.90	25.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	990.00	890.00	47.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,002.40	4,058.50	1,943.90	32.39
Approved Total (Overridden) (S\$)		3,200.00		

(S\$)	6,002.40	3,200.00	2,802.40	46.69
+ GST 7.00/7.00% (S\$)	420.17	224.00	196.17	46.69
Nett Amount (S\$)	6,422.57	3,424.00	2,998.57	46.69
+ Loss of Use (3.0 x S\$40.00/day) (S\$)		120.00		
+ Car Rental (3.0 x S\$104.67/day) (S\$)		314.01		
(S\$)		3,858.01		
Liabe Amount (50.00%) (S\$)		1,929.01		
Global Sum Settlement (S\$)		1,900.00		

INSPECTION

Date of Assignment: 06/05/2019

Date Inspected: 06/05/2019

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Aug 2021)
Parts:	143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC6670R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S HEAD LAMP	Cracked	1,028.00 FL	*1,028.00 FL
2	1		*SUPPORT PANEL	Repair	645.00 FL	*- FL
3	1		*AIR DUCT	Cracked	210.00 FL	*210.00 FL
4	1		*FRONT BUMPER	Dented	531.00 FL	*531.00 FL
5	1		*FRONT BUMPER EMBLEM	Necessary	44.00 FL	*44.00 FL
6	1		*FRONT BUMPER SPONGE	Serviceable	116.00 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Serviceable	328.00 FL	*- FL
8	2		*FRONT BUMPER N/S & O/S SIDE RETAINER	Serviceable	32.00 FL	*- FL
9	1		*FRONT BUMPER N/S PROTECTOR	Necessary	51.00 FL	*51.00 FL
10	1		*FRONT BUMPER N/S FOG LAMP COVER	Cracked	66.00 FL	*66.00 FL
11	1		*BONNET	Bent	979.00 FL	*979.00 FL
12	1		*BONNET GRILLE	Cut	386.00 FL	*386.00 FL
13	1		*SET FRONT BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
14	1		*FRONT NO.PLATE	Necessary	50.00 FS	*35.00 FS
15	1		*SUNDRY	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,564.00	3,398.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	441.60	329.50
Total Parts (\$\$)	4,122.40	3,068.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TOP UP AIRCON GAS	New	80.00	0.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE SAME ,ETC	New	900.00	400.00
4	TO PUTTY AND SPRAY PAINTING ON BONNET ,FRONT BUMPER ,FRONT N/S FENDER	New	600.00	540.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	50.00
Gross Labour Cost (S\$)			1,880.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >