



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 6019T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (CONSISTENT)	TORN	900.00	566.10
1	LH REAR DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	690.00	-
1	LH REAR FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	741.60	-
	LESS 25% DISCOUNT		-	-141.53
			2,331.60	424.57
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	40.00	40.00
			40.00	40.00
	<u>LABOUR</u>			
	PANEL KNOCKING ON LH DOOR REAR ,FENDER ARC & DOOR ARC.INCLUSIVE OF THE REPAIR OF LH REAR DOOR AND LH REAR FENDER .		800.00	600.00
	SPRAY PAINTING ON ALL AFFECTED PARTS (DOOR ,FENDER ,DOOR ARC).		800.00	700.00
			1,600.00	1,300.00
	GRAND TOTAL		3,971.60	1,764.57
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,400.00

Report Ref No. CC4/ASM19008034/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.