

ASS. REC. BY:

REF: CS/PCI19008083/K1td3n2

Special Instructions:

Surveyor: KJLW

ASSIGNMENT (Office)

CWS

From (Person): Serine

of FCI

Date/Time: 8.5.19 1.16p.m

Estimated Cost:

Bill to:

OD/PT/WS/TPRES/ODRES/EVA/INV/MV/CS

To Inspect Vehicle No: SHC 6381A

Insured: SHC 8589E

at Workshop m/s Premier Automotive

Tel: 62148880

of 23 Changi South Avenue 2 #01-02

Policy No:

Claim No: D19002998MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 3.5.2019

CA / REV / REP. / REV 24 HRS

rup?

H.O.D. Endorsement:

Date/Time: 8.5.19 1.20p.m

Person Contacted:

Vehicle (IN) OUT

Date/Time	Action/Instruction	Estimated (✓)
	SHC 6381A - CS/PCI18021720/K1td3n2	D.O.A - 30/11/2018
	SHC 8589E - CS/PCI17018069/T11bn2	D.O.A - 17/09/2017
9/5@10.15am	Revised preli advise via email.	

Surveyor: Kalvin

REF: _____

ASSIGNMENT

From _____ Date: _____

Estimated cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/INV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vch: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IOAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 6381A Yr Regn: 6 Feb 2019Type: M.Car / M.Cycle / Bus / Van / Lorry / 6 / Prime Mover /

Truck / Trailer or

Make: KIA optima cc 1680Colour: Silver A/C: In 6 / Std / NI / NASp. Reading: 411 x 50 T/Radio: Insud / Std / NI / NA

Eng/No: _____

C/No: KN AHM 414 MF 5578017Gen. Cond: Good / 6 / Poor / BurntSteering: Inord / 6 / Jammed / Leaked / Burnt or AbuseBrake: Inord / 6 / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD 6 / orTyre Size: F: 205 / 65 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front: _____ Rear: _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 3/5/19 D.O.I. 8/5/19Survey held at Premier

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
11/6/19	Letter up \$ 6400 / 5 Pages. (Ref: 6583.52, 5070) FCZ

RECEIVED 11 JUN 2019

Date/Time, File Pass to?

1) 11/6 Typist

Date/Time, File Return to?

2) _____

Signature (Surveyor)

Signature (Client)

☐ : Prel. Report☒ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Insp (\$ _____)☐ : Media (\$ _____)

Survey Fee:

Transportation:

Phone:

Other:

TOTAL

3x16 = 48

120+48

50

60

40

345

TP

6400

Your Ref: D19002998MFSH

Date: 9/5/2019

Our Ref: CS/FCI19008083/K1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6381A

Please be informed that we had conducted the inspection of the abovementioned vehicle 08/05/2019 at the premises of M/s Premier Auto have the following to report: -

Workshop Estimate Amount	: S\$ <u>12,983.52</u>
Revised Estimate Amount	: S\$ <u>7,120.01</u>
"Check" Items Amount	: S\$ <u>178.20</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the
o/s front portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kalvin

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	07-05-2019	Our Ref No. D19002998MFSH
Accident Date	03-05-2019	Claim Type. Third Party
Insured Vehicle	SHC8589E	Third Party Vehicle. SHC6381A
Survey Location	23 CHANGI SOUTH AVENUE 2 #01-02	
Contact Person.	LIEW HAI LEONG	
Contact No.	62148880/ 0	Fax No. 65446682
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 9 May 2019 10:15 AM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments; SUR
Cc: 'Serene Ler'
Subject: RE: SURVEY ASSESSMENT - D19002998MFSH/1
Attachments: PRELI ADVISED SHC 6381A-1.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHC 6381A**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 8 May 2019 1:31 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19002998MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 8 May, 2019 1:16 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002998MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	06 Feb 2015 / 09:21:33	Receipt No.:	AACCK001-AX239-150206-000008
Asset Type:	Vehicle	Transaction Amount:	\$66,712.00
Asset ID:	SHC6381A	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150206092133373825		

Vehicle No.:	SHC6381A
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	06 Feb 2015
Original Registration Date:	06 Feb 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5578017

Engine No.:	D4FDEH313286
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-

Manufacturing Year:	2014
Open Market Value:	\$20,834.00
Minimum PARF Benefit:	\$8,200.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	06 Feb 2015 09:21:33
COE No.:	2015020601001516Z
COE Expiry Date:	05 Feb 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$52,904.00
Lifespan Expiry Date:	05 Feb 2023

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

7-May-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6381 A

1 pc	Front o/s head lamp	✓ m	\$ 1,028.00
1 pc	Bonnet grille	X su	\$ 385.00
1 pc	Front bumper	✓ m	\$ 531.00
1 pc	Front bumper emblem	✓ m	\$ 44.00
1 pc	o/s rocker panel garnish	X su	\$ 286.00
1 pc	Bonnet	✓ RALU	\$ 979.00
1 pc	Engine under cover- o/s	✓ m	\$ 174.00
1 pc	Front bumper o/s protector	✓ m	\$ 51.00
1 pc	Front bumper o/s fog lamp cover	✓ m	\$ 66.00
1 pc	Support panel	✓ Bad	\$ 645.00
1 pc	Front bumper lower stiffer	✓ Bad	\$ 134.00
1 pc	Front o/s fender inner shield	✓ m	\$ 120.00
1 pc	Front bumper lip	✓ m	\$ 52.00
1 pc	Front bumper inner sponge	X m	\$ 110.00
1 pc	Front bumper reinforcement	X su	\$ 328.00
1 pc	Washer tank	✓ m	\$ 47.00
1 pc	Washer tank motor	✓ m	\$ 48.00
1 pc	Front o/s lower arm	✓ Bad	\$ 439.00
1 pc	Front o/s shock absorber	✓ Bad	\$ 330.00
1 pc	Front o/s ball joint	✓ Bad	\$ 59.00
1 pc	Front o/s driveshaft	✓ Bad	\$ 971.00
1 pc	Front insulator strut	X m	\$ 105.00
1 pc	Front strut bearing	X m	\$ 34.00
1 pc	Steering rack and pinion	X su	\$ 866.00
1 pc	Front crossmember	X su	\$ 789.00
1 pc	Front o/s fender	✓ RALU	\$ 514.02
1 pc	Front o/s door	X RALU	\$ 791.00
1 pc	Wheel cover	X su	\$ 116.00
1 pc	Front bumper o/s side retainer	✓ m	\$ 16.00
1 pc	Front bumper o/s upper bracket	✓ m	\$ 16.00
1 pc	Front bumper o/s support bracket	✓ m	\$ 16.00
1 pc	Rear o/s door	X su	\$ 765.00
			\$ 10,855.02
Less 10%			\$ 1,085.50
			\$ 9,769.52

7-May-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6381 A

S/NETT

1 pc	Front bumper clips	✓	\$ 48.00
1 pc	Front o/s fender sticker	X	\$ 30.00
1 set	Front o/s fender inner shield clips	✓	\$ 28.00
1 set	o/s rocker panel garnish clips	X	\$ 38.00
1 set	o/s door stickers	✓	\$ 100.00
	To check front o/s wheel alignment	✓	\$ 60.00
	To dismantle / refit front o/s wheel undercarriage	✓	\$ 250.00 150
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the support panel, etc.		\$ 1,200.00 800
	To putty and spray painting on front bumper, front o/s fender, bonnet, front o/s door, grille front, rear o/s door, o/s rocker panel garnish	X	\$ 1,400.00 1080
	To apply rustproofing on the repaired and replaced panels.		\$ 300.00 30
			<u>\$ 12,983.52</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

13060.92

16/05/19

8/5/19 1535hrs

5 Days

4/5

After Repair



PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

7-May-19

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6381 A

1 pc	Front o/s stabilizer link	✓ <i>84</i>	\$	86.00
		Less 10%	\$	8.60
			\$	<u>77.40</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19008083/K1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 21-06-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8589E	Veh. Inspected	SHC 6381A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002998MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	08/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5578017	Colour	SILVER	
Odometer	411450	Steering	AFFECTED	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/05/2019	Inspection Date	08/05/2019	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6381A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT O/S HEAD LAMP	CRACKED	1,028.00	1,028.00
1	BONNET GRILLE	SERVICEABLE	385.00	-
1	FRONT BUMPER	CRACKED	531.00	531.00
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	O/S ROCKER PANEL GARNISH	SERVICEABLE	286.00	-
1	BONNET	BUCKLED	979.00	979.00
1	ENGINE UNDER COVER-O/S	CRACKED	174.00	174.00
1	FRONT BUMPER O/S PROTECTOR	CRACKED	51.00	51.00
1	FRONT BUMPER O/S FOG LAMP COVER	CRACKED	66.00	66.00
1	SUPPORT PANEL	BENT	645.00	645.00
1	FRONT BUMPER LOWER STIFFER	BENT	134.00	134.00
1	FRONT O/S FENDER INNER SHIELD	TORN	120.00	120.00
1	FRONT BUMPER LIP	CRACKED	52.00	52.00
1	FRONT BUMPER INNER SPONGE	SERVICEABLE	110.00	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	328.00	-
1	WASHER TANK	CRACKED	47.00	47.00
1	WASHER TANK MOTOR	CRACKED	48.00	48.00
1	FRONT O/S LOWER ARM	BENT	439.00	439.00
1	FRONT O/S SHOCK ABSORBER	BENT	330.00	330.00
1	FRONT O/S BALL JOINT	BENT	59.00	59.00
1	FRONT O/S DRIVESHAFT	BENT	971.00	971.00
1	FRONT INSULATOR STRUT	SERVICEABLE	105.00	-
1	FRONT STRUT BEARING	SERVICEABLE	34.00	-
1	STEERING RACK AND PINION	SERVICEABLE	866.00	-
1	FRONT CROSSMEMBER	SERVICEABLE	789.00	-
1	FRONT O/S FENDER	BUCKLED	514.02	514.02
1	FRONT O/S DOOR	TO REPAIR SEE LABOUR	791.00	-
1	WHEEL COVER	SERVICEABLE	116.00	-
1	FRONT BUMPER O/S SIDE RETAINER	CRACKED	16.00	16.00
1	FRONT BUMPER O/S UPPER BRACKET	CRACKED	16.00	16.00

Report Ref No. CS/FCI19008083/K1td3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER O/S SUPPER BRACKET	CRACKED	16.00	16.00
1	REAR O/S DOOR	SERVICEABLE	765.00	-
1	FRONT O/S STABILIZER LINK (ADDITIONAL)	BENT	86.00	86.00
	LESS 10% DISCOUNT		-1,094.10	-636.60
			9,846.92	5,729.42
	SPECIAL NETT ITEMS			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	FRONT O/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SET FRONT O/S FENDER INNER SHIELD CLIPS (SN)	NECESSARY	28.00	28.00
1	SET O/S ROCKER PANEL GARNISH CLIPS (SN)	NOT NECESSARY	38.00	-
1	SET O/S DOOR STICKERS (SN)	NECESSARY	100.00	100.00
			244.00	176.00
	LABOUR			
	TO CHECK FRONT O/S WHEEL ALIGNMENT.		60.00	60.00
	TO DISMANTLE/REFIT FRONT O/S WHEEL UNDERCARRIAGE.		250.00	150.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE SUPPORT PANEL,ETC.INCLUSIVE OF THE REPAIR OF FRONT O/S DOOR.		1,200.00	800.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER,FRONT O/S FENDER,BONNET,FRONT O/S DOOR,GRILLE FRONT,REAR O/S DOOR,O/S ROCKER PANEL GARNISH.		1,400.00	1,080.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		60.00	30.00
			2,970.00	2,120.00
	GRAND TOTAL		13,060.92	8,025.42
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,400.00

Report Ref No. CS/FCI19008083/K1td3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.