

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



471

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224

Email: Winsongkk@hotmail.com Contact: 9747 0063


Company Register No. 53326249J

Our Ref: WG/TP/2019-01
Invoice No: TP/PLATINUM/2019-01
Vehicle No: SGP3409T
Attn: MUHAMMAD ERMAN BIN JOHARI
Company: PLATINUM WERKZ PTE LTD
Address: 53 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK,
SINGAPORE 408934

Date 03 January 2019

Invoice

Surveyor Fee:	S\$260
Re-inspection Fee:	S\$50
Transport:	S\$50
Photographs:	S\$44/- (@ \$1 per photo, total 44 photos)
Total:	S\$404

Surveyor: Winson Goh
Signature: 
Date: 03 January 2019



WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224

Email: winsongkk@hotmail.com Contact: 9747 0063

Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : MUHAMMAD ERMAN BIN JOHARI
C/O PLATINUM WERKZ PTE LTD
53, UBI AVENUE 1, #01-25, PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934

Date : 03 January 2019
Our Ref : WG/TP/2019-01

REFERENCE PARTICULARS

Date of Accident : 03 December 2018
Date of Inspection : 04 December 2018

Type of Inspection : Third Party Claim
Date of Re-Inspn : 11 December 2018

VEHICLE PARTICULARS

Registration No : SGP3409T
Make : TOYOTA
Model : WISH 1.8 A
Year : 2006

Engine No : 1ZZ2694945
Chassis No : ZNE100326032
Odometer : 273877km
Colour : Blue

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size
Front Near side	Pirelli	215/45ZR17
Front Off Side	Pirelli	215/45ZR17
Rear Near Side	Pirelli	215/45ZR17
Rear off Side	Pirelli	215/45ZR17

Thread Balance
5 mm
5 mm
5 mm
5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the rear portion.
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$5,000.00** nett at lump sum basis. (Subject to GST if applicable)
Under normal circumstances, estimated period required for repairs : Five (05) working days.

Enclosed Forty-four (44) photographs depicting damage to the vehicle.

Inspection conducted at : PLATINUM WERKZ PTE LTD
53 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408934

In accordance to your instruction, we have **not** authorise repairs and inspection was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

VEHICLE NO : SGP3409T
MODEL : WISH 1.8 A

Our Ref : WG/TP/2019-01

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

SPARE PARTS	QTY PC/SET	ASSESSED CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
1 TAILGATE	1	DENTED	\$ 1,210.15	\$ 1,210.15
2 TAILGATE GLASS	1	SHATTERED	\$ 1,163.00	\$ 1,163.00
3 TAILGATE GLASS MOULDING ASSY	1	NECESSARY	\$ 220.00	\$ 220.00
4 TAILGATE RH SIDE GARNISH	1	GRAZED	\$ 115.00	\$ 115.00
5 TAILGATE LOCK	1	JAMMED	\$ 443.00	\$ 443.00
6 TAILGATE LOCK STRIKER	1	NOT NECESSARY	\$ 45.00	\$ -
7 TAILGATE EMBLEM LOGO	1	NECESSARY	\$ 61.00	\$ 61.00
8 TAILGATE WEATHERSTRIP	1	TORN	\$ 329.10	\$ 329.10
9 REAR RH TAILLAMP	1	CRACKED	\$ 485.10	\$ 485.10
10 TAILGATE INNER TRIM	1	CRACKED	\$ 312.00	\$ 312.00
11 REAR BUMPER	1	CRACKED	\$ 511.20	\$ 511.20
12 REAR BUMPER RETAINER	2	NECESSARY	\$ 157.30	\$ 157.30
13 REAR LH TAILGATE ABSORBER	1	JAMMED	\$ 283.20	\$ 283.20
			\$ 5,335.05	\$ 4,830.05
		Less 25%	\$ 1,333.76	\$ 1,207.51
			\$ 4,001.29	\$ 3,622.54
B) S/NETT ITEM				
14 REAR BUMPER CLIP	1 SET	NECESSARY	\$ 50.00	\$ 40.00
15 REAR REVERSE SENSOR	1 SET	NOT NECESSARY	\$ 400.00	\$ -
16 TAILGATE INNER TRIM CLIP	1 SET	NECESSARY	\$ 30.00	\$ 20.00
17 JOINT SEALANT	1	NECESSARY	\$ 150.00	\$ 130.00
18 WINDSCREEN SEALANT	1	NECESSARY	\$ 150.00	\$ 130.00
			\$ 780.00	\$ 320.00
		Parts Total :	\$ 4,781.29	\$ 3,942.54
C) LABOUR CHARGES & MISC				
19 CHECK REAR WIRING AND LIGHTNING SYSTEM			\$ 70.00	\$ 00.00
20 REMOVE AND RENEW REAR REVERSE SENSOR			\$ 150.00	\$ 130.00
21 REMOVE AND RENEW REAR WINDSCREEN			\$ 150.00	\$ 130.00
22 TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO ATTACHMENT			\$ 200.00	\$ 180.00
23 PANEL BEATING ON AFFECTED AREAS			\$ 600.00	\$ 500.00
24 SPRAY PAINTING ON AFFECTED AREAS			\$ 700.00	\$ 600.00
25 APPLY ANTI RUST ON AFFECTED AREAS			\$ 100.00	\$ 00.00
		Labour Total :	\$ 1,970.00	\$ 1,680.00
		Total Parts and Laboure :	\$ 6,751.29	\$ 5,622.54
FINAL LUMP SUM ADJUSTMENT				\$ 5,000.00

L/s \$3200/- 4 days

POINT OF IMPACT

The impact was confined to the rear portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **S\$5,000.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully
WG APPRAISAL SERVICES



Winson Goh
Automotive Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Dec 2018		10 Dec 2018 14:43 Edit Adj Rpt	S\$3,450.00 Edit Estimates	S\$3,450.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TRACTORS SINGAPORE LTD , Co. Reg. No.: 196600025H		
Main Claimant:	MUHAMMAD ERMAN BIN JOHARI , ID: S1323229F		
Vehicle Reg. No.:	SGP3409T	Date of Loss:	03/12/2018 17:00 - :59 [143 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 578235	Policy/Cover Note No.:	B29040188MKF (Comprehensive) Coverage: 01/10/2017 - 30/09/2019
Vehicle Reg. No. (Insured):	YN1702G	Policy No. (Claimant):	
		Excess:	
Repairer:	Platinum Werkz Pte Ltd (HQ) 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park, 408934 Ubi - Tel: 6741 610		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 08/05/2019]		
Driver/Custodian (Insured):	TAN CHOON PENG (), NRIC: S6932208E, Tel: +6593394316 Email:		
Adj Asg. Remarks:	Liability 100%. SJE DISAGREE LKK. Contact person: Dora 88261413		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (06/05/2019): Report Send Back Alerts - SGP3409T (TP)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGP3409T (578235)**
[YN1702G]

TP
MUHAMMAD ERMAN BIN JOHARI
Dec 3 2018 5:00PM
[TRACTORS SINGAPORE LTD]
Platinum Werkz Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser

Assessment Reports

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/12/18 17:52	Accident Statement From: SC - Reg. No: YN1702G, Claimant: TRACTORS SINGAPORE LTD	 Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/12/18 14:39	General View	 Load JPG	☒
2	11/12/18 14:39	General View	 Load JPG	☒
3	11/12/18 14:39	General View	 Load JPG	☒
4	11/12/18 14:39	General View	 Load JPG	☒
5	11/12/18 14:39	General View	 Load JPG	☒
6	11/12/18 14:39	General View	 Load JPG	☒
7	11/12/18 14:39	General View	 Load JPG	☒
8	11/12/18 14:39	General View	 Load JPG	☒
9	11/12/18 14:39	General View	 Load JPG	☒
10	11/12/18 14:39	General View	 Load JPG	☒
11	11/12/18 14:39	General View	 Load JPG	☒
12	11/12/18 14:39	General View	 Load JPG	☒
13	11/12/18 14:39	General View	 Load JPG	☒
14	11/12/18 14:39	General View	 Load JPG	☒
15	11/12/18 14:39	General View	 Load JPG	☒
16	11/12/18 14:39	General View	 Load JPG	☒
17	11/12/18 14:39	General View	 Load JPG	☒
18	11/12/18 14:39	General View	 Load JPG	☒
19	11/12/18 14:39	General View	 Load JPG	☒
20	12/12/18 09:48	Dismantled Parts	 Load JPG	☒
21	12/12/18 09:48	Dismantled Parts	 Load JPG	☒
22	12/12/18 09:48	Dismantled Parts	 Load JPG	☒
23	12/12/18 09:48	Dismantled Parts	 Load JPG	☒
24	12/12/18 09:48	Dismantled Parts	 Load JPG	☒
25	12/12/18 09:48	Dismantled Parts	 Load JPG	☒
26	12/12/18 09:48	Dismantled Parts	 Load JPG	☒
27	12/12/18 09:48	Dismantled Parts	 Load JPG	☒
28	12/12/18 09:48	Dismantled Parts	 Load JPG	☒
29	12/12/18 09:48	Dismantled Parts	 Load JPG	☒
30	12/12/18 09:48	Dismantled Parts	 Load JPG	☒
31	12/12/18 09:48	Dismantled Parts	 Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	12/12/18 09:48	Dismantled Parts	 Load JPG	✓
33	12/12/18 09:48	Dismantled Parts	 Load JPG	✓
34	12/12/18 09:48	Dismantled Parts	 Load JPG	✓
35	12/12/18 09:48	Dismantled Parts	 Load JPG	✓
36	12/12/18 09:48	Dismantled Parts	 Load JPG	✓
37	12/12/18 09:48	Dismantled Parts	 Load JPG	✓
38	17/12/18 10:32	Photo After Spray	 Load JPG	✓
39	17/12/18 10:32	Photo After Spray	 Load JPG	✓
40	17/12/18 10:32	Photo After Spray	 Load JPG	✓
41	17/12/18 10:32	Photo After Spray	 Load JPG	✓
42	17/12/18 10:32	Photo After Spray	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/12/18 17:52	PRI From: SC - Reg. No: YN1702G, Claimant: TRACTORS SINGAPORE LTD	 Load PDF	
2	07/12/18 17:52	TP SGP3409T E-REPORT From: SC - Reg. No: YN1702G, Claimant: TRACTORS SINGAPORE LTD	 Load PDF	
3	10/12/18 10:05	SJE DISAGREE LKK	 Load PDF	
4	10/12/18 10:29	workshop details	 Load PDF	
5	06/05/19 16:16	SGP3409T survey report	 Load PDF	
6	06/05/19 16:16	SGP3409T photos	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/05/19 12:08	PRS INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18022162/JVD3S2-1
Date: 22/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B29040188MKF
 Claimant Vehicle No : SGP3409T Insured Vehicle No : YN1702G
 Date of Loss: 03/12/2018 Nature of Claim: TP Claim No: 578235

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGP3409T**
 Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ2694945
 Reg. Date: 13/12/2006 (Man. Year: 2006) Chassis No: ZNE100326032
 Colour: Blue Odometer: 273896 km
 Engine Capacity: 1794 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R17 Rear Tyre Size: 215/45R17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,781.29	3,224.04	1,557.25	32.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,970.00	1,110.00	860.00	43.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,751.29	4,334.04	2,417.25	35.80
Approved Total (Overridden) (S\$)		3,450.00		
Nett Amount (S\$)	6,751.29	3,450.00	3,301.29	48.90

INSPECTION

Date of Assignment: 10/12/2018
 Date Inspected: 11/12/2018 Inspected At: Platinum Werkz Pte Ltd (HQ)
 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park
 Singapore 408934
 Estimated Period of Repair: 4.0 days

Adjuster: ONG HWEE JIE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGP3409T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,210.15 FL	*1,070.00 FL
2	1		*TAILGATE GLASS	Cracked	1,163.00 FL	*970.00 FL
3	1		*TAILGATE GLASS MOULDING ASSY	Necessary	220.00 FL	*220.00 FL
4	1		*TAILGATE RH SIDE GARNISH	Cracked	115.00 FL	*115.00 FL
5	1		*TAILGATE LOCK	Serviceable	443.00 FL	*- FL
6	1		*TAILGATE LOCK STRIKER	Not Necessary	45.00 FL	*- FL
7	1		*TAILGATE EMBLEM LOGO	Necessary	61.00 FL	*61.00 FL
8	1		*TAILGATE WEATHERSTRIP	Cut	329.10 FL	*329.10 FL
9	1		*REAR RH TAILLAMP	Cracked	485.10 FL	*485.10 FL
10	1		*TAILGATE INNER TRIM	Cracked	312.00 FL	*312.00 FL
11	1		*REAR BUMPER	Deformed	511.20 FL	*511.20 FL
12	1		*REAR BUMPER RETAINER	O/s Cracked	157.30 FL	*78.65 FL
13	1		*REAR RH TAILGATE ABSORBER	Not Necessary	283.20 FL	*- FL
14	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
15	1		*SET REAR REVERSE SENSOR	Not Necessary	400.00 FS	*- FS
16	1		*SET TAILGATE INNER TRIM CLIP	Necessary	30.00 FS	*20.00 FS
17	1		*JOINT SEALANT	Not Necessary	150.00 FS	*- FS
18	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,115.05	4,262.05
- List Item Discount on L Items 25.00/25.00% (S\$)	1,333.76	1,038.01
Total Parts (S\$)	4,781.29	3,224.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM.	New	70.00	30.00
2	REMOVE AND RENEW REAR REVERSE SENSOR.	New	150.00	0.00
3	REMOVE AND RENEW REAR WINDSCREEN.	New	150.00	100.00
4	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO ATTACHMENT.	New	200.00	50.00
5	PANEL BEATING ON AFFECTED AREAS.	New	600.00	400.00
6	SPRAY PAINTING ON AFFECTED AREAS.	New	700.00	500.00
7	APPLY ANTI RUST ON AFFECTED AREAS.	New	100.00	30.00
Gross Labour Cost (S\$)			1,970.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >