

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19005497/R1VD3E2-1
Date: 16/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: A80405609QMY
Claimant Vehicle No : SKG6198G	Insured Vehicle No : SGV4578A
Date of Loss: 20/01/2019	Nature of Claim: TP Claim No: 583165

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG6198G		
Make & Model:	VOLVO S80, 3.2 (A)	Engine No:	B4164T4121329
Reg. Date:	25/09/2012 (Man. Year: 2012)	Chassis No:	YV1AS48HBD1165724
Colour:	Grey	Odometer:	184650 km
Engine Capacity:	1596 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50Z R17	Rear Tyre Size:	225/50Z R17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,901.70	1,569.33	1,332.37	45.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	800.00	600.00	42.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,301.70	2,369.33	1,932.37	44.92
Approved Total (Overridden) (S\$)		1,900.00		
Nett Amount (S\$)	4,301.70	1,900.00	2,401.70	55.83

INSPECTION

Date of Assignment:	27/03/2019	
Date Inspected:	28/03/2019	Inspected At: Hong San Hong Wei Pte Ltd (HQ) Blk 1002 Bukit Merah Lane 3 #01-85 Singapore 159719
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 May 2019)

Parts: 143 VOLVO S80 3.2 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKG6198G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Badly Dented	1,254.00 F	*1,254.00 FL
2	1		*REAR BUMPER BRACKET N/S	Bent	85.70 F	*85.70 FL
3	10		*REAR BUMPER CLIP	Necessary	50.00 F	*50.00 FL
4	2		*REAR BUMPER SENSOR	Serviceable	308.00 F	*- FL
5	1		*N/S TAILLAMP	Cracked	354.00 F	*354.00 FL
6	1		*REAR BUMPER LOWER SPOILER	Repair	850.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,901.70	1,743.70
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	174.37
Total Parts (S\$)	2,901.70	1,569.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE THE NECESSARY AFFECTED PARTS, STRAIGHTEN REAR PANEL AND REPLACE PARTS	New	600.00	300.00
2	PUTTY AND SPRAYPAINT (INCLUDE REAR BUMPER AND SPOILER)	New	600.00	400.00
3	CHECK ELECTRICAL	New	50.00	40.00
4	REMOVE AND REFIT REAR BUMPER SENSORS	New	100.00	60.00
5	REWIRE REAR PORTION	New	50.00	0.00
Gross Labour Cost (S\$)			1,400.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >