



Case Details

Case Reference Number :

TAX/05/19/2033

Type of Repair : Accident Repair

Vehicle Registration Number :

SHD6323M

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-6805-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : AXA Insurance Singapore Pte Ltd

Accident Date and Time : 06/05/2019 10:05 AM

Vehicle Age(In Months) : 18

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0	Repair ▾	
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Not Give ▾	nn
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace ▾	DEF
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾	REC

One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give ▾	
Total Spare Part Cost									1,275.74	Surveyor Total				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				
Final Spare Part Cost									1,275.74	Final Sur Total				
										538.72				
										0				
										538.72				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	338.00	200	
Total:			338.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
Total:			558.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
2	Main	TO WASH AND VACUUM	60.00	0	
3	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			280.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,275.74	538.72
Total Labour Cost	338.00	200.00
Total Spray Painting	558.00	200.00
Other	280.00	0.00
Overall Total	2,451.74	938.72
Lump Sum Repair Option		
Lump Sum Total	0.00	938.72
Surveyor Approved Amount		938.72
No of Repair Days*	3	2
Remarks	-	p/p repair, photo before paint

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Surveyor Name		Hwee jie
Signature		
		Save Clear
Survey Date	08/05/2019	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: