

REPAIR ESTIMATE*

VEHICLE NO : SHA 3077J

DATE 7/5/2019 11:49

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>X repair</i>			\$ 544.50
	Front Bumper Bracket Top (RH) <i>X</i>			\$ 22.40
	Front Bumper Bracket (RH) <i>X</i>			\$ 24.60
	Front Door Mirror Assy (RH) <i>-</i>			\$ 670.00
	Front Wheel Hub Cap (RH) <i>-</i>			\$ 107.10
	<i>Front fender (RH) X repair</i>			
	SUB TOTAL			\$ 1,368.60
	LESS 20%			\$ 273.72
	DISCOUNTED TOTAL			\$ 1,094.88
	Front Fender Advertisement Logo (RH) <i>-</i>			\$ 100.00
	Labour Charge			<i>200</i>
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 700.00 <i>450</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>X</i>
	FRT Wheel Alignment			\$ 80.00 <i>X</i>
	TOTAL LABOUR			\$ 1,280.00
	ESTIMATE TOTAL			\$ 2,474.88
	<i>Kaluh (CKK)</i>			
	<i>7/5/19 1220 hrs</i>			
	<i>2 hrs</i>			
	<i>4/5</i>			
	<i>After Repair photo</i>			
	<div><div>LKK Auto Consultants hence notify the Repairer of the following:</div><ul style="list-style-type: none">To remedy bearing the surveyor's feeTo display a large banner during surveyTo provide any other necessary informationTo provide any other necessary informationTo provide any other necessary information<div>Signature: _____</div><div>Date: _____</div></div>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				