

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 88H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER, REAR : FIBRE GLASS, FOR MB OC500 BUS	CRACKED	1,863.00	1,863.00
1	COVER, LAMP : REAR, LH, FOR MB OC500 BUS	CRACKED	1,242.00	1,242.00
1	PIPE, EXHAUST : REAR, FOR MB OC500 LE BUS	DEFORMED	6,230.40	6,230.40
	LESS 10% DISCOUNT		-	-933.54
			9,335.40	8,401.86
	<u>SPECIAL NETT ITEMS</u>			
1	ADVERTISEMENT STICKER (SN)	NECESSARY	1,440.00	1,440.00
1	SMRT LOGO (SN)	NECESSARY	75.00	75.00
			1,515.00	1,515.00
	<u>LABOUR</u>			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		2,120.00	1,590.00
	TO PUTTY & RESPRAY.		878.00	708.00
			2,998.00	2,298.00
GRAND TOTAL			13,848.40	12,214.86
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				9,750.00

Report Ref No. NS/INC19008134/Nvd3e2


MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor


K.K.LAU CPT(RET)
**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**
REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.