



V/C

Case Details

Case Reference Number : TAX/05/19/2031
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHD6332L

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-6804-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 07/05/2019 01:15 AM
 Vehicle Age(In Months) : 35

Documents / Photographs

View Documents / Photographs

Total Documents : 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Coating Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	DEF /
One Time Key In	Main			BUMPER CLIPS	1	1.61	1.61	25.00	1.21	Replace	1	1.21	Replace	rec /
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check	X N/A
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	0	0	Not Give	un X
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	BVC /
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	rec /
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	un X
One Time Key In	Main			FENDER LINER PAD, FR WHEEL. RH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	un X
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair	X R
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	un X
Total Spare Part Cost						3,800.64	Surveyor Total 1,074.75							
Lump Sum Discount (%)						0.00	Lump Sum Dis (%) 0							
Final Spare Part Cost						3,800.64	Final Sur Total 1,074.75							

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			CAP SUB-ASSY. WHEEL	1	174.10	174.10	25.00	130.57	Replace	1	130.57	Replace	SCR ✓
One Time Key In	Main			WHEEL HUB FRT	1	549.70	549.70	25.00	412.28	Replace	0	0	Not Give	nn X

Total Spare Part Cost 3,800.64

Surveyor Total 1,074.75

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 3,800.64

Final Sur Total 1,074.75

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION RH	507.00	400	
Total:			507.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
3	Main	TO RESPRAY RIM	180.00	50	
4	Main	RESPRAY WHEEL CAP	180.00	40	
Total:			1,116.00	490.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	AR
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	ARC
5	Main	TO WASH AND VACUUM	60.00	0	
Total:			580.00	50.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
6	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			580.00	50.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	3,800.64	1,074.75
Total Labour Cost	507.00	400.00
Total Spray Painting	1,116.00	490.00
Other	580.00	50.00
Overall Total	6,003.64	2,014.75
Lump Sum Repair Option		
Lump Sum Total	0.00	2,014.75
Surveyor Approved Amount		2,014.75
No of Repair Days*	4	3
Remarks	-	p/p repair, photo before paint.
Surveyor Name		Hwee Jie
Signature		

D

Save Clear

Survey Date

08/05/2019

LKK Auto Consultants hence notify the Repairer of the following:



- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details	
Registration Number	SHD6332L
Case Reference Number	TAX/05/19/2031
Registration Date	28/6/2018
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	KOH WEE TECK
Type of Accident	Head To Side
Accident Date and Time	7/5/2019 9:15 AM
Accident Reported Date and Time	7/5/2019 12:31 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101404
Special Instruction to ARC, If any	TP
Prepared Date and Time	7/5/2019 8:54 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Top View

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$400.00
Total Spray Cost	\$1,118.00	\$490.00
Total Spare Part Cost	\$3,800.64	\$1,074.77
Total Other Cost	\$580.00	\$50.00
TOTAL COST	\$6,003.64	\$2,014.77 (PIP)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Kim Ming Chin	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	07/05/2019 9:08 PM	08/05/2019 3:15 PM
Signature		
Remarks	p/p repair, photo before paint.	

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-1905-0430	Invoice Number	
Quotation Date	23.05.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION RH	\$507.00	\$400.00
Total Labour	\$507.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
RESPRAY WHEEL CAP	\$180.00	\$40.00
Total Spray Painting & Panel Beating	\$1,116.00	\$490.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$580.00	\$50.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace
		52161-18010	BUMPER CLIPS	1.00	\$1.61	25.00	\$1.21	Replace	Replace
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Check
		81130-47500	HEAD LAMP RH	0.00	\$945.20	0.00	\$0.00	Replace	Not Given
		53801-47050	FENDER FRT/RH	1.00	\$723.40	25.00	\$542.55	Replace	Replace
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace
		53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given
		53851-47040	FENDER LINER PAD, FR WHEEL RH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given
		42611-47140(Frt)	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
		42602-47060	CAP SUB-ASSY, WHEEL	1.00	\$174.10	25.00	\$130.58	Replace	Replace
		43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Not Given
Total					\$4,836.25		\$1,074.77		

1074.77
+ 400.00
+ 590.00
2019.77