

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19008211/T1PA3Q2

**Date:** 31/03/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994238

**Claimant**  
**Vehicle No :** FE6565A **Insured Vehicle No :** SJE496H

Date of Loss: 06/05/2019 Nature of Claim: TP Claim No: 5137135931SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FE6565A		
Make & Model:	YAMAHA RXZ135, 133cc (M)	Engine No:	55K002202
Reg. Date:	18/07/1986 (Man. Year: 1985)	Chassis No:	55K002202
Colour:	Red	Odometer:	17770 km
Engine Capacity:	133 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	2.75/18	Rear Tyre Size:	2.75/18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,871.00	4,190.40	680.60	13.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	690.00	460.00	230.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,561.00</b>	<b>4,650.40</b>	<b>910.60</b>	<b>16.37</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,561.00</b>	<b>3,700.00</b>	<b>1,861.00</b>	<b>33.47</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 10/05/2019

Date Inspected: 10/05/2019 Inspected At:

Pang Scooter Service (HQ)  
BLK 1006 BUKIT MERAH LANE 2  
#01-06  
Singapore 159762

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLIGHT	Cracked	165.00 F	*165.00 FL
2	1		*HEADLIGHT COVER	Missing	85.00 F	*85.00 FL
3	1		*HEADLIGHT STAY	Bent	110.00 F	*110.00 FL
4	1		*METER ASSY	Cracked	585.00 F	*585.00 FL
5	1		*HANDLE BAR	Bent	98.00 F	*98.00 FL
6	1		*HANDLE BAR CLAMP	Repair	215.00 F	*- FL
7	1		*UNDER BRACKET	Bent	265.00 F	*265.00 FL
8	1		*STEERING CON	Bent	110.00 F	*110.00 FL
9	2		*FORK INNER TUBE	Bent	350.00 F	*350.00 FL
10	2		*SIGNAL LIGHT	Cracked	120.00 F	*120.00 FL
11	1		*TAIL LIGHT ASSY	Cracked	230.00 F	*230.00 FL
12	1		*EXHAUST PIPE	Dented	480.00 F	*480.00 FL
13	1		*FRONT WHEEL RIM	Bent	385.00 F	*385.00 FL
14	1		*FRONT BRAKE DISK	Bent	185.00 F	*185.00 FL
15	2		*SIDE COVER	Cracked	180.00 F	*180.00 FL
16	1		*TAIL COVER	Cracked	98.00 F	*98.00 FL
17	1		*FUEL TANK	Dented	520.00 F	*520.00 FL
18	1		*REAR BOX	Distorted	285.00 F	*285.00 FL
19	1		*BOX BRACKET	Bent	180.00 F	*180.00 FL
20	1		*IU UNIT	Cut	165.00 F	*165.00 FL
21	1		*FORK OIL SEAL	Necessary	60.00 F	*60.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,871.00</b>	<b>4,656.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$)</b>	0.00	465.60
<b>Total Parts (\$)</b>	<b>4,871.00</b>	<b>4,190.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PRESS BODY	New	280.00	150.00
2	TRANSPORT	New	60.00	60.00
3	LABOUR	New	350.00	250.00
<b>Gross Labour Cost (S\$)</b>			<b>690.00</b>	<b>460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >