

12/01/2012

ASS. REC. BY:

REF: C1/TD19008246/PC

Special Instructions:

SURV/DY

ASSIGNMENT (Office)

From (Person): Kamaliah Kamle

at SPF

Date/Time: 29/4/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SHB 8760 G

Insured:

at Workshop m/s

Tel:

of

Policy No: MHASPFDE0000017235

Claim No: TP/IP/21525/2019

Sum Insured:

Excess:

D.O.A. 29/4/2019

Make of Veh:
(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	SHB 8760 G - X

45019
500f

- z) Case IAFP-IB-20190405 - Mechanical Inspection of Motorcycle, JST4219
(TP/IP/08411/2019)
- aa) Case IAFP-IB-20190405 - Mechanical Inspection of Mini Bus, PC3215Y
(TP/IP/08411/2019)

On 13 February 2019 at about 8.13 a.m., the mini bus, PC3215Y was travelling straight along BKE (Woodlands Checkpoint), 2.5 km on lane 2 of the 3 lanes road while the motorcycle (deceased) was travelling straight on lane 3 of the 3 lanes road, diagonally ahead of the mini bus. The mini bus then made a left lane changed from lane 2 to lane 3. While in the midst of switching lanes, the accused claimed to have felt an impact at the front left portion of his mini bus and moments later, he felt that he had run over something. The accused then stopped his mini bus and alighted from his mini bus to make a check. He realised that there was a person lying on the road and a motorcycle not far from him. Due to the collision, the Deceased sustained multiple injuries and was conveyed unconscious by an ambulance to the Ng Teng Fong General Hospital (NTFGH). However, on the same day at 9.09 a.m., the Deceased was pronounced dead by Dr Chong Cher Cheong in NTFGH.

Vehicle to be inspected: JST4219 (Deceased)
PC3215Y (Accused)

IO In-Charge: SIO Kamaliah

- bb) Case IAFP-IB-20190405 - Mechanical Inspection of Motor Taxi, SHB8760G
(TP/IP/21525/2019)

On 29 March 2019 at about 4.04 a.m., the driver of motor taxi; SHB8760G claimed that the engine suddenly revved up (speed increased) for no apparent reason which he had no control causing it to veer and collided onto a pillar of the pick-up/drop-off point of BLK 226 Serangoon Ave 2. As such, this vehicle has to undergo a thorough mechanical inspection by an external expert.

Vehicle to be inspected: SHB8760G (Potential Defendant)

IO In-Charge: DOC Tan Chin Yong

General Investigation
(Non-Fatal)