


Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



YSK AUTO WORKSHOP

1 KAKI BUKIT AVE 6 #01-71 AUTOBAY SINGAPORE 417883

UEN: 53311047E

Name : RAINBOW BUS SERVICES

Address : C/o No. 1 Kaki Bukit Ave 6
#01-71 AutoBay
Singapore 417883

Vehicle Model : TOYOTA HIACE

Date of Accident : 23.04.2018

Final Repair cost PC 8020J

Lump Sum Repair Costs

\$ 18,200.00

Enquire Vehicle & Owner Information (Vehicle No. SDP8885D As At 23 Apr 2018 / 21:00:00)

View From Search Results

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: YSK(V)

Click on the icon to download

Owner ID Type: Singapore NRIC
Owner ID: S0571629B
Owner Name: GOH LAY CHOO
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 301
Registered Street Name: JALAN BUKIT HO SWEE
Registered Unit No.: # 33 - 01
Registered Building Name: -
Registered Postal Code: 169568

Click on the icon to download

Vehicle No.: SDP8885D
Make Description/Model: B.M.W. / 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

Thank you



Fun Lynn has successfully logged out.

Your last login date and time was 24 Apr 2018, 13:16:48.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History:

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction
1	Vehicle	SDP8885D	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224

Email: Winsongkk@hotmail.com Contact: 9747 0063

Company Register No. 53326249J

Our Ref: WG/TP/2019-106
Invoice No: TP/YSK/2019-106
Vehicle No: PC8020J
Attn: RAINBOW BUS SERVICES
Company: YSK WORKSHOP
Address: No. 1 Kaki Bukit, Avenue 6, #01-49 Autobay, Singapore 417883

Date 25 March 2019

Invoice

Surveyor Fee:	S\$570
Re-inspection Fee:	S\$50
Transport:	S\$50
Photographs:	S\$82/- (@ \$1 per photo, total 82 photos)
Total:	S\$752

Surveyor:
Signature:
Date:

Winsong Goh

25 March 2019



WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : RAINBOW BUS SERVICES
C/O YSK AUTO WORKSHOP
No. 1 Kaki Bukit, Avenue 6, #01-49 Autobay
Singapore 417883

Date : 25 March 2019
Our Ref : WG/TP/2019-106

REFERENCE PARTICULARS

Date of Accident : 23 April 2018
Date of Inspection : 25 April 2018

Type of Inspection : Third Party Claim
Date of Re-Inspn : 30 April 2018

VEHICLE PARTICULARS

Registration No : PC8020J
Make : TOYOTA
Model : HIACE HOH ROOF COMMUTER TURBO AUTO
Year : 2013

Engine No : 1KD2361607
Chassis No : JTFST22P700018704
Odometer : 207451km
Colour : White

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size	Thread Balance
Front Near side	: Michelin	195R15C	5 mm
Front Off Side	: Michelin	195R15C	5 mm
Rear Near Side	: Michelin	195R15C	5 mm
Rear off Side	: Michelin	195R15C	5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the left side portion.
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$8,050.00** nett at lump sum basis. (Subject to GST if applicable)
Under normal circumstances, estimated period required for repairs : Ten (10) working days.

Enclosed Eighty-two (82) photographs depicting damage to the vehicle.

Inspection conducted at : YSK AUTO WORKSHOP
No. 1 Kaki Bukit, Avenue 6, #01-49 Autobay, Singapore 417883

In accordance to your instruction, we have **not** authorise repairs and inspection
was conducted strictly on a **"WITHOUT PREJUDICE BASIS"**.

VEHICLE NO : PC80203

MODEL : HIACE HOH ROOF COMMUTER TURBO AUTO

Our Ref : WG/TP/2019-106

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTSDESCRIPTION OF PARTS AND NATURE OF REPAIRS

SPARE PARTS	QTY PC/SET	ASSESSED CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
1 FRONT LH DOOR HINGE	2	NOT NECESSARY	\$ 200.40	\$ -
2 FRONT LH DOOR CHECKER	1	NOT NECESSARY	\$ 145.90	\$ -
3 FRONT LH DOOR GLASS CHANNEL	1	NECESSARY	\$ 298.80	\$ 298.80 XNN
4 FRONT LH DOOR REGULATOR	1	BENT	\$ 570.80	\$ 570.80 XNN
5 FRONT LH DOOR REGULATOR MOTOR	1	MALFUNCTION	\$ 709.80	\$ 709.80 XNN
6 FRONT LH DOOR WEATHERSTRIP	1	DEFORMED	\$ 310.00	\$ 310.00 XNN
7 FRONT LH DOOR INNER TRIM BOARD	1	CRACKED	\$ 890.50	\$ 890.50 XNN
8 FRONT LH DOOR LOCK ASSY	1	MALFUNCTION	\$ 599.80	\$ 599.80 XNN
9 FRONT LH DOOR PANEL	1	DENTED	\$ 1,904.50	\$ 1,904.50 XNN
10 REAR LH SLIDING DOOR	1	DENTED	\$ 3,319.30	\$ 3,319.30 1546
11 REAR LH SLIDING DOOR HINGE	1	BENT	\$ 50.40	\$ 50.40 789
12 REAR LH SLIDING DOOR INNER TRIM	1	CRACKED	\$ 858.90	\$ 858.90 1718
13 REAR LH SLIDING DOOR LOCK	1	MALFUNCTION	\$ 699.80	\$ 699.80 1718
14 REAR LH FENDER	1	DENTED	\$ 3,594.50	\$ 3,594.50 1718
15 REAR LH INNER FENDER PANEL	1	DENTED	\$ 1,521.30	\$ 1,521.30 1718
16 LH LOWER STEP PANEL	1	DENTED	\$ 2,031.50	\$ 2,031.50 1718
17 REAR LH SLIDING ROLLER GARNISH	1	BENT	\$ 219.40	\$ 219.40 1718
18 REAR LH LOWER PANEL GARNISH	1	DEFORMED	\$ 391.10	\$ 391.10 1718
19 REAR LH PILLER LOWER GARNISH	1	DEFORMED	\$ 151.93	\$ 151.93 1718
20 REAR LH DOOR WIRE HARNESS	1	MALFUNCTION	\$ 2,093.30	\$ 2,093.30 XNN
21 REAR LH WINDOW GLASS	1	SHATTERED	\$ 510.40	\$ 510.40 XNN
22 LH CORNER PANEL	1	DENTED	\$ 190.30	\$ 190.30 50(SN)
23 TYRE TRIM	1	GRAZED	\$ 240.90	\$ 240.90 50(SN)
24 LH SLIDING DOOR LOWER LOCK ASSY	1	MALFUNCTION	\$ 673.09	\$ 673.09 50(SN)
25 SLIDING DOOR HANDLE	1	JAMMED	\$ 139.40	\$ 139.40
			\$ 22,316.02	\$ 22,070.72
		Less 25%	\$ 5,579.00	\$ 5,517.68
			\$ 16,737.02	\$ 16,553.04
B) S/NETT ITEM				
26 FRONT LH DOOR INNER TRIM CLIP	1 SET	NECESSARY	\$ 40.00	\$ 30.00 1
27 REAR LH DOOR INNER TRIM CLIP	1 SET	NECESSARY	\$ 40.00	\$ 30.00 1
28 FLOOR PANEL LOWER BOARD	1	CRACKED	\$ 1,200.00	\$ 800.00 XNN
29 WINDSCREEN SEALANT	1	NECESSARY	\$ 150.00	\$ 130.00 40
30 JOINT SEALANT	1	NECESSARY	\$ 150.00	\$ 130.00 90
			\$ 1,580.00	\$ 1,120.00
		Parts Total :	\$ 18,317.02	\$ 17,673.04
C) LABOUR CHARGES & MISC				
31 CHECK WIRING AND LIGHTNING SYSTEM			\$ 70.00	\$ 60.00 30
32 REMOVE, REFIT LINING, TRIM AND GARNISH			\$ 200.00	\$ 180.00 60
33 REMOVE AND REPLACE LH QUARTER GLASS			\$ 150.00	\$ 120.00 80
34 TRANSFER PARTS, ATTACHMENT FROM FRONT LH DOOR TO NEW			\$ 200.00	\$ 180.00 XNN
35 TRANSFER PARTS, ATTACHMENT FROM LH SLIDING DOOR TO NEW			\$ 350.00	\$ 250.00 60
36 CHECK FRONT AND REAR WHEEL ALIGNMENT			\$ 200.00	\$ 180.00 60
37 PANEL BEATING ON AFFECTED AREAS			\$ 2,500.00	\$ 2,200.00 1400
38 SPRAY PAINTING ON AFFECTED AREAS			\$ 1,800.00	\$ 1,600.00 1200
39 APPLY ANTI RUST ON AFFECTED AREAS			\$ 200.00	\$ 180.00 120
40 TOWING SERVICE			\$ 150.00	\$ 120.00 XNN
		Labour Total :	\$ 5,820.00	\$ 5,070.00
		Total Parts and Labour :	\$ 24,137.02	\$ 22,743.04
FINAL LUMP SUM ADJUSTMENT				\$ 18,200.00

9/02.86
20% = 7300

9 days.

POINT OF IMPACT

The impact was confined to the left portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of \$18,200.00 nett corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully

WG APPRAISAL SERVICES

Winson Goh
Automotive Appraiser



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Apr 2018		25 Apr 2018 11:11 Edit Adj Rpt	S\$7,300.00 Edit Estimates	S\$7,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	GOH LAY CHOO, ID: S8804590D, Tel: +6597654726		
Main Claimant:	RAINBOW BUS SERVICES, Co. Reg. No.: 52835750J		
Vehicle Reg. No.:	PC8020J	Date of Loss:	23/04/2018 00:00 - :59 [50 Months and 30 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 556465	Policy/Cover Note No.:	27025168SMP (Comprehensive) Coverage: 20/12/2017 - 19/12/2018
Vehicle Reg. No. (Insured):	SDP8885D	Policy No. (Claimant):	
		Excess:	S\$750.00
Repairer:	Ysk Auto Workshop (HQ) No.1 Kaki Bukit Avenue 6, #01-71 Autobay, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 13/05/2019]		
Driver/Custodian (Insured):	CHUA PENG HWEE (), Tel: +6591725333 Email:		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- MSIG_SG (09/05/2019): Report Send Back Alerts - PC8020J (TP)

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***PC8020J (556465)**
[SDP8885D]

TP
RAINBOW BUS SERVICES
Apr 23 2018 12:00AM
[GOH LAY CHOO]
Ysk Auto Workshop

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/07/18 12:26	General View	 Load JPG	☒
2	18/07/18 12:26	General View	 Load JPG	☒
3	18/07/18 12:26	General View	 Load JPG	☒
4	18/07/18 12:26	General View	 Load JPG	☒
5	18/07/18 12:26	General View	 Load JPG	☒
6	18/07/18 12:26	General View	 Load JPG	☒
7	18/07/18 12:26	General View	 Load JPG	☒
8	18/07/18 12:26	General View	 Load JPG	☒
9	18/07/18 12:26	General View	 Load JPG	☒
10	18/07/18 12:26	General View	 Load JPG	☒
11	18/07/18 12:26	General View	 Load JPG	☒
12	18/07/18 12:26	General View	 Load JPG	☒
13	18/07/18 12:26	General View	 Load JPG	☒
14	18/07/18 12:26	General View	 Load JPG	☒
15	18/07/18 12:26	General View	 Load JPG	☒
16	18/07/18 12:26	General View	 Load JPG	☒
17	18/07/18 12:26	General View	 Load JPG	☒
18	18/07/18 12:26	General View	 Load JPG	☒
19	18/07/18 12:26	General View	 Load JPG	☒
20	18/07/18 12:26	General View	 Load JPG	☒
21	19/07/18 12:58	Photo After Spray	 Load JPG	☒
22	19/07/18 12:58	Photo After Spray	 Load JPG	☒
23	19/07/18 12:58	Photo After Spray	 Load JPG	☒
24	19/07/18 12:58	Photo After Spray	 Load JPG	☒
25	19/07/18 12:58	Photo After Spray	 Load JPG	☒
26	19/07/18 12:58	Photo After Spray	 Load JPG	☒
27	19/07/18 12:58	Photo After Spray	 Load JPG	☒
28	19/07/18 12:58	Photo After Spray	 Load JPG	☒
29	19/07/18 12:58	Photo After Spray	 Load JPG	☒
30	19/07/18 12:58	Photo After Spray	 Load JPG	☒
31	19/07/18 12:58	Photo After Spray	 Load JPG	☒
32	19/07/18 12:58	Photo After Spray	 Load JPG	☒
33	19/07/18 12:58	Photo After Spray	 Load JPG	☒
34	19/07/18 12:58	Photo After Spray	 Load JPG	☒
35	19/07/18 12:58	Photo After Spray	 Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	19/07/18 12:58	Photo After Spray	 Load JPG	☒
37	19/07/18 12:58	Photo After Spray	 Load JPG	☒
38	19/07/18 12:58	Photo After Spray	 Load JPG	☒
39	19/07/18 12:58	Photo After Spray	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/04/18 10:57	SDP8885D GIA Rpt	 Load PDF	
2	25/04/18 10:57	PC8020J GIA Rpt	 Load PDF	
3	25/04/18 11:01	PRI	 Load PDF	
4	09/05/19 09:01	LOD & SUPPORTING DOCUMENTS	 Load PDF	
5	09/05/19 09:01	SURVEY REPORT & COLOURED IMAGES PART 1	 Load PDF	
6	09/05/19 09:01	COLOURED IMAGES PART 2	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/06/19 15:33	PRS INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18007603/GTD3S2-1

Date: 20/06/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27025168SMP

Claimant Vehicle No : PC8020J

Insured Vehicle No : SDP8885D

Date of Loss: 23/04/2018

Nature of Claim: TP

Claim No: 556465

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC8020J

Make & Model: TOYOTA HIACE, 3.0 D GL High-roof Commuter (A)

Engine No: 1KD2361607

Reg. Date: 24/01/2014 (Man. Year: 2013)

Chassis No: JTFST22P700018704

Colour: White

Odometer: 207451 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size:

195 R15C

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,317.02	6,212.86	12,104.16	66.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,820.00	3,010.00	2,810.00	48.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,137.02	9,222.86	14,914.16	61.79
Approved Total (Overridden) (S\$)		7,300.00		
Nett Amount (S\$)	24,137.02	7,300.00	16,837.02	69.76

INSPECTION

Date of Assignment: 25/04/2018

Date Inspected: 25/04/2018 Inspected At:

Ysk Auto Workshop (HQ)

No.1 Kaki Bukit Avenue 6, #01-71 Autobay

Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 20 Jun 2019)

Parts: N/A TOYOTA HIACE 3.0 D GL High-roof Commuter (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PC8020J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT LH DOOR HINGE	Not Necessary	200.40 FL	*- FL
2	1		*FRONT LH DOOR CHECKER	Not Necessary	145.90 FL	*- FL
3	1		*FRONT LH DOOR GLASS CHANNEL	Not Necessary	298.80 FL	*- FL
4	1		*FRONT LH DOOR REGULATOR	Not Necessary	570.80 FL	*- FL
5	1		*FRONT LH DOOR REGULATOR MOTOR	Not Necessary	709.80 FL	*- FL
6	1		*FRONT LH DOOR WEATHERSTRIP	Not Necessary	310.00 FL	*- FL
7	1		*FRONT LH DOOR INNER TRIM BOARD	Not Necessary	890.50 FL	*- FL
8	1		*FRONT LH DOOR LOCK ASSY	Not Necessary	599.80 FL	*- FL
9	1		*FRONT LH DOOR PANEL	Repair	1,904.50 FL	*- FL
10	1		*REAR LH SLIDING DOOR	Dented	3,319.30 FL	*1,546.00 FL
11	1		*REAR LH SLIDING DOOR HINGE	Bent	50.40 FL	*50.40 FL
12	1		*REAR LH SLIDING DOOR INNER TRIM	Cracked	858.90 FL	*789.00 FL
13	1		*REAR LH SLIDING DOOR LOCK	Malfunction	699.80 FL	*699.80 FL
14	1		*REAR LH FENDER	Dented	3,594.50 FL	*1,718.00 FL
15	1		*REAR LH INNER FENDER PANEL	Repair	1,521.30 FL	*- FL
16	1		*LH LOWER STEP PANEL	Dented	2,031.50 FL	*885.00 FL
17	1		*REAR LH SLIDING ROLLER GARNISH	Bent	219.40 FL	*219.40 FL
18	1		*REAR LH LOWER PANEL GARNISH	Deformed	391.10 FL	*391.10 FL
19	1		*REAR LH PILLER LOWER GARNISH	Deformed	151.93 FL	*151.93 FL
20	1		*REAR LH DOOR WIRE HARNESS	Not Necessary	2,093.30 FL	*- FL
21	1		*REAR LH WINDOW GLASS	Shattered	510.40 FL	*510.40 FL
22	1		*LH CORNER PANEL	Dented	190.30 FL	*190.30 FL
23	1		*LH SLIDING DOOR LOWER LOCK ASSY	Malfunction	673.09 FL	*673.09 FL
24	1		*SLIDING DOOR HANDLE	Jammed	139.40 FL	*139.40 FL
25	2		*TYRE TRIM	Grazed 1pc Only	180.68 FS	*50.00 FS
26	1		*SET FRONT DOOR INNER TRIM CLIP	Necessary	40.00 FS	*30.00 FS
27	1		*SET REAR LH DOOR INNER TRIM CLIP	Necessary	40.00 FS	*30.00 FS
28	1		*FLOOR PANEL LOWER BOARD	Not Necessary	1,200.00 FS	*- FS
29	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
30	1		*JOINT SEALANT	Necessary	150.00 FS	*90.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	23,835.80	8,203.82
- List Item Discount on L Items 25.00/25.00% (S\$)	5,518.78	1,990.96
Total Parts (S\$)	18,317.02	6,212.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND LIGHTING SYSTEM.	New	70.00	30.00
2	REMOVE, REFIT LINING, TRIM AND GARNISH.	New	200.00	60.00
3	REMOVE AND REPLACE LH QUARTER GLASS.	New	150.00	80.00
4	TRANSFER PARTS, ATTACHMENT FROM FRONT LH DOOR TO NEW.	New	200.00	0.00
5	TRANSFER PARTS, ATTACHMENT FROM LH SLIDING DOOR TO NEW.	New	350.00	60.00
6	CHECK FRONT AND REAR WHEEL ALIGNMENT.	New	200.00	60.00
7	PANEL BEATING ON AFFECTED AREAS.	New	2,500.00	1,400.00
8	SPRAY PAINTING ON AFFECTED AREAS.	New	1,800.00	1,200.00
9	APPLY RUST ON AFFECTED AREAS.	New	200.00	120.00
10	TOWING SERVICE.	New	150.00	0.00
Gross Labour Cost (\$\$)			5,820.00	3,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >