

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Tel: 6315 1239, Fax: 6315 3298, Mobile: 9061 0543

StarHub Cable Vision Ltd
c/o 53 Ubi Avenue 1
#01-19
Singapore 408934

Invoice no:	POS044/19
Date:	28 March 2019
Report no:	44M0219.KM
Vehicle :	GBH5825M

INVOICE

No	Item Description	Qty	Unit Price	Total Amount(\$)
01	Being charges for the inspection of the accident vehicle, transport and photographs.			1,487.00
SGD(\$): One Thousand foru hundred and eighty- seven only		Payable Amount:		1,487.00

"Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES

Authorised Signature

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Fax: 6315 3298, Mobile: 9061 0543

ACCIDENT VEHICLE INSPECTION REPORT

Report no : 44M0219.KM
Vehicle no : GBH5825M

1 REFERENCE

Date of inspection : 15 February 2019
Requested by : StarHub Cable Vision Ltd
c/o 53 Ubi Avenue 1
#01-19
Singapore 408934
Type of survey : Independent
Repairer : K & M Motor Pte Ltd
53 Ubi Avenue 1, #01-19 Paya Ubi Industrial Park Singapore 408934
Date of accident : 13 February 2019

2 VEHICLE DATA

Make/model : Nissan NV200 1.5 MT
Chassis no : VSKYBAM20Z0158410
Engine no : K9KE628D438059
Date of registration : 20 Jul 2018 COE Expiry Date: 19 Jul 2028
Engine capacity : 1461 cc
Odometer reading : 7996 km
Colour : Lime Green

3 STATIC CONDITION CHECK

Steering : Serviceable
Foot brakes : Serviceable
Hand brakes : Serviceable
Paintwork : Good
General Condition : Fair

4 TIRE CONDITION CHECK

	<u>RH/MAKE</u>	<u>LH/MAKE</u>	<u>SIZE</u>
Front tread	: 6 mm/Goodyear	6 mm/Goodyear	175/70R14
Rear tread	: 6 mm/Goodyear	6 mm/Goodyear	175/70R14

5 BRIEF DESCRIPTION OF DAMAGE

Rear bumper crushed, rear LH/RH tail doors crushed, rear end panel – inner/outer crushed, rear LH/RH fenders buckled/distorted, front bonnet dented/buckled, front support panel bent, RH front fender bent, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs : \$25,300.00 (lump sum)
Estimated no of days : Twenty-one (21)

8 ASSESSMENT OF DAMAGE AND COSTS

Report no: 44M0219.KM

Vehicle no: GBH5825M

A SPARE PARTS

Nett Item	Description	Qty	Assessed Condition	Repairer's Amount	Revised Amount
Rear bumper		1	crushed	460.80	✓ 460.80 BT
Rear bumper side retainer		2	necessary	70.40	✓ 70.40
Rear bumper clip		10	necessary	40.00	30.00 40.00
Rear bumper inner foam		1	bent/deformed	88.90	✓ 88.90 BRV
Rear bumper side reflector L/R		2	leg broken	83.20	60.00 83.20 BRV
Rear end panel – outer		1	crushed	246.60	192.00 246.60 DDV
Rear end panel – inner		1	crushed	841.80	480.00 841.80 DDV
Rear end panel top garnish		1	broken	55.50	✓ 55.50 BRV
Rear end panel top garnish clip		4	necessary	21.60	10.00 21.60 NECV
Rear floor panel		1	crumpled/distorted	1,880.40	1,880.40 DDV
Rear floor panel top mat		1	cut	238.10	120.00 238.10 CVT
Rear floor panel underside support brace		1	bent	257.60	✓ 257.60 BT
LH tail door assy		1	crushed	1,404.90	1,404.90 DDV
LH tail door check		1	bent	111.10	1281.10 111.10 BT
LH tail door hinge – upper/lower		2	bent	202.40	99.20 202.40 BT
LH tail door "Nissan" logo		1	necessary	45.60	✓ 45.60
LH tail door "NV200" emblem		1	necessary	66.50	✓ 66.50
LH tail door outer garnish		1	mount bracket broken	351.50	351.50 BRV
LH tail door outer garnish clip		2	necessary	10.80	✓ 10.80 NECV
Rear license plate lamp		1	to reuse	55.00	0.00
LH tail door wiper arm		1	serviceable	78.90	0.00
LH tail door wiper motor		1	jammed	469.50	469.50 NNX
LH tail door third brake light		1	serviceable	123.00	0.00
LH tail door inner trim board		1	bent/creased	175.80	✓ 175.80 BT
LH tail door inner trim board clip		9	necessary	49.50	30.00 49.50 NECV
LH tail door inner lock handle		1	to reuse	102.10	-0.00
LH tail door inner lock link mechanism		1	bent	128.90	109.90 128.90 BT
LH sliding door centre sliding rail		1	to repair	314.20	-0.00
Tail door weatherstrip		1	squashed/deformed	133.80	✓ 133.80 DISV
Tail door central lock assy		1	bent/distorted	112.60	✓ 112.60 JM
Tail door central lock catch		1	broken	42.10	31.80 42.10 BT
RH tail door assy		1	dented/bent/distorted	1,053.70	✓ 1,053.70 DDV
RH tail door hinge – upper/lower		2	bent	202.40	✓ 202.40 BT
RH tail door upper lock assy		1	bent/distorted	155.10	✓ 155.10 JM
RH tail door upper lock catch		1	bent	39.60	31.80 39.60 BT
RH tail door lower lock assy		1	bent/distorted	91.80	✓ 91.80 JM
RH tail door lower lock catch		1	broken	28.00	✓ 28.00 BT
RH tail door "dCI" emblem		1	missing	59.70	✓ 59.70 MIS
RH tail door check		1	bent	111.10	99.20 111.10 BT
RH tail door inner trim board		1	bent/creased	118.10	✓ 118.10 BT
RH tail door inner trim board clip		8	necessary	44.00	30.00 44.00 NECV
RH sliding door centre sliding rail		1	to repair	314.20	0.00
RH tail door inner edge weathertrip		1	deformed	75.10	✓ 75.10 DISV
RH tail door glass		1	shattered	345.80	345.80 NNX
LH tail lamp assy		1	casing broken	258.70	✓ 258.70 BRV

Not consistent, Refer to 1st survey photo

11160.40

Report no: 44M0219.KM
Vehicle no: GBH5825M

LH tail lamp side clip	2 necessary	8.00	8.00 NEC
LH tail lamp base panel	1 bent/distorted	154.40	154.40 RX
RH tail lamp assy	1 cracked	258.70	258.70 CR
RH tail lamp side clip	2 necessary	8.00	8.00 NEC
RH tail lamp base panel	1 bent/distorted	154.40	154.40 RX
LH rear fender	1 buckled/distorted	2,997.20	2,997.20 DDV
RH rear fender	1 buckled/distorted	2,997.20	2,997.20 DDV
Rear wheelhouse panel LH	1 to repair	458.20	0.00
Rear wheelhouse panel RH	1 to repair	458.20	0.00
Exhaust tail pipe	1 bent	225.10	225.10 BT
Spare tyre bracket	1 buckled/distorted	185.40	185.40 BT
Front bumper	1 dented/torn	563.50	563.50 DD
Front bumper reinforcement	1 bent	651.10	651.10 BT
Front bumper inner foam	1 broken	280.70	280.70 BR
Front bumper side retainer L/R	2 necessary	52.20	52.20 NEC
Front bumper clip	10 necessary	54.00	54.00 NEC
Engine lower splash shield	1 bent/deformed	312.00	312.00 BT
LH fog lamp assy	1 leg cut/distorted	320.70	320.70 NNX
RH fog lamp assy	1 leg cut/distorted	320.70	320.70 BR
Front support panel	1 bent	325.00	325.00 BT
Front support top side panel LH	1 bent/distorted	67.60	67.60 RX
Front support top side panel RH	1 to repair	67.60	0.00
RH headlamp assy	1 leg broken	454.50	454.50 BR
RH headlamp lower bracket	1 to reuse	69.10	0.00
RH headlamp lower apron panel	1 scraped/bracket twisted	347.60	347.60 RX
LH headlamp assy	1 casing bent	454.50	454.50 BR
LH headlamp lower bucket	1 broken	69.10	69.10 BR
LH headlamp lower apron panel	1 bent/bracket twisted	347.60	347.60 RX
Front grille	1 leg broken	344.10	344.10 NNX
Front grille clip	6 necessary	24.00	24.00
Front grille "Nissan" logo	1 necessary	60.30	60.30 NEC
RH front fender	1 to repair	548.80	0.00
RH front fender splash shield	1 to reuse	204.00	0.00
RH front fender splash shield clip	8 not required	32.00	0.00
Front bonnet	1 dented/buckled	858.50	858.50 DD
Front bonnet lock assy	1 bent/distorted	54.60	54.60 NNX
Front bonnet hinge L/R	2 bent	240.00	240.00 NNX
Front bonnet insulator	1 to reuse	135.10	0.00
Front bonnet insulator clip	10 necessary	54.00	54.00 NEC
Turbo inter-cooler	1 dented	1,657.30	1,657.30 DDV
Radiator air flow deflector L/R	2 bent/cut/distorted	72.40	72.40 NNX
Radiator assy	1 serviceable	685.70	0.00
Aircon condenser	1 serviceable	674.50	0.00
Radiator fan assy	1 serviceable	577.60	0.00
Radiator overflow tank	1 serviceable	89.60	0.00
	Subtotal of the above	30,135.20	25,147.40
	Discount	10% / 10%	3,013.52
	Subtotal 1:	27,121.68	22,632.66
(Special nett)			
Reverse sensor set	1 squashed/shorted	280.00	280.00
RH tail door glass sealant	1 necessary	80.00	80.00
LH tail door glass sealant	1 necessary	80.00	80.00
LH tail door "70 km/h" sticker	1 necessary	15.00	15.00

Report no: 44M0219.KM
 Vehicle no: GBH5825M

Rear number plate set	1 to reuse	70.00	0.00
Rear floor panel plywood board	1 dented/end frayed	125.00	125.00 NNX
Front number plate set	1 dented/bent/broken	70.00	70.00 ✓
Subtotal 2:		720.00	650.00

Total cost of parts:	27,841.68	23,282.66
----------------------	-----------	-----------

B LABOUR
FRONT PORTION

✓ To check wiring.	45.00	30.00 ✓
To align headlamps and refocus headlamp beams to specifications.	80.00	40.00 60.00 ✓
To apply anti-rust undercoat.	150.00	60.00 90.00
To remove and refit radiator & fan to facilitate the necessary repairs; and to conduct pressure test to prevent leak.	120.00	0.00
To remove and refit aircon condenser and to vacuum and charge up aircon gas.	120.00	0.00
✓ Labour charges to remove and replace, to cut and weld, to panel beating affected and damaged parts.	900.00	400.00 600.00
Spray painting charges to paint the front RH fender, front bonnet, front bonnet hinges, front support panel, headlamp lower apron panels and affected areas.	1,500.00	600.00 1,000.00
To supply front bonnet Starhub logo stickers and affix into place.	150.00	100.00 150.00

REAR PORTION

✓ To check wiring.	60.00	30.00 45.00
To install reverse sensors and check for proper functions.	80.00	60.00
To apply anti-rust undercoat.	250.00	100.00 210.00
To remove and refit rear LH tail door glass.	120.00	60.00 90.00
To install rear RH tail door glass.	120.00	60.00 90.00
✓ Labour charges to remove and replace, to cut and weld, to panel beating affected and damaged parts.	4,200.00	2,800.00 3,600.00
Spray painting charges to paint the LH tail door, RH tail door, rear LH fender, rear RH fender, rear end panel inner/outer, rear floor panel and affected areas.	2,000.00	1,200.00 1,750.00
To remove and replace exhaust tailpipe.	90.00	40.00 50.00
To supply LH & RH tail doors Starhub related stickers and affix into place.	400.00	300.00 400.00

Total cost of labour:	10,385.00	8,235.00
-----------------------	-----------	----------

Total cost of repair:	38,226.68	31,517.66
-----------------------	-----------	-----------

Report no: 44M0219.KM
Vehicle no: GBH5825M

9 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is

\$31,517.66

(a) The final cost of repair based on lump sum repairs would be

\$25,300.00

(b) The estimated number of days for the repairs would be

Twenty-one (21)

(1st Reinspection conducted on 18 February 2019)

(Post Repair Inspection conducted on 6 March 2019)

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

Yours faithfully



.....
Liaw Leong San
Licensed Automotive Appraiser

Dated: 28 March 2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2019		15 Feb 2019 09:47 Edit Adj Rpt	S\$18,050.00 Edit Estimates	S\$18,050.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TRACTORS SINGAPORE LTD, Co. Reg. No.: 196600025H		
Main Claimant:	STARHUB CABLE VISION LTD, Co. Reg. No.: 199103398C		
Vehicle Reg. No.:	GBH5825M	Date of Loss:	13/02/2019 16:00 - :59 [6 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 585224	Policy/Cover Note No.:	B29040188MKF (Comprehensive) Coverage: 01/10/2018 - 30/09/2019
Vehicle Reg. No. (Insured):	GBB7865R	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	K & M Motor Pte Ltd (HQ) 53 Ubi Ave 1 #01-19 Paya Ubi Industrial Park, 408934 Ubi - Tel: 66945965		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 13/05/2019]		
Driver/Custodian (Insured):	RAMALINGAM RENGARASU (36 / Male), NRIC: G7791419L Email:		
Adj Asg. Remarks:	on WP. SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:100% CONTACT:VICKI 9753 8067		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (09/05/2019): Report Send Back Alerts - GBH5825M (TP)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[Home](#)

[About Us](#)

[Contact Us](#)

Claim Documents

*GBH5825M (585224)
[GBB7865R]
TP
STARHUB CABLE VISION LTD
Feb 13 2019 4:00PM
[TRACTORS SINGAPORE LTD]
K & M Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Video			1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/02/19 15:41	Video - Accident (TP) - Front	 Load MP4	☒
2	14/02/19 15:42	Video - Accident (TP) - Rear	 Load MP4	☒
Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/19 09:49	General View	 Load JPG	☒
2	25/02/19 09:49	General View	 Load JPG	☒
3	25/02/19 09:49	General View	 Load JPG	☒
4	25/02/19 09:49	General View	 Load JPG	☒
5	25/02/19 09:49	General View	 Load JPG	☒
6	25/02/19 09:49	General View	 Load JPG	☒
7	25/02/19 09:49	General View	 Load JPG	☒
8	25/02/19 09:49	General View	 Load JPG	☒
9	25/02/19 09:49	General View	 Load JPG	☒
10	25/02/19 09:49	General View	 Load JPG	☒
11	25/02/19 09:49	General View	 Load JPG	☒
12	25/02/19 09:49	General View	 Load JPG	☒
13	25/02/19 09:49	General View	 Load JPG	☒
14	25/02/19 09:49	General View	 Load JPG	☒
15	25/02/19 09:49	General View	 Load JPG	☒
16	25/02/19 09:49	General View	 Load JPG	☒
17	25/02/19 09:49	General View	 Load JPG	☒
18	25/02/19 09:49	General View	 Load JPG	☒
19	25/02/19 09:49	General View	 Load JPG	☒
20	25/02/19 09:49	General View	 Load JPG	☒
21	25/02/19 09:49	General View	 Load JPG	☒
22	25/02/19 09:49	General View	 Load JPG	☒
23	25/02/19 09:49	General View	 Load JPG	☒
24	25/02/19 09:49	General View	 Load JPG	☒
25	25/02/19 09:49	General View	 Load JPG	☒
26	25/02/19 09:49	General View	 Load JPG	☒
27	25/02/19 09:49	General View	 Load JPG	☒
28	25/02/19 09:49	General View	 Load JPG	☒
29	25/02/19 09:49	General View	 Load JPG	☒
30	25/02/19 09:49	General View	 Load JPG	☒
31	25/02/19 09:49	General View	 Load JPG	☒

Video			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	25/02/19 09:49	General View	 Load JPG	✓
33	25/02/19 09:49	General View	 Load JPG	✓
34	25/02/19 09:49	General View	 Load JPG	✓
35	25/02/19 09:49	General View	 Load JPG	✓
36	25/02/19 09:49	General View	 Load JPG	✓
37	25/02/19 09:49	General View	 Load JPG	✓
38	25/02/19 09:49	General View	 Load JPG	✓
39	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
40	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
41	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
42	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
43	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
44	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
45	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
46	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
47	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
48	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
49	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
50	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
51	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
52	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
53	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
54	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
55	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
56	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
57	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
58	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
59	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
60	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
61	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
62	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
63	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
64	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
65	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
66	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
67	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
68	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
69	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
70	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
71	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
72	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
73	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
74	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
75	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
76	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
77	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
78	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	✓
79	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓

Video			1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
80	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
81	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
82	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
83	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
84	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
85	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
86	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
87	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
88	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
89	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
90	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
91	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
92	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
93	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
94	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
95	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
96	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
97	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
98	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
99	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
100	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
101	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
102	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
103	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
104	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
105	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
106	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
107	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
108	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
109	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
110	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	☒
Documentation			1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/02/19 15:34	GBB7865R E-FILE REPORT	Load PDF	
2	14/02/19 15:34	GBH5825M TP E-FILE REPORT	Load PDF	
3	14/02/19 15:34	SMH4105J TP E-FILE REPORT	Load PDF	
4	14/02/19 15:35	PRI - LAWRENCE LEE & CO	Load PDF	
5	14/02/19 17:13	SURVEY DISAGREE ON SJE - ASSIGN LKK	Load PDF	
6	04/05/19 10:37	LOD & Supporting Documents	Load PDF	
7	04/05/19 10:50	TP Survey Rpt pt 1	Load PDF	
8	04/05/19 10:50	TP Survey Rpt pt 2	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/07/19 14:59	PRS INVOICE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19002903/BSD3S2-1

Date: 05/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B29040188MKF

Claimant Vehicle No : GBH5825M

Insured Vehicle No : GBB7865R

Date of Loss: 13/02/2019

Nature of Claim: TP

Claim No: 585224

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBH5825M

Make & Model: NISSAN NV200, 1.5 (M)

Engine No: K9KE628D438059

Reg. Date: 20/07/2018 (Man. Year: 2017)

Chassis No: VSKYBAM20Z0158410

Colour: Green/Silver

Odometer: 7996 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70R14

Rear Tyre Size: 175/70R14

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	27,841.68	16,694.42	11,147.26	40.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,385.00	5,880.00	4,505.00	43.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,226.68	22,574.42	15,652.26	40.95
Approved Total (Overridden) (S\$)		18,050.00		
Nett Amount (S\$)	38,226.68	18,050.00	20,176.68	52.78

INSPECTION

Date of Assignment: 15/02/2019

Date Inspected: 15/02/2019 Inspected At:

K & M Motor Pte Ltd (HQ)
53 Ubi Ave 1 #01-19 Paya Ubi Industrial Park
Singapore 408934

Estimated Period of Repair: 15.0 days

Adjuster: Lim Teow Guan

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Jul 2019)	
Parts:	N/A	NISSAN NV200 1.5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH5825M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Bent	460.80 FN	*460.80 FN
2	2	*REAR BUMPER SIDE RETAINER	Necessary	70.40 FN	*70.40 FN
3	10	*REAR BUMPER CLIP	Necessary	40.00 FN	*30.00 FN
4	1	*REAR BUMPER INNER FOAM	Broken	88.90 FN	*88.90 FN
5	2	*REAR BUMPER SIDE REFLECTOR L/R	Broken	83.20 FN	*60.00 FN
6	1	*REAR END PANEL - OUTER	Dented	246.60 FN	*192.00 FN
7	1	*REAR END PANEL - INNER	Dented	841.80 FN	*480.00 FN
8	1	*REAR END PANEL TOP GARNISH	Broken	55.50 FN	*55.50 FN
9	4	*REAR END PANEL TOP GARNISH CLIP	Necessary	21.60 FN	*10.00 FN
10	1	*REAR FLOOR PANEL	Dented	1,880.40 FN	*1,420.00 FN
11	1	*REAR FLOOR PANEL TOP MAT	Cut	238.10 FN	*120.00 FN
12	1	*REAR FLOOR PANEL UNDERSIDE SUPPORT BRACE	Bent	257.60 FN	*257.60 FN
13	1	*LH TAIL DOOR ASSY	Dented	1,404.90 FN	*1,281.10 FN
14	1	*LH TAIL DOOR CHECK	Bent	111.10 FN	*99.20 FN
15	2	*LH TAIL DOOR HINGE - UPPER / LOWER	Bent	202.40 FN	*202.40 FN
16	1	*LH TAIL DOOR NISSAN LOGO	Necessary	45.60 FN	*45.60 FN
17	1	*LH TAIL DOOR NV200 EMBLEM	Necessary	66.50 FN	*66.50 FN
18	1	*LH TAIL DOOR OUTER GARNISH	Broken	351.50 FN	*351.50 FN
19	2	*LH TAIL DOOR OUTER GARNISH CLIP	Necessary	10.80 FN	*10.80 FN
20	1	*REAR LICENCE PLATE LAMP	Reuse	55.00 FN	*- FN
21	1	*LH TAIL DOOR WIPER ARM	Serviceable	78.90 FN	*- FN
22	1	*LH TAIL DOOR WIPER MOTOR	Not Necessary	469.50 FN	*- FN
23	1	*LH TAIL DOOR THIRD BRAKE LIGHT	Serviceable	123.00 FN	*- FN
24	1	*LH TAIL DOOR INNER TRIM BOARD	Bent	175.80 FN	*175.80 FN
25	1	*LH TAIL DOOR INNER BOARD CLIP 9pcs	Necessary	49.50 FN	*30.00 FN
26	1	*LH TAIL DOOR INNER LOCK HANDLE	Reuse	102.10 FN	*- FN
27	1	*LH TAIL DOOR INNER LOCK LINK MECHANISM	Bent	128.90 FN	*109.90 FN
28	1	*LH SLIDING DOOR CENTRE SLIDING RAIL	Repair	314.20 FN	*- FN
29	1	*TAIL DOOR WEATHERSTRIP	Distorted	133.80 FN	*133.80 FN
30	1	*TAIL DOOR CENTRAL LOCK ASSY	Jammed	112.60 FN	*112.60 FN
31	1	*TAIL DOOR CENTRAL LOCK CATCH	Bent	42.10 FN	*31.80 FN
32	1	*RH TAIL DOOR ASSY	Dented	1,053.70 FN	*1,053.70 FN
33	2	*RH TAIL DOOR HINGE - UPPER / LOWER	Bent	202.40 FN	*202.40 FN
34	1	*RH TAIL DOOR UPPER LOCK ASSY	Jammed	155.10 FN	*155.10 FN
35	1	*RH TAIL DOOR UPPER LOCK CATCH	Bent	39.60 FN	*31.80 FN
36	1	*RH TAIL DOOR LOWER LOCK ASSY	Jammed	91.80 FN	*91.80 FN
37	1	*RH TAIL DOOR LOWER LOCK CATCH	Bent	28.00 FN	*28.00 FN
38	1	*RH TAIL DOOR DCI EMBLEM	Missing	59.70 FN	*59.70 FN
39	1	*RH TAIL DOOR CHECK	Bent	111.10 FN	*99.20 FN
40	1	*RH TAIL DOOR INNER TRIM BOARD	Bent	118.10 FN	*118.10 FN

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
41	8	*RH TAIL DOOR INNER TRIM BOARD CLIP	Necessary	44.00 FN	*30.00 FN
42	1	*RH SLIDING DOOR CENTRE SLIDING RAIL	Repair	314.20 FN	*- FN
43	1	*RJH TAIL DOOR INNER EDGE WEATHERSTRIP	Distorted	75.10 FN	*75.10 FN
44	1	*RH TAIL DOOR GLASS (SHATTERED)	Not Consistent With The Impact	345.80 FN	*- FN
45	1	*LH TAIL LAMP ASSY	Broken	258.70 FN	*258.70 FN
46	2	*LH TAIL LAMP SIDE CLIP	Necessary	8.00 FN	*8.00 FN
47	1	*LH TAIL LAMP BASE PANEL	Repair	154.40 FN	*- FN
48	1	*RH TAIL LAMP ASSY	Cracked	258.70 FN	*258.70 FN
49	2	*RH TAIL LAMP SIDE CLIP	Necessary	8.00 FN	*8.00 FN
50	1	*RH TAIL LAMP BASE PANEL	Repair	154.40 FN	*- FN
51	1	*LH REAR FENDER	Dented	2,997.20 FN	*1,650.80 FN
52	1	*RH REAR FENDER	Dented	2,997.20 FN	*1,650.80 FN
53	1	*REAR WHEELHOUSE PANEL LH	Repair	458.20 FN	*- FN
54	1	*REAR WHEELHOUSE PANEL RH	Repair	458.20 FN	*- FN
55	1	*EXHAUST TAIL PIPE	Bent	225.10 FN	*225.10 FN
56	1	*SPARE TYRE BRACKET	Bent	185.40 FN	*185.40 FN
57	1	*FRONT BUMPER	Dented	563.50 FN	*563.50 FN
58	1	*FRONT BUMPER REINFORCEMENT	Bent	651.10 FN	*614.90 FN
59	1	*FRONT DOOR INNER FOAM	Broken	280.70 FN	*280.70 FN
60	2	*FRONT BUMPER SIDE RETAINER L/R	Necessary	52.20 FN	*52.20 FN
61	10	*FRONT BUMPER CLIP	Necessary	54.00 FN	*30.00 FN
62	1	*ENGINE LOWER SPLASH SHIELD	Bent	312.00 FN	*312.00 FN
63	1	*LH FOG LAMP ASSY	Not Necessary	320.70 FN	*- FN
64	1	*RH FOG LAMP ASSY	Broken	320.70 FN	*320.70 FN
65	1	*FRONT SUPPORT PANEL	Bent	325.00 FN	*325.00 FN
66	1	*FRONT SUPPORT TOP SIDE PANEL LH	Repair	67.60 FN	*- FN
67	1	*FRONT SUPPORT TOP SIDE PANEL RH	Repair	67.60 FN	*- FN
68	1	*RH HEADLAMP ASSY	Broken	454.50 FN	*454.50 FN
69	1	*RH HEADLAMP LOWER BRACKET	Reuse	69.10 FN	*- FN
70	1	*RH HEADLAMP LOWER APRON PANEL	Repair	347.60 FN	*- FN
71	1	*LH HEADLAMP ASSY	Broken	454.50 FN	*454.50 FN
72	1	*LH HEADLAMP LOWER BRACKET	Broken	69.10 FN	*69.10 FN
73	1	*LH HEADLAMP LOWER APRON PANEL	Repair	347.60 FN	*- FN
74	1	*FRONT GRILLE	Not Necessary	344.10 FN	*- FN
75	6	*FRONT GRILLE CLIP	Necessary	24.00 FN	*24.00 FN
76	1	*FRONT GRILLE NISSAN LOGO	Necessary	60.30 FN	*60.30 FN
77	1	*RH FRONT FENDER	Repair	548.80 FN	*- FN
78	1	*RH FRONT FENDER SPLASH SHIELD	Reuse	204.00 FN	*- FN
79	8	*RH FRONT FENDER SPLASH SHIELD CLIP	Not Required	32.00 FN	*- FN
80	1	*FRONT BONNET	Dented	858.50 FN	*858.50 FN
81	1	*FRONT BONNET LOCK ASSY	Not Necessary	54.60 FN	*- FN
82	2	*FRONT BONNET HINGE L/R	Not Necessary	240.00 FN	*- FN
83	1	*FRONT BONNET INSULATOR	Reuse	135.10 FN	*- FN
84	10	*FRONT BONNET INSULATOR CLIP	Necessary	54.00 FN	*30.00 FN
85	1	*TURBO INTER-COOLER	Dented	1,657.30 FN	*1,657.30 FN
86	2	*RADIATOR AIR FLOW DEFLECTOR L/R	Not Necessary	72.40 FN	*- FN
87	1	*RADIATOR ASSY	Serviceable	685.70 FN	*- FN
88	1	*AIRCON CONDENSER	Serviceable	674.50 FN	*- FN
89	1	*RADIATOR FAN ASSY	Serviceable	577.60 FN	*- FN
90	1	*RADIATOR OVERFLOW TANK	Serviceable	89.60 FN	*- FN
91	1	*SET REVERSE SENSOR	Cut	280.00 FS	*200.00 FS
92	1	*RH TAIL DOOR GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
93	1	*LH TAIL DOOR GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
94	1	*LH TAIL DOOR 70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
95	1	*SET REAR NUMBER PLATE	Reuse	70.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
96	1		*REAR FLOOR PANEL PLYWOOD BOARD	Not Necessary	125.00 FS	*- FS
97	1		*SET FRONT NUMBER PLATE	Dented / Bent / Broken	70.00 FS	*25.00 FS
F=Franchise part, S=SpcNett, N=NettItemDisc.						
Sub Total (S\$)					30,855.20	18,513.80
- Nett Item Discount on N Items 10.00/10.00% (S\$)					3,013.52	1,819.38
Total Parts (S\$)					27,841.68	16,694.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING.	New	105.00	60.00
2	TO ALIGN HEADLAMPS AND REFOCUS HEADLAMP BEAMS TO SPECIFICATIONS.	New	80.00	40.00
3	TO APPLY ANTI-RUST UNDERCOAT.	New	150.00	60.00
4	TO REMOVE AND REFIT RADIATOR & FAN FACILITATE THE NECESSARY REPAIRS; AND TO CONDUCT PRESSURE TEST TO PREVENT LEAK.	New	120.00	0.00
5	TO REMOVE AND REFIT AIRCON CONDENSER AND TO VACUUM AND CHARGE UP AIRCON GAS.	New	120.00	0.00
6	LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO PANEL BEATING AFFECTED AND DAMAGED PARTS.	New	5,100.00	3,200.00
7	SPRAY PAINTING CHARGES TO PAINT THE FRONT RH FENDER, FRONT BONNET, FRONT BONNET HINGES, FRONT SUPPORT PANEL, HEADLAMP LOWER APRON PANELS AND AFFECTED AREAS.	New	1,500.00	600.00
8	TO SUPPLY FRONT BONNET STARHUB LOGO STICKERS AND AFFIX INTO PLACE.	New	150.00	100.00
9	TO INSTALL REVERSE SENSORS AND CHECK FOR PROPER FUNCTIONS.	New	80.00	60.00
10	TO APPLY ANTI-RUST UNDERCOAT.	New	250.00	100.00
11	TO REMOVE AND REFIT REAR LH TAIL DOOR GLASS.	New	120.00	60.00
12	TO INSTALL REAR RH TAIL DOOR GLASS.	New	120.00	60.00
13	SPRAY PAINTING CHARGES TO PAINT THE LH TAIL DOOR, RH TAIL DOOR, REAR LH FENDER, REAR RH FENDER, REAR END PANEL INNER / OUTER, REAR FLOOR PANEL AND AFFECTED AREAS.	New	2,000.00	1,200.00
14	TO REMOVE AND REPLACE EXHAUST PIPE.	New	90.00	40.00
15	TO SUPPLY LH & RH TAIL DOORS SARHUB RELATED STICKERS AND AFFIX INTO PLACE.	New	400.00	300.00
Gross Labour Cost (S\$)			10,385.00	5,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >