



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

WITHERS KHATTARWONG LLP

Ref : CS/LAW19008267/Gvd3e2

80, RAFFLES PLACE #25-01
UOB PLAZA 1 SINGAPORE 048624

Date : 21-05-2019



Code : L001

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	FBJ 8554P	Veh. Inspected	GBC 1458S
Policy No.		Coverage (\$)	0.00
Claim No.	PYK/YHT/KW00007.2135(abk)	Excess (\$)	0.00
Assign From	JAYNA TAN	Assign Date	05/04/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN CABSTAR	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JN1SC2F24Z0850004	Colour	SILVER
Odometer	247146	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	BRIDGESTONE	5 mm
L/H Front Tyre	195 R15	BRIDGESTONE	5 mm
R/H Rear Tyre	165 R13	BRIDGESTONE	5 mm
L/H Rear Tyre	165 R13	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	12/04/2017	Inspection Date	16/05/2019
Survey held at	BLK 4024 ANG MO KIO IND PK 1 #01-311		
Repairer	WAH YU AUTOMOTIVE BODY WORK		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------