


Sketch Plan #2 Pg. 1

SKETCH PLAN



A : SLF8448R

B : SJH8503C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The accident happened on 19/08/2018 at 4:45pm at Junction of Stadium walk / cres. Vehicle A stop at the stop line and proceed to move very slowly across the Junction. Suddenly, vehicle B dashes forward and the front of vehicle A crashes the rear of vehicle B.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

20/8/18 10.20pm
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

LETTER OF UNDERTAKING

I/We, SENTOSA BUILDING CONSTRUCTIONS PTE LTD, the owner of vehicle no. SLF 8448R

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, AUTO N CARS

Signed and Acknowledge by:



.....
Nric no. and signature of policyholder



.....
Company Stamp

20/05/2018

.....
Date

2

[illegible]

68417181

[illegible]

New Journals

23/08/2017

2006-2007-2008
INVESTMENT (INVESTMENT) AGENCY PIA
LTD / 00190

For ordering visit our online
store

Your SmartDrive Comprehensive Flexi

Your policy snapshot

Policyholder name	SINGLA BUILDING CONSTRUCTION Polypropylene	Wkt / 04/02/2016
Company	PKC LTD.	
Policy number	2001071111	
Period of insurance	from 12/05/2017 to 12/05/2018 (12 months)	

	0.08% premium after 10% MCT	\$60 1,793.80
	Total Expenses:	\$60 11.12
	7% GST	\$60 11.290
	Final Premium	\$60 1,782.00

Your friends & family:

- 24/7 Imaging & Transportation in Singapore at the best
- Affordable one-time treatment with Express CA Repair with a minimum of your insurance (could save you \$50 cash reward with no excess)
- Labor & Materials
- Legal Liability
- Insurance of Your Choice
- Maximum dental expenses up to \$1,000 per person for you, your named family and your immediate family members
- Reimbursement of 145% of your cash medical bill in the event of total loss (up to \$100,000 based on the actual bill)

Vehicle details

Make & Model of Vehicle	Mc NABA VEZEL 1.5 S CVT	Year of acquisition	2010
Vehicle registration number	\$LFS415H	Type of Lien	Private law
Body type	S4, LOCK	Import country (C.C.)	USA
Getting capacity (cc; driver)	1600	Engine number	L15B403559
Off-Peak use	No	Chassis number	RH13073507

Medical Group, Inc. (MGI) is a leading provider of medical services and products. MGI is a public company and its securities are listed on the New York Stock Exchange. MGI is a leading provider of medical services and products. MGI is a public company and its securities are listed on the New York Stock Exchange. MGI is a leading provider of medical services and products. MGI is a public company and its securities are listed on the New York Stock Exchange.

Excess applicable: In this Policy, words & phrases shall have the following meanings:

Gas & Over Damage Expense	SGU 300.00
Vandalism & Theft	SGU 100.00


AAA Insurance Plc Ltd (0208025124)
 19-20 Abchurch Lane, E14 6RT, London, UK
 5 Hgcccrg DE9881
 Customer Care 78.851-31

142

Accident Photo



Accident Photo



Accident Photo



Acciden: Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MU JINDUO

BLK 115B YISHUN RING ROAD #15-821

SINGAPORE 762115

Contact : 83238870

TAX INVOICE

Date : 10/04/2019

Date in : 20/08/2018

Vehicle Num. : SJH8503C

Make/Model : MITSUBISHI LANCER 1.6 M-2008

Chassis/Eng# : JMYSNCS3A8U006033/4G18JS4583

Accident Date : 19/08/2018

Claim No : CLM14183

Reference : AUG-10/2018

Policy No. : 10811551 (08/02/2020)

LUMPSUM REPAIR BILL
AS PER SURVEYOR REPORT
REF : 0164-19-TCA DATED 25/03/2019
BY PAR AUTOMOTIVE CONSULTANCY

Amount S\$

13,100.00

E. & O.E. Sub S\$: 13,100.00

Add GST (7 %) S\$: 917.00

Total Amount S\$: 14,017.00



for TWINCAR AUTOMOTIVE PTE LTD

PAR Automotive Consultancy

Regn No: 52960974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0164-19-TCA

25 March 2019

ACCIDENT VEHICLE SURVEY REPORT

Mu Jinduo
Blk 115B Yishun Ring Road #15-821
Singapore 762115

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SJH8503C	<i>Odometer:</i>	107737km
<i>Make & Model:</i>	Mitsubishi Lancer 1.6M	<i>Colour:</i>	Grey
<i>Chassis number:</i>	JMYSNCS3A8U006033	<i>Date of accident:</i>	19/08/2018
<i>Year of Regn.:</i>	27/08/2008	<i>Date inspected:</i>	21/08/2018
<i>Repairer at:</i>	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	31/08/2018

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0164-19-TCA

25 March 2019

Mu Jinduo
Blk 115B Yishun Ring Road #15-821
Singapore 762115

INVOICE No. **0164-19-TCA**

Vehicle No. **SJH8503C**

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	
		\$1,097.00
	Total amount payable	<u>\$1,097.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0164-19-TCA

25 March 2019

ACCIDENT VEHICLE SURVEY REPORT

Mu Jinduo
Blk 115B Yishun Ring Road #15-821
Singapore 762115

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SJH8503C	<i>Odometer:</i>	107737km
<i>Make & Model:</i>	Mitsubishi Lancer 1.6M	<i>Colour:</i>	Grey
<i>Chassis number:</i>	JMYSNCS3A8U006033	<i>Date of accident:</i>	19/08/2018
<i>Year of Regn.:</i>	27/08/2008	<i>Date inspected:</i>	21/08/2018
<i>Repairer at:</i>	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	31/08/2018

STATIC CHECKS, where applicable:

<i>Steering :</i>	serviceable
<i>Footbrake :</i>	serviceable
<i>Handbrake :</i>	serviceable
<i>Paintwork :</i>	Good
<i>General condition :</i>	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
<i>Front:</i>	4mm/Falken	4mm/Falken	195/60R15
<i>Rear:</i>	6mm/Falken	6mm/Falken	195/60R15

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear RH and LH portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
REAR ABS SENSOR L/R	2	shorted	630.60	X 630.60 <i>nn</i>
REAR BOOTLID	1	repair	593.00	0.00
REAR BOOTLID 'LANCER' EMBLEM	1	necessary	35.00	35.00 <i>/</i>
REAR BOOTLID 'LOGO' EMBLEM	1	necessary	38.00	38.00 <i>/</i>
REAR BOOTLID HINGES L/R	2	bent	176.00	X 176.00 <i>Repair</i>
REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R	2	deformed	56.20	X 56.20 <i>nn</i>
REAR BOOTLID INNER TRIM	1	na	331.40	0.00 <i>nn</i>
REAR BOOTLID LOCK STRIKER	1	bent	28.00	X 28.00 <i>nn</i>
REAR BOOTLID MECHANISM LOCK	1	repair	58.00	0.00
REAR BOOTLID NUMBER PLATE LAMP L/R	2	reuse	96.00	0.00 <i>nn</i>
REAR BOOTLID OUTER GARNISH	1	reuse	100.00	0.00
REAR BOOTLID WEATHERSTRIP	1	deformed	150.00	150.00 <i>/</i>
REAR BUMPER	1	squashed	745.10	745.10 <i>- 639</i>
REAR BUMPER CENTER BRACKET	1	repair	165.00	0.00
REAR BUMPER SIDE RETAINER L/R	2	necessary	130.60	130.60 <i>- 80</i>
REAR END PANEL	1	repair	398.00	0.00
REAR END PANEL INNER TOP GARNISH	1	reuse	140.00	0.00
REAR EXHAUST GASKET	1	reuse	20.00	0.00
REAR EXHAUST RUBBER MOUNTING	1	reuse	26.00	0.00 <i>nn</i>
REAR EXHAUST SILENCER BOX	1	reuse	359.00	0.00
REAR FENDER INNER SHIELD L/R	2	reuse	270.20	0.00
REAR FENDER INNER TRIM L/R	2	R-fractured	770.60	185.00 <i>/</i>
REAR FENDER L/R	2	R-buckled	1,870.20	935.10 <i>- 628</i>
REAR FLOOR PANEL TOP BOARD COVER	1	reuse	435.00	0.00 <i>nn</i>
REAR LOWER ARM L/R	2	bent	186.00	186.00 <i>/</i>
REAR RH DOOR	1	bent	767.00	767.00 <i>/</i>
REAR RH DOOR CHECKER	1	reuse	38.00	0.00
REAR RH DOOR GLASS CHANNEL	1	reuse	112.10	0.00 <i>nn</i>
REAR RH DOOR GLASS OUTER MOULDING	1	necessary	101.00	X 101.00 <i>nn</i>
REAR RH DOOR GLASS REGULATOR	1	reuse	345.10	0.00 <i>nn</i>
REAR RH DOOR GLASS REGULATOR MOTOR	1	reuse	310.20	0.00 <i>nn</i>
REAR RH DOOR HINGE (LOWER)	1	repair	44.00	0.00
REAR RH DOOR HINGE (TOP)	1	repair	44.00	0.00
REAR RH DOOR INNER TRIM BOARD	1	reuse	521.00	0.00 <i>nn</i>
REAR RH DOOR LOCK STRIKER	1	bent	18.00	X 18.00 <i>nn</i>
REAR RH DOOR MECHANISM LOCK	1	bent	260.00	260.00 <i>/</i>
REAR RH DOOR OUTER CHROME MOULDING	1	necessary	74.00	74.00 <i>/</i>
REAR RH DOOR OUTER HANDLE	1	distorted	125.10	125.10 <i>/</i>
RR RH DOOR OUTER HANDLE INNER RUBBER GASKET - SET	1	necessary	18.50	18.50 <i>/</i>
REAR RH DOOR WEATHERSTRIP	1	deformed	108.00	108.00 <i>/</i>
REAR SHOCK ABSORBER L/R	2	bent	376.00	376.00 <i>/</i>
REAR SPORT RIM L/R	2	abraded	2,770.00	1,200.00 <i>600(SN)</i>

REAR STABILIZER BAR L/R	2	reuse	474.00	0.00	NN
REAR TAILLAMP INNER PANEL L/R	2	repair	92.00	0.00	
REAR TAILLAMP L/R	2	broken	688.00	688.00	/
REAR TRAILING ARM L/R	2	bent	778.20	778.20	X } NN
REAR UPPER ARM L/R	2	bent	916.60	916.60	X } NN
REAR WHEEL BEARING L/R	2	dislodged	778.00	778.00	/
REAR WINDSCREEN MOULDING	1	necessary	45.00	45.00	/
Subtotal before discount			S\$ 17,611.70	S\$ 9,549.00	5230.6
Percentage discount 10% and 10%			S\$ 1,761.17	S\$ 954.90	
Sub-total 1			S\$ 15,850.53	S\$ 8,594.10	4707.54
REAR BOOTLID INNER TRIM CLIPS - SET	1	necessary	80.00	80.00	X NN
REAR BOOTLID NUMBER PLATE	1	reuse	25.00	0.00	
REAR BOOTLID NUMBER PLATE HOLDER	1	reuse	50.00	0.00	NN
REAR BOOTLID OUTER GARNISH CLIPS - SET	1	reuse	60.00	0.00	
REAR BUMPER CLIPS - SET	1	necessary	100.00	100.00	40
REAR BUMPER REVERSE SENSOR - SET	1	reuse	350.00	0.00	NN
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	necessary	50.00	50.00	20
REAR FENDER INNER SHIELD CLIPS L/R - SET	2	necessary	100.00	100.00	60
REAR FENDER INNER TRIM CLIPS L/R - SET	2	necessary	100.00	100.00	60
REAR FLOOR PANEL INSULATOR MAT	1	necessary	300.00	300.00	X NN
REAR RH DOOR INNER TRIM BOARD CLIPS - SET	1	necessary	30.00	30.00	/
REAR TAILLAMP CLIPS L/R - SET	2	necessary	80.00	80.00	20
REAR TYRE L/R	2	abraded	760.00	760.00	200
REAR WINDSCREEN SEALANT	1	necessary	100.00	100.00	40
Subtotal before discount			S\$ 2,185.00	S\$ 1,700.00	470
Sub-total 2			S\$ 2,185.00	S\$ 1,700.00	
Parts-total			S\$ 18,035.53	S\$ 10,294.10	

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	120.00	60.00	30
To remove, reinstall window glass. (to FR)	150.00	100.00	20
To remove, reinstall windscreen (REAR)	150.00	120.00	✓
To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.	550.00	500.00	400
To road test driving, check and resetting wheel alignments system.	160.00	160.00	60
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00	120.00	60
To send vehicle for cleaning, shampoo, upholstery and cushion seat.	200.00	150.00	40
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	200.00	100.00	40
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel, rear bumper, rear doors (L/R), and roof top panel.	2,400.00	1,760.00	1200
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	180.00	180.00	X NA
To provide labour, workmanship to change the above damaged bodyparts, repair, reconstruct and re-align body structure, body alignments and damaged consistent to the accident.	3,200.00	1,750.00	1000
To apply anti-rust chemical on repaired and replaced panel.	120.00	90.00	60
Labour Total	SS 7,570.00	SS 5,090.00	
Parts & Labour Total	SS 25,605.53	SS 15,384.10	3030

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 13,100.00 and the recommended number of working days for the repairs is within 11 day(s).

ks

B J Loi (I Eng., MIM, AIRTE)
Automotive Appraiser

8807.54
20% = 7050
10 Days.



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: 19.26963 PD-O

Date: 28th June 2019

Our Ref: CS3/ASM18015108/Gsd3s2-1

M/s AXA Insurance Pte Ltd
C/o: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJH 8503C
INSURED VEHICLE: SLF 8448R ACCIDENT DATE: 19/08/2018**

We thank you for your instruction on 07/05/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJH 8503C from M/s PAR Automotive Consultancy.
- b) Final Repair Bill of SJH 8503C from M/s TwinCar Automotive Pte Ltd.
- c) Singapore Accident Statement of Vehicles SJH 8503C and SLF 8448R.
- d) Damaged vehicle photographs of SJH 8503.

Pre-Repair Inspection Date : 21/08/2018 at M/s TwinCar Automotive Pte Ltd, 2 Kaki Bukit Ave 2
#01-17 Kaki Bukit Autohub Singapore 417921

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJH 8503C
Make & Model	: Mitsubishi Lancer 1.6M
Year of Registration	: 2008
Chassis Number	: JMYSNCS3A8U006033
Engine Capacity	: 1584 cc

2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 8503C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	REAR ABS SENSOR L/R	NOT NECESSARY	630.60	-
1	REAR BOOTLID	TO REPAIR SEE LABOUR	593.00	-
1	REAR BOOTLID 'LANCER' EMBLEM	NECESSARY	35.00	35.00
1	REAR BOOTLID 'LOGO' EMBLEM	NECESSARY	38.00	38.00
2	REAR BOOTLID HINGES L/R	TO REPAIR SEE LABOUR	176.00	-
2	REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R	NOT NECESSARY	56.20	-
1	REAR BOOTLID INNER TRIM	NOT NECESSARY	331.40	-
1	REAR BOOTLID LOCK STRIKER	NOT NECESSARY	28.00	-
1	REAR BOOTLID MECHANISM LOCK	TO REPAIR SEE LABOUR	58.00	-
2	REAR BOOTLID NUMBER PLATE LAMP L/R	NOT NECESSARY	96.00	-
1	REAR BOOTLID OUTER GARNISH	NOT NECESSARY	100.00	-
1	REAR BOOTLID WEATHERSTRIP	DEFORMED	150.00	150.00
1	REAR BUMPER	SQUASHED	745.10	689.00
1	REAR BUMPER CENTER BRACKET	TO REPAIR SEE LABOUR	165.00	-
2	REAR BUMPER SIDE RETAINER L/R	NECESSARY	130.60	80.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	398.00	-
1	REAR END PANEL INNER TOP GARNISH	NOT NECESSARY	140.00	-
1	REAR EXHAUST GASKET	NOT NECESSARY	20.00	-
1	REAR EXHAUST RUBBER MOUNTING	NOT NECESSARY	26.00	-
1	REAR EXHAUST SILENCER BOX	NOT NECESSARY	359.00	-
2	REAR FENDER INNER SHIELD L/R	NOT NECESSARY	270.20	-
2	REAR FENDER INNER TRIM L/R	O/S FRACTURED	770.60	185.00
2	REAR FENDER L/R	O/S BUCKLED	1,870.20	628.00
1	REAR FLOOR PANEL TOP BOARD COVER	NOT NECESSARY	435.00	-
2	REAR LOWER ARM L/R	BENT	186.00	186.00
1	REAR RH DOOR	BENT	767.00	767.00
1	REAR RH DOOR CHECKER	NOT NECESSARY	38.00	-
1	REAR RH DOOR GLASS CHANNEL	NOT NECESSARY	112.10	-
1	REAR RH DOOR GLASS OUTER MOULDING	NOT NECESSARY	101.00	-
1	REAR RH DOOR GLASS REGULATOR	NOT NECESSARY	345.10	-

Report Ref No. CS3/ASM18015108/Gsd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR RH DOOR GLASS REGULATOR MOTOR	NOT NECESSARY	310.20	-
1	REAR RH DOOR HINGE (LOWER)	TO REPAIR SEE LABOUR	44.00	-
1	REAR RH DOOR HINGE (TOP)	TO REPAIR SEE LABOUR	44.00	-
1	REAR RH DOOR INNER TRIM BOARD	NOT NECESSARY	521.00	-
1	REAR RH DOOR LOCK STRIKER	NOT NECESSARY	18.00	-
1	REAR RH DOOR MECHANISM LOCK	BENT	260.00	260.00
1	REAR RH DOOR OUTER CHROME MOULDING	NECESSARY	74.00	74.00
1	REAR RH DOOR OUTER HANDLE	DISTORTED	125.10	125.10
1	SET RR RH DOOR OUTER HANDLE INNER RUBBER GASKET	NECESSARY	18.50	18.50
1	REAR RH DOOR WEATHERSTRIP	DEFORMED	108.00	108.00
2	REAR SHOCK ABSORBER L/R	BENT	376.00	376.00
2	REAR STABILIZER BAR L/R	NOT NECESSARY	474.00	-
2	REAR TAILLAMP INNER PANEL L/R	TO REPAIR SEE LABOUR	92.00	-
2	REAR TAILLAMP L/R	BROKEN	688.00	688.00
2	REAR TRAILING ARM L/R	NOT NECESSARY	778.20	-
2	REAR UPPER ARM L/R	NOT NECESSARY	916.60	-
2	REAR WHEEL BEARING L/R	DISLODGE	778.00	778.00
1	REAR WINDSCREEN MOULDING	NECESSARY	45.00	45.00
	LESS 10% DISCOUNT		-1,484.17	-523.06
			13,357.53	4,707.54
2	REAR SPORT RIM L/R (SN)	ABRADED	2,770.00	600.00
	LESS 10% DISCOUNT		-277.00	-
			2,493.00	600.00
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	80.00	-
1	REAR BOOTLID NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR BOOTLID NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR BOOTLID OUTER GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	100.00	40.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	350.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	50.00	20.00
2	SET REAR FENDER INNER SHIELD CLIPS L/R (SN)	NECESSARY	100.00	60.00

Report Ref No. CS3/ASM18015108/Gsd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	SET REAR FENDER INNER TRIM CLIPS L/R (SN)	NECESSARY	100.00	60.00
1	REAR FLOOR PANEL INSULATION MAT (SN)	NOT NECESSARY	300.00	-
1	SET REAR RH DOOR INNER TRIM BOARD CLIPS (SN)	NECESSARY	30.00	30.00
2	SET REAR TAILLAMP CLIPS L/R (SN)	NECESSARY	80.00	20.00
2	REAR TYRE L/R (SN)	ABRADED	760.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	40.00
			2,185.00	470.00
	LABOUR			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		120.00	30.00
	TO REMOVE, REINSTALL WINDOW GLASS. (TO FR)		150.00	20.00
	TO REMOVE, REINSTALL WINDSCREEN (REAR)		150.00	120.00
	TO REMOVE, CHANGE REAR SUSPENSION PARTS, AXLE CARRIAGE, ABSORBER, LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC.		550.00	400.00
	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENT SYSTEM.		160.00	60.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		140.00	60.00
	TO SEND VEHICLE FOR CLEANING, SHAMPOO, UPHOLSTERY AND CUSHION SEAT.		200.00	40.00
	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE.		200.00	40.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL, REAR BUMPER, REAR DOORS (L/R), AND ROOF TOP PANEL.		2,400.00	1,200.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	180.00	-
	TO PROVIDE LABOUR. WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOTLID, REAR BOOTLID HINGES L/R, REAR BOOTLID MECHANISM LOCK, REAR BUMPER CENTER BRACKET, REAR END PANEL, REAR RH DOOR HINGE (LOWER), REAR RH DOOR HINGE (TOP) AND REAR TAILLAMP INNER PANEL L/R.		3,200.00	1,000.00

Report Ref No. CS3/ASM18015108/Gsd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL		120.00	60.00
			7,570.00	3,030.00
GRAND TOTAL			25,605.53	8,807.54
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,050.00

Report Ref No. CS3/ASM18015108/Gsd3s2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.