SS. REC. BY:	REF:	ASSTONMEN	T (Office)	Special b		
irveyor	1 1/- 1-	ADDIVINI		Date	Time: A H	· . Plas
row (Person): Kamali		or	Bill to:			
stimated Coal: D / TP / WS / TP RES	OD BES / EV					
o Imped Vehicle No:	Pr goile	ń				
o Inspect Venante Pro: it Workshop m/s				Tel:		
1						
0						
LE LUNGEPCH	Monopolity 35		·Claim No:_	TPIPIO	3945 2019	
			'Claim No: _ Excess: _		PIOC 2.4PE	
Sum Inspect:					3945 2014	
(Client's Record)				D.0	DA 23 1	2019
Sum insured: Make of Veh: (Client's Resert) CA / REV / REP. / 1	REV 24 HRS		Excess: _	D.	0.A. 23 -	2019
Sum insured: Make of Yeh: (Clent's Record)	REV 24 HRS		Excess: _	D.	DA 23 1	2019
Sum Insured: Make of Veh: (Client's Resort) CA / REV / REP. / 1 Date/Time	REV 24 HRS		Excess: _	D.	0.A. 23 -	2019
Sum Insured: Make of Veh: (Client's Resert) CA / REV / REP. / 1 Date/Time Date/Time Action/Is	REV 24 HRS	erson Contacted:	Excess: _	D.	0.A. 23 -	2019
Sum Insured: Make of Veh: (Client's Resert) CA / REV / REP. / 1 Date/Time Action/Is	REV 24 HRS	erson Contacted:	Excess: _	D.	0.A. 23 -	2019
Sum Insured: Make of Veh: (Client's Resert) CA / REV / REP. / 1 Date/Time Action/Is	REV 24 HRS	erson Contacted:	Excess: _	D.	0.A. 23 -	2019

d) Case IAFP-IB-20190405 - Mechanical Inspection of Motor Bus, PC8218G (TP/IP/03945/2019)

On 23 January 2019 at about 8.29 a.m., footage from the Accused's private motor bus revealed that the Accused was driving his motor bus along Jurong West Avenue 5 towards Jalan Boon Lay and he had stopped his motor bus at signalised cross junction of Jurong West Street 82 on lane 3 of 3 lanes due to red light signal. The Accused started driving off along Jurong West Avenue 5 and made a left turn onto Jurong West Street 82 towards Jurong West Street 81 when the front left portion of the motor bus collided onto the Deceased whom was cycling across from the downslope pavement straight onto the signalised pedestrian crossing at unknown pedestrian signal. Upon collision, the Deceased fell to the road and was ran over by the left front and rear tyres of the motor bus. As a result of the accident, the Deceased sustained head injuries. He was pronounced dead at scene by paramedic Sidika at 8.35 a.m.

Vehicles to be inspected: PC8218G (Potential Defendant)

IO In-Charge: SIO Clarence Lim

e) Case IAFP-IB-20190405 - Mechanical Inspection of Motor Lorry, GBH4382E (TP/IP/10579/2019)

On 21 February 2019 at about 6 a.m., footage retrieved from the CCTV cameras from the Singtel server building revealed that the Deceased was travelling at a slow speed on an unknown lane when the 1st Defendant came from the rear at a fast speed and collided onto the Deceased and subsequently ran over him. After the collision, the 1st Defendant drove off from the scene. About 3 - 4 minutes after the accident, the 2nd Defendant was travelling on lane 3 of Ang Mo Kio Avenue 1 towards Upper Thomson Rd, when he drove over the Deceased. Due to the accident, the Deceased sustained multiple injuries and was pronounced dead at the scene by paramedic Sgt Nizham at 6.15 a.m.

Vehicles to be inspected: GBH4382E (Accused)

IO In-Charge: SIO Clarence Lim

f) Case IAFP-IB-20190405 - Mechanical Inspection of Motor Bus, SB\$7637T (TP/IP/10579/2019)

On 21 February 2019 at about 6 a.m. Footage retrieved from the CCTV cameras from the Singtel server building revealed that the Deceased was travelling at a slow speed on an unknown lane when the 1st Defendant came from the rear at a fast speed and collided onto the Deceased and subsequently ran over him. After the collision, the 1st Defendant drove off from the scene. About 3 - 4 minutes after the accident, the 2nd Defendant was travelling on lane 3 of Ang Mo Kio Avenue 1 towards Upper Thomson Rd, when he drove over the Deceased. Due to the accident, the Deceased sustained multiple injuries and was pronounced dead at the scene by paramedic Sgt Nizham at 6.15 a.m.

Vehicles to be inspected: SBS7637T (Potential Defendant)

10 In-Charge: SIO Clarence Lim