


11/14/19
 ASS. REC. BY: _____ REF: 01/TPD19008269/NC Special Instruction: _____
 Surveyor: _____ **ASSIGNMENT (Office)**
 From (Person): Kamaliah Kamic of SPF Date/Time: 2/4/2019
 Estimated Cost: _____ Bill to: _____
 OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No.: GBH 4382E Insured: _____
 at Workshop m/s _____ Tel: _____
 of _____
 Policy No: MH88PF06000017235 Claim No: TP/IP/10579/2019
 Sum Insured: _____ Excess: _____
 Make of Vch: _____ D.O.A. 2/2/2019
 (Client's Award)
 CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____
 Date/Time: _____ Person Contacted: _____ Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	<u>GBH 4382E - X</u>



(WH
 Lot
 class
 Long
 Car L...



d) Case IAFP-IB-20190405 - Mechanical Inspection of Motor Bus, PC8218G (TP/IP/03945/2019)

On 23 January 2019 at about 8.29 a.m., footage from the Accused's private motor bus revealed that the Accused was driving his motor bus along Jurong West Avenue 5 towards Jalan Boon Lay and he had stopped his motor bus at signalised cross junction of Jurong West Street 82 on lane 3 of 3 lanes due to red light signal. The Accused started driving off along Jurong West Avenue 5 and made a left turn onto Jurong West Street 82 towards Jurong West Street 81 when the front left portion of the motor bus collided onto the Deceased whom was cycling across from the downslope pavement straight onto the signalised pedestrian crossing at unknown pedestrian signal. Upon collision, the Deceased fell to the road and was ran over by the left front and rear tyres of the motor bus. As a result of the accident, the Deceased sustained head injuries. He was pronounced dead at scene by paramedic Sidika at 8.35 a.m.

Vehicles to be inspected: PC8218G (Potential Defendant)

IO In-Charge: SIO Clarence Lim

e) Case IAFP-IB-20190405 - Mechanical Inspection of Motor Lorry, GBH4382E (TP/IP/10579/2019)

On 21 February 2019 at about 6 a.m., footage retrieved from the CCTV cameras from the Singtel server building revealed that the Deceased was travelling at a slow speed on an unknown lane when the 1st Defendant came from the rear at a fast speed and collided onto the Deceased and subsequently ran over him. After the collision, the 1st Defendant drove off from the scene. About 3 - 4 minutes after the accident, the 2nd Defendant was travelling on lane 3 of Ang Mo Kio Avenue 1 towards Upper Thomson Rd, when he drove over the Deceased. Due to the accident, the Deceased sustained multiple injuries and was pronounced dead at the scene by paramedic Sgt Nizham at 6.15 a.m.

Vehicles to be inspected: GBH4382E (Accused)

IO In-Charge: SIO Clarence Lim

(FAIT)

f) Case IAFP-IB-20190405 - Mechanical Inspection of Motor Bus, SBS7637T (TP/IP/10579/2019)

On 21 February 2019 at about 6 a.m. Footage retrieved from the CCTV cameras from the Singtel server building revealed that the Deceased was travelling at a slow speed on an unknown lane when the 1st Defendant came from the rear at a fast speed and collided onto the Deceased and subsequently ran over him. After the collision, the 1st Defendant drove off from the scene. About 3 - 4 minutes after the accident, the 2nd Defendant was travelling on lane 3 of Ang Mo Kio Avenue 1 towards Upper Thomson Rd, when he drove over the Deceased. Due to the accident, the Deceased sustained multiple injuries and was pronounced dead at the scene by paramedic Sgt Nizham at 6.15 a.m.

Vehicles to be inspected: SBS7637T (Potential Defendant)

IO In-Charge: SIO Clarence Lim

Pg 12, 17