

ASS. REC. BY:

REF: CS/FCI19008292/kqd3ⁿ²

Special Instruction:

Surveior: Kenneth

ASSIGNMENT (Office)

From (Person): Joanne

of FCI

Date/Time: 10.5.19 9.37a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 5976R

Insured: SHA 7227S

at Workshop m/s Trans-cab Auto

Tel: 62876666

of No 2 Ang Mukio Street 63

Policy No:

Claim No: D19003085 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 9.5.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.5.19

Person Contacted:

Amanda

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 5976R - CC3/ICS17008752/Keb 352 D.O.A - 01/05/2017
	SHA 7227S - CS/FCI19001724/1001322 D.O.A - 17/01/2019
14/5/19 @ 4.55pm	visited to Joanne Yong by email.

ASS. REC. BY:

REF:

1021

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S14C 5976R Yr Regn: 03, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perant Lorry c.c. 1995

Colour:

M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading

575354 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

V11 ABL 15 AUC 281506

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S/Rlm / STD A/Rlm or

Tyre Size:

F: 215/60 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm 6 mm

L/Bal.

mm 6 mm

D.O.A.

9/5/19 D.O.I. 10/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

61 Sm @ 15,500k (Rep to 37786.42, 68'10)

RECEIVED 21 MAY 2019

Date/Time, File Pass to?

11/15/19

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

71
15500

Days Of Repair:

8

Resurvey No. of Trip:

Add Fee:

Site Insp (\$

Interview (\$

Tech Invs (\$

Weekend (\$

Survey Fee:

Transportation

S + RS, SI

Fees

Others

TOTAL

350



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003085MFSH

Date: 14 May 2019

Our Ref: CS/FCI19008292/Kqd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 5976R .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 10/05/2019 at the premises of M/s TRANS-CAB, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>47,886.42</u> .
Revised Estimate Amount	: S\$ <u>19,378.43</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the rear o/s portio.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	09-05-2019	Our Ref No. D19003085MFSH
Accident Date	09-05-2019	Claim Type. Third Party
Insured Vehicle	SHA7227S	Third Party Vehicle. SHC5976R
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	AMANDA TAY	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Friday, 17 May 2019 3:48 PM
To: Shiau Chan (LKKAUTO)
Subject: FW: TP VEHICLE SHC 5976R (DOA: 09/05/2019) -- AAD1905-072
Attachments: image005.wmz; image002.wmz; image004.wmz; SHC5976 EST.pdf

Hi Shiau Chan

We confirmed COR amount \$ 15,500.00 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shiau Chan (LKKAUTO) [<mailto:siewsc@lkkauto.com>]
Sent: Wednesday, 15 May, 2019 11:28 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: RE: TP VEHICLE SHC 5976R (DOA: 09/05/2019) -- AAD1905-072

Dear Wai Yin,

Please refer to the attached of our surveyor's marking.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Wednesday, 15 May 2019 10:44 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: TP VEHICLE SHC 5976R (DOA: 09/05/2019) -- AAD1905-072

Hi Shiau Chan

I can't get your figure le.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 14 May 2019 4:55 PM
To: 'CWS Motor Claims'; assignments; SUR
Cc: 'Joanne Yong Lai fong'
Subject: RE: SURVEY ASSESSMENT - D19003085MFSH/1
Attachments: CSFCI19008292Kqd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SHC 5976R.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 10 May 2019 9:44 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19003085MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 10 May, 2019 9:37 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003085MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHC5976R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	09 May 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002678
Chassis No.:	VF1ABL15AUC281506
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	23 Mar 2015
First Registration Date:	23 Mar 2015
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Mar 2023
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	22 Mar 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,092.00
COE Rebate Amount:	\$24,704.00
Total Rebate Amount:	\$34,077.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 09 May 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5976R**AAD1905-072**

Not Authorized
Clamp @ 15, 500/-
Direct Settlement

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5976R

VF1ABL15AUC281506

RENAULT

LATITUDE

9.5.19

FIRST CAPITAL

23/3/2015

PART**LIST**

1	1	BUMPER COVER REAR	\$	<i>BT/CM</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>CM</i> 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	X
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>DI</i> 135.97	✓
5	1	BUMPER RETAINER RH REAR	\$	<i>DI</i> 44.99	✓
6	1	BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61	✓
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1	BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99	X
9	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	X
10	1	BUMPER BEAM REAR	\$	<i>R</i> 777.52	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>DI</i> 225.95	✓
13	1	BOOT REAR	\$	<i>R</i> 2,872.68	✓
14	1	BOOT FINISHER	\$	<i>Sn</i> 470.06	X
15	1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05	X
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35	X
17	1	BOOT REFLECTOR LAMP RH	\$	<i>CM</i> 493.35	✓
18	1	BOOT BADGE 'RENAULT'	\$	<i>Mc</i> 225.36	—
19	1	BOOT BADGE	\$	<i>Mc</i> 225.36	—
20	1	BOOT STRUT LH	\$	<i>Sn</i> 276.08	} X
21	1	BOOT STRUT RH	\$	<i>Sn</i> 276.08	
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1	BOOT INNER TRIM	\$	<i>Sn</i> 586.45	
25	1	BOOT SWITCH	\$	<i>Sn</i> 168.13	
26	1	BOOT LOCK	\$	<i>R</i> 202.67	
27	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40	}
28	2	LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	
29	2	BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	

Trans-cab Auto Services Pte Ltd

AAD1905-072

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5976R

30	1	FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	X
31	1	FENDER PANEL REAR RH	\$	Bu	3,299.13	✓
32	1	WHEELARCH REAR RH	\$	Sn	543.47	X
33	1	TAILLAMP RH	\$	ngcm	552.55	✓
34	1	TAILLAMP PANEL RH	\$	n	986.70	X
35	1	TAILLAMP LH	\$	Sn	552.55	✓
36	1	TAILLAMP PANEL LH	\$	n	986.70	X
37	1	OUTER PANEL REAR (End Panel)	\$	B	1,471.77	✓
38	1	OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56	X
39	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	n	2,189.88	X
40	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
41	1	EXHAUST REAR P/T	\$	B	7,489.05	✓ 4800SN
42	1	EXHAUST CAP REAR	\$	n	230.49	✓
TOTAL			\$		31,354.89	
10%			\$		3,135.49	
			\$		28,219.40	

Special Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	n	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	n	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	nn	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	n	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	nn	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	nn	24.20	X
12	1	BOOT ADVERTISEMENT STICKER	\$	n	330.00	150SN
13	1	REAR BUMPER ADVERTISEMENT STICKER	\$	n	330.00	100SN
14	1	REAR RIGHT FENDER ADVERTISEMENT STICKER	\$	n	330.00	150SN
15	1	BOOT INNER TRIM CLIP	\$	nn	45.00	X
16	1SET	FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	X
17	1	FENDER INNER TRIM CLIP RH	\$	nn	28.00	X
18	1	TAILLAMP CLIP RH	\$	n	5.00	✓
19	2	REAR WINDSCREEN SEALANT	\$	n	80.00	40SN
20	1	WINDSCREEN MOULDING	\$	n	100.00	✓

Trans-cab Auto Services Pte Ltd**AAD1905-072**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5976R

21	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	<i>305m</i>
21	1	TAILLAMP CLIP LH	\$	<i>na</i>	5.00	X
22	1	Rear right tyre	\$	<i>sm</i>	330.00	X
23	1	Rear right tyre rim	\$	<i>sm</i>	380.00	X
TOTAL			\$		3,087.02	

TOTAL PARTS \$ 31,306.42**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	<i>880l</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>1200l</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>60l</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>60l</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	<i>80l</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} <i>100l</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To check steering geometry and computer wheel alignment	\$	220.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>90l</i>
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	X

Trans-cab Auto Services Pte Ltd

AAD1905-072

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5976R

To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 120/
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X
To Check Electrical Lighting Concerned.	\$	170.00 20/
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00 X
TOTAL	\$	16,580.00
Over All Total	\$	47,886.42

(LUMP SUM) Repair Days

20 DAYS

8 days

LTP Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FC19008292/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7227S	Veh. Inspected	SHC 5976R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003085MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	10/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VF1ABL15AUC281506	Colour	METALLIC WHITE / RED	
Odometer	575354	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	6 mm	
L/H Rear Tyre	215/60 R16	GITI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/05/2019	Inspection Date	10/05/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5976R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BENT / CRACKED	1,108.46	1,108.46
1	BUMPER LOWER REAR	CRACKED	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	DISTORTED	135.97	135.97
1	BUMPER RETAINER RH REAR	DISTORTED	44.99	44.99
1	BUMPER REFLECTOR RH	CRACKED	43.61	43.61
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	DISTORTED	225.95	225.95
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	CRACKED	493.35	493.35
1	BOOT BADGE "RENAULT"	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-

Report Ref No. CS/FCI19008292/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	BUCKLED	3,299.13	3,299.13
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	MTG CRACKED	552.55	552.55
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST CAP REAR	DENTED	230.49	230.49
	LESS 10% DISCOUNT		-2,386.58	-1,247.60
			21,479.24	11,228.43
1	EXHAUST REAR (SN)	BENT	7,489.05	4,800.00
	LESS 10% DISCOUNT		-748.91	-
			6,740.14	4,800.00
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00

Report Ref No. CS/FCI19008292/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT ADVERTISEMENT STICKER (SN)	NECESSARY	330.00	150.00
1	REAR BUMPER ADVERTISEMENT STICKER (SN)	NECESSARY	330.00	100.00
1	REAR RIGHT FENDER ADVERTISEMENT STICKER (SN)	NECESSARY	330.00	150.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NECESSARY	5.00	5.00
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
1	REAR RIGHT TYRE (SN)	SERVICEABLE	330.00	-
1	REAR RIGHT TYRE RIM (SN)	SERVICEABLE	380.00	-
			3,087.02	740.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	880.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR,BOOT HINGE LH,BOOT HINGE RH,BOOT LOCK,BOOT LOCK CATCH,TAILLAMP PANEL RH,TAILLAMP PANEL LH AND SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL).		6,000.00	1,200.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.		170.00	80.00
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	100.00

Report Ref No. CS/FCI19008292/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	90.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
			16,580.00	2,610.00
	GRAND TOTAL		47,886.40	19,378.43
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			15,500.00

Report Ref No. CS/FC119008292/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.