

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19008324/T1pa3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD			Date: 17-07-2020 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 777B	Veh. Inspected	SHB 2304E
	Policy No.	VPX/P1680520	Coverage (\$)	0.00
	Claim No.	S9M01MUC	Excess (\$)	0.00
	Assign From		Assign Date	10/05/2019
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI 140	c.c	1685
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	KMHLB41UMHU097850	Colour	YELLOW
	Odometer	370817	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	WEST LAKE	6 mm
	L/H Front Tyre	205/60 R16	WEST LAKE	6 mm
	R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
	L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	08/05/2019	Inspection Date	10/05/2019
	Survey held at	DING AUTOMOTIVE PTE LTD		
	BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645			
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			