

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 May 2019 Edit Reg		13 May 2019 00:00 Edit Adj Rpt	S\$26,711.00 Edit Estimates	S\$26,711.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LCRF PTE LTD , Co. Reg. No.: 201624597K, Tel: +6599999999									
Main Claimant: BUS-PLUS SERVICES PTE LTD , Co. Reg. No.: 199403524H									
Vehicle Reg. No.:	PC6045B	Date of Loss:	10/04/2018 06:00 - :59 [8 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6019522734SG	Policy/Cover Note No.:	0999994815 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLD1130M	Policy No. (Claimant):	D-II027593MFBP						
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Yogarajah, Jegaparakash - 6419 1758] Jegaparakash.Yogarajah@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 23/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***PC6045B (6019522734SG)**
[SLD1130M]
TP
BUS-PLUS SERVICES PTE LTD
Apr 10 2018 6:00AM
[LCRF PTE LTD]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/05/19 09:27	General View	 Load JPG	☒
2	15/05/19 09:27	General View	 Load JPG	☒
3	15/05/19 09:27	General View	 Load JPG	☒
4	15/05/19 09:27	General View	 Load JPG	☒
5	15/05/19 09:27	General View	 Load JPG	☒
6	15/05/19 09:27	General View	 Load JPG	☒
7	15/05/19 09:27	General View	 Load JPG	☒
8	15/05/19 09:27	General View	 Load JPG	☒
9	15/05/19 09:27	General View	 Load JPG	☒
10	15/05/19 09:27	General View	 Load JPG	☒
11	15/05/19 09:27	General View	 Load JPG	☒
12	15/05/19 09:27	General View	 Load JPG	☒
13	15/05/19 09:27	General View	 Load JPG	☒
14	15/05/19 09:27	General View	 Load JPG	☒
15	15/05/19 09:27	General View	 Load JPG	☒
16	15/05/19 09:27	General View	 Load JPG	☒
17	15/05/19 09:27	General View	 Load JPG	☒
18	15/05/19 09:27	General View	 Load JPG	☒
19	15/05/19 09:27	General View	 Load JPG	☒
20	15/05/19 09:27	General View	 Load JPG	☒
21	15/05/19 09:27	General View	 Load JPG	☒
22	15/05/19 09:27	General View	 Load JPG	☒
23	15/05/19 09:27	General View	 Load JPG	☒
24	15/05/19 09:27	General View	 Load JPG	☒
25	15/05/19 09:27	General View	 Load JPG	☒
26	15/05/19 09:27	General View	 Load JPG	☒
27	15/05/19 09:27	General View	 Load JPG	☒
28	15/05/19 09:27	General View	 Load JPG	☒
29	15/05/19 09:27	General View	 Load JPG	☒
30	15/05/19 09:27	General View	 Load JPG	☒
31	15/05/19 09:27	General View	 Load JPG	☒
32	15/05/19 09:27	General View	 Load JPG	☒
33	15/05/19 09:27	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/05/19 15:32	EMAIL FROM AIG DD 13052019	 Load PDF	
2	13/05/19 15:32	TP GIA REPORT	 Load PDF	
3	14/05/19 19:12	TP ESTIMATE- MARKED.	 Load PDF	
4	19/07/19 15:49	EMAIL TO OI	 Load PDF	
5	30/06/20 16:26	POLICE INVESTIGATION RESULT	 Load PDF	
6	03/07/20 13:27	Email to AIG seek approval to reject TP claim	 Load PDF	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
7	06/07/20 10:02	AIG APPROVAL TO REJECT TP CLAIM		Load PDF
8	06/07/20 10:11	EMAIL TO TP - REJECT TP CLAIM		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	14/05/19 11:43	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/LCR19008410/JKA3S2**Date:** 13/07/2020**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994815
Claimant Vehicle No :	PC6045B	Insured Vehicle No :	SLD1130M
Date of Loss:	10/04/2018	Nature of Claim:	TP
		Claim No:	6019522734SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC6045B		
Make & Model:	MITSUBISHI ROSA, 3.0 D BE641GRMDEB (A)	Engine No:	4P10C58035
Reg. Date:	17/07/2017 (Man. Year: 2017)	Chassis No:	BE641JK30358
Colour:	White	Odometer:	0 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	7.00 R16	Rear Tyre Size:	7.00 R16 (D)
Front Left Side:	Condor 7 mm	Rear Left Side:	Condor 7/7 mm
Front Right Side:	Condor 7 mm	Rear Right Side:	Condor 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,911.00	23,201.00	17,710.00	43.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,540.00	3,510.00	5,030.00	58.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	49,451.00	26,711.00	22,740.00	45.98

INSPECTION

Date of Assignment:	13/05/2019	
Date Inspected:	13/05/2019	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	14.0 days	

Adjuster: ONG HWEE JIE**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/13/2020

Adjuster Report

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$16,302.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Buckled	1,430.00 F	*1,430.00 F
2	2	*FRONT BUMPER BRACKET	Necessary	44.00 F	*44.00 F
3	2	*FRONT BUMPER FOG LAMP ASSY	Cracked	132.00 F	*132.00 F
4	1	*FRONT BUMPER FOG LAMP COVER LH	Cracked	385.00 F	*385.00 F
5	1	*FRONT BUMPER TOWING HOOK LH	Bent	132.00 F	*132.00 F
6	1	*FRONT BUMPER INNER CROSSMEMBER	Bent	418.00 F	*418.00 F
7	1	*FRONT BUMPER RADIATOR GRILLE	Cracked	715.00 F	*715.00 F
8	1	*FRONT BUMPER GRILLE EMBLEM ROSA	Necessary	93.50 F	*93.50 F
9	1	*FRONT HEADLAMP ASSY LH	Cracked	638.00 F	*638.00 F
10	1	*FRONT HEADLAMP BRACKET LH	Buckled	275.00 F	*275.00 F
11	1	*FRONT SIDE LAMP ASSY LH	Missing	60.50 F	*60.50 F
12	1	*FRONT HEADLAMP TOP GARNISH LH	Missing	88.00 F	*88.00 F
13	1	*FRONT PANEL	Buckled	2,420.00 F	*2,420.00 F
14	1	*FRONT PANEL ADVERTISEMENT STICKER	Necessary	440.00 F	*440.00 F
15	1	*FRONT PANEL FUSO STICKER	Necessary	44.00 F	*44.00 F
16	1	*FRONT WIPER ARM	N/s Bent	132.00 F	*66.00 F
17	1	*FRONT WIPER MOTOR	*Check	418.00 F	*- F
18	2	*FRONT WIPER LINK	*Check	1,210.00 F	*- F
19	1	*FRONT WIPER BLADE	N/s Bent	121.00 F	*60.50 F
20	1	*FRONT WIPER INSTRUMENT PANEL	*Check	638.00 F	*- F
21	1	*FRONT WINDSCREEN GLASS	Cracked	1,980.00 F	*1,980.00 F
22	1	*FRONT WINDSCREEN GLASS RUBBER	Necessary	572.00 F	*572.00 F
23	1	*FRONT SIDE MIRROR BRACKET LH	Cracked	627.00 F	*627.00 F
24	1	*FRONT SIDE MIRROR GLASS LH	Missing	132.00 F	*132.00 F
25	1	*FRONT SIDE MIRROR GLASS (ROUND) LH	Missing	71.50 F	*71.50 F
26	1	*FRONT WIPER TANK WITH MOTOR	*Check	165.00 F	*- F
27	1	*FRONT HEADLAMP WIRE HARNESS LH	Not Necessary	330.00 F	*- F
28	1	*FRONT PASSENGER SIDE PANEL LH	Buckled	3,630.00 F	*3,630.00 F
29	1	*FRONT PASSENGER SIDE PANEL SIGNAL LAMP LH	Cracked	242.00 F	*242.00 F
30	1	*FRONT PASSENGER SIDE PANEL ADVERTISEMENT LH	Not Necessary	880.00 F	*- F
31	1	*FRONT PASSENGER SIDE GLASS ASSY LH	Cracked	6,160.00 F	*6,160.00 F
32	1	*FRONT PASSENGER SIDE ONE QUARTER GLASS LH	Cracked	638.00 F	*638.00 F
33	1	*FRONT PASSENGER SIDE ONE QUARTER GLASS SEALANT LH	Necessary	44.00 F	*44.00 F
34	1	*FRONT PASSENGER SIDE SPLASHIELD LH	Cut	253.00 F	*253.00 F
35	1	*FRONT PASSENGER SIDE SPLASHIELD BRACKET LH	Not Necessary	71.50 F	*- F
36	1	*FRONT PASSENGER SIDE INNER AIR PUMP LH	*Check	418.00 F	*- F
37	2	*FRONT PASSENGER SIDE INNER AIR PUMP HOSE LH	*Check	99.00 F	*- F
38	1	*FRONT PASSENGER SIDE PANEL INNER TRIM LH	Deformed	1,320.00 F	*1,320.00 F
39	1	*FRONT DASHBOARD	*Check	3,850.00 F	*- F
40	1	*FRONT A/C BLOWER MOTOR WITH HOUSING	*Check	715.00 F	*- F
41	1	*FRONT A/C HEATER ASSY	*Check	638.00 F	*- F
42	1	*FRONT A/C COOLER COIL WITH HOUSING	*Check	880.00 F	*- F
43	1	*FRONT A/C SECTION PIPE	*Check	275.00 F	*- F
44	1	*FRONT A/C PRESSURE PIPE	*Check	418.00 F	*- F
45	1	*FRONT INTERCOOLER ASSY	*Check	6,050.00 F	*- F
46	2	*FRONT ENGINE MOUNTING	*Check	396.00 F	*- F
47	1	*FRONT GEAR BOX MOUNTING	*Check	132.00 F	*- F
48	1	*FRONT NUMBER PLATE	Deformed	20.00 F	*20.00 F
49	5	*FRONT RADIATOR GRILLE CLIP	Necessary	15.00 F	*15.00 F
50	1	*FRONT IU BRACKET	Necessary	25.00 F	*25.00 F
51	10	*FRONT PASSENGER SIDE SPLASHIELD CLIP LH	Necessary	30.00 F	*30.00 F

F=Franchise part.

Total Parts (\$\$) 40,911.00 23,201.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE ABOVE ITEMS AND REPAIR LH CENTRE & FRT PORTION LH.	New	3,500.00	2,000.00
2	TO RESPRAY ALL AFFECTED AREA.	New	1,600.00	1,000.00
3	TOWING CHARGE.	New	150.00	0.00
4	TO REMOVE / REFIT WINDSCREEN.	New	350.00	260.00
5	TO POLISH AFFECTED AREA.	New	400.00	0.00
6	TO REMOVE AND REFIT ENGINE MOUNTING.	New	350.00	0.00
7	TO REMOVE & REFIX AIR-CON CONDENSER.	New	120.00	0.00
8	TO REMOVE AND REFIX DASHBOARD.	New	350.00	0.00
9	TO REMOVE / REFIT SEAT.	New	400.00	0.00
10	TO CHECK WIRING AND SYSTEM FUNCTION.	New	120.00	50.00
11	TO RESET & PROGRAMME ENGINE.	New	550.00	0.00
12	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER.	New	150.00	150.00
13	TO REMOVE & REFIX SIDE WINDOW GLASS.	New	200.00	50.00
14	TO REMOVE AND REFIT AIRCON BLOWER.	New	300.00	0.00
Gross Labour Cost (\$\$)			8,540.00	3,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >