



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2016 LAMBORGHINI HURACAN LP580-2
XXXXXX (SMA838R)

Date of Loss

4 May 2019

Time of Loss

23.15

Loss Description

SMA838R (INSD) HIT GUARDRAIL

Comment

Workshop Details

Total Rebate Amount

284472

Nett Loss Amount

\$665,528.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion *

20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#	SMA838R	Purchase Date	dd/mm/yyyy
Registration State	SINGAPORE	Registration Date *	27/04/2018
Mileage	7940	Age of Vehicle	1

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2016	2016
Make	LAMBORGHINI HURACAN LP580-2	LAMBORGHII

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	TAY HIN NGAN (ZHENG XINYAN)	
Date of Birth	19 October 1972	dd/mm/yyyy

Model CATEGORY	XXXXXX POLICY INFORMATION	HURACAN LP INFORMATION
Type		
Type of Paint		
Chassis No	ZHWEC2ZF1GLA04755	ZHWEC2ZF1G
Engine No	CSJ005887	CSJ005887
Engine Capacity		5204
Sum Insured	0	0
Market Value	0	950000

CATEGORY Age	FNOL INFORMATION 46	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	26	
Driver License #		
License Type		
License Issue Date		dd/mm/yyyy 
License Expiration Date		dd/mm/yyyy 

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Address	23 MARIGOLD DRIVE, 576425, Singapore	
Address type	Residential	▼
Gender	Male	▼
Marital status	Married	▼
Identification #	S7238383D	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

13/05/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

18000

Young/Inexperienced/
Unnamed Driver
Excess

0

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%		Salvage%	
Discount%		Settlement%	100

Paint Labour/Material Ratio

Paint Labour Ratio	20	Paint Material Ratio	80
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		STORAGE FRAME FRNT	Bent	0	1440.14	No					1440.14	Reviewir
		0	1		WING LF	Dented	0	5896.8	No					5896.8	Reviewir
		0	1		WING RH	Dented	0	5978.7	No					5978.7	Reviewir
		0	1		HEADLIGHT RH	Broken	0	9970.93	No					9970.93	Reviewir
		0	1		HEADLIGHT LF	Cut	0	9970.93	No					9970.93	Reviewir
		0	1		FRONT END	Dented	0	11021.4	No					11021.4	Reviewir
		0	1		BUMPER WITH PARKING SENSOR	Broken	0	9374.4	No					9374.4	Reviewir
		0	1		FRONT SPOILER	Missing	0	532.15	No					532.15	Reviewir
		0	1		FRONT SPOILER RIGHT	Damaged	0	532.15	No					532.15	Reviewir

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		LAMBORGHINI EMBLEM	Cut	0	655.2	No					655.2	Reviewir
		0	1		BONNET FRNT	Dented	0	9266.4	No					9266.4	Reviewir
		0	1		HINGE LF	Bent	0	302.22	No					302.22	Reviewir
		0	1		HINGE RH	Bent	0	302.22	No					302.22	Reviewir
		0	1		ARM	Bent	0	66.98	No					66.98	Reviewir
		0	1		GAS FILLED STRUT	Bent	0	100.96	No					100.96	Reviewir
		0	1		ATTACHMENT BARS LF	Dented	0	86.72	No					86.72	Reviewir
		0	1		ATTACHMENT BARS RH	Dented	0	85.28	No					85.28	Reviewir
		0	1		ARM LF	Serviceable	0	0	No					0	Deny
		0	1		ARM RH	Serviceable	0	0	No					0	Deny
		0	1		BONNET LOCK LOWER PART	Bent	0	131.49	No					131.49	Reviewir
		0	1		CATCH HOOK FRNT	Bent	0	46.22	No					46.22	Reviewir
		0	1		CAP NUT, SELF LOCKING	Serviceable	0	0	No					0	Deny
		0	1		COVER (CENTRE)	Serviceable	0	0	No					0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		COVER RH	Broken	0	452	No					452	Reviewir
		0	1		COVER LH	Broken	0	452	No					452	Reviewir
		0	1		WHEEL HOUSING LINER LH	Damaged	0	352.8	No					352.8	Reviewir
		0	1		WHEEL HOUSING LINER RH	Damaged	0	352.94	No					352.94	Reviewir
		0	1		LAMBORGHINI EMBLEM FRONT	Serviceable	0	0	No					0	Deny
		0	1		LUGGAGE COMPARTMENT TRIM SEAL	Damaged	0	3652.92	No					3652.92	Reviewir
		0	1		SEAL (RUBBER)	Damaged	0	186.03	No					186.03	Reviewir
		0	1		AIRBAG FOR STEERING (RH)	Broken	0	810	No					810	Reviewir
		0	1		AIRBAG UNIT (RH)	Broken	0	2308.5	No					2308.5	Reviewir
		0	1		ADDITIONAL COOLER FOR COOLANT	Necessary	0	1167.66	No					1167.66	Reviewir
		0	1		AIR GUIDE LH	Broken	0	116.78	No					116.78	Reviewir
		0	1		AIR GUIDE RH	Broken	0	106.7	No					106.7	Reviewir
		0	1		COOLER FOR COOLANT (CENTRE)	Dented	0	644.4	No					644.4	Reviewir

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		AIR GUIDE CENTER	Broken	0	112.39	No					112.39	Reviewir
		0	1		AIR GUIDE REAR CENTER	Broken	0	167.58	No					167.58	Reviewir
		0	1		RIVETS AND FASTENERS, GLUE AND SEALERS	Serviceable	0	0	No					0	Deny
		0	1		MOUNTING BAR (RIGHT) FOR BUMPER PROTECTION	Dented	0	110.77	No					110.77	Reviewir
		0	1		FRONT BUMPER BRACKET (CENTER RIGHT)	Broken	0	63	No					63	Reviewir
		0	1		AIR GUIDE (LEFT) FOR RADIATOR	Cut	0	57.6	No					57.6	Reviewir
		0	1		REINFORCEMENT- BRACKET (LEFT)	Missing	0	118.8	No					118.8	Reviewir
		0	1		AIR GUIDE FOR RADIATOR (LEFT)	Broken	0	42.95	No					42.95	Reviewir
		0	1		AIR GUIDE FOR RADIATOR (RIGHT)	Broken	0	42.95	No					42.95	Reviewir
		0	1		AIR GUIDE FOR RADIATOR (LEFT)	Broken	0	70.92	No					70.92	Reviewir
		0	20		SCREW	Necessary	0	1.13	No					22.6	Reviewir

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	10		CLAMP	Necessary	0	1.82	No					18.2	Reviewir
		0	1		BRACKET ARM FOR FRONT BONNET (RIGHT)	Bent	0	75.96	No					75.96	Reviewir
		0	2		CLIP	Necessary	0	18.9	No					37.8	Reviewir
		0	5		COOLANT LIQUID FOR RADIATOR 1.5L (AUDI)	Missing	0	38	No					190	Reviewir
		0	20		NUT	Necessary	0	0.52	No					10.4	Reviewir
		0	10		SCREW	Necessary	0	1.51	No					15.1	Reviewir
		0	20		SCREW	Necessary	0	0.36	No					7.2	Reviewir
		0	4		SCREW	Necessary	0	11.12	No					44.48	Reviewir
		0	10		BOLT	Necessary	0	2.25	No					22.5	Reviewir
		0	1		MOUNTING BAR (LEFT) FOR BUMPER PROTECTION	Dented	0	110.77	No					110.77	Reviewir
		0	1		REINFORCEMENT- BRACKET (RIGHT)	Missing	0	65.05	No					65.05	Reviewir
		0	1		CENTRE MOUNTING BRACKET	Bent	0	89.6	No					89.6	Reviewir
		0	20		CLAMPING CAP NUT M6	Necessary	0	0.99	No					19.8	Reviewir

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	10		EXPANSION RIVET 8.1X13.0	Necessary	0	2.25	No					22.5	Reviewir
		0	20		BOLT	Necessary	0	0.77	No					15.4	Reviewir
		0	2		FRONT AIRBAG SENSOR LP610	Shorted	0	183.58	No					367.16	Reviewir
		0	1		COOLANT HOSE FOR RADIATOR (LEFT)	Missing	0	30.6	No					30.6	Reviewir
		0	2		CAR BATTERY BRACKET	Bent	0	63.54	No					127.08	Reviewir
		0	2		AIRCON CONDENSER	Dented	0	746.46	No					1492.92	Reviewir
		0	2		REFRIGERANT LINE, AIRCON PIPING	Bent	0	288	No					576	Reviewir
		0	1		REFRIGERANT LINE, AIRCON PIPING	Bent	0	288	No					288	Reviewir
		0	1		COVER PLATE SIDE PANEL (RIGHT)	Necessary	0	155.59	No					155.59	Reviewir
		0	1		COVER PLATE SIDE PANEL (LEFT)	Necessary	0	155.59	No					155.59	Reviewir
		0	1		UPPER SIDE MEMBER (LEFT BAR)	Necessary	0	156.31	No					156.31	Reviewir

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		UPPER SIDE MEMBER (RIGHT BAR)	Necessary	0	169.88	No					169.88	Reviewir
		0	1		SEAT BELT (DRIVER)	Shorted	0	2655	No					2655	Reviewir
		0	1		CONNECTING PART (LOWER MEMBER PLATE PANEL)	Dented	0	187.67	No					187.67	Reviewir
		0	1		BRACKET ARM FOR FRONT BONNET (LEFT)	Missing	0	75.96	No					75.96	Reviewir
		0	1		AIR GUIDE (RIGHT)	Broken	0	70.92	No					70.92	Reviewir
		0	1		COVER PLATE FRONT (FOR FRONT CHASSIS)	Serviceable	0	0	No					0	Deny
		0	1		REINFORCEMENT BAR LEFT	Missing	0	118.8	No					118.8	Reviewir
		0	1		AIR GUIDE (RIGHT) FOR RADIATOR	Cut	0	57.6	No					57.6	Reviewir
		0	20		BOLT	Necessary	0	2.25	No					45	Reviewir
		0	1		BRACKET RIGHT	Missing	0	153.47	No					153.47	Reviewir
		0	1		ATTACHEMENT BAR FOR BONNET DAMPER - 2PCS	Damaged	0	86.72	No					86.72	Reviewir

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		HEAD LAMP BRACKETS - 2PCS	Missing	0	85.28	No					85.28	Reviewir
		0	1		STOP BAR FOR HEAD LAMP MOUNT (LEFT)	Bent	0	40.5	No					40.5	Reviewir
		0	1		STOP BAR FOR HEAD LAMP MOUNT (RIGHT)	Serviceable	0	0	No					0	Deny
		0	1		FRONT BUMPER BRACKET (CENTER LEFT)	Broken	0	63	No					63	Reviewir
		0	1		CONTROL UNIT FOR BATTERY CUT OFF SENSOR	Shorted	0	351	No					351	Reviewir
		0	1		ARM / BRACKET FOR BUMPER PROTECTION LEFT	Dented	0	327.17	No					327.17	Reviewir
		0	1		ARM / BRACKET FOR BUMPER PROTECTION RIGHT	Dented	0	279.23	No					279.23	Reviewir
		0	1		UNDER BODY TRIM PANEL (FRONT)	Broken	0	1051.2	No					1051.2	Reviewir
		0	1		UNDER BODY TRIM PANEL (CENTER)	Broken	0	796.28	No					796.28	Reviewir

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		PARTITION TRIM FOR BONNET COMPARTMENT	Broken	0	340.31	No					340.31	Reviewir
		0	2		COVER (CENTER CONSOLE)	Broken	0	192.08	No					384.16	Reviewir
		0	1		HORN WITH BRACKET	Bent	0	157.68	No					157.68	Reviewir
		0	1		WIRE SET HARNESS FOR FRONT SENSORS	Damaged	0	230.72	No					230.72	Reviewir
		0	1		FRONT UNDER BONNET TRIM	Broken	0	358.7	No					358.7	Reviewir
		0	1		DASHBOARD UPPER LP610	Broken	0	11008.4	No					11008.4	Reviewir
		0	1		CAR BATTERY 95AH LP580/LP610	Broken	0	651.45	No					651.45	Reviewir
		0	1		MAIN FUSE BOX LP610	Shorted	0	287.82	No					287.82	Reviewir
		0	1		TOWING HOOK COVER (LEFT)	Missing	0	187.63	No					187.63	Reviewir
		0	1		SEAT BELT (PASSENGER)	Shorted	0	2389.5	No					2389.5	Reviewir
		0	1		HOSE CLAMP	Necessary	0	3	No					3	Reviewir
		0	4		FRT PARKING SENSOR LP580	Shorted	0	217.88	No					871.52	Reviewir

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	20		HEX SOCKET	Necessary	0	0.79	No					15.8	Reviewir
		0	1		TOWING HOOK COVER (RIGHT)	Serviceable	0	0	No					0	Deny
		0	1		FRONT WINDSCREEN GLASS	Damaged	0	8900	No					8900	Reviewir
		0	1		WINDSCREEN GLASS SEALANT AND GASKET	Serviceable	0	0	No					0	Deny
		0	1		LICENCE PLATE BRACKET LP580	Missing	0	67.59	No					67.59	Reviewir
		0	1		NEW PLATE SMA838R	Broken	0	40	No					40	Reviewir

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
		0		DISMANTLE, RE FITTING AND REPAIR / KNOCKING	0	9600	0	0	Reviewing	
		0		RESPRAY FRONT BUMPER AND FENDER AND SPOILER	0	4800	0	0	Reviewing	
		0		LABOUR FOR WINDSCREEN	0	500	0	0	Reviewing	

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	DAYS OF REPAIR : 12 DAYS	Reviewing	0		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount	\$0.00			Adjusted Claim Amount	\$110,676.55		
CATEGORY	ESTIMATE	ADJUSTED					
Spare Parts	\$0.00	\$113,776.55					
Labour	\$0.00	\$14,900.00					
Excess		-\$18,000.00					

Submit for Review