

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: FWD	DATE	: 13/05/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: GBJ2744Y		
MODEL	: TOYOTA HIACE		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 10-May-19
		TIME	: 15:45HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>dent</i>	1	\$ 2,115.00	\$ 2,115.00 2072
2	TAILGATE LOGO <i>new</i>	1	\$ 68.00	\$ 68.00
3	TAILGATE HIACE EMBLEM <i>new</i>	1	\$ 50.00	\$ 50.00
4	TAILGATE MAX WEIGHT STICKER <i>new</i>	1	\$ 55.00	\$ 55.00
5	TAILGATE WEATHERSTRIP <i>cut</i>	1	\$ 380.00	\$ 380.00
6	TAILGATE INNER LOCK <i>Dented</i>	1	\$ 270.00	\$ 270.00
7	TAILGATE LOWER LOCK <i>new</i>	1	\$ 116.30	\$ 116.30
8	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 190.00	\$ 190.00
9	REAR BUMPER <i>Dented</i>	1	\$ 580.00	\$ 580.00
10	REAR BUMPER STEP PANEL <i>Best</i>	1	\$ 410.00	\$ 410.00 235
11	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 78.60	\$ 157.20
12	REAR FENDER AIR VENT LH <i>new Dented</i>	1	\$ 90.00	\$ 90.00
13	TAIL LAMP <i>LH cracked</i>	2	\$ 355.30	\$ 710.60 353.30
14	TAILLAMP LOWER GARNISH <i>Dented LH</i>	2	\$ 122.20	\$ 244.40 122.20
15	TAILLAMP LOWER GARNISH RETAINER <i>new</i>	2	\$ 45.00	\$ 90.00
16	REAR END PANEL (INNER) <i>Dented</i>	1	\$ 630.00	\$ 630.00
17	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 590.30	\$ 590.30

TOTAL PRICE \$ 6,746.80

5843
4382.25

LESS 25% \$ 1,686.70
 SUB TOTAL PRICE \$ 5,060.10

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
3	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
4	STICKER 70KM/H <i>new</i>	1	\$ 50.00	\$ 50.00
5	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
6	REAR END PANEL (INNER) SEALANT <i>3 new</i>	1	\$ 60.00	\$ 60.00
7	REAR END PANEL (OUTER) SEALANT	1	\$ 60.00	\$ 60.00
8	REVERSE SENSOR <i>2 new</i>	1	\$ 220.00	\$ 220.00

365 TOTAL \$ 540.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING AND REPLACE PARTS	\$ 1,400.00	<i>900</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	<i>1000</i>	
3	TUFF COAT	\$ 150.00	<i>60</i>	
4	WIRNING, BULB CHECKING	\$ 80.00	<i>30</i>	
5	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 160.00	<i>120</i>	
6	TRANSFER TAILGATE MECHAISM	\$ 120.00	<i>80</i>	
7	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	<i>50</i>	

2240

TOTAL \$3,390.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,600.10
 TOTAL LABOUR COST : \$ 3,390.00
 TOTAL REPAIR COST : \$ 8,990.10

**APPROVED DETAILS
 SURVEYOR**

LKK Auto Consultants hence notify the Repaired of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian Lj *total: 6687.25*
14/05/19 *4/5: 5350*
OT Pays.

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :