Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19008503/GEA3Q2

Date: 20/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 1800030750 Policy No: Claimant SLQ2574R Insured Vehicle No: SLZ6362L Vehicle No:

Date of Loss: 09/05/2019 ΤP Nature of Claim: Claim No: 7658879067SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLQ2574R Reg No:

BMW 216D, 1.5 D GRAN TOURER LED NAV 7 Make & Model: Engine No:

33139586B37C15A SEATER (A)

WBA2E320205B45150 Reg. Date: 05/07/2016 (Man. Year: 2016) Chassis No:

Colour: Black Odometer: 97658 km

Engine Capacity: 1496 cc Market Value/New Car N/A

Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm Front Right Side: Rear Right Side: Toyo 6 mm Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,913.90	2,768.20	145.70	5.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,130.00	720.00	38.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,763.90	3,898.20	865.70	18.17
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	4,763.90	3,100.00	1,663.90	34.93
+ GST 7.00/7.00% (S\$)	333.47	217.00	116.47	34.93
Nett Amount (S\$)	5,097.37	3,317.00	1,780.37	34.93
Global Sum S	Global Sum Settlement (S\$)			

INSPECTION

Date of Assignment: 13/05/2019

Supreme Auto Service Pte Ltd (HQ) Date Inspected: 16/05/2019 Inspected At:

176 Sin Ming Drive #02-01, Sin Ming

Autocare

Singapore 575721

Estimated Period of Repair: 4.0 days Adjuster Report Page 2 of 4

Adjuster: XING GUO QIANG Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*REAR BOOT LID	Buckled	1,204.35 F	*1,204.35 FL		
2	1		*REAR BOOT LOCK (NPA)	Not Necessary	0.00 F	*- FL		
3	1		*REAR BOOT LAMP	Cut	485.00 F	*485.00 FL		
4	1		*REAR BUMPER	Deformed	1,045.45 F	*1,045.45 FL		
5	1		*REAR BUMPER REINFORCEMENT (NPA)	Not Necessary	0.00 F	*- FL		
6	1		*REAR BUMPER TOWING COVER	Cut	42.85 F	*42.85 FL		
7	1		*REAR BUMPER SUPPORT BRACKET (NPA)	Not Necessary	0.00 F	*- FL		
8	1		*REAR BUMPER SIDE BRACKET (NPA)	Not Necessary	0.00 F	*-FL		
9	1		*REAR BUMPER REFLECTOR (NPA)	Not Necessary	0.00 F	*- FL		
10	1		*REAR BUMPER CHROME MOULDING	Cracked	108.40 F	*108.40 FL		
11	1		*REAR BUMPER BEAM (NPA)	Not Necessary	0.00 F	*- FL		
12	1		*SET WINDSCREEN GLASS SEALANT	Necessary	27.85 F	*27.85 FL		
13	4		*REVERSE SENSOR (NPA)	Not Necessary	0.00 F	*- FL		
F=Fra	F=Franchise part. L=ListItemDisc.							
				Sub Total (S\$)	2,913.90	2,913.90		
			- List Item Discount on L Items	s 0.00/5.00% (S\$)	0.00	145.70		
				Total Parts (S\$)	2,913.90	2,768.20		
	Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE PANEL BEAT AND ALIGN THE NECESSARY AFFECTED AREAS	New	700.00	400.00
2	TO CHECK WIRING SYSTEM	New	30.00	30.00
3	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	50.00	0.00
4	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	800.00	500.00
5	TO INSTALL REVERSE SENSORS	New	50.00	40.00
6	TO REMOVE REAR WINDSCREEN GLASS (ES) TO ENABLE REPAIR	New	120.00	100.00
7	TO TRANSFER REAR BOOT LID ACCESSORIES	New	100.00	60.00
	Gross Labour Cost (S\$)		1,850.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >