

### **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## **TAX INVOICE**

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00

SPRINGLEAF TOWER SINGAPORE 079909

INV No. AC2003564

INV Date 29/04/2020

Reference CC6/CTI19008516/Kda3n2

Code CT



Vehicle No. SKL 8208Y

Insured Veh. SJV 2522M

Claim No. SNM19D202108C02/2

Policy No. DMPCSN3010071904

Accident Date 08/05/2019

Inspection Date 13/05/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

HYN



# **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile								
CHIN	A TAIPING INSUI	NG INSURANCE (S) PTE LTD Ref: CC6/CTI19008516/Kda3n2						
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date: 29-04-2020 Code: CTI						
1.	1. Policy Particulars :- THIRD PARTY CLAIM							
	Insured Veh.	SJV 2522M	Veh. Inspected	SKL 8208Y				
	Policy No.	DMPCSN3010071904	Coverage (\$)	0.00				
	Claim No.	SNM19D202108C02/2	Excess (\$)	0.00				
	Assign From		Assign Date	13/05/2019				
2.		Vehicle Partic	culars & Condition					
	Make & Model	MERCEDES S300L AMG (A)	c.c	2997				
	Engine No.	HIDDEN	Year of Reg.	2013				
	Chassis No.	WDD2211542A527997	Colour	METALLIC BLACK				
	Odometer	52953	Steering	IN ORDER				
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM				
	General	GOOD						
3.		Condition	ons of Tyres					
		Size	Make	Balance				
	R/H Front Tyre	255/45 R18	MICHELIN	5 mm				
	L/H Front Tyre	255/45 R18	MICHELIN	5 mm				
	R/H Rear Tyre	255/45 R18	MICHELIN	6 mm				
	L/H Rear Tyre	255/45 R18	MICHELIN	6 mm				
4.		Description	on of Damages					
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR N/S PORTION.					
	DAMAGES SEE D	ETAILS.						
5.		General	Information					
	Accident Date	08/05/2019	Inspection Date	13/05/2019				
	Survey held at	CITY AUTO PTE LTD						
		BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.						
5a.		Re	emarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							
5b.	Estimate Days of Repair							
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days							



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 8208Y

(TO ITS PRE-ACCIDENT CONDITION)

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	2,520.00	2,520.00
1	REAR BUMPER LOWER	DISTORTED	580.00	580.00
1	REAR BUMPER SPONGE	SERVICEABLE	245.00	-
1	REAR BUMPER REINFORCEMENT	BENT	670.00	670.00
12	REAR BUMPER CLIPS @\$4.50	NECESSARY	54.00	54.00
1	LH EXHAUST DIP	SERVICEABLE	115.00	-
4	PARKING SENSOR @\$270.00	CRACKED (1 PC ONLY)	1,080.00	270.00
	LESS 10% DISCOUNT		-526.40	-409.40
			4,737.60	3,684.60
	<u>LABOUR</u>			
	TO CHECK AND RE-WIRING OF PARKING SENSOR .		45.00	45.00
	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS.		450.00	280.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		650.00	300.00
			1,145.00	625.00
	GRAND TOTAL		5,882.60	4,309.60
	RECOMMENDED COST OF LUMP SUM REPAIRS			3,450.00

Report Ref No. CC6/CTI19008516/Kda3n2

KONG SENG CHEONG

**Licensed Appraiser**