



華豐私人有限公司  
**HUA HONG PRIVATE LIMITED**

Blk 4, No.393-H Yew Tee Industrial Estate, Woodlands Road, Singapore 678016  
 Tel: (65) 6760 8815 / 6760 8539 Fax: (65) 6765 4915 Email: huahong@singnet.com.sg

INSURER: **FWD Singapore Pte. Ltd. (HQ)**

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	HHFWDCLAIMS19-05
Policy No:	PNPV2018-00012332	Date of Loss:	10/05/2019
Vehicle Reg. No.:	<b>SKP8804E</b>	Driveable?	
Driver Age/Info:	38 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LYE MEE FONG	Contact No:	+6591776680
Driver:	CHANG KIAN BAO		
Make/Model:	TOYOTA WISH, 1.8 X CVT (A)	Vehicle Reg. Date:	17/10/2014
Vehicle Colour:	BLACK		
Engine No:	2ZR1398172	Chassis No:	ZGE206014629
Odometer:	0 KM		
Paint Type:			
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	AS PER SKETCH PLAN		
Remarks:	VEHICLE IN OUR PREMISE, KINDLY ARRANGE FOR SURVEY. ANY ENQUIRY, PLEASE CONTACT US @ 6661 9688.		
Present Location:	HUA HONG PTE LTD (SUNGEI KADUT)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	4,418.00
Miscellaneous Items	35.00
Labour	2,220.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>6,673.00</b>
<b>+ GST 7.00% (\$\$)</b>	<b>467.11</b>
<b>Nett Amount (\$\$)</b>	<b>7,140.11</b>

This claim is handled by: **YVONNE TOH**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS**

**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 May 2019)  
 Parts: M1-MPV TOYOTA WISH 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Hua Hong Pte Ltd/SKP8804E/14/05/2019 15:12  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front Bumper DEF ✓	0.00	0.00	*200.00 F
2	10		*Front Bumper Clip nec ✓	0.00	0.00	*15.00 F
3	2		*Front Bumper Retainer (LH/RH) nec ✓	0.00	0.00	*50.00 F
4	1		*Front Bumper Foam CRA ✓	0.00	0.00	*45.00 F
5	1		*Front Reinforcement ?	0.00	0.00	*95.00 F
6	1		*Front Grille CRA ✓	0.00	0.00	*160.00 F
7	10		*Front Grille Clip nec ✓	0.00	0.00	*15.00 F
8	1		*Emblem nec ✓	0.00	0.00	*28.00 F
9	1		*Front Support Panel (Complete) ?	0.00	0.00	*450.00 F
10	1		*Front Brace Panel ?	0.00	0.00	*45.00 F
11	1		*Bonnet BUC ✓	0.00	0.00	*280.00 F
12	1		*Bonnet Lock Jam ✓	0.00	0.00	*40.00 F
13	2		*Bonnet Hinge (LH/RH) BT ✓	0.00	0.00	*60.00 F
14	1		*Bonnet Insulator DEF ✓	0.00	0.00	*145.00 F
15	10		*Bonnet Insulator Clip nec ✓	0.00	0.00	*15.00 F
16	1		*Bonnet Seal nec ✓	0.00	0.00	*20.00 F
17	2		*Head Lamp (LH/RH) ?	0.00	0.00	*480.00 F
18	2		*Front Fender (LH/RH) BUC-RH ✓	0.00	0.00	*480.00 F
19	2		*Front Inner Shield (LH/RH) nxx	0.00	0.00	*140.00 F
20	20		*Front Inner Shield Clip (LH/RH) nxx	0.00	0.00	*30.00 F
21	1		*Radiator Top Garnish ?	0.00	0.00	*45.00 F
22	10		*Radiator Top Garnish Clip ?	0.00	0.00	*15.00 F
23	2		*Radiator Side Air Guide (LH/RH) ?	0.00	0.00	*50.00 F
24	1		*Radiator ?	0.00	0.00	*420.00 F
25	1		*Radiator Shroud Top Cover ?	0.00	0.00	*35.00 F
26	1		*Radiator Shroud ?	0.00	0.00	*85.00 F
27	2		*Radiator Fan Motor (LH/RH) ?	0.00	0.00	*390.00 F
28	1		*Radiator Fan Blade (LH) ?	0.00	0.00	*75.00 F
29	1		*Radiator Fan Blade (RH) ?	0.00	0.00	*60.00 F
30	1		*Aircon Condensor ?	0.00	0.00	*450.00 F

F=Franchise part.

**Total Parts (S\$) 4,418.00**

Hua Hong Pte Ltd/SKP8804E/14/05/2019 15:12. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	Front Number Plate <i>nm X</i>	35.00
Sub Total (S\$)			35.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	To dismantle, cut & weld front panel, change front bumper, bonnet, front LH/RH head lamp, front reinforcement, front LH/RH fender, knocking & pull straight front chassis frame and all area affected by accident.	New	1,100.00 <i>900</i>
2	To perform wire checking.	New	20.00 ✓
3	To dismantle & refit radiator, aircon condensor and top up aircon gas.	New	100.00 ?
4	To spray front bumper, bonnet, front reinforcement, front panel, front LH/RH fender and front RH door.	New	1,000.00 <i>800</i>
Gross Labour Cost (S\$)			2,220.00

Hua Hong Pte Ltd/SKP8804E/14/05/2019 15:12. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**LKK Auto Consultants** hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Hwee Jie - Lkk*  
*15/5/19*  
*P/P 5 days.*  
*Not Authorise*  
*Excess - \$600*  
