



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 8493Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER-FACE,REAR (CONSISTENT)	BUCKLED	594.00	594.00
1	BACK BEAM COMPLETE-REAR (CONSISTENT)	SERVICEABLE	396.00	-
1	BRACKET-REAR BUMPER CORNER,RIGHT (CONSISTENT)	SERVICEABLE	23.40	-
1	BRACKET-REAR BUMPER CORNER,LEFT (CONSISTENT)	SERVICEABLE	23.40	-
1	BRACKET-REAR BUMPER SIDE-RIGHT (CONSISTENT)	NOT NECESSARY	36.00	-
1	BRACKET-REAR BUMPER SIDE-LEFT (CONSISTENT)	NOT NECESSARY	36.00	-
1	COVER-REAR BUMPER (CONSISTENT)	NOT NECESSARY	10.80	-
1	COVER-REAR BUMPER (CONSISTENT)	NOT NECESSARY	7.20	-
	LESS 20% DISCOUNT		-	-118.80
			1,126.80	475.20
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (CONSISTENT)(SN)	NOT NECESSARY	100.00	-
1	REVERSE SENSOR-2 EYES (CONSISTENT)(SN)	SERVICEABLE	300.00	-
			400.00	-
	<u>LABOUR</u>			
	REMOVE/REPLACE REAR BUMPER & END PANEL.		2,240.00	560.00
	RESPRAY REAR BUMPER & END PANEL.		1,680.00	420.00
			3,920.00	980.00
	GRAND TOTAL		5,446.80	1,455.20
	RECOMMENDED COST OF REPAIRS			1,455.20

Report Ref No. CC4/ASM19008533/Kbs3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.