

22/03/2011

ASS. REC. BY:

REF:

C8/FCI/19008537/Kgd3

12

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time: 9.45am @ 14/5/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 3222L

Insured:

SH 9046S

at Workshop m/s

Chuan Ho Auto

Tel:

9069 1985

of

160 Bin Ming Drive # 07-09

Policy No:

Claim No:

D19002940 MP44

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/09/2019

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

11.49am @ 14/5/19

Person Contacted:

shwin

Vehicle IN / OUT

Date/Time

Action/Instruction

Estimate

✓

SKQ 3222L - C8/AIG/6428 387 / 7/19h 3d1

DOA: 3/5/2016

SH 9046S - C8/FCI/8011945/Ntd 3g'd

DOA: 27/6/2018

06/6/19 @ 2.49pm revised to Karen by email.

17/6 V/Lr 8235d Cabins (Red # 7454.80, 76%)

(Red # 7047, 75%)

ASSIGNMENT

From: _____ Date: 36. 2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKQ 3222L

at Workshop m/s Chuan HO AUTO
of 160 sin ming Drive #07-09

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: After 12.00 p.m

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 10410

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

rup

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKQ 3222L Yr Regn: 10, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: To Veillon C.C. 2362

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 175287 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AHNH 20. 8339186

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / RIM or

Tyre Size: F: _____

R: 245/408R1P

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 30/4/19

Rear

R/Bal. 5 mm

L/Bal. 5 mm

D.O.I. 31/6/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 17 JUN 2019

Date/Time, File Pass to?

1) 17/6 14:50

Date/Time, File Return to?

2) _____

☐ : Preli. Report☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: 4P

Lump Sum / I.B.I: (\$ 2350)

170
50
50+50
15
335



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002940MFSH

Date: 06 June 2019

Our Ref: CS/FCI19008537/Kqd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKQ 3222L .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/06/2019 at the premises of M/s CHUAN HO AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>9,804.80</u> .
Revised Estimate Amount	: S\$ <u>2,488.00</u> .
"Check" Items Amount	: S\$ <u>512.25</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear body.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	03-05-2019	Our Ref No. D19002940MFSH
Accident Date	30-04-2019	Claim Type. Third Party
Insured Vehicle	SH9046S	Third Party Vehicle. SKQ3222L
Survey Location	160 SIN MING DRIVE, #07-09 SIN MING DRIVE	
Contact Person.	SHARIN	
Contact No.	0/ 90691985	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUAN HO AUTO SERVICE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 6 June 2019 2:49 PM
To: CWS Motor Claims; Admin-D (LKKAUTO)
Cc: Karen Tan
Subject: RE: SURVEY ASSESSMENT - D19002940MFSH/1
Attachments: CSFCI19008537Kqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SKQ 3222L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Tuesday, 21 May 2019 11:09 AM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: Karen Tan <karentan@msfirstcapital.com.sg>; CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19002940MFSH/1

Dear Sir,

Please find below mail from third party and kindly do the needful.

Thank you.

Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited

From: CHUAN HO AUTO SERVICE [<mailto:chuanhoautoservice@gmail.com>]
Sent: Tuesday, May 21, 2019 7:41 AM
To: CWS Motor Claims
Subject: Re: OUR REF (D19002940MFSH) SKQ 3222 L / SH 9046 S ON 30/04/2019

Hi,

Please provide us the survey firm to contact for survey.

Thank you.

CHUAN HO AUTO SERVICE

SIN MING AUTO CITY

160 SIN MING DRIVE #07-09

SINGAPORE 575722

Not Authorised
 11 Rm 823504
 Murray Allen Pains

Vehicle & Document Information

ESTIMATE : SKQ 3222 L

9 days

Date: 03/06/2019

Vehicle No: SKQ 3222 L

Make/Model: TOYOTA VELLFIRE

S/N	Description	Qty	Repairer's Est	Revised Est
1	REAR BOOTLID	1	\$ 1,877.00	\$ 1,877.00 X
2	REAR BUMPER 137P	1	\$ 1,539.00	\$ 1,539.00 ✓
3	REAR TAIL LAMPS RH (ON BOOTLID)	1	\$ 437.00	\$ 437.00 X
4	REAR TAIL LAMPS LH (ON BOOTLID)	1	\$ 437.00	\$ 437.00 X
5	REAR BOOTLID CHROME GARNISH	1	\$ 1,387.00	\$ 1,387.00 X
6	REAR END PANEL	1	\$ 683.00	\$ 683.00 X
7	REAR BUMPER BRACKET RH	1	\$ 107.00	\$ 107.00 X
8	REAR BUMPER BRACKET LH	1	\$ 107.00	\$ 107.00 X
9	REAR BOOTLID LOCK	1	\$ 453.00	\$ 453.00 X
10	REAR REFLECTOR RH	1	\$ 93.00	\$ 93.00 X
11	REAR REFLECTOR LH	10	\$ 93.00	\$ 93.00 X
12	REAR BUMPER SENSORS	1	\$ 360.00	\$ 360.00 2000
13	REAR BUMPER DIFFUSER	1	\$ 358.00	\$ 358.00 X
14	REAR BUMPER TOP CHROME	1	\$ 225.00	\$ 225.00 ✓

Total : \$ 8,156.00

-25% \$ 1,631.20

Parts Total : \$ 6,117 6,524.80

1	ANTIRUST PROOFING, GALVANISING SPOT WIELD	\$ 200.00 X
1	TO CHECK LIGHTING, WIRING & FUSES	\$ 280.00
1	LABOUR TO DISMANTLE, REPAIR AND REPLACE PARTS	\$ 1,000.00
1	LABOUR TO REMOVE AND REFIT, TRANSFER REAR WINSCREEN	\$ 300.00 X
1	TO PUTTY, PRIMER, RE-SPRAY REAR BOOTLID INNER, REAR BOOTLID OUTER, REAR BUMPER AND REAR DIFFUSER	\$ 1,500.00

Labour Total : \$ 3,280.00

Parts Total : \$ 6,524.80

Total : \$ 9,397 9,804.80

-20% \$ 1,960.96

Grand Total : \$ 7,843.84

Lump Sum : \$ 7,800.00

CHUAN HO AUTO SERVICE



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19008537/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-06-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9046S	Veh. Inspected	SKQ 3222L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002940MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	14/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VELLFIRE (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	ANH208339146	Colour	METALLIC BLACK	
Odometer	175287	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 ZR 19	MICHELIN	5 mm	
L/H Front Tyre	245/40 ZR 19	MICHELIN	5 mm	
R/H Rear Tyre	245/40 ZR 19	MICHELIN	5 mm	
L/H Rear Tyre	245/40 ZR 19	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/04/2019	Inspection Date	03/06/2019	
Survey held at	160 SIN MING DRIVE# 07-09			
Repairer	CHUAN HO AUTO SERVICE			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 3222L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOTLID	TO REPAIR SEE LABOUR	1,877.00	-
1	REAR BUMPER	BUCKLED	1,539.00	1,379.00
1	REAR TAILS LAMPS RH (ON BOOTLID)	SERVICEABLE	437.00	-
1	REAR TAILS LAMPS LH (ON BOOTLID)	SERVICEABLE	437.00	-
1	REAR BOOTLID CHROME GARNISH	SERVICEABLE	1,387.00	-
1	REAR END PANEL	BENT	683.00	683.00
1	REAR BUMPER BRACKET RH	TO REPAIR SEE LABOUR	107.00	-
1	REAR BUMPER BRACKET LH	TO REPAIR SEE LABOUR	107.00	-
1	REAR BOOTLID LOCK	TO REPAIR SEE LABOUR	453.00	-
1	REAR REFLECTOR RH	SERVICEABLE	93.00	-
1	REAR REFLECTOR LH	SERVICEABLE	93.00	-
1	REAR BUMPER DIFFUSER	TO REPAIR SEE LABOUR	358.00	-
1	REAR BUMPER TOP CHROME	DENTED	225.00	225.00
	LESS 25% DISCOUNT		-1,949.00	-571.75
			5,847.00	1,715.25
1	REAR BUMPER SENSORS (SN)	SCRATCHED	360.00	200.00
	LESS 25% DISCOUNT		-90.00	-
			270.00	200.00
LABOUR				
	ANTIRUST PROOFING, GALVANISING SPOT WIELD.	NOT NECESSARY	200.00	-
	TO CHECK LIGHTING, WIRING & FUSES.		280.00	15.00
	LABOUR TO DISMANTLE, REPAIR AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF REAR BOOTLID, REAR BUMPER BRACKET RH, REAR BUMPER BRACKET LH, REAR BOOTLID LOCK AND REAR BUMPER DIFFUSER.		1,000.00	500.00
	LABOUR TO REMOVE AND REFIT, TRANSFER REAR WINDSCREEN.	NOT NECESSARY	300.00	-

Report Ref No. CS/FCI19008537/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY, PRIMER, RE-SPRAY REAR BOOTLID INNER, REAR BOOTLID OUTER, REAR BUMPER AND REAR DIFFUSER.		1,500.00	550.00
			3,280.00	1,065.00
GRAND TOTAL			9,397.00	2,980.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,350.00

Report Ref No. CS/FCI19008537/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.