

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pang Xiu Shi

Date: 16 May 2019

Preliminary Advice

Vehicle No	: GBB6185B	Accident Date	: 03/05/2019
Make	: TOYOTA DYNA 1.5T	Policy No.	: 28677599MKC
Assignment Date	: 15/05/2019	Excess	: S\$750.00
Date of Inspection	: 15/05/2019	Est. Duration of Repair	: 14 days
Inspection At	: Hup Hup Workshop Pte Ltd (HQ) 27-A Jurong Port Rd, #01-29 Singapore 619101		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,669.27
Revised Amount	:S\$	17,111.92
Check Items (Estimated)	:S\$	5,081.40
Total	:S\$	22,193.32
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	8,000.00
COE / PARF Rebate	:S\$	520.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,480.00

Remarks

- () The vehicle is economical/not economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.
- (X) Remarks : We are still pending repair cost from repairer.