

Surveyor

REF:

CS/19008597/Cyd392

Special Instruction:

ASSIGNMENT (Office)

From (Person): Lalitha

of

(N)

Date/Time:

3/4/2019

Estimated Cost:

Bill to:

Third Parties:

Claimant:

Surveyor:

Workshop:

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No:

SKB 6922J

Insured:

8W5738X

at Workshop m/s

Tel:

of

Policy No:

Claim No:

MC20192030

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/1/2019

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time:

Confirmed with

Final Fig

days (Red \$ / %; Original days)

Date/Time:

15/5/19

Submit Final Fig

2700

5 days (Red \$ 1900 / 41 %; Original 5 days)

Date/Time

Action/Instruction

Send soft copy to Lalitha - to

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 16 MAY 2019

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/

Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date:

250

1) Date/Time

16/5/19

File Pass to

Amir

2) Date/Time

File Return to

3) Date/Time

File Pass to

4) Date/Time

File Return to

5) Date/Time

File Pass to

6) Date/Time

File Return to

Celine Fong (LKKAUTO)

From: KKLau
Sent: Wednesday, 3 April 2019 6:13 PM
To: Celine Fong (LKKAUTO); Bryan Ang (LKKAUTO)
Cc: Olivia Lau (LKKAUTO)
Subject: Fwd: MC2019/2030
Attachments: SKB6922J.PDF; SLP5738X.PDF; MC20192030.PDF; photos.pdf

Hi Celine, Confidential from Lalitha. Please print all. Thank you KKLau

Get [Outlook for iOS](#)

From: Lalitha Krishnan - III <lalitha@iii.com.sg>
Sent: Wednesday, April 3, 2019 2:40 PM
To: KKLau
Cc: Gabriel Wee; Mekavathanan Sarangapani
Subject: FW: MC2019/2030

URGENT

Dear Lau,

We spoke on above matter.

Kindly check on the recommendation of the surveyor and let us know if same is in order.

Best Regards

Lalitha Krishnan

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

DID: 6347 6139 Fax: 6224 4174



This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be

intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

VEHICLE DAMAGE INSPECTION REPORT

Our File No:
Date: 12/02/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	M496916
Claimant Vehicle No :	SKB6922J	Insured Vehicle No :	SLP5738X
Date of Loss:	23/01/2019	Nature of Claim:	TP
		Claim No:	MC20192030

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB6922J	Engine No:	1NZY299958
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305233358
Reg. Date:	22/06/2011 (Man. Year: 2011)	Odometer:	162544 km
Colour:	White		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,526.77	4,012.47	1,514.30	27.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,440.00	990.00	450.00	31.25
Paintwork Labour	1,100.00	800.00	300.00	27.27
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,066.77	5,802.47	2,264.30	28.07
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	8,066.77	4,600.00	3,466.77	42.98
+ GST 7.00/7.00% (S\$)	564.67	322.00	242.67	42.98
Nett Amount (S\$)	8,631.44	4,922.00	3,709.44	42.98

INSPECTION

Date of Assignment: 24/01/2019

Date Inspected: 25/01/2019 Inspected At:

Estimated Period of Repair: 5.0 days

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Feb 2019)
 Parts: 143 TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	dented/distorted	817.30 FL	*817.30 FL
2	1		*REAR BOOT LID LOGO EMBLEM	necessary	56.70 FL	*56.70 FL
3	1		*REAR BOOTLID HINGES L/R	bent/repair	179.40 FL	Repair
4	1		*REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R	refit	52.80 FL	Refit
5	1		*REAR BOOTLID MECHANISM LOCK	bent	182.25 FL	*182.25 FL
6	1		*REAR BOOTLID WEATHER STRIP	bent	165.60 FL	*165.60 FL
7	1		*REAR BUMPER	dented	677.85 FL	*677.85 FL
8	1		*REAR BUMPER REFLECTOR L/R	refit	230.60 FL	Refit
9	1		*REAR BUMPER SIDE BRACKET L/R	cracked	264.50 FL	*264.50 FL
10	1		*REAR BUMPER SIDE RETAINER L/R	cracked	282.90 FL	*282.90 FL
11	1		*REAR END PANEL	dented	666.00 FL	*666.00 FL
12	1		*REAR END PANEL INNER TOP GARNISH	deformed	191.40 FL	*191.40 FL
13	1		*REAR EXHAUST GASKET	not necessary	56.40 FL	See Remarks
14	1		*REAR EXHAUST RUBBER MOUNTING X 2 PCS	not necessary	96.80 FL	See Remarks
15	1		*REAR EXHAUST SILENCER BOX	bent/repair	596.40 FL	Repair
16	1		*REAR FLOOR PANEL TOOL BOX SPONGE TRAY LH	cracked	285.30 FL	*285.30 FL
17	1		*REAR FLOOR PANEL TOOL BOX SPONGE RH	cracked	285.30 FL	*285.30 FL
18	1		*REAR FLOOR PANEL TOP BOARD COVER	dented/cracked	358.50 FL	*358.50 FL
19	1		*REAR TAILLAMP INNER BLACK RUBBER GASKET L/R	torn/necessary	87.90 FL	*87.90 FL
20	1		*REAR TAILLAMP L/R	grazed	721.80 FL	*721.80 FL
21	1		*REAR BOOTLID NUMBER PLATE	refit	25.00 FS	Refit
22	1		*REAR BOOTLID NUMBER PLATE HOLDER	refit	50.00 FS	Refit
23	1		*REAR BUMPR CLIPS X 1 SET	necessary	80.00 FS	*30.00 FS
24	1		*REAR BUMPER REVERSE SENSOR X 1 SET	dented	350.00 FS	*200.00 FS
25	1		*REAR END PANEL INNER TOP GARNISH CLIPS X 1 SET	not necessary	30.00 FS	See Remarks
26	1		*REAR FLOOR PANEL INSULATOR MAT	not necessary	300.00 FS	See Remarks

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,090.70	5,273.30
- List Item Discount on L Items 25.00/25.00% (S\$)	1,563.93	1,260.83
Total Parts (S\$)	5,526.77	4,012.47

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER	New	1,100.00	800.00 600
<u>Labour Items</u>				
2	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR	New	100.00	20.00
3	TO REMOVE, REINSTALL TRIM UPHOLSTERY, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	140.00	120.00 60
4	TO REMOVE AND CHANGE REPAIR EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	100.00	60.00 X
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	900.00	700.00 500
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	40.00
7	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR	New	80.00	50.00
Gross Labour Cost (\$\$)			2,540.00	1,790.00

< END OF ESTIMATES >



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 6922J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOTLID	TO REPAIR SEE LABOUR	817.30	-
1	REAR BOOT LID LOGO EMBLEM	NECESSARY	56.70	56.70
1	REAR BOOTLID HINGES L/R	TO REPAIR SEE LABOUR	179.40	-
1	REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R	NOT NECESSARY	52.80	-
1	REAR BOOTLID MECHANISM LOCK	BENT	182.25	182.25
1	REAR BOOTLID WEATHER STRIP	BENT	165.60	165.60
1	REAR BUMPER	DENTED	677.85	677.85
1	REAR BUMPER REFLECTOR L/R	NOT NECESSARY	230.60	-
1	REAR BUMPER SIDE BRACKET L/R	CRACKED	264.50	264.50
1	REAR BUMPER SIDE RETAINER L/R	CRACKED	282.90	282.90
1	REAR END PANEL	TO REPAIR SEE LABOUR	666.00	-
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	191.40	191.40
1	REAR EXHAUST GASKET	NOT NECESSARY	56.40	-
2	REAR EXHAUST RUBBER MOUNTING	NOT NECESSARY	96.80	-
1	REAR EXHAUST SILENCER BOX	NOT NECESSARY	596.40	-
1	REAR FLOOR PANEL TOOL BOX SPONGE TRAY LH	NOT NECESSARY	285.30	-
1	REAR FLOOR PANEL TOOL BOX SPONGE RH	NOT NECESSARY	285.30	-
1	REAR FLOOR PANEL TOP BOARD COVER	NOT NECESSARY	358.50	-
1	REAR TAILLAMP INNER BLACK RUBBER GASKET L/R	NOT NECESSARY	87.90	-
1	REAR TAILLAMP L/R	CRACKED	721.80	721.80
	LESS 25% DISCOUNT		-1,563.93	-635.75
			4,691.77	1,907.25
SPECIAL NETT ITEMS				
1	REAR BOOTLID NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR BOOTLID NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	350.00	200.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-

Report Ref No. CS1/III19008597/Cqd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FLOOR PANEL INSULATOR MAT (SN)	NOT NECESSARY	300.00	-
			835.00	230.00
	LABOUR			
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.		1,100.00	600.00
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.		100.00	20.00
	TO REMOVE, REINSTALL TRIM UPHOLSTERY, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		140.00	60.00
	TO REMOVE AND CHANGE REPAIR EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	100.00	-
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS., REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOTLID, REAR BOOTLID HINGES L/R AND REAR END PANEL.		900.00	500.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	40.00
	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR.		80.00	50.00
			2,540.00	1,270.00
GRAND TOTAL			8,066.77	3,407.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CS1/III19008597/Cqd3s2

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.