

INS. CASE OWNER:

CC 4 FWD 1900 8607, EQA32

LKK:
IDAC:

Surveyor:

Steve

DOI:

ASSIGNMENT

16/5/19

Date / Time:

15/5/19

Registered in Merimen:

15/5/19

Pre-assign / CCU / FTE

SJR3790U



Insured Vehicle No.:

Name of Insured:

FODEI RATHMAI B. ZAIR

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

13/5/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

SJR3790U

smk 7724U

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

YES

NO

TP GIA REPORT: YES / NO

YES

NO

Insured Liability: %

Final ? Yes / No

666 6674E



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

pms 60

7p



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

smk 7724U - 15/05/19 8606/pas 100% 13/5/19
SJR3790U - 15/05/19 8606/pas 100% 13/5/19

15-05-19

Email WSP Liability 100%

18-05-19

File pass to typist to prepare report.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: CT

Repair Cost:

45 SS 25,600

(12 days)

Reduction:

75 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 05.08.19

Confirm with 414 HAD

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 0%

Repair Cost:

W1451 SS 21,390.00

3 veh cc ord 1985

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS 1,020.00

(\$ 60 x 17 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS 29.00

Medical:

SS

Disbursement:

SS 60.00

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: +500

Total:

SS 28,500.00

Global Sum SS: 28,500

FINAL PAYMENT

Date/Time: 05.08.19

Confirm with 414 HAD

Email ☒ Call ☐

Payee 1:

SS 28,500.00

Name 1:

RICO 60 AUTO SERVICES PTE. LD.

Payee 2: (Strike if N.A.)

SS

Payee 3:

SS

Payee 3: (Strike if N.A.)

SS

Steve

REF: PWD


8607/6

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
QD / TP / WS / TP RES / QD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 12 days Res.: Yes or No
 Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time : _____ Action / Instruction

MV - 105K

45: 25000 (RBD: 66,062.99 73%)

Veh No: **SMK 2724 U** To Regn: **2/4/19**
 Type: **M. Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **OPEL INSIGNIA** cc: **1598**
 Colour: **Black** A/C Insured / Std / NI / N/
 Sp. Reading: **4773** T/Rndln: Insured / Std / NI / N.
 Eng/No: _____
 C/No: **W0V2M6EF5K 1035180**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brake: **In order** / Jammed / Leaked / Burnt or
 Modi: **Nil** / S/Rim / STD A/Rim or
 Tyre Size: F: **225/55R17**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front
 R/Bal. **7** mm Rear
 L/Bal. **7** mm L/Bal. **7** mm
 D.O.A. **13/5/19** D.O.I. **16/5/19**
 Survey held at **RICO 60**
 Des. of Damages: **Frt** / **Rear** / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision

Date/Time, File Pass to:

☐ : Prel. Report

Days Of Repair:

4)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$

Survey Fee:

Transportation

) S + R: 21

) Photos

) Fuel

Report Format :

Lump Sum / I.B. I: (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

2019



CHASSIS NUM:

WOVZM6EF5K1035180

ATTN:		CHASSIS NUM:		W0VZM6EF5K1035180	
NO	DESCRIPTION - PARTS	QTY	PRICE		
1	REAR WINDSCREEN MOULDING X NAI	1	\$268.24	X	
2	THIRD BRAKE LAMP X NAI	1	\$416.80	X	
3	BOOT LID X R	1	\$2984.60	X	
4	BOOT LID LOGO (OPEL) / AEC	1	\$148.60	/	
5	BOOT LID EMBLEM (INSIGNIA) / AEC	1	\$109.44	/	
6	BOOT LID EMBLEM (TURBO) - AEC	1	\$124.88	/	
7	BOOT LID EMBLEM (D) / AEC	1	\$86.73	/	
8	BOOT LID LOCK X NAI	1	\$496.77	X	
9	BOOT LID CATCH X NAI	1	\$153.61	X	
10	BOOT LID LAMP (L+R) X NAI	2	\$1026.74	X	
11	BOOT LID LAMP PANEL (L+R) X NAI	2	NIL.	X	
12	BOOT LID BOARD (CENTER) X NAI	1	\$236.87	X	
14	BOOT LID BOARD (L+R) X NAI	2	\$633.46	X	
15	BOOT LID HANDLE X NAI	1	\$526.83	X	
16	BOOT LID DAMPER (L+R) X NAI	2	\$628.70	X	
17	BOOT LID HINGE (L+R) X NAI	2	\$328.42	X	
18	BOOT LID WIRE PROTECTOR RUBBER (L+R) X NAI	2	\$128.74	X	
19	BOOT LID STOPPER (L+R) X NAI	2	\$84.44	X	
20	BOOT LID INNER BOARD X NAI	1	\$537.13	X	
21	BOOT LID WEATHER STRIP / CR4	1	\$248.70	/	
22	TAIL LAMP (L+R) LH 2. DR RH X - DR	2	\$1898.46	/	
23	TAIL LAMP PANEL (L+R) LH NAI? X RH X NAI	2	\$988.74	X	
24	REAR BUMPER / DD	1	\$2051.89	/	
25	REAR BUMPER RETAINER (L+R) / DR	2	\$272.32	/	
26	REAR BUMPER CARPLATE LAMP (L+R) 1 LH / DR RH X NAI	2	\$206.30	103.15 /	
27	REAR BUMPER TOWING CAP (L+R) 1 PC (RH) / CR4	2	\$86.74	43.37 /	
28	REAR BUMPER REFLECTOR (L+R) / TH / TH CAT	2	\$308.40	134 /	
29	REAR BUMPER REINFORCEMENT BAR ? / DD	1	\$647.31	/	
30	REAR BUMPER BEAM ? / CR4	1	\$595.70	/	
31	REAR BUMPER SPONGE ? X NAI	1	NIL.	X	
32	REAR BUMPER BRACKET (L+R) ? R178 LH - DR	2	\$898.74	/	
33	REAR FENDER (L+R) X NAI	2	\$496.36	X	
34	REAR FENDER INNER TRIM (L+R) X NAI	2	\$2988.12	X	
35	REAR FENDER COWLING (L+R) X NAI	2	\$338.74	X	
36	END PANEL ? / DD	1	\$984.70	/	
37	END PANEL TOP GARNISH ? X NAI	1	\$364.23	X	
38	SPAREWHEEL PANEL X / DD	1	\$1682.71	/	
39	SPAREWHEEL PANEL TOP BOARD X / TN	1	\$435.70	/	
40	SPAREWHEEL PANEL TOP BOARD TOP MAT X NAI	1	\$319.86	X	
41	SPAREWHEEL PANEL TOOL BOX ? / CR4	1	\$323.82	/	

42	EXHAUST PIPE	?	DU	1	\$1842.34	/
43	EXHAUST GASKET	?	MEC	1	\$312.44	218 /
44	EXHAUST BRACKET (L+R)	X	LH - BR	2	\$214.70	108.35 /
45	EXHAUST HEAT SHIELD	?	DD	1	\$327.41	/
46	FRONT WINDSCREEN MOULDING	X	NAI	1	\$216.30	X
47	BONNET	/	DD	1	\$3268.16	1989 /
48	BONNET INNER TRIM	?	X NAI	1	\$301.61	X
49	BONNET LOCK	?	- BT	1	\$185.91	/
50	BONNET CATCH	?	X NAI	1	\$86.74	X
51	BONNET HINGE (L+R)	X	? / BT	2	\$218.70	/
52	BONNET STOPPER (L+R)	X	NAI	2	\$56.32	X
53	BONNET INNER RUBBER	X	NAI	1	\$102.70	X
54	FRONT CENTER GARNISH	X	NAI	1	\$216.74	X
55	FRONT CENTER GRILLE BASE	/	CU	1	\$656.78	479 /
56	FRONT CENTER GRILLE CHROME (L+R)	X	PH - LH / CU	2	\$580.02	/
57	FRONT CENTER GRILLE FRAME CHROME	/	BR	1	\$544.07	356 /
58	FRONT CENTER GRILLE LOGO (OPEL)	/	OR	1	\$167.77	/
59	HEAD LAMP (L+R)	?	PH - LH / CU	2	\$6980.76	2446 /
60	HEAD LAMP BRACKET (L+R)	?	X NAI	2	\$568.70	X
61	FRONT BUMPER	/	DD	1	\$2431.93	2238 /
62	FRONT BUMPER RETAINER (L+R)	/	BR	2	\$821.44	/
63	FRONT BUMPER GARNISH (L+R)	X	NAI	1	\$148.70	X
64	FRONT BUMPER GRILLE	X	NAI	1	\$328.40	X
65	FRONT BUMPER FOG LAMP (L+R)	X	NAI	2	\$598.74	X
66	FRONT BUMPER FOG LAMP GARNISH (L+R)	X	NAI	2	\$298.76	X
67	FRONT BUMPER FOG LAMP GARNISH CHROME (L+R)	X	NAI	2	\$328.78	X
68	FRONT BUMPER FOG LAMP GRILLE (L+R)	X	NAI	2	\$186.88	X
69	FRONT BUMPER REINFORCEMENT BAR	?	- DD	1	\$834.89	/
70	FRONT BUMPER BEAM	?	- DD	1	\$796.88	/
71	FRONT BUMPER SPONGE	?	- BR	1	\$437.91	/
72	FRONT BUMPER BRACKET (L+R)	?	X NAI	2	\$436.40	X
73	FRONT BUMPER LOWER LAMP	X	NAI	1	\$216.70	X
74	FRONT FENDER (L+R)	X	NAI	2	\$1896.71	X
75	FRONT FENDER COWLING (L+R)	X	NAI	2	\$637.81	X
76	AIR CON CONDENSOR	?	DD	1	\$896.71	/
77	HIGH PRESSURE HOSE	?	X NAI	1	\$297.80	X
78	LOW PRESSURE HOSE	?	X NAI	1	\$286.71	X
79	RADIATOR	?	X NAI	1	\$1076.83	X
80	DISCHARGE PIPE	?	X NAI	1	\$236.11	X
81	SUCTION PIPE	?	X NAI	1	\$247.23	X
82	RADIATOR FAN COWLING	?	X NAI	1	\$416.77	X
83	RADIATOR FAN BLADE	?	X NAI	1	\$316.70	X
84	RADIATOR FAN MOTOR	?	X NAI	1	\$776.81	X
85	WIPER WASHER TANK	X	X NAI	1	\$371.31	X
86	WIPER WASHER MOTOR	X	X NAI	1	\$216.77	X
P = \$30,934.45						
SUBTOTAL					\$	-
LESS 10%					\$	-

		PARTS TOTAL		\$	
SPECIAL NETT		QTY	PRICE		
1	REAR WINDSCREEN SEALANT X <i>NAI</i>	1	\$ 120.00	X	
2	BOOT LID LAMP CLIP (L+R) X <i>NEC</i> <i>NAI</i>	1	\$ 100.00	X	
3	BOOT LID BOARD CLIP (CENTER) X <i>NAI</i>	10	\$ 100.00	X	
4	BOOT LID BOARD CLIP (L+R) X <i>NAI</i>	10	\$ 100.00	X	
5	BOOT LID INNER BOARD CLIP X <i>NAI</i>	10	\$ 100.00	X	
6	BOOT LID LAMP CLIP (L+R) X <i>NAI</i>	10	\$ 100.00	X	
7	TAIL LAMP CLIP (L+R) / <i>NEC</i>	10	\$ 100.00	30 /	
8	REAR BUMPER CLIP / <i>NEC</i>	10	\$ 100.00	35 /	
9	REAR CARPLATE / <i>NR</i>	1	\$ 120.00	50 /	
10	REVERSE CAMERA / <i>MIS</i>	1	\$ 850.00	480 /	
11	REAR FENDER SEALANT (L+R) X <i>NAI</i>	1	\$ 120.00	X	
12	REAR FENDER COWLING CLIP (L+R) X <i>NAI</i>	10	\$ 100.00	X	
13	REAR FENDER INNER TRIM CLIP (L+R) X <i>NAI</i>	10	\$ 100.00	X	
14	END PANEL SEALANT / <i>NEC</i>	1	\$ 120.00	30 /	
15	SPAREWHEEL SEALANT / <i>NEC</i>	1	\$ 120.00	30 /	
16	BONNET INNER TRIM CLIP / <i>NEC</i>	10	\$ 100.00	70 /	
17	HEAD LAMP CLIP (L+R) ? X <i>NAI</i>	10	\$ 100.00	X	
18	FRONT BUMPER CLIP / <i>NEC</i>	10	\$ 100.00	30 /	
19	FRONT BUMPER SENSOR (L+R) ? X <i>NAI</i>	6	\$ 900.00	X	
20	FRONT BUMPER FOG LAMP CLIP (L+R) X <i>NAI</i>	10	\$ 100.00	X	
21	FRONT FENDER SEALANT (L+R) X <i>NAI</i>	1	\$ 120.00	X	
22	AIRCON GAS ? X <i>NEC</i>	1	\$ 120.00	/	
				850	
SPECIAL NETT TOTAL			\$ 3,890.00		
LABOUR		QTY	PRICE		
TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN			\$ 5,200.00	1550 /	
TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA			\$ 3,200.00	1400 /	
TO RUST PROOF ACCIDENT AFFECTED AREA			\$ 200.00	30 /	
TO RNR REAR WINDSCREEN			\$ 400.00	X	
TO RNR FRONT WINDSCREEN			\$ 400.00	X	
TO RNR REAR BOOT MECHANISM			\$ 120.00	X	
TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS		100	\$ 400.00	40	
TO RNR REVERSE SENSOR & CHECK FUNCTION.			\$ 120.00	30 60 /	
TO RNR FRONT SENSOR & CHECK FUNCTION			\$ 120.00	30 60 /	
TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS		80	\$ 120.00	96	
TO RNR A/C CONDENSOR ASSY AND REFILL GAS ? /			\$ 120.00	100 30 /	
TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS			\$ 120.00	30 30 /	
TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION			\$ 120.00	30 /	
TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.			\$ 400.00	X	
TO DO WATER LEAK TEST .			\$ 80.00	30 /	
TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD ? /			\$ 120.00	30 /	
TO RNR FUEL TANK TO ASSIST WORK LOAD			\$ 250.00	X	
TO CHECK CHASSIS ALIGNMENT			\$ 600.00	X	
				3450	



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:	SMK 2724 U
MAKE & MODEL:	OPEL INSIGNIA
MILEAGE:	4773
TYRE:	
CHASSIS NUM:	WOVZM6EF5K1035180

NO	DESCRIPTION - PARTS	QTY	PRICE
1	REVERSE SENSOR CONTROL UNIT (L+R) <i>✓ NIN</i>	2	\$1988.25 <i>X</i>
2	REVERSE SENSOR SET (Rear) <i>/ B SH</i>	6	\$2008.78 <i>800 /</i>
3	SMART LOCK ANTENNA <i>/ BR BR</i>	1	\$879.73 <i>/</i>
4	FRONT SENSOR CONTROL UNIT (L+R) <i>X NIN</i>	2	\$1903.26 <i>X</i>
5	FRONT BUMPER UNDERCOVER <i>* / BR</i>	1	\$516.81 <i>/</i>
6	FRONT BRACE PANEL <i>/ DD</i>	1	\$1094.36 <i>768 /</i>
7	FRONT SUPPORT PANEL <i>/ DD</i>	1	\$1687.11 <i>1180 /</i>
8	FRONT LOCK PANEL <i>* / DD</i>	1	\$878.31 <i>316 /</i>
9	FRONT SUPPORT PANEL TOP GARNISH <i>/ BR</i>	1	\$399.73 <i>/</i>
10	UPPER AIR GUIDE (L+R) <i>/ CR4</i>	2	\$46.12 <i>/</i>
11	LOWER AIR GUIDE (L+R) <i>/ CR4</i>	2	\$231.42 <i>/</i>
12	CENTER AIR GUIDE <i>/ CR4</i>	1	\$311.17 <i>/</i>
13	AIRCON CONDENSOR AIR DUCT <i>/ BR</i>	1	\$309.24 <i>/</i>
14	AIRBOX CLEANER <i>/ BR</i>	1	\$189.93 <i>447 /</i>
	<i>P = \$41,778.44</i>		
	SUBTOTAL	\$	- <i>6355.27</i>
	LESS 10%	\$	- <i>- 10%</i>
	PARTS TOTAL	\$	- <i>5719.74</i>
SPECIAL NETT		QTY	PRICE
1	RIVERT <i>SIN = \$1225.00 net</i>	20	\$ 150.00 <i>50 /</i>
	SPECIAL NETT TOTAL	\$	150.00
LABOUR		QTY	PRICE
1	TO CHECK AND TEST FUNCTION FOR REVERSE SENSOR CONTROL UNIT	1	\$ 150.00 <i>X</i>
2	TO CHECK AND TEST FUNCTION FOR SMART LOCK ANTENNA	1	\$ 150.00 <i>60 /</i>
3	TO CHECK AND TEST FUNCTION FOR FRONT SENSOR CONTROL UNIT	1	\$ 150.00 <i>X</i>
	<i>L = \$8330</i>		
	<i>T = \$46,233.44</i>		
	<i>\$ - 20% = \$37,100</i>		
	TOTAL	\$	300.00 <i>110</i>
	GRAND TOTAL COST	\$	450.00

5829.74

	TOTAL	\$ 12,090.00
	GRAND TOTAL COST	\$ 15,980.00

PAGE 2 OF 2

91662.99

Steve (LKK)
832 2 8813

Wn 12 ~~12~~ days 16/5/19, 3:30 PM
L/S
Ry AL sky

P- 21,862.71
SUPP- 5829.74

NI- 850

L- 3450

31,992.45

L/S - 25,593.96

= 25,600.00

LKA Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SMK2724U		
Vehicle Type :	Z10 - Private Hire (Chauffeur) Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	OPEL		
Vehicle Model :	INSIGNIA GRANDSPORT B16DTH		
Chassis No. :	W0VZM6EF5K1035180		
Propellant :	Diesel		
Engine No. :	A3183378JSUX0548		
Engine Capacity :	1598 cc		
Maximum Power Output :	100.0 kW (134 bhp)		
Maximum Laden Weight :	2095 kg		
Unladen Weight :	1447 kg		
Year Of Manufacture :	2019		
Original Registration Date :	02 Apr 2019		
Lifespan Expiry Date :	-		
COE Category :	E - Open - all except motorcycle		
Quota Premium :	\$32,909.00		
COE Expiry Date :	01 Apr 2029		
Road Tax Expiry Date :	01 Oct 2019		
PARF Eligibility Expiry Date :	01 Apr 2029		
Inspection Due Date :	01 Apr 2022		
Intended Transfer Date :	16 May 2019		
CO2 Emission :	134.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	0.010310 (g/km)		
HC Emission :	0.018640 (g/km)		
NOx Emission :	0.017310 (g/km)		
PM Emission :	0.110000 (mg/km)		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

IS YOUR CAR DUE FOR SCRAP OR EXPORT?

Use Our **FREE** Service To Get The Best Selling Price!



Opel Insignia Grandsport

Min Price ▼

No Max ▼

Depreciation ▼

Vehicle Type ▼

Category ▼



Advanced Search

Home » New Cars » Opel Insignia Grandsport Search Results

Opel Insignia Grandsport Search Results (2 vehicles)

Sort by Model (Ascending) ▼

15 ▼ results/page

Car Model	Price	Dealer	Built in	User Rating
Opel Insignia Grandsport		Auto Germany	Germany	
 1.5 Turbo Innovation (A)	\$139,777 ▲	• 16.3km/l 162bhp 6-speed (A)		5 User Review
1.5 Turbo Innovation Premium Edition (A)	\$144,777 ▲	• 16.3km/l 162bhp 6-speed (A)		Editor's Review
2.0 Turbo AWD Innovation Premium Edition (A)	\$174,777	• 11.6km/l 256bhp 8-Speed (A)		
Opel Insignia Grandsport Diesel		Auto Germany	Germany	
 1.6 Turbo Enjoy (A)	\$124,777 ▲ \$11,100 /yr ↗	• 19.6km/l 134bhp 6-speed (A)		Rate it!

Car Model

Price

Dealer

Built in

User Rating

15 ▼ results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car site for buying Singapore cars, including new cars, parallel import cars & used cars. View all new cars, such as Toyota, Honda, Nissan, Volkswagen, Mitsui, BMW. We have new car dealers comprising parallel importers, authorised car distributors, and used car dealers. Find new car pricelists, new car launches, new car promotions, new car reviews, latest car news & car advice. Also join our car discussion and forum discussion for car reviews, motoring news & motoring guides. Visit our partner sites who have job openings for Singapore jobs, Singapore classifieds, mover and real estate properties for sale.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

[Compare](#)

> Back to OneMotoring

Samy

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5055D
Vehicle Details	
Vehicle No.:	SMK2724U
Vehicle to be Exported:	No
Intended Deregistration Date:	13 May 2019
Vehicle Make:	OPEL
Vehicle Model:	INSIGNIA GRANDSPORT B16DTH
Primary Colour:	Black
Manufacturing Year:	2019
Engine No.:	A3183378JSUX0548
Chassis No.:	W0VZM6EF5K1035180
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$25,878.00
Original Registration Date:	02 Apr 2019
First Registration Date:	02 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$28,230.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Apr 2029
PARF Rebate Amount:	\$21,172.00
Intended COE Rebate Details	
COE Expiry Date:	01 Apr 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$32,909.00
COE Rebate Amount:	\$31,828.00
Total Rebate Amount:	\$53,000.00

The information contained herein is correct as at 13 May 2019

OK

Das WeltAuto.
Used cars you can trust. Guaranteed.

Low on mileage. High on savings.



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Buy Back Guaranteed! \$20 + + + + k Depreciation!



Come with Warranty! Road Tax Recently Renewed! Sunroof

KA-HUP

**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997 [View our cars](#)

Sort by Date Posted 20 results/page

1 vehicles

Opel Insignia

Basic Search

Price Any price **Depre** Any depre
Fuel Any fuel **Mileage** Any
Category All categories **Scheme** All schemes
Reg Date 2016 to 2019 **Eng Cap** Any
OMI 2016 to 2019 **Past Owners** Any
Deale **Status** Available
Reset Apply

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status



Opel Insignia 1.6A Turbo

\$98,888

\$11,430 /yr

17-Nov-2016

1,598 cc

38,500 km

Luxury

Available

Loan Interest At 2.28%, Extremely Well Maintained And Fully Agent Maintained. This Beast Does Not Just Look Beautiful, It's 80% Accident-Free. View To Believe! Up To 100% Financing Possible! Trade In ...

PREMIUM AD

Posted: 04-May-2019 Tags: 2016 Opel Insignia, 2016 opel insignia, Opel Insignia, opel insignia, Opel, Insignia, insignia, Used Opel

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Opel Insignia, Opel Insignia Singapore, used Opel Insignia Singapore, used Opel Insignia, used vehicles Singapore or even buy used Opel Insignia Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.



Rico 60 Auto Services Pte Ltd , Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:

SMK 2724 U

MAKE & MODEL:

OPEL INSIGNIA

MILEAGE:

4773

TYRE:

CHASSIS NUM:

WOVZM6EF5K1035180

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR WINDSCREEN MOULDING X		
2	THIRD BRAKE LAMP X		
3	BOOT LID X R		
4	BOOT LID LOGO (OPEL) / AEC		
5	BOOT LID EMBLEM (INSIGNIA) / AEC		
6	BOOT LID EMBLEM (TURBO) / AEC		
7	BOOT LID EMBLEM (D) / AEC		
8	BOOT LID LOCK X		
9	BOOT LID CATCH X		
10	BOOT LID LAMP (L+R) X		
11	BOOT LID LAMP PANEL (L+R) X		
12	BOOT LID BOARD (CENTER) X		
14	BOOT LID BOARD (L+R) X		
15	BOOT LID HANDLE X		
16	BOOT LID DAMPER (L+R) X		
17	BOOT LID HINGE (L+R) X		
18	BOOT LID WIRE PROTECTOR RUBBER (L+R) X		
19	BOOT LID STOPPER (L+R) X		
20	BOOT LID INNER BOARD X		
21	BOOT LID WEATHER STRIP / CR4		
22	TAIL LAMP (L+R) LH ? RH X		
23	TAIL LAMP PANEL (L+R) LH ? RH X		
24	REAR BUMPER / DD		
25	REAR BUMPER RETAINER (L+R) / BR		
26	REAR BUMPER CARPLATE LAMP (L+R) ?		
27	REAR BUMPER TOWING CAP (L+R) 1 pc (RH) / CR4		
28	REAR BUMPER REFLECTOR (L+R) / LH - RH CUT		
29	REAR BUMPER REINFORCEMENT BAR ?		
30	REAR BUMPER BEAM ?		
31	REAR BUMPER SPONGE ?		
32	REAR BUMPER BRACKET (L+R) ?		
33	REAR FENDER (L+R) X		
34	REAR FENDER INNER TRIM (L+R) X		
35	REAR FENDER COWLING (L+R) X		
36	END PANEL ?		
37	END PANEL TOP GARNISH ?		
38	SPAREWHEEL PANEL X / DD		
39	SPAREWHEEL PANEL TOP BOARD X / TN		
40	SPAREWHEEL PANEL TOP BOARD TOP MAT X		
41	SPAREWHEEL PANEL TOOL BOX ?		

[illegible]

	PARTS TOTAL	S	-
	SPECIAL NETT	QTY	PRICE
1	REAR WINDSCREEN SEALANT X	1	\$ 120.00
2	BOOT LID LAMP CLIP (L+R) X A/E/C	10	\$ 100.00
3	BOOT LID BOARD CLIP (CENTER) X	10	\$ 100.00
4	BOOT LID BOARD CLIP (L+R) X	10	\$ 100.00
5	BOOT LID INNER BOARD CLIP X	10	\$ 100.00
6	BOOT LID LAMP CLIP (L+R) X	10	\$ 100.00
7	TAIL LAMP CLIP (L+R) / A/E/C	10	\$ 100.00
8	REAR BUMPER CLIP / N/E/C	10	\$ 100.00
9	REAR CARPLATE / BR	1	\$ 120.00
10	REVERSE CAMERA / MIS	1	\$ 850.00
11	REAR FENDER SEALANT (L+R) X	1	\$ 120.00
12	REAR FENDER COWLING CLIP (L+R) X	10	\$ 100.00
13	REAR FENDER INNER TRIM CLIP (L+R) X	10	\$ 100.00
14	END PANEL SEALANT / A/E/C	1	\$ 120.00
15	SPAREWHEEL SEALANT / A/E/C	1	\$ 120.00
16	BONNET INNER TRIM CLIP / A/E/C	10	\$ 100.00
17	HEAD LAMP CLIP (L+R) ?	10	\$ 100.00
18	FRONT BUMPER CLIP / A/E/C	10	\$ 100.00
19	FRONT BUMPER SENSOR (L+R) ?	6	\$ 900.00
20	FRONT BUMPER FOG LAMP CLIP (L+R) X	10	\$ 100.00
21	FRONT FENDER SEALANT (L+R) X	1	\$ 120.00
22	AIRCON GAS ?	1	\$ 120.00
	SPECIAL NETT TOTAL		\$ 3,890.00
	LABOUR	QTY	PRICE
	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN 1300~1500		\$ 5,200.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA 1150		\$ 3,200.00
	TO RUST PROOF ACCIDENT AFFECTED AREA		\$ 200.00
	TO RNR REAR WINDSCREEN		\$ 400.00
	TO RNR FRONT WINDSCREEN		\$ 400.00
	TO RNR REAR BOOT MECHANISM		\$ 120.00
	TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS 100		\$ 400.00
	TO RNR REVERSE SENSOR & CHECK FUNCTION.		\$ 120.00
	TO RNR FRONT SENSOR & CHECK FUNCTION		\$ 120.00
	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS 80		\$ 120.00
	TO RNR A/C CONDENSOR ASSY AND REFILL GAS ?		\$ 120.00
	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS		\$ 120.00
	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION		\$ 120.00
	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.		\$ 400.00
	TO DO WATER LEAK TEST .		\$ 80.00
	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD ?		\$ 120.00
	TO RNR FUEL TANK TO ASSIST WORK LOAD		\$ 250.00
	TO CHECK CHASSIS ALIGNMENT		\$ 600.00

		TOTAL	S 12,090.00
		GRAND TOTAL COST	S 15,980.00

PAGE 2 OF 2

Steve (LKK)
832 2 8813

WR 12
Prejudice 16/5/19, 3:30 PM
chys
L/S
Ry AL spy

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Nivitha (LKK Auto)

From: lionel.tan@fwd.com
Sent: Wednesday, 15 May 2019 11:01 AM
To: assignments@lkkauto.com; sur@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: PRI Arrangement for SMK 2724 U

Our Ref: 1201900012868/LT

Hi

Please arrange PRI with TP repairer.

Regards,
Lionel

From: Rico 60 [mailto:claims@rico60.com]
Sent: Wednesday, May 15, 2019 10:48 AM
To: Lionel Tan Tian Pei - SGUser
Cc: Motor Claims SG - SG Common
Subject: RE: PRI Arrangement for SMK 2724 U

Dear all,

Please have Marcus from LKK survey the said vehicle.

Thank you.

Best Regards,
John Ong



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 8811 2101 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: claims@rico60.com

Vel In

From: lionel.tan@fwd.com
Sent: Tuesday, 14 May 2019 6:56 PM
To: claims@rico60.com
Cc: motorclaims.sg@fwd.com
Subject: RE: PRI Arrangement for SMK 2724 U

Our Ref: 1201900012868/LT

Without Prejudice

Dear Sir/Madam,

Please select one of our surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD

If you are not agreeable to any of the above, we would proceed to appoint a surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We look forward to your reply.

Thank you.

Lionel

From: Enquiry [<mailto:claims@rico60.com>]

Sent: Tuesday, 14 May, 2019 4:43 PM

To: Motor Claims SG - SG Common

Subject: PRI Arrangement for SMK 2724 U

Dear All,

Kindly arrange PRI to survey the said vehicle as follows:

Our Client – SMK 2724 U

Your Insured – SJR 3790 U

DOA – 13/05/2019

Thank you.

Best Regards,
Shanelle Lim



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 9187 8064 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any

attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Saturday, 15 June 2019 4:09 PM
To: Enquiry
Subject: Accident Involving SMK 2724U & SJR 3790U on 13/05/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Your Ref: SMK 2724U
Our Ref: CC4/FWD19008607/Eea3

Dear Sir/Madam,

Accident Involving SMK 2724U & SJR 3790U on 13/05/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	15 May 2019 15:03	Clim Dtl Modified	Claimant's Name: -> -.	[A] HOW MEI KWAN
2	15 May 2019 15:03	Clim Veh Model Changed	(204611) HONDA VEZEL 1.5 1.5X CVT (A).	[A] HOW MEI KWAN
3	15 May 2019 15:03	Clim Created	Reg No: SMK2724U. Acct Date: 2019/05/13. Claim Type: TP. Insurer: FWD Singapore Pte. Ltd. (HQ). TP Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Workshop: RICO 60 AUTO SERVICES PTE LTD (HQ)	[A] HOW MEI KWAN
4	15 May 2019 15:03	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Sug gested Adj. : VICOM Ltd.	[A] HOW MEI KWAN
5	15 May 2019 15:03	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/05/27	[A] HOW MEI KWAN
6	15 May 2019 15:03	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
7	15 May 2019 15:03	Label Added	(20005):Direct Settlement .	[A] HOW MEI KWAN
8	15 May 2019 15:03	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] HOW MEI KWAN
9	15 May 2019 17:37	Clim Registration Modified	Pol No:->PNPV2018-00007724.	[I] Clara Li Zi Rong
10	21 May 2019 09:16	Adj Adjuster Assigned	MARCUS CHUA -> CHEN TSUE YEE	[A] HOW MEI KWAN
11	21 May 2019 09:17	Clim Dtl Modified	Claimant's Name: - -> BIS MOTORING PTE LTD. Claimant's ID: -> 201735055D.	[A] HOW MEI KWAN
12	21 May 2019 09:17	TP Ins Updated	TPPolNo:[None] -> 999994322.	[A] HOW MEI KWAN
13	21 May 2019 09:17	Clim Registration Modified	Acct Time:00:00:00->15:00:00.	[A] HOW MEI KWAN
14	21 May 2019 09:17	Clim Veh Model Changed	(204611) -> (204270) OPEL INSIGNIA 1.6 Turbo (A).	[A] HOW MEI KWAN
15	17 Jul 2019 17:49	Adj Rpt Initiated		[A] NUR SHAQILAH BTE ABDOL WAHAB
16	17 Jul 2019 17:49	Clim Dtl Modified	JPJ Reg. Date: -> 2019/04/02.	[A] NUR SHAQILAH BTE ABDOL WAHAB
17	17 Jul 2019 17:49	Clim Details Notified		[A] NUR SHAQILAH BTE ABDOL WAHAB
18	19 Jul 2019 10:53	Adj Mandate Request	Cur.Req:29181.00:LIABILITY: 100% B:28 3VEH CC LAST QUANTUM: (a) COR w/GST : \$27,392.00 + (b) LOR : \$1,700.00 (17days x \$100) + (c) TOWING FEE: \$60.00 + (d) LTA: \$29.00 Total: a+b+c+d = \$29,181.00 PLEASE REVERT WITH YOUR APPROVA L / MANDATE / INSTRUC	[A] Asher Sng Rong YI

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2216115	17/07/2019 17:49	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMK2724U	SJR3790U	11.77

8/1/2019

Merimen e-Claims

Print Received Message

This mail is associated with :

***SMK2724U (1201900012868)**
[SJR3790U]

TP
BIS MOTORING PTE LTD
May 13 2019 3:00PM
[EDDEI RAHMAT BIN TAIB]
RICO 60 AUTO SERVICES PTE LTD

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 26/07/2019 13:08 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$28501.00) - SMK2724U - Claim Handler: Lionel Tan

Approved:28501.00.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 May 2019 Edit Reg		15 May 2019 00:00 Edit Adj Rpt	S\$25,600.00 Edit Estimates	S\$25,600.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	EDDEI RAHMAT BIN TAIB , ID: S7249124F		
Main Claimant:	BIS MOTORING PTE LTD , Co. Reg. No.: 201735055D		
Vehicle Reg. No.:	SMK2724U	Date of Loss:	13/05/2019 15:00 - :59 [1 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201900012868	Policy/Cover Note No.:	PNPV2018-00007724 (Comprehensive) Coverage: 22/06/2018 - 21/06/2019
Vehicle Reg. No. (Insured):	SJR3790U	Policy No. (Claimant):	999994322
		Excess:	
Repairer:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 27/05/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- FWD_SG (26/07/2019): Alert - Adj Mandate Approved (S\$28501.00) - SMK2724U - Claim Handler: Lionel Tan
- FWD_SG (23/07/2019): Alert - Adj Mandate Maintained - SMK2724U - Claim Handler: Lionel Tan

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMK2724U (1201900012868)

[SJR3790U]

TP

BIS MOTORING PTE LTD

May 13 2019 3:00PM

[EDDEI RAHMAT BIN TAIB]

RICO 60 AUTO SERVICES PTE LTD

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Letters/Correspondences

1 per page ▼

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit

Photos/Images

3 per page ▼

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/05/19 08:43	General View		Load JPG
2	24/05/19 08:43	General View		Load JPG
3	24/05/19 08:43	General View		Load JPG
4	24/05/19 08:43	General View		Load JPG
5	24/05/19 08:43	General View		Load JPG
6	24/05/19 08:43	General View		Load JPG
7	24/05/19 08:43	General View		Load JPG
8	24/05/19 08:43	General View		Load JPG
9	24/05/19 08:43	General View		Load JPG
10	24/05/19 08:43	General View		Load JPG
11	24/05/19 08:43	General View		Load JPG
12	24/05/19 08:43	General View		Load JPG
13	24/05/19 08:43	General View		Load JPG
14	24/05/19 08:43	General View		Load JPG
15	24/05/19 08:43	General View		Load JPG
16	24/05/19 08:43	General View		Load JPG
17	24/05/19 08:43	General View		Load JPG
18	24/05/19 08:43	General View		Load JPG
19	24/05/19 08:43	General View		Load JPG
20	24/05/19 08:43	General View		Load JPG
21	24/05/19 08:43	General View		Load JPG
22	24/05/19 08:43	General View		Load JPG
23	24/05/19 08:43	General View		Load JPG
24	24/05/19 08:43	General View		Load JPG
25	24/05/19 08:43	General View		Load JPG
26	24/05/19 08:43	General View		Load JPG
27	24/05/19 08:43	General View		Load JPG
28	24/05/19 08:43	General View		Load JPG
29	24/05/19 08:43	General View		Load JPG
30	24/05/19 08:43	General View		Load JPG
31	24/05/19 08:43	General View		Load JPG
32	24/05/19 08:43	General View		Load JPG

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	24/05/19 08:43	General View	 Load JPG	☒
34	24/05/19 08:43	General View	 Load JPG	☒
35	24/05/19 08:43	General View	 Load JPG	☒
36	24/05/19 08:43	General View	 Load JPG	☒
37	24/05/19 08:43	General View	 Load JPG	☒
38	24/05/19 08:43	General View	 Load JPG	☒
39	24/05/19 08:43	General View	 Load JPG	☒
40	24/05/19 08:43	General View	 Load JPG	☒
41	24/05/19 08:43	General View	 Load JPG	☒
42	24/05/19 08:43	General View	 Load JPG	☒
43	24/05/19 08:43	General View	 Load JPG	☒
44	24/05/19 08:43	General View	 Load JPG	☒
45	24/05/19 08:43	General View	 Load JPG	☒
46	24/05/19 08:43	General View	 Load JPG	☒
47	24/05/19 08:43	General View	 Load JPG	☒
48	24/05/19 08:43	General View	 Load JPG	☒
49	24/05/19 08:43	General View	 Load JPG	☒
50	24/05/19 08:43	General View	 Load JPG	☒
51	24/05/19 08:43	General View	 Load JPG	☒
52	24/05/19 08:43	General View	 Load JPG	☒
53	24/05/19 08:43	General View	 Load JPG	☒
54	24/05/19 08:44	General View	 Load JPG	☒
55	24/05/19 08:44	General View	 Load JPG	☒
56	24/05/19 08:44	General View	 Load JPG	☒
57	24/05/19 08:44	General View	 Load JPG	☒
58	24/05/19 08:44	General View	 Load JPG	☒
59	24/05/19 08:44	General View	 Load JPG	☒
60	24/05/19 08:44	General View	 Load JPG	☒
61	24/05/19 08:44	Odometer Reading	 Load JPG	☒
62	24/05/19 08:44	Chassis Number	 Load JPG	☒
63	24/05/19 08:44	General View	 Load JPG	☒
64	24/05/19 08:44	General View	 Load JPG	☒
65	24/05/19 08:44	General View	 Load JPG	☒
66	24/05/19 08:44	General View	 Load JPG	☒
67	24/05/19 08:44	General View	 Load JPG	☒
68	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
69	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
70	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
71	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
72	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
73	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
74	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
75	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
76	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
77	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
78	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
79	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
80	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒

Letters/Correspondences			1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
82	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
83	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
84	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
85	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
86	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
87	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
88	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
89	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
90	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
91	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
92	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
93	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
94	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
95	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
96	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
97	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
98	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
99	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
100	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
101	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
102	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
103	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
104	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
105	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
106	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
107	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
108	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
109	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
110	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
111	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
112	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
113	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
114	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
115	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
116	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
117	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
118	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
119	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
120	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
121	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
122	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
123	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
124	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
125	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
126	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
127	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	☒
128	24/05/19 08:44	Photographs of Damaged Parts	Load JPG	☒

Letters/Correspondences			1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
129	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
130	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
131	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
132	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
133	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
134	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
135	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
136	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
137	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
138	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
139	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
140	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
141	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
142	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
143	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
144	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
145	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
146	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
147	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
148	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
149	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
150	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
151	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
152	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
153	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
154	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
155	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
156	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
157	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
158	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
159	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
160	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
161	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
162	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
163	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
164	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
165	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
166	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
167	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
168	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
169	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
170	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
171	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
172	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
173	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
174	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
175	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	
176	24/05/19 08:44	Photographs of Damaged Parts	Load JPG	

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
177	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	✓
178	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	✓
179	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	✓
180	24/05/19 08:44	Photographs of Damaged Parts	 Load JPG	✓
181	10/06/19 08:53	Photo After Spray	 Load JPG	✓
182	10/06/19 08:53	Photo After Spray	 Load JPG	✓
183	10/06/19 08:53	Photo After Spray	 Load JPG	✓
184	10/06/19 08:53	Photo After Spray	 Load JPG	✓
185	10/06/19 08:53	Photo After Spray	 Load JPG	✓
186	10/06/19 08:53	Photo After Spray	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/05/19 15:03	ACKNOWLEDGEMENT EMAIL TO FWD DD 15.5.19	 Load PDF	
2	22/05/19 07:48	TP ESTIMATE - INCOMPLETE	 Load PDF	
3	18/07/19 17:53	GIA SEARCH	 Load PDF	
4	18/07/19 17:53	TOWING FEE	 Load PDF	
5	23/07/19 15:47	LOD	 Load PDF	
6	19/08/19 10:03	AUTHORISATION TO ACT	 Load PDF	
7	19/08/19 10:03	RELEASE VOUCHER	 Load PDF	
8	19/08/19 10:03	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	21/05/19 15:09	E-filed GIA report From:OD - Reg. No: SJR3790U, Claimant: EDDEI RAHMAT BIN TAIB	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJR3790U (Insd veh)	Model:	OPEL INSIGNIA 1.6 TURBO (A)
	SMK2724U (TP veh)		
Date of Accident:	13/05/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	98,079.40
Final Repair Cost	:	\$	28,500.00
Loss of Use	:	\$	17.00 days at \$60.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	28,500.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ 100 _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 0 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	RICO 60 AUTO SERVICES PTE. LTD.	: \$	28,500.00
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

19 Aug
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19008607/EEA3S2
Date: 19/08/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00007724
Claimant Vehicle No: SMK2724U Insured Vehicle No: SJR3790U
Date of Loss: 13/05/2019 Nature of Claim: TP Claim No: 1201900012868

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK2724U**
Make & Model: OPEL INSIGNIA, 1.6 Turbo (A) Engine No: A3183378JSUX0548
Reg. Date: 02/04/2019 (Man. Year: 2019) Chassis No: W0VZM6EF5K1035180
Colour: Black Odometer: 4773 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	79,122.99	28,467.10	50,655.89	64.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,540.00	3,510.00	9,030.00	72.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	91,662.99	31,977.10	59,685.89	65.11
Approved Total (Overridden) (\$\$)		25,600.00		
(\$\$)	91,662.99	25,600.00	66,062.99	72.07
+ GST 7.00/7.00% (\$\$)	6,416.41	1,792.00	4,624.41	72.07
Nett Amount (\$\$)	98,079.40	27,392.00	70,687.40	72.07
+ Loss of Use (17.0 x S\$60.00/day) (\$\$)		1,020.00		
+ Doc/Search Fee (\$\$)		29.00		
+ Other Costs (\$\$)		60.00		
Nett Liability (\$\$)		28,501.00		
Global Sum Settlement (\$\$)		28,500.00		

INSPECTION

Date of Assignment: 15/05/2019
Date Inspected: 16/05/2019 Inspected At:
Estimated Period of Repair: 12.0 days

RICO 60 AUTO SERVICES PTE LTD (HQ)

8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT
Singapore 415875

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Aug 2019)
Parts:	143	OPEL INSIGNIA 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK2724U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	268.44 FL	*- FL
2	1		*THIRD BRAKE LAMP	Not Necessary	416.80 FL	*- FL
3	1		*BOOTLID	Repair	2,984.60 FL	*- FL
4	1		*BOOT LID LOGO (OPEL)	Necessary	148.60 FL	*148.60 FL
5	1		*BOOT LID EMBLEM (INSIGNIA)	Necessary	109.44 FL	*109.44 FL
6	1		*BOOT LID EMBLEM (TURBO)	Necessary	124.88 FL	*124.88 FL
7	1		*BOOT LID EMBLEM (D)	Necessary	86.73 FL	*86.73 FL
8	1		*BOOT LID LOCK	Not Necessary	496.77 FL	*- FL
9	1		*BOOT LID CATCH	Not Necessary	153.61 FL	*- FL
10	2		*BOOT LID LAMP (L+R)	Not Necessary	1,096.74 FL	*- FL
11	2		*BOOT LID LAMP PANEL (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
12	1		*BOOT LID BOARD (CENTER)	Not Necessary	736.37 FL	*- FL
13	2		*BOOT LID BOARD (L+R)	Not Necessary	633.46 FL	*- FL
14	1		*BOOT LID HANDLE	Not Necessary	536.83 FL	*- FL
15	2		*BOOT LID DAMPER (L+R)	Not Necessary	628.70 FL	*- FL
16	2		*BOOT LID HINGE (L+R)	Not Necessary	328.42 FL	*- FL
17	2		*BOOT LID WIRE PROTECTOR RUBBER (L+R)	Not Necessary	128.74 FL	*- FL
18	2		*BOOT LID STOPPER (L+R)	Not Necessary	84.44 FL	*- FL
19	1		*BOOT LID INNER BOARD	Not Necessary	537.13 FL	*- FL
20	1		*BOOT LID WEATHERSTRIP	Crushed	298.70 FL	*298.70 FL
21	2		*TAIL LAMP (L+R)	Broken	1,898.46 FL	*1,898.46 FL
22	2		*TAIL LAMP PANEL (L+R)	Not Necessary	988.74 FL	*- FL
23	1		*REAR BUMPER	Dented	2,051.84 FL	*2,051.84 FL
24	1		*REAR BUMPER RETAINER (L+R)	Broken	278.32 FL	*278.32 FL
25	1		*REAR BUMPER CARPLATE LAMP (L+R)	N/s Broken / O/s Not Necessary	206.30 FL	*103.15 FL
26	1		*REAR BUMPER TOWING CAP (L+R)	O/s Crushed	86.74 FL	*43.37 FL
27	2		*REAR BUMPER REFLECTOR (L+R)	Cut	308.40 FL	*134.00 FL
28	1		*REAR BUMPER REINFORCEMENT BAR	Dented	647.31 FL	*647.31 FL
29	1		*REAR BUMPER BEAM	Crushed	595.70 FL	*595.70 FL
30	1		*REAR BUMPER SPONGE (NPA)	Not Necessary	0.00 FL	*- FL
31	2		*REAR BUMPER BRACKET (L+R)	Broken	398.74 FL	*398.74 FL
32	2		*REAR FENDER (L+R)	Not Necessary	4,968.36 FL	*- FL
33	2		*REAR FENDER INNER TRIM (L+R)	Not Necessary	2,988.12 FL	*- FL
34	2		*REAR FENDER COWLING (L+R)	Not Necessary	438.74 FL	*- FL
35	1		*END PANEL	Dented	984.70 FL	*984.70 FL
36	1		*END PANEL TOP GARNISH	Not Necessary	364.88 FL	*- FL
37	1		*SPARE WHEEL PANEL	Dented	1,683.71 FL	*1,683.71 FL
38	1		*SPARE WHEEL PANEL TOP BOARD	Torn	435.70 FL	*435.70 FL
39	1		*SPARE WHEEL PANEL TOP BOARD TOP MAT	Not Necessary	319.36 FL	*- FL
40	1		*SPARE WHEEL PANEL TOOL BOX	Crushed	323.82 FL	*323.82 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*EXHAUST PIPE	Dented	1,342.34 FL	*1,342.34 FL
42	1		*EXHAUST GASKET	Necessary	312.44 FL	*218.00 FL
43	1		*EXHAUST BRACKET	N/s Broken	216.70 FL	*108.35 FL
44	1		*EXHAUST HEAT SHIELD	Dented	327.41 FL	*327.41 FL
45	1		*FRONT WINDSCREEN MOULDING	Not Necessary	216.80 FL	*- FL
46	1		*BONNET	Dented	3,268.16 FL	*1,989.00 FL
47	1		*BONNET INNER TRIM	Not Necessary	301.61 FL	*- FL
48	1		*BONNET LOCK	Bent	185.91 FL	*185.91 FL
49	1		*BONNET CATCH	Not Necessary	86.74 FL	*- FL
50	2		*BONNET HINGE (L+R)	Bent	218.70 FL	*218.70 FL
51	2		*BONNET STOPPER (L+R)	Not Necessary	56.32 FL	*- FL
52	1		*BONNET INNER RUBBER	Not Necessary	102.30 FL	*- FL
53	1		*FRONT CENTER GARNISH	Not Necessary	216.74 FL	*- FL
54	1		*FRONT CENTER GRILLE BASE	Cut	656.78 FL	*479.00 FL
55	2		*FRONT CENTER GRILLE CHROME (L+R)	Cut	580.02 FL	*580.02 FL
56	1		*FRONT CENTER GRILLE FRAME CHROME	Broken	544.07 FL	*356.00 FL
57	1		*FRONT CENTER GRILLE LOGO (OPEL)	Broken	167.78 FL	*167.78 FL
58	2		*HEAD LAMP (L+R)	Cut	6,980.76 FL	*2,446.00 FL
59	2		*HEAD LAMP BRACKET (L+R)	Not Necessary	568.70 FL	*- FL
60	1		*FRONT BUMPER	Dented	2,431.93 FL	*2,238.00 FL
61	2		*FRONT BUMPER RETAINER (L+R)	Broken	321.44 FL	*321.44 FL
62	1		*FRONT BUMPER GARNISH (L+R)	Not Necessary	148.70 FL	*- FL
63	1		*FRONT BUMPER GRILLE	Not Necessary	328.40 FL	*- FL
64	2		*FRONT BUMPER FOG LAMP (L+R)	Not Necessary	598.74 FL	*- FL
65	2		*FRONT BUMPER FOG LAMP GARNISH (L+R)	Not Necessary	298.76 FL	*- FL
66	2		*FRONT BUMPER FOG LAMP GARNISH CHROME (L+R)	Not Necessary	328.78 FL	*- FL
67	2		*FRONT BUMPER FOG LAMP GRILLE (L+R)	Not Necessary	186.88 FL	*- FL
68	1		*FRONT BUMPER REINFORCEMENT BAR	Dented	834.89 FL	*834.89 FL
69	1		*FRONT BUMPER BEAM	Dented	796.88 FL	*796.88 FL
70	1		*FRONT BUMPER SPONGE	Broken	437.91 FL	*437.91 FL
71	2		*FRONT BUMPER BRACKET (L+R)	Not Necessary	436.40 FL	*- FL
72	1		*FRONT BUMPER LOWER LAMP	Not Necessary	216.70 FL	*- FL
73	2		*FRONT FENDER (L+R)	Not Necessary	1,896.71 FL	*- FL
74	2		*FRONT FENDER COWLING (L+R)	Not Necessary	637.81 FL	*- FL
75	1		*AIR CON CONDENSOR	Dented	896.71 FL	*896.71 FL
76	1		*HIGH PRESSURE HOSE	Not Necessary	297.80 FL	*- FL
77	1		*LOW PRESSURE HOSE	Not Necessary	286.71 FL	*- FL
78	1		*RADIATOR	Not Necessary	1,076.83 FL	*- FL
79	1		*DISCHARGE PIPE	Not Necessary	9,236.11 FL	*- FL
80	1		*SUCTION PIPE	Not Necessary	247.23 FL	*- FL
81	1		*RADIATOR FAN COWLING	Not Necessary	416.77 FL	*- FL
82	1		*RADIATOR FAN BLADE	Not Necessary	316.70 FL	*- FL
83	1		*RADIATOR FAN MOTOR	Not Necessary	731.81 FL	*- FL
84	1		*WIPER WASHER TANK	Not Necessary	371.31 FL	*- FL
85	1		*WIPER WASHER MOTOR	Not Necessary	216.77 FL	*- FL
86	1		*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
87	1		*BOOT LID LAMP (L+R)	Not Necessary	100.00 FS	*- FS
88	10		*BOOT LID BOARD CLIP (CENTER)	Not Necessary	100.00 FS	*- FS
89	10		*BOOT LID BOARD CLIP (L+R)	Not Necessary	100.00 FS	*- FS
90	10		*BOOT LID INNER BOARD CLIP	Not Necessary	100.00 FS	*- FS
91	10		*BOOT LID LAMP CLIP (L+R)	Not Necessary	100.00 FS	*- FS
92	10		*TAIL LAMP (L+R)	Necessary	100.00 FS	*30.00 FS
93	10		*REAR BUMPER CLIP	Necessary	100.00 FS	*35.00 FS
94	1		*REAR CARPLATE	Broken	120.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
95	1		*REVERSE CAMERA	Missing	850.00 FS	*480.00 FS
96	1		*REAR FENDER SEALANT (L+R)	Not Necessary	120.00 FS	*- FS
97	10		*REAR FENDER COWLING CLIP (L+R)	Not Necessary	100.00 FS	*- FS
98	10		*REAR FENDER INNER TRIM CLIP (L+R)	Not Necessary	100.00 FS	*- FS
99	1		*END PANEL SEALANT	Necessary	120.00 FS	*30.00 FS
100	1		*SPARE WHEEL SEALANT	Necessary	120.00 FS	*30.00 FS
101	10		*BONNET INNER TRIM CLIP	Necessary	100.00 FS	*30.00 FS
102	10		*HEAD LAMP (L+R)	Not Necessary	100.00 FS	*- FS
103	10		*FRONT BUMPER CLIP	Necessary	100.00 FS	*30.00 FS
104	6		*FRONT BUMPER SENSOR (L+R)	Not Necessary	900.00 FS	*- FS
105	10		*FRONT BUMPER FOG LAMP CLIP (L+R)	Not Necessary	100.00 FS	*- FS
106	1		*FRONT FENDER SEALANT (L+R)	Not Necessary	120.00 FS	*- FS
107	1		*AIRCON GAS	Necessary	120.00 FS	*120.00 FS
108	2		*REVERSE SENSOR CONTROL UNIT (L+R)	Not Necessary	1,988.23 FL	*- FL
109	1		*SET REVERSE SENSOR (REAR)	Shorted	2,208.78 FL	*800.00 FL
110	1		6pcs *SMART LOCK ANTENNA	Broken	879.73 FL	*879.73 FL
111	2		*FRONT SENSOR CONTROL UNIT (L+R)	Not Necessary	1,968.26 FL	*- FL
112	1		*FRONT BUMPER UNDERCOVER	Broken	596.81 FL	*596.81 FL
113	1		*FRONT BRACE PANEL	Dented	1,097.36 FL	*768.00 FL
114	1		*FRONT SUPPORT PANEL	Dented	1,687.11 FL	*1,180.00 FL
115	1		*FRONT LOCK PANEL	Dented	878.31 FL	*316.00 FL
116	1		*FRONT SUPPORT PANEL TOP GARNISH	Broken	319.73 FL	*319.73 FL
117	2		*UPPER AIR GUIDE (L+R)	Crushed	196.12 FL	*196.12 FL
118	2		*LOWER AIR GUIDE (L+R)	Crushed	231.42 FL	*231.42 FL
119	1		*CENTER AIR GUIDE	Crushed	311.17 FL	*311.17 FL
120	1		*AIRCON CONDENSOR AIR DUCT	Broken	309.29 FL	*309.29 FL
121	1		*AIRBOX CLEANER	Broken	639.93 FL	*447.00 FL
122	20		*RIVET	Necessary	150.00 FS	*50.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$) **87,465.55** **31,531.78**

- List Item Discount on L Items 10.00/10.00% (S\$) 8,342.56 3,064.68

Total Parts (S\$) **79,122.99** **28,467.10**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR ACCIDENT DAMAGE PARTS, CUT / WELD, KNOCK & REALIGN.	New	5,200.00	1,550.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.	New	3,200.00	1,400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA.	New	200.00	30.00
4	TO RNR REAR WIDSCREEN.	New	400.00	0.00
5	TO RNR FRONT WINDSCREEN.	New	400.00	0.00
6	TO RNR REAR BOOT MECHANISM.	New	120.00	0.00
7	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS.	New	400.00	100.00
8	TO RNR REVERSE SENSOR & CHECK FUNCTION.	New	120.00	60.00
9	TO RNR FRONT SENSOR & CHECK FUNCTION.	New	120.00	60.00
10	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS.	New	120.00	80.00
11	TO RNR A/C CONDENSER ASSY AND REFILL GAS.	New	120.00	30.00
12	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS.	New	120.00	50.00
13	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION.	New	120.00	30.00
14	TO DO DIAGNOSTIC AND RESET, REPROGRAM OR CODING FAULT CODE.	New	400.00	0.00
15	TO DO WATER LEAK TEST.	New	80.00	30.00
16	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD.	New	120.00	30.00
17	TO RNR FUEL TANK TO ASSIST WORK LOAD.	New	250.00	0.00
18	TO CHECK ASSIST ALIGNMENT.	New	600.00	0.00
19	TO CHECK AND TEST FUNCTION FOR REVERSE SENSOR CONTROL UNIT.	New	150.00	0.00
20	TO CHECK AND TEST FUNCTION FOR SMART LOCK ANTENNA.	New	150.00	60.00
21	TO CHECK AND TEST FUNCTION FOR FRONT SENSOR CONTROL UNIT.	New	150.00	0.00
Gross Labour Cost (\$\$)			12,540.00	3,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >