



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
LHO LEE HENG BLK 10 JALAN LEMPENG #13-02 SINGAPORE 128797 Contact No Mobile: 96188243	Cust No/Name	KCV09743/LHO LEE HENG
	Reg No/Reg Date	SMF8289X / 27/11/201
	Date In/Mileage	/ 0
	Chassis No	GF7W0600621
	Engine No	4J11AC4792
	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	13/05/2019/ 20:58	QUD	247 / DonBong	39830			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED ON REAR TAILGATE, REAR BUMPER FACE, CUT/WELD REAR END PANEL, REPAIR BOTH REAR FENDER								1100 2750.00
E PNT88000 RENEW REAR WINDSCREEN GLASS								✓ 240.00
M SUNDRY SUPPLY REAR WINDSCREEN SEALANT								✓ 80.00
E PNT88000 TRANSFER REAR TAILGATE MECHANISM, TRIM AND OTHERS ATTCAHMENT TO NEW TAILGATE PANEL								275 300.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST								✓ 80.00
E PNT88000 REMOVE AND INSTALL REAR CABIN SIDE TRIM, FLOOR ATTACHMENT TO FACILIATE REPAIR WORK								? 200.00
E PNT98000 PAINT WORK REAR END PANEL, REAR BUMPER FACE, ✓ REAR TAILGATE, RH REAR FENDER, LH REAR FENDER ✓ AND AFFECTED PORTION								840 2520.00
M SUNDRY APPLY BODY SEALANT								80 240.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								30 50.00
M SUNDRY PERFORM RUST PREVENTION								80 180.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								✓ 200.00
M SUNDRY SUPPLY MIVEC EMBLEM								new 50.00
M SUNDRY SUPPLY C&C LOGO								new 50.00
M SUNDRY								? 2801.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LHO LEE HENG	Cust No/Name KCV09743/LHO LEE HENG
BLK 10 JALAN LEMPENG	Reg No/Reg Date SMF8289X / 27/11/201
#13-02	Date In/Mileage / 0
SINGAPORE 128797	Chassis No GF7W0600621
Contact No Mobile: 96188243	Engine No 4J11AC4792
	Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	13/05/2019/ 20:58	QUD	247 / DonBong	39830

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
SUPPLY PARKING SENSOR				20. 50.00
M SUNDRY				? 211.00
SUNDRIES				bt ✓ 974.00
M W/STRIP, TAILGATE OPENING	1.00	211.00	00.00	as ✓ 12.00
M PANEL ASSY, TAILGATE	1.00	974.00	00.00	as ✓ 54.00
M DAM, TAILGATE, UPR	1.00	12.00	00.00	as ✓ 41.00
M DAM, TAILGATE SIDE	2.00	27.00	00.00	as ✓ 6.00
M DAM, TAILGATE, LWR	1.00	41.00	00.00	? 743.00
M STOPPER, WINDSHIELD GLASS	2.00	3.00	00.00	Rx 489.00
M GLASS, TAILGATE WINDOW	1.00	743.00	00.00	? 422.00
M GARNISH, TAILGATE	1.00	489.00	00.00	? 422.00
M SENSOR, TAILGATE LOCK, LH	1.00	422.00	00.00	? 470.00
M SENSOR, TAILGATE LOCK, RH	1.00	422.00	00.00	? 19.00
M LATCH, TAILGATE	1.00	470.00	00.00	as ✓ 94.00
M STRIKER, TAILGATE LATCH	1.00	19.00	00.00	? 78.00
M MARK, OUTLANDER	1.00	94.00	00.00	? 78.00
M REINFORCEMENT, RR BUMPER, RH	1.00	78.00	00.00	? 12.00
M REINFORCEMENT, RR BUMPER, LH	1.00	78.00	00.00	? 12.00
M BRKT, R/BMPR FACE SIDE, LH	1.00	12.00	00.00	as ✓ 8.00
M BRKT, R/BMPR FACE SIDE, RH	1.00	12.00	00.00	? 289.00
M CLIP, FR BUMPER	4.00	2.00	00.00	x 99.00
M EXTENSION, RR BUMPER	1.00	289.00	00.00	x 99.00
M REFLECTOR, TAIL LAMP, LH	1.00	99.00	00.00	Rx 243.00
M REFLECTOR, TAIL LAMP, RH	1.00	99.00	00.00	Rx 144.00
M PANEL, RR END	1.00	243.00	00.00	Rx 144.00
M PANEL, RR END, INR RH	1.00	144.00	00.00	
M PANEL, RR END, INR LH	1.00	144.00	00.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Tanplu 97495749SURVEYOR SIGNATURE: [Signature]DATE: 4/6/19 1130 WP

Confirm & accepted by

REMARKS: * Resurvey before paintsurv @ 10 days

Nett 14,954.00
7% GST on 14954.00 1046.78
Total Payable 16,000.78

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.