

22/03/2002

ASS. REC. BY:

REF: (S3/MSG) 19008624 / GC d3d Special Instruction:

SUNVAJOY

GQ

## ASSIGNMENT (Office)

From (Person): Christina Wong of MSIG Date/Time: 15.5.19 16.16pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLB 66859 Insured: FBC 1357A

at Workshop m/s Sau Hock motor Tel: 91098638

of 10 Amp Industrial Park 2A #02-14

Policy No: MSD/VMT/18-389692 Claim No: MSC/V/19-000561

Sum Insured: Excess:

Make of Veh: D.O.A. 11.5.19  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 15.5.19 4.26pm Person Contacted: Robert Vehicle: IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	SLB 66859 - X
	FBC 1357A - X
	Dismantle: 17/5/2019
	After repair: 21/5/2019

Surveyor

62L  
DRS

REF: MSIG

87486

# ASSIGNMENT

From: Date: 16.5.2019

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: SLB 6685G  
at Workshop m/s Sau Hock motor  
of 10 AMK Industrial Park 2A #02-14

Insured: ~~909~~

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: ~~ADINA~~

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "up"

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLB6685G Yr Regn: 18 Apr 2016

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel 1.5X c.c 1496

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 43640 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RU 11113153

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16  
R: 11

BS / ☒ BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at w/s

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$4000 - \$5000  
17/5/2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format: PRC

Lump Sum / I.B.I. (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

120

11

131

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 May 2019 11:10		15 May 2019 16:16 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	<b>BEE TECK INTERNATIONAL PTE LTD, Co. Reg. No.: 200310572K</b>								
Main Claimant:	<b>LIM ENG HIONG JOSEPH, ID: S0188748C</b>								
Vehicle Reg. No.:	<b>SLB6685G</b>	Date of Loss:	11/05/2019 00:00 - :59 [36 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP</b>	Policy/Cover Note No.:	MSD/VMT/18-389692 Coverage: 29/09/2018 - 28/09/2019						
Vehicle Reg. No. (Insured):	<b>FBC1357A</b>	Policy No. (Claimant):							
Repairer:	Sau Hock Motor Services (HQ) 10 Ang Mo Kio Industrial Park 2A, #02-14 AMK Autopoint, 568047 Ang Mo Kio - Tel: 91098638								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/05/2019]								
Driver/Custodian (Insured):	TAMILARASAN SUBURAYAN (), NRIC: G5245138N Email:								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: 100% CONTACT: ROBERT 9109 8638								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	8748C
Vehicle No.:	SLB6685G
Vehicle to be Exported:	No
Intended Deregistration Date:	16 May 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	L15B4033159
Chassis No.:	RU11113153
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,675.00
Original Registration Date:	18 Apr 2016
First Registration Date:	18 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$9,675.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Apr 2026
PARF Rebate Amount:	\$7,256.00
COE Expiry Date:	17 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,009.00
COE Rebate Amount:	\$31,835.00
<b>Total Rebate Amount:</b>	<b>\$39,091.00</b>

The information contained herein is correct as at 16 May 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/05/2019 10:59
Date Of Accident	11/05/2019 19:55
Exact Location Of Accident	ROCHOR CANAL ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB6685G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM ENG HIONG JOSEPH
NRIC No	S0188748C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90254773
Alternative Phone No	OTHERS-96744320

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X A
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5108534644
Cover Note Number	

### Driver

Name of Driver	LIM ENG HIONG JOSEPH
NRIC No	S0188748C
Date Of Birth	26/08/1950
Occupation	INDOOR
Date Of Driving Pass	23/01/1981
Driving Experience	38 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90254773
Fax Number	
Contact Number	OTHERS-96744320
Email Address	NOEMAIL

Address	BLK 553 ANG MO KIO AVENUE 10 #06-1992
Postcode	560553
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: CHUA LEE BUEH
	GENDER: FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ACCIDENT STATEMENT AS ATTACHED.


#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBC1357A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	TAMILARASAN SUBURAYAN
NRIC/Passport Number	03551581
Contact Number	98530618
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While turning into ~~the~~ Minor Road Rochor Canal just before Zebra Crossing I stop my vehicle to allow an elderly man to cross. M/c suddenly hit from behind with heavy force. No injury on both sides.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Joelle Tan  
NRIC/FIN NO.: AMK AUTOPPOINT PTE LTD  
13.05.2019

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 May 2019 11:10		15 May 2019 16:16 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>




































  



















































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>BEE TECK INTERNATIONAL PTE LTD</b> , Co. Reg. No.: 200310572K								
Main Claimant:	<b>LIM ENG HIONG JOSEPH</b> , ID: S0188748C								
Vehicle Reg. No.:	<b>SLB6685G</b>	Date of Loss:	11/05/2019 19:00 - :59 [36 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MSC/V/19-000561</b>	Policy/Cover Note No.:	MSD/VMT/18-389692-CA (TP, Fire & Theft) Coverage: 29/09/2018 - 28/09/2019						
Vehicle Reg. No. (Insured):	<b>FBC1357A</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Sau Hock Motor Services (HQ)</b> 10 Ang Mo Kio Industrial Park 2A, #02-14 AMK Autopoint, 568047 Ang Mo Kio - Tel: 91098638								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Imm.Advice due 16/05/2019]								
Driver/Custodian (Insured):	TAMILARASAN SUBURAYAN (), NRIC: G5245138N Email:								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: 100% CONTACT: ROBERT 9109 8638								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SLB6685G (MSC/V/19-000561)  
[FBC1357A]  
TP  
LIM ENG HIONG JOSEPH  
May 11 2019 7:00PM  
[BEE TECK INTERNATIONAL PTE LTD]  
Sau Hock Motor Services

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print
1	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
2	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
3	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
4	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
5	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
6	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
7	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
8	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
9	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
10	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
11	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
12	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
13	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
14	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
15	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
16	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
17	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
18	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
19	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
20	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
21	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
22	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
23	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
24	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
25	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
26	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
27	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
28	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
29	06/06/19 13:59	General View							Load JPG	<input checked="" type="checkbox"/>
30	06/06/19 13:59	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
31	06/06/19 13:59	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
32	06/06/19 13:59	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
33	06/06/19 13:59	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
34	06/06/19 13:59	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
35	06/06/19 13:59	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
36	06/06/19 13:59	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
37	06/06/19 13:59	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
89	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
90	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
91	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
92	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
93	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
94	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
95	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
96	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
97	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
98	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
99	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
100	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
101	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
102	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
103	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
104	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
105	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
106	06/06/19 13:59	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
107	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
108	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
109	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
110	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
111	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
112	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
113	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
114	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
115	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
116	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
117	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
118	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
119	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
120	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
121	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
122	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
123	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
124	06/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/05/19 11:11	Notice of PRI	Load PDF	
2	15/05/19 09:41	SURVEY DISAGREE ON SJE - ASSIGN LKK	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19008628/GCD3E2

Date: 10/06/2019

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/18-389692-CA
Claimant Vehicle No :	SLB6685G	Insured Vehicle No :	FBC1357A
Date of Loss:	11/05/2019	Nature of Claim:	TP
		Claim No:	MSCN/19-000561

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLB6685G	Engine No:	L15B4033159
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU11113153
Reg. Date:	18/04/2016 (Man. Year: 2016)	Odometer:	43640 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	15/05/2019	
Date Inspected:	16/05/2019 Inspected At:	Sau Hock Motor Services (HQ) 10 Ang Mo Kio Industrial Park 2A, #02-14 AMK Autopoint Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2019)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLB6685G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >