

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG19008633/KBA3Q2**Date:** 29/12/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700070414
Claimant
Vehicle No : SHC5819L **Insured Vehicle No :** SLT6813J
Date of Loss: 10/05/2019 Nature of Claim: TP Claim No: 2108233382SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5819L**
Make & Model: RENAULT LATITUDE, 2.0 D dCi (A) Engine No: M9R8839C002329
Reg. Date: 11/12/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC280917
Colour: Metallic White/Red Odometer: 472758 km
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Giti 7 mm Rear Left Side: Giti 7 mm
Front Right Side: Giti 7 mm Rear Right Side: Giti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,547.83	1,904.92	19,642.91	91.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,180.00	900.00	19,280.00	95.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,727.83	2,804.92	38,922.91	93.28
Approved Total (Overridden) (S\$)		2,250.00		
(S\$)	41,727.83	2,250.00	39,477.83	94.61
+ GST 7.00/7.00% (S\$)	2,920.95	157.50	2,763.45	94.61
Nett Amount (S\$)	44,648.78	2,407.50	42,241.28	94.61
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$96.99/day) (S\$)		387.96		
Nett Liability (S\$)		2,995.46		
Global Sum Settlement (S\$)		2,800.00		

INSPECTION

Date of Assignment: 14/05/2019
Date Inspected: 14/05/2019 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111
Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	*- FL
2	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
3	1		*BUMPER RETAINER FRT RH	Serviceable	151.41 FL	*- FL
4	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
5	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
6	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
7	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
8	1		*BUMPER BEAM FRT	Serviceable	914.08 FL	*- FL
9	1		*HEADLAMP RH	Serviceable	1,184.43 FL	*- FL
10	1		*HEADLAMP PANEL FRT RH	Serviceable	152.15 FL	*- FL
11	1		*FENDER PANEL FRT RH	Buckled	783.83 FL	*783.83 FL
12	1		*WHEELARCH FRT RH	Serviceable	278.84 FL	*- FL
13	1		*FENDER BRACKET LOWER RH	Repair	15.79 FL	*- FL
14	1		*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
15	1		*TOW COVER FRT	Serviceable	28.61 FL	*- FL
16	1		*FRONT BRACE PANEL	Serviceable	177.22 FL	*- FL
17	1		*RADIATOR GRILLE	Serviceable	1,707.78 FL	*- FL
18	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*- FL
19	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	*- FL
20	1		*FRAME FULL SUPPORT PANEL	Serviceable	615.90 FL	*- FL
21	1		*FRAME FULL SUPPORT BRACKET	Serviceable	89.79 FL	*- FL
22	1		*DOOR PANEL FRT RH	Serviceable	2,844.66 FL	*- FL
23	1		*DOOR MIRROR ASSY RH	Serviceable	1,483.40 FL	*- FL
24	1		*DOOR MIRROR GLASS RH	Serviceable	148.20 FL	*- FL
25	1		*DOOR MIRROR BACK COVER RH	Serviceable	218.46 FL	*- FL
26	1		*WIPER RESERVOIR MOTOR	Serviceable	270.06 FL	*- FL
27	1		*WIPER RESERVOIR	Serviceable	348.25 FL	*- FL
28	1		*WIPER RESERVOIR NECK	Serviceable	136.11 FL	*- FL
29	1		*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	*- FL
30	1		*ROCKER PANEL INNER RH	Serviceable	1,024.79 FL	*- FL
31	1		*ROCKER PANEL CENTER RH	Serviceable	990.25 FL	*- FL
32	1		*ROCKER PANEL OUTER RH	Serviceable	1,184.99 FL	*- FL
33	1		*DOOR HARNESS WIRE RH	Serviceable	2,670.00 FL	*- FL
34	1		*BUMPER COVER FRT	Missing	1,259.42 FL	*1,259.42 FL
35	1		*FRONT DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
36	1		*FRONT DOOR STICKER CLASSIC	Not Necessary	80.00 FS	*- FS
37	1		*BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
38	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
39	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
40	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
41	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
42	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
43	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
44	1		*WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	*- FS
45	1		*FRONT RIGHT TYRE	Serviceable	300.00 FS	*- FS
46	1		*FRONT RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS
47	1		*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS
48	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
49	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 23,798.03 2,109.25
- List Item Discount on L Items 10.00/10.00% (\$\$) 2,250.20 204.33

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (\$)	21,547.83	1,904.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	7,500.00	400.00
2	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	50.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	400.00
5	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	50.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
9	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
10	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
12	TO TRANSFER OF BONNET FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
13	TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING	New	380.00	0.00
14	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
15	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
16	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET VEHICLE WARNING INDICATORS	New	480.00	0.00
17	TO CHECK ABS BRAKE EFFICIENCY,FINAL CHECKING AND TESTING	New	380.00	0.00
18	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT,VACUUM AND CHARGE-IN-GAS	New	380.00	0.00
Gross Labour Cost (\$\$)			20,180.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >