



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS3/SPF18022678/R1vd3s2-1

ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 18-06-2019



ATTN: HAFIZUL FARHAN

Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 4170B	Veh. Inspected	SLF 909E
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/172	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	14/05/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C250 AMG	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD2050452R058523	Colour	WHITE
Odometer	29575	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40ZR19	MICHELIN	6 mm
L/H Front Tyre	225/40ZR19	MICHELIN	6 mm
R/H Rear Tyre	225/40ZR19	MICHELIN	6 mm
L/H Rear Tyre	225/40ZR19	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information


Accident Date	14/12/2018	Inspection Date	07/01/2019
Survey held at	MIRACLE WORKZ PTE LTD 48 TOH GUAN ROAD EAST #04-126 ENTERPRISE HUB SINGAPORE 608586		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 909E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	NOT NECESSARY	1,850.00	-
1	FRONT BONNET 'LOGO' EMBLEM	NOT NECESSARY	55.00	-
2	FRONT BONNET LOCK STRIKER L/R	NOT NECESSARY	60.00	-
2	FRONT BONNET MECHANISM LOCK L/R	NOT NECESSARY	390.00	-
2	FRONT BONNET RUBBER GUIDE STOPPER L/R	NOT NECESSARY	18.00	-
1	FRONT BONNET WEATHER STRIP	NOT NECESSARY	135.00	-
2	FRONT HEADLAMP L/R	NOT NECESSARY	3,150.00	-
1	FRONT GRILLE	NOT NECESSARY	768.00	-
1	FRONT GRILLE 'LOGO' EMBLEM	NOT NECESSARY	123.00	-
1	FRONT GRILLE 'LOGO' EMBLEM BASE	NOT NECESSARY	85.00	-
1	FRONT GRILLE CHROME GARNISH ASSY	NOT NECESSARY	297.00	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,420.00	-
1	FRONT BUMPER INNER FRAME	NOT NECESSARY	350.00	-
6	FRONT BUMPER PARKING SENSOR (ORIGINAL)	NOT NECESSARY	1,650.00	-
6	FRONT BUMPER PARKING SENSOR HOLDER	NOT NECESSARY	111.00	-
6	FRONT BUMPER PARKING SENSOR RUBBER SEAL	NOT NECESSARY	33.00	-
1	SET FRONT BUMPER PARKING SENSOR WIRE HARNESS	NOT NECESSARY	268.00	-
2	FRONT BUMPER FOGLAMP GARNISH L/R	NOT NECESSARY	178.00	-
2	FRONT AIRBAG SENSOR	NOT NECESSARY	382.00	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	295.00	-
1	FRONT BUMPER LOWER CENTER GRILLE	NOT NECESSARY	65.00	-
1	FRONT BUMPER DIFFUSER CHROME MOULDING	NOT NECESSARY	650.00	-
2	FRONT BUMPER SIDE BRACKET L/R	NOT NECESSARY	114.00	-
2	FRONT BUMPER SIDE RETAINER L/R	NOT NECESSARY	70.00	-
1	FRONT BUMPER TOW HOOK COVER	NOT NECESSARY	72.00	-
	LESS 10% DISCOUNT		-1,258.90	-
			11,330.10	-
SPECIAL NETT ITEMS				
1	FRONT BUMPER NUMBER PLATE (SN)	BENT	25.00	25.00
1	FRONT BUMPER NUMBER PLATE HOLDER (SN)	CRACKED	50.00	50.00
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	50.00	-
			125.00	75.00

Report Ref No. CS3/SPF18022678/R1vd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.	NOT NECESSARY	140.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	150.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		1,200.00	250.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLAED PANEL.	NOT NECESSARY	100.00	-
			2,440.00	400.00
	GRAND TOTAL		13,895.10	475.00
RECOMMENDED COST OF REPAIRS				475.00

Report Ref No. CS3/SPF18022678/R1vd3s2-1

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.